IS-63) LICENSEE EVENT REPORT (LER)													U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO. 3150-0104 EXPIRES 8/31/85						
													DOCKET NUMBER (2)						
LaSalle County Station Unit 2													01317	4	10	F012			
TITLE (4	1				100000	lich Art	lent	Temp	eratu	P ISC	lation								
	Read	tor	Wate	er C	Teanup r	11gn Am	ment	Temp	racui	C 130									
EVI	ENT DAT	E (B)		- 1	LER NUMBER (B)	RE	PORT DAT	E (7)		FACILITY NAT	FACILITIES INVOL	DOCKET NUMBER(S)						
MONTH DAY YEAR YEAR SEQUENTIAL REVE						NUMBER	MONTH	DAY	TEAR				0 151010101 1 1						
								. F					<u></u>						
0 4	23	81	4 8	4-	0 16	- 00	0 5	116	8 4				0 1510	0	101	11			
0.00	BATING	-+	THIS	REPOR	T IS SUBMITTE	D PUR TI	TO THE R	EQUIREME	NTS OF 10	CFR &: /0	Check one or more	of the following) (11	1)						
MODE (9) 1 20.402(b)							20.405	(c)		X	50.73(a)(2)(iv)		73.71(6)						
POWER LEVEL 0 1 6 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(ii)							50.36ic	1)(1)			60.73(a)(2)(v)		73.71(e	3.71(e)					
							50.36ic)(2)		-	50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form						
			-	20.408	(.)(1)(iiii)		60.73ia	2)(1)		-	60.73(a)(2)(viii)(A)	366A)						
20.405(a)(1)(iv)							80.73(a	1)(2)(0)			60.73(a)(2)(viii)	•,							
				20,406	(a)(1)(v)		80.73ia	(2)(III)		LEP (19)	BG.73(a)(2)(x)								
NAME							ICENSEE	CONTACT	FOR THIS	LEH (12)		1	TELEPHONE	UM	IER				
Kermit C Wittenburg, exten							on 77	12				AREA CODE							
Kermite G, writtenburg, exten												81115	5 3 1 51 71 - 1 61 716						
					COMPLETE	ONE LINE FOR	EACH C	OMPONENT	FAILURE	DESCRIBE	D IN THIS REPOR	AT (13)		-					
CAUSE	SYSTEN	- co	MPONEN	T	MANUFAC. TURER	REPORTABLE TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTAB TO NPRO	LE					
~	JIN	4 T 1	1151		R1217 1 9	N						1		Ι					
		1	1121	1		1							1	1					
				_		1			1	1			1		T	,			
					SUPPLEM	INTAL REPORT	EXPECT	ED (14)				EXPECT	ED MO	NTH	DAY	YEAR			
XIVE	S (11 yes,	compie	. EXPECT	TED SU	BMISSION DATE	E)	H	NO				DATE (1	5) 1	11	111	0 814			
Wit 2 R 081 wer tha The the tes fer A W cau	h La h La eaction e ch n 85 Rea sys t sw enti lork ition	sall or V urs. ecke OF v ctor tem itch al t Requ	e Co later Th ed fo which Wat was nes i tempe uest rd wa	er l er l er l er l was	y Statio eanup (C occurred urrent t well be Cleanup tarted. test". ure alar written laced to	n Unit E) high about emperat low the System The sam The sam m came to fin warn o	2 ope ambi 5 mir ure c trip was c me su up a d the	aratin ient t hutes data. b setp checke witche visior fter s e caus e prob	ng at emper after The boint ad for as wer 1 2 is 5 1/2 se of blem.	16% p ature the data of 11 room e che colati minut the u	ower on / isolatio individu showed an 6°F. n leaks, cked aga on alarm ces.	April 23, on signal al tempera mbient tem and when in, but w as well ed isolat	1984, was rea ature so mperatu none we ith the as the ion sig	a l ce wi re i hi na)ivi ived tche s le fou sola gh d l an	sion at ss ss nd, tion if-			
		84 PD S	0530 R AD	002	0 8405 05000	16 374 PDR													

NRC Form 366 19-831

.

LICENSEE EVENT REPORT (LEF.) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED ON& NO. 3150-6104 EXPIRES. 8/31/86

FACILITY NAME (1)	DOCK	DOCKI / NUMBER (2)					1	NUM	PAGE (3)								
		*					VEAP		58	NUM			NUMBER				
LaSalle County Station Unit 2	0 1	5 10	10	10	3	714	8 14	-	- 0) [1	16	-	0 0	0 2	OF	0	2

I. EVENT DESCRIPTION

With LaSalle County Station Unit 2 operating at 16% power on April 23, 1984, a Division 2 Reactor Water Cleanup (CE) high ambient temperature isolation signal (JM) was received at 0810 hours. The individual Riley temperature switches had been taken to the "read" position about 5 minutes earlier for current temperature data per LOD-15, "Containment Isolation System Temperature Monitoring". The data had shown ambient temperatures less than 85°F which is below the trip setpoint of 116°F. After coming up, the isolation signal had immediately cleared.

III. CAUSE

NAC Ferre 386A

The exact cause of the spurious isolation signal is not known; however, it is believed to be associated with taking one or more of the Division 2 temperature switches to the "read" position.

III. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The system operated as designed after receiving the isolation signal and was placed in a safe condition. This type of event did not occur ten days earlier when the same switches had been read for LOD-15.

IV. CORRECTIVE ACTIONS

After ensuring that the system had isolated as designed, the unit Operator had the Reactor Water Cleanup Rooms checked for leaks. When none were found, the system was restarted at 0825 hours. The same switches were checked again, but with the isolation test switches in the "test" position. The same Division 2 isolation alarm as well as the High Differential Temperature Alarm came up after 5 1/2 minutes. The isolation test switch was then returned to normal and a Work Request written to find the cause of the isolation signal. A caution card was placed by the Division 2 switches to warn of the problem and to state that the isolation test switch should be placed in "test" before reading the temperatures. AIR 01-84-67074 tracks the completion of a supplemental LER when the actual cause is determined.

V. PREVIOUS EVENTS

This event has not occurred before either on Unit 1 or Unit 2. The high ambient temperature switches have not had a history of spurious isolations. At no time has the temperature in the various rooms been observed to be near the trip setpoints.

VI. NAME AND TELEPHONE NUMBER OF PREPARER

Kermit C. Wittenburg, 815-357-6761, extension 772.



.

Commonwealth Edison LaSalle County Nuclear Station Rural Route #1, Box 220 Marseilles, Illinois 61341 Telephone 815/357-6761

May 16, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

Reportable Occurrence Report #84-016-00, Docket #050-374 is being submitted to your office in accordance with 10 CFR 50.73.

Deelevil

G. J. Diederich Superintendent LaSalle County Station

GJD/MLD/kg

Enclosure

xc: NRC, Regional Director INPO-Records Center File/NRC

IE22 11