

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) CALVERT CLIFFS, UNIT 2	DOCKET NUMBER (2) 050003118	PAGE (3) 1 OF 013
---	--------------------------------	----------------------

TITLE (4)  
D/G Inoperability

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					
									N/A					
0	4	2	6	8	4	8	4	0	0	5	0	0	0	0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

OPERATING MODE (9) 6	20.402(b)	20.406(e)	80.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 000	20.406(a)(1)(i)	80.36(a)(1)	80.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	80.36(a)(2)	80.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii)	X 80.73(a)(2)(i)	80.73(a)(2)(viii)(A)		
20.406(a)(1)(iv)	80.73(a)(2)(ii)	80.73(a)(2)(viii)(B)		
20.406(a)(1)(v)	80.73(a)(2)(iii)	80.73(a)(2)(ix)		

LICENSEE CONTACT FOR THIS LER (12)

NAME P. PIERINGER, SR. ENGINEER-OPERATIONS	TELEPHONE NUMBER 310 11 216 10 1-1417 4 12
AREA CODE	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

With the Plant in MODE 6, an electrical lineup was performed to allow preventive maintenance on 24A 480V AC Bus. This lineup powered 21 Diesel Generator (DG) auxiliaries from a bus receiving its backup power from 12 DG, thereby causing a loss of independence between 21 and 12 DGs. Although 21 DG was considered inoperable at this point, that fact was not conveyed to personnel on subsequent shifts. Since only one DG is required operable in MODE 6, no technical specification action statements were entered and hence no log entry to the effect that 21 DG was inoperable was made. The following shift, not realizing the lack of independence, removed 12 DG from service, which resulted in inoperability of both DGs. Believing 21 DG to be operable, T.S. 3.8.2.2 was violated in that containment integrity was not established within 8 hours. To prevent a recurrence of a similar event the conditions surrounding this event will be reviewed with all licensed personnel. Additionally, lists of equipment required for the operability of each DG have been compiled for use in aiding the operator in ascertaining the operability of required DGs prior to removing the redundant DG from service.

8405300029 840524  
PDR ADDCK 05000318  
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  CALVERT CLIFFS, UNIT 2	DOCKET NUMBER (2)  0 5 0 0 0 3 1 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 4	- 0 0 5	-- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During this event Unit 2 was in MODE 6 with a refueling outage in progress. The reactor vessel head (RPV) was deaerated and reactor vessel water level ranged between 1.2 and 1.5 feet above the bottom of the hot leg. Primary temperature ranged between 106° and 112° F and the steam generator (SG) manways were removed. No core alterations had yet been performed and none were scheduled during the period of concern. No reactivity changes occurred during the period of concern.

At 2115 on April 25, 1984, 24A 480V AC Safety bus (ED-BU) was removed from service for preventive maintenance. To maximize 21 DG (EK-DG) availability, 21 DG auxiliaries (Fuel oil transfer pump DC-9, room ventilation fan VJ-Fan, air start system air compressor LC-CMP, and various other engine auxiliaries LB-EHT, P and LA-EHT, P), normally supplied from 24A 480V AC Bus via MCC 204R (ED-BU), were kept energized by powering MCC 204R from MCC 214R (ED-BU) via a tie breaker (ED-BKR). This lineup, which is shown in the drawing (see Attachment 1), allowed 12 DG (EK-DG) to power 21 DG auxiliaries but in turn removed the independence between the two DGs. 21 DG was declared out of service, but not logged as such since T.S. 3.9.1.2 requires only one diesel to be operable in MODES 5 and 6. Had the unit been in a higher mode, less severe consequences would have occurred as the log entry concerning entry into a T.S. action statement would have prevented 12 DG from being taken out of service.

At 0625 on April 26, 1984, licensed personnel on the next shift failed to recognize the dependence of 21 DG on 12 DG and placed 12 DG out of service so preventive maintenance could be performed. Although operations personnel were aware that Unit 2 480V Bus 24A was out of service, the correlation was not made between that work and its effect on 21 DG operability. Consequently, both 12 and 21 Diesels were made inoperable.

At 1615 on April 26, 1984, a Senior licensed operator noted that both 12 and 21 DGs were inoperable and containment integrity had not been established as required by T.S. 4.8.2.2. Restoration of 12 DG to operability was in progress at the time and was continued. At 2105 12 DG was declared operable terminating the event.

During this event, the 2 500KV offsite power circuits and the 69KV SMECO offsite power circuit remained operable. Had the 2 normal offsite power circuits been lost during the event, the 69KV SMECO power supply could have been aligned to Unit 2 to supply the safety loads required for shutdown operation. Had a total loss of off-site power occurred during the event, DG 11 would have automatically started and paralleled to Unit 1 Bus 11 (EK-DG). DG 21 would have automatically started and paralleled but would have eventually shutdown when the fuel oil day tank was depleted or on a fault condition caused by the high DG room temperature (because of the inoperable ventilation fan). Existing inspection procedures and Control Room alarms would have ensured the operators' awareness of these conditions prior to an actual diesel trip condition. By realigning 11 DG to Unit 2 4KV Bus 21 and 21 DG to Unit 1 4KV Bus 14, an independent DG would be available for each unit allowing, in this case, Unit 1 to be safely shutdown and Unit 2 to be maintained in a MODE 6 configuration.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  CALVERT CLIFFS, UNIT 2	DOCKET NUMBER (2)  0   5   0   0   0   3   1   8	LER NUMBER (6)			PAGE (7)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   4	-   0   0   5	-   0   0	0   3	OF 0   3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Procedurally, the Unit 2 operations staff would be expected to implement the abnormal operating procedure dealing with loss of shutdown cooling should a total loss of off-site power occur. For various times after shutdown, this procedure provides time periods until core boiling and fuel uncover. Following a complete loss of shutdown cooling, the calculations supporting this information assume the reactor coolant system (AB) is drained to the bottom of the hot leg, that initial RCS temperature is 150° and the reactor vessel head is removed. All of these conditions are conservative to those actually existing. Had an offsite power loss occurred at the time of maximum decay heat for this event (when both DGs first became inoperable) the operator would have determined he had approximately 18 minutes until primary coolant saturation temperature was reached and 68 minutes prior to the start of fuel assembly uncover. As the required electric system lineup could be established well within the time before fuel uncover, it is concluded that the loss of offsite power condition could not have produced consequences of a more serious nature.


To prevent a recurrence of a similar event the following corrective actions will be (or have been) taken:

1. A list of equipment required to maintain DG operability has been prepared for each DG. When a condition arises which requires a DG to be placed out of service, these lists which will become part of the Calvert Cliffs Operating Manual, are used as an operator aid for verifying the operability of the redundant DG. These lists include both mechanical and electrical systems, which are required to maintain DG operability.
2. All licensed operators will receive training during the annual requalification cycle on the conditions surrounding this event. Particular emphasis will be given to the role electrical distribution plays in supporting DG operability.

No similar events have been reported.


ATTACHMENT 1

NORMAL LINEUP



KEY:  $\times$  ⇒ closed BREAKER  
 $)$  ⇒ open BREAKER

EVENT LINEUP





KEY:  $\times$  ⇒ closed BREAKER  
 $)$  ⇒ open BREAKER

↑  
 ABNORMAL  
 CROSS TIE  
 CONNECTION

ATTACHMENT 2

REQUIRED ELECTRICAL LINEUP  
DURING LOSS OF OFFSITE POWER



KEY : | / \ ⇒ CLOSED BREAKER  
| ) ⇒ OPEN BREAKER



BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT  
CALVERT CLIFFS NUCLEAR POWER PLANT  
LUSBY, MARYLAND 20657

May 24, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington D.C. 20555

Dear Sir:

The attached LER 84-05 is being sent to you as required by  
10 CFR 50.73.

Should you have any questions regarding this report, we would  
be pleased to discuss them with you.

Very truly yours,

*LBR*

L. B. Russell  
Plant Superintendent

*1/1*

LBR:PAP:srm

cc: Dr. T. E. Murley  
Director, Office of Management Information  
and Program Control  
Messrs: A. E. Lundvall, Jr.  
J. A. Tiernan

IE22  
1/1