NRC FORM 36	56	U.S. NUCLEAR REGULATORY COMMISSION
	LICENSEE EVENT REPORT	EXHIBIT A
	CONTROL BLOCK: 1_1_1_1_1_1_1_1 (PLEASE PRINT OR TYPE AN	L REQUIRED INFORMATION)
$\frac{10}{7} \frac{11}{8}$	9 LICENSEE CODE 1 1 12 10 101 - 10101010101 - 1010101 - 101013 14 LICENSEE CODE 14 15 - 101010101010101 - 10101010101 - 101013 14	LICENSE TYPE 30 57 CAT 58
$\frac{10}{7} \frac{11}{8}$	REPORT I L I <td></td>	
10121	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 [On 5/24/83, while performing annual surveillance testing on the electric drive	n emergency feedwater pump P-78, [
10131	lit was observed that the outboard thrust bearing temperature was high. The pu	mp was declared inoperable.
1014	This event is reportable per Technical Specifications 3.4.1.4 and 6.12.3.2.b.	Similar LER's include (50-313)
10151	179-007 and 78-003.	1
10161	1	
10171	· · · · · · · · · · · · · · · · · · ·	
10181	9	
	SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE 1 H H H H 1 H H H H 1 H H H H	COMP VALVE 80 SUBCODE SUBCODE SUBCODE 1 I B 115 I Z 116
17 RI	ER/R0 I II III IIII III IIII IIII IIII IIII IIII IIII IIIII IIII IIII IIII IIII IIIII IIIII IIIIIIIIII IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	19 20 REPORT REVISION TYPE NO 1 X 1 1 1 30 31 32
TAI	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	JB SUPPLIER MANUFACTURER
11101	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 IExcessive thrust bearing clearance was found. This resulted in the balance dru	
	lexcessive thrust causing the bearing to overheat. The thrust bearing clearance	
1121	Itolerance range is .0005"002". The thrust bearing was replaced, and the cl	
11131	laddition, the bearing cooling lines were inspected and found clear of blockage.	
$\left[1 \right] 4$	Icates that the previous "as-left" clearance was .002". Since no determination	
F	ACILITY METHOD OF	80 VERY DESCRIPTION e Test 132
AR	ELEASED OF RELEASE AMOUNT OF ACTIVITY	ATION OF RELEASE
	9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 44 45 1 0 1 0 1 12 138 1 NA 9 11 12 138 1 NA 13 13	80
	RSONNEL INJURIES	139 80
	NUMBER DESCRIPTION 9 1 0 1 0 140 1 NA 9 1 1 12	[41
	LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 1_Z_142 1NA	
	PUBLICITY ISSUED DESCRIPTION I N 144 I NA 9 10	NRC USE ONLY
N	NAME OF PREPARER Dan E. Moeggerts rg	PHONE: (501) 964-3100
	8405300078 840518	

8405300078 840518 PDR ADDCK 05030313 S PDR

*

IE22

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/83-011/03X-1

Occurrence Date: 5/24/83

Cause Description and Corrective Actions (Continued)

clearance increased from .002" to .013", the thrust bearing clearance will be rechacked during the next cold shutdown to ascertain whether or not it remains within allowable tolerance. The increase in thrust was due to a "cushioning effect" caused by having an excessive number of shims installed. Procedures for this and similar equipment were changed to adequately address thrust clearance and torque value. In addition, a shim spacer was installed on both EFW pumps to alleviate the "cushioning effect".



ARKANSAS POVVER & LIGHT COMPANY PCST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 May 18, 1984

1CANØ584Ø7

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

> Subject: Arkansas Nuclear One - Unit 1 Docket No. 50-313 License No. DPR-51 Licensee Event Report No. 83-011/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specifications 3.4.1.4 and 6.12.3.2.b, attached is the subject report concerning excessive outboard thrust bearing temperature of the electric driven emergency feedwater pump P-7B. This is a revision to a previous submittal dated June 9, 1983.

Very truly yours,

John R. Marshall Manager, Licensing

JRM: RJS: ac

Attachment

cc: Mr. Richard P. Denise, Director Division of Resident Reactor Projects and Engineering Programs U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011