

INCIDENT EVENT REPORT

EXHIBIT A

LER No. 59-369/83-005/03X-1

Occurrence Date: 02/01/83

Event Description and Probable Consequences (Continued)

regarding hydraulic problems were reported in LERs 79-043, 79-089, 79-089, 79-090, 79-093, 80-003, 81-032 and 82-019.

Cause Description and Corrective Action (Continued)

motor to shut off. The hydraulic pump was replaced and the hydraulic system was filled and vented. The valve was proven operable and returned to service. The valve operator for 2CV-1025-1 is manufactured by Weston Hydraulics. Brown & Sharp manufactured the hydraulic pump (model MFC-4-10a1) that was replaced. Long-term corrective action was to replace these Weston-Hydraulic valve actuators with Limatorque SMB-000-2 460 A.C. motor operators during the 2R3 refueling outage.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 25, 1984

2CANØ584Ø5

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

SUBJECT: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-005/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning an emergency feedwater control valve failure. This is an update to a previous submittal dated February 22, 1983.

Very truly yours,

John R. Marshall
Manager, Licensing

JRM:RJS:ac

Attachment

cc: Mr. Richard P. Denise, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

IE22
11