COMPANY Houston Lighting & Power P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

May 17, 1984 ST-HL-AE-1084 File No.: G12.95

Mr. John T. Collins Regional Administrator, Region IV Nuclear Regulatory Commission 611 Ryan Plaza Dr., Suite 1000 Arlington, Texas 76012

Dear Mr. Collins:

**The Light** 

South Texas Project Units 1 & 2 Docket Nos. STN 50-498, STN 50-499 Supplemental Report Concerning the Heating, Ventilation and Air Conditioning Design Deficiency

On May 8, 1981, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P) notified your office of an item concerning the consideration of certain faulted condition heat loads in the design of portions of the Heating, Ventilation and Air Conditioning (HVAC) system. Based on an assessment of preliminary thermal environmental data, it was determined that certain spaces and cubicles within the Mechanical-Electrical Auxiliary Building (MEAB) and the Fuel Handling Building (FHB) would likely require additional HVAC capacity.

On July 6, 1982, HL&P expanded the scope of this item to include two additional items: use of fail open isolation dampers in the HVAC design and single failure criteria in the EAB supply air mixing box. There was a concern that the failure mode of isolation dampers had not been adequately assessed by Brown & Root, Inc. (B&R) in the HVAC design.

On October 20, 1982, HL&P submitted the Final Report on these items. The statement in the final report indicating that all safety-related equipment has safety-related cooling is incomplete. The design criteria is to qualify all safety-related equipment for the environmental conditions in which it must perform its safety function. Where controls, instrumentation, valves, etc., are not served by safety-related cooling, these components will be qualified to the most severe environmental conditions to which they may be exposed.

8405300110 840517 PDR ADDCK 05000498 S PDP

W2/NRC2/f

Houston Lighting & Power Company

May 17, 1984 ST-HL-AE-1084 File No.: G12.95 Page 2

Due to design changes made subsequent to the submittal of our Final Report, the information presented below modifies and updates that report.

- (1) Paragraph 1(b) of Findings for Deficiency (A): The containment atmosphere hydrogen monitors are now being relocated outside the radwaste control room to reduce any unnecessary personnel exposure that might arise from the air sample filter and lines. Safety-related HVAC cooling will be provided to the hydrogen monitors in their new location on elevation 60 feet of the MEAB.
- (2) Corrective Action for Item A(b)2 of Deficiency B: Each makeup air pressurizer damper will be driven by an electro-hydraulic actuator which is controlled by a manual loading station within the main control room. The damper will automatically open to a preset position to permit pressurization of the control room envelope. During operation of the makeup air filtration system, the operator can maintain positive pressure by manually adjusting the damper to accommodate filter loading conditions.
- (3) Corrective Action for Deficiency C: As stated in the Final Report, this deficiency will now be resolved by deleting the EAB HVAC dual duct concept and providing a single cold supply air duct. This involves deleting the mixing boxes and hot duct in the existing design. With deletion of the mixing boxes there will be no active component to isolate in the supply duct distribution system downstream of the air handling unit safety isolation dampers, thus eliminating the possibility of the subject active failure.

The above corrective action involves complete revision of the existing duct layout in EAB and purchase of new reheat coils for certain areas requiring close temperature control. The reheat coils for the EAB (except 1E battery rooms) need not be safety-related; however, they will be provided with safety-related isolation controls. Reheat coils for 1E battery rooms will be safety-related to maintain battery room temperature conditions.

This information supplements the Final Report concerning this item.

If you should have any questions concerning this item, please contact Mr. Michael E. Powell at (713) 993-1328.

Very truly yours, W. Obrea

Executive Vice President

MEP/mpg Attachment W2/NRC2/f

## Houston Lighting & Power Company

## cc:

Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, DC 20555

Victor Nerses, Project Manager U.S. Nuclear Regulatory Commission 7920 Norfolk Avenue Bethesda, MD 20016

D. P. Tomlinson Resident Inspector/South Texas Project c/o U.S. Nuclear Regulatory Commission P. O. Box 910 Bay City, TX 77414

M. D. Schwarz, Jr., Esquire Baker & Botts One Shell Plaza Houston, TX 77002

J. R. Newman, Esquire Newman & Holtzinger, P.C. 1025 Connecticut Avenue, N.W. Washington, DC 20036

Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

E. R. Brooks/R. L. Range Central Power & Light Company P. O. Box 2121 Corpus Christi, TX 78403

H. L. Peterson/G. Pokorny City of Austin P. O. Box 1088 Austin, TX 78767

J. B. Poston/A. vonRosenberg City Public Service Board P. O. Box 1771 San Antonio, TX 78296 May 17, 1984 ST-HL-AE-1084 File Number: G12.95 Page 3

Brian E. Berwick, EsquireAssistant Attorney General for the State of TexasP. O. Box 12548, Capitol StationAustin, TX 78711

Lanny Sinkin Citizens Concerned About Nuclear Power 114 W. 7th, Suite 220 Austin, TX 78701

Robert G. Perlis, Esquire Hearing Attorney Office of the Executive Legal Director U.S. Nuclear Regulatory Commission Washington, DC 20555

Charles Bechhoefer, Esquire Chairman, Atomic Safety & Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. James C. Lamb, III 313 Woodhaven Road Chapel Hill, NC 27514

Judge Ernest E. Hill Hill Associates 210 Montego Drive Danville, CA 94526

William S. Jordan, III, Esquire Harmon & Weiss 1725 I Street, N.W. Suite 506 Washington, DC 20006

Citizens for Equitable Utilities, Inc. c/o Ms. Peggy Buchorn Route 1, Box 1684 Brazoria, TX 77422