

DATE: July 10, 1990

TO: Director, Office of Allegation Coordinator, Region 1

FROM: Edward C. Menzinger, Chief, Reactor Projects
Branch 4 *ECM*

TO: Donald P. Haverkamp, Chief, Reactor Projects
Section 4A

SUBJECT: CLOSURE OF ALLEGATION RI-90-4-0031 FOR MILLSTONE NUCLEAR
POWER STATION UNIT TWO.

This allegation is closed. The alleged has expressed his concerns
to the Northeast Utilities Nuclear Safety Concerns Program, thereby
no further NRC follow up specific to this allegation is required.

I have enclosed my closing file to complete your records.

Donald P. Haverkamp

Donald P. Haverkamp, Chief
Reactor Projects Section 4A
Division of Reactor Projects

Enclosure: As stated

H/S

DISCUSSION AND CONCLUSIONS:

1. The resident did not achieve clarification for major points of disagreement on number 8, 9, and 10.
2. Engineer provided licensee's steam generator structural integrity assessment action plan that includes: DA analytical evaluation of all 11/90 tube crack profiles, tube rupture pressure tests over three regions of the limit load curve, review of industry burst test results, 3-D finite element analysis of tube L45/R13 by combustion engineering, calculation of probability of one tube being unacceptable versus time at monthly increments, probability of secondary side depressurization event during the remaining fuel cycle, and licensee structural integrity position to generation engineering management. Completion date is 3/28/90.
3. Engineer did not attend presentation to NRC on 2/22, however senior vice president made it clear it was the engineer's option.
4. The safety assessment lead for the licensee was the NMC organization. Engineer believes organization comes to conclusion without a basis (i.e. evaluations).
5. Senior Vice President extension basis for presentation to NRC as reported internally to licensee organization was if there is no supporting basis, ^{get} then extension; ^{for meeting date} if no basis available shut the unit down.
6. The night prior to the NRC presentation, the licensee added the one tube failure to regulatory guide 1.121.
7. Senior Vice president according to engineer, made it clear to technical staff that resolution of his concerns is priority, and all available cooperation is necessary.
8. The steam generator safety evaluation according to the engineer is not normal NU engineering development.
9. The CE evaluation of the pulled steam generator tubes concluded the cause of stress corrosion cracking (i.e. caustic/acidic environs) is indeterminate. NMC influenced the CE conclusions in this regards.
10. Engineer did not go to local newspapers, nor did they come to him. He believes this was information within the licensee organization.
11. The NU response to the engineer, was not a collective response by those who signed the safety assessment (i.e. the engineers supervisor was the author of the response).

Conclusions: The resident inspector's recommendation for this issue based on review of the supporting documentation, attendance of the 2/22 meeting, and discussion with the engineer are as follows:

a. NRC review of the requested information, which was the NOV/DEC report on 3/22 final evaluations, CE report on burst tested tubes, and current engineering evaluation.

b. Development of questions during review, and in early April have licensee explain position based on additional scope of work, and if unsupported information was provided to the NRC on 3/22.

TO: CAC

FR: A Vigil

SUBJ: Allegation File RI-90-A-0032

On June 13, 1990 Bob Hamilton the author of the NL Day Article of March 2, 90. ~~He~~ He stated that he did not have source other than MR. Keenan from NL who ~~made~~ discussed this issue at a news conference. He did agree to review his files, and if he did find names of sources he will contact us.

✓
R
AV

H/sg

APPENDIX 3.1

ALLEGATION RECEIPT REPORT

Date/Time Received: 3/9/90 Allegation No. RZ-90-A-0032
 (leave blank)

Name: ANONYMOUS Address: —

Phone: — City/State/Zip: —

Confidentiality:

Was it requested? Yes No
 Was it initially granted? Yes No
 Was it finally granted by the allegation panel? Yes No
 Does a confidentiality agreement need to be sent to allegor? Yes No
 Has a confidentiality agreement been signed? Yes No
 Memo documenting why it was granted is attached? Yes No

Allegor's Employer: — Position/Title: —

Facility: MILLSTONE UNIT 2 Docket No.: 50-336

(Allegation Summary (brief description of concern(s): Received newspaper article (N.Y. Day 03/02/90) [discussed engineer dissenting view on S/G problem] → Engineering Data concerning S/G condition, ^{to be} the ~~information~~ engineering info provided to NRC was not complete

Number of Concerns: 1

Employee Receiving Allegation: P. Habighorst
 (first two initials and last name)

Type of Regulated Activity (a) Reactor (d) Safeguards
 (b) Vendor (e) Other: —
 (c) Materials (Specify)

Materials License No. (if applicable): —

Functional Area(s): (a) Operations (e) Emergency Preparedness
 (b) Construction (f) Onsite Health and Safety
 (c) Safeguards (g) Offsite Health and Safety
 (d) Transportation (h) Other: Safety

H/25

New London
Day
March 2, 90

Generator problems won't close Millstone 2

By ROBERT A. HAMILTON
Day Staff Writer

Approval expected

Northeast, owner and operator of the plant, has submitted the engineer's concerns with an analysis to justify continued operation, and federal regulators are likely to approve it, said U.S. Nuclear Regulatory Commission spokesman Karl Abraham.

"We feel they have things under control," Abraham said. "It appears, after their meeting with us, that there is not going to be a need for them to shut down. But that situation could change, if the behavior of the system changes."

In the event of a tube failure, radioactive water from the primary coolant loop could contaminate the secondary coolant loop and the turbine, and a large enough failure could release radiation from the plant.

Many utilities have experienced problems with steam generators similar to the problems at Millstone 2, a pressurized water reactor manufactured by Combustion Engineering of Stamford.

In the system, a primary coolant loop routes water through the reactor, where it is heated to

See MILLSTONE page A8

Waterford — Northeast Utilities will continue to operate the Millstone 2 nuclear plant until a refueling in September, even though one of its own engineers said it could be unsafe because of cracks in steam generator tubes.

The company also noticed "spikes," sudden, temporary surges in radiation level in the radioactivity of secondary coolant system water, indicating a leak in the steam generator system. Company officials said, however, that problem appears to be unrelated to the tube cracks.

Steven Scace, superintendent of Millstone Station, said plans are to replace the two steam generators at Millstone 2 in 1992. Previously, the company had said only that replacement might take place sometime in the 1990s.

Scace said the company hopes to do the job in six months and still has no firm estimate of the cost.

But Kenneth Bosson, director of the Critical Mass Energy Project, an anti-nuclear research organization, said the steam generators at other plants have cost \$80 million to \$100 million, "and a year is a bit more standard" as opposed to six months to do the job.

Bosson called it "highly unusual" that the company made public the engineer's objections to the application to run the plant through the summer. "Usually, by the time it's public, it's a consensus decision," he said.

The engineer "had concerns that some of the assumptions that were made were not supported by enough data, and some of the engineering analyses applied on top of the data were not justified," said Jack Keenan, superintendent of Millstone 2.

* } |

* } |

Millstone From A1

about 620 degrees and pressures of 2,250 pounds per square inch (PSI), and from there to a steam generator.

In the generator, high pressure heated water passes through tubes and heats water in the secondary loop, which is at 1,000 PSI. That water boils into steam that spins the turbines, while the primary water, cooled to about 550 degrees, goes back to the reactor.

Problems not new

The seawater used in the secondary loop caused problems from the start of operations. Under the extreme heat and pressure, organic matter decomposed and positively charged sodium ions and negatively charged chloride ions were released, creating pitting on the tubes.

To correct that problem the company installed a water treatment system to remove the ions, and the concentration dropped from 30 parts per billion (ppb) to 1 ppb, said Keenan.

But in doing that, the water changed from slightly acidic to

slightly caustic. That set up a chemical reaction that made the tubes prone to stress corrosion cracking.

Keenan said that problem has since been solved by adding boric acid to the defionized water. In the meantime, between 6,000 and 7,000 of the 17,000 tubes have been plugged or have had sleeves installed to cover damaged areas.

Keenan said, however, that the cracks are on the circumference rather than along the lengths of the tubes. Lengthwise cracks would weaken the tubes, he said.

Keenan said burst tests show the tubes would have to be cracked 79 percent of the way through their 0.048-inch thickness before they begin to weaken, and that none of the tubes found so far have been cracked more than 50 percent of their thickness.

In the tests, the cracked tubes withstood pressures up to 11,600 pounds before they burst, and even then they burst along their lengths, rather than along the cracks, he said.

"He (the engineer) is saying

there's no proof those cracks will not go beyond 79 percent. And he's right, there isn't any," Keenan said. "But the best engineering judgment" is that the cracks will not progress that far.

Leak suspected

There has been some indication of a leak between the two coolant systems already, based on radiation detected in the secondary system, which should not be contaminated.

In recent days the leaks have been no more than a gallon a day, which is normal for a pressurized water reactor, although earlier this year they measured as high as 10 to 14 gallons a day, "which indicates we're having some periodic leakage," Keenan said.

But because the leaks are not steady, he said engineers believe they are the result of leaks in the plugs in the faulty tubes, rather than cracks in the operating tubes.

Keenan said the steam generators, scheduled to be installed in 1992, will cost about \$30 million, but the company is still working on

a cost estimate for the entire project. Seace said it should be completed within six months.

But at Critical Mass, spokesman Dan Borson said Northeast officials estimated in an interview with Nucleonics Week last year that the total cost could exceed \$150 million, not including replacement power.

Borson said a 1982 steam generator replacement at two reactors owned by Florida Power and Light took 12 months and cost \$165 million. A similar project at a much smaller reactor at Southern California Edison cost \$53 million and took 13 months, Borson said.

Seace pointed out that the engineer who dissented was one of several who reviewed the data and was the only one who did not agree to continued operation.

"Obviously, the ideal situation would be to have everyone in agreement," Seace said. "But I'm perfectly satisfied that ... the conclusions are the right conclusions, based on the information we have."

Millstone leakage is safe, NRC says

By Terry Sacks
Register Staff

WATERFORD — Worn tubes in a Millstone 2 nuclear plant steam generator are leaking more radioactive water, but regulators have decided to let the plant keep operating, utility and regulatory officials said Thursday.

The increased leakage detected over the past few weeks is within legal safety limits, and regulators decided last week to allow the plant to operate until its next scheduled shutdown in October, Nuclear Regulatory Commission spokesman Karl Abraham said.

Radiation monitors have detected increased radioactivity in the "secondary" side of the 15-year-old plant where steam drives turbine generators that make electricity. Such leakage is cause for concern at nuclear plants because it could lead to radioactive gases released into the environment.

But Louis Keezing, a spokesman for Northeast Utilities, the Berlin, Conn. company that owns and operates the plant, said there's no evidence of increased leakage into the environment.

The NRC allows a leakage rate into the secondary system of one-tenth of a gallon per minute, or 144 gallons a day. The NRC's Abraham said the actual leakage from the steam generator tubes has been about half a gallon a day.

NU officials met with the NRC last week to argue for continued operation of the plant, Abraham said.

"They convinced us that if there are no abrupt changes in any of these numbers, they can go until the next scheduled shutdown," he said.

Troubled by worn steam generator tubes, Millstone 2 has plugged or repaired nearly 3,000 of the 17,000 tubes since 1977. Plant operators discovered last year that they had plugged hundreds of tubes using Westinghouse Corp. plugs that the NRC believes were defective and possibly prone to

3/24/90
Indeed, NU engineers suspect that a tube plug may be cracked and leaking, Keezing said. The relatively slow rate of leakage suggests that a tube itself hasn't ruptured, he said.

Problems with the steam generators prompted the plant to shut down in October for a mid-cycle inspection. The NRC's Abraham said NU had predicted, through theoretical calculations, that about 75 tubes would show signs of

Turn to Millstone, Page 44

Millstone: Plant stays in use despite radioactive leakage

Continued from Page 41

cracking. But NU actually found about 160 tubes with signs of cracking.

Keezing said engineers did pressure tests on three of the cracking tubes, which didn't fail until pressure reached more than 8,000 pounds per square inch. That was considered safe because the plant normally runs about 2,250 psi. Based on those tests, NU restarted the plant in November.

"We've had steam generator problems ever since we've had nuclear plants," said Abraham. "So we pay a lot of attention to the maintenance and quality of generators."

Keezing said NU plans to replace Millstone 2's steam generator system in 1992, at an estimated cost of about \$190 million.

The worst accident involving a ruptured steam generator tube was in January 1982, at the Robert E. Ginna nuclear plant operated by the Rochester Gas and Electric Corp. in New York. A rupture of a steam generator tube resulted in "massive" amount of radiation going into the secondary side of the plant, allowing radioactive gases to leak into the environment, Abraham said. But weather conditions and snow on the ground prevented any ground contamination, he said.

"It showed that it is possible to have catastrophic failures of tubes and still not have an accident that impacts the public," he said.

RECORD OF ALLEGATION PANEL DECISIONS

SITE: Milwaukee Unit 2

PANEL ATTENDEES:

ALLEGATION NO.: RI-90-A-0032

Chairman - W. Kane

DATE: 3/15/90 (Mtg. 1 2 3 4 5)

Branch Chief - E. Woyner

PRIORITY: High Medium Low

Section Chief (AOC) - D. Hunsberr

SAFETY SIGNIFICANCE: Yes No Unknown

Others - C. White

CONCURRENCE TO CLOSEOUT: DD BC SC

P. Halglorst

CONFIDENTIALITY GRANTED: Yes No
(See Allegation Receipt Report)

B. Raymond

IS THEIR A DOL FINDING: Yes No

J. Stronsider

IS CHILLING EFFECT LETTER WARRANTED: Yes No

A. Vogel

HAS CHILLING EFFECT LETTER BEEN SENT: Yes No

B. Olsen

HAS LICENSEE RESPONDED TO CHILLING EFFECT LETTER: Yes No

ACTION:

- 1) DRS to perform inspection on MS-2 S/G tube linkage
to verify engineering info provided to NRC as correct
- 2) Reported after completion of inspection
- 3) AOC to contact newspaper to attempt to find
source of story
- 4) _____
- 5) _____

NOTES:

H/SL

more than doubled the number of water and gas samples it is taking to detect problems, and has installed new monitors.

Although none of radiation releases has exceeded the plant's permit limits, some employees, and a former U.S. Nuclear Regulatory Commission official, have suggested the plant be shut down and examined to determine why the radiation counts have risen so sharply, and have been so erratic. Northeast Utilities, which owns and operates the plant, contends it is safe to run the plant through September, when the plant is scheduled to be shut down for refueling. The NRC has agreed to allow the operation provided the problem does not grow any worse.

'Little bit of leakage'

"The reason the set point was originally at 360 was to detect any kind of leakage," said company spokesman Richard Gallagher.

"Right now, we know there's a

who is this

H/b7

SI APERTURE CARD

Also Available On
Aperture Card

9203310237-01

Engineers
about O rings
weren't legally

Robert Pollard
Union of Concerned Scientists

became available last week
what seems to be a
problem.

In addition to the rising radi-
ations, the number of cracked
has been rising, from 26 at
of the eighth fuel cycle in
er 1987 to 309 at the end of
h fuel cycle in February

The report contends the
was because of better and
through inspections. It also
t when the company shut
a special inspection last
The engineers said the
imate" was that 60 new
could be found, 104 were
as well as 11 that were
for suspected cracks.

er through a tube crack or
plus, clearly there is a
ween the two systems, as
ed by the radiation counts
secondary cooling system,
not supposed to be radio-

water from the primary
into the secondary loop,
are dissolved under the
ary pressure come out of
and are siphoned off by a
air ejector that passes
radiation monitor.

Employee said most of the
nd in that air ejector are
s, xenon 135, and a variant
non 135 metastable. All
es have short half-lives,
er of minutes to days. A
s the time during which
radioactive material will

decay and become safe.

At the maximum rate of 9,200
counts per minute that has been
measured at the ejector, the ra-
dioactivity would be about 0.0001
microcuries per cubic centimeter,
about 10 times the maximum ex-
posure allowed for workers. But
once out of the stack the radioac-
tivity would quickly be diluted to
much lower levels.

A serious situation

Clearly, the company is taking
the situation seriously. One of the
employees said the company has
gone from one to two tests a day of
air that is vented to the atmo-
sphere, and some days as many as
four samples are taken. In addi-
tion, liquid sampling in the coolant
system has been tripled, to three
times a day, the worker said.

Gallagher said there have also
been new, sophisticated, and highly
sensitive radiation monitors in-
stalled on the system. With all the
extra provision, he said, "We
would see a definite trend before
we would be concerned about a
failure of a tube."

Employee said there are several
reasons Northeast might not be
shutting down, and the first is that
while the steam generator re-
placements are on order, they are
not ready. The company has
scheduled replacement for 1992,
which would be the first refueling
outage after the generators are de-
livered.

Gallagher said, though, that the
planned replacement could be
moved up, or moved back, depend-
ing on the performance of the
plant.

"That date is for planning pur-
poses, the target date," Gallagher
said. "We're not saying we're defi-
nitely going to do it then. We're
going to take things as they go
along, and if conditions change, our
plans will change."

Employees also said the corpo-
rate image is at stake. Northeast
prides itself on having one of the
top performance records in the in-

dustry. But Millstone 2 is starting
to slip towards average, and the
company does not want it to seem
the plant has slipped into medioc-
rity. In addition, shareholders
would start to get edgy if it ap-
peared the company's performance
was slipping, the employees said.

In 1988 Millstone 2 was operat-
ing at 75.3 percent of capacity,
compared with 65.1 percent for the
industry; by 1989, that had slipped
to 64.7 percent, compared with an
industry average of 61.9 percent.

Gallagher, though, said the 1988
results were because the plant had
a refueling outage early in the
year, followed by a planned mid-
cycle shutdown in October, that
lasted more than a month, for in-
spection of the steam generator
tubes.

Capacity factor good

"When you take those things into
consideration, the capacity factor
for 1989 was actually quite good,"
Gallagher said.

Finally, some employees have
said Northeast, and the NRC, are
concerned that if there are ex-
tended shutdowns at Millstone 2,
following the long Connecticut
Yankee shutdown, it would be used
in an attempt to question the com-
pany's management practices dur-
ing proceedings in the company's
application to take over the back-
stop at Public Service Co. of New
Hampshire, including the Seabrook
nuclear power plant.

But Gallagher said such specula-
tion is meaningless, that if the
company believed there was any
threat to public safety, or threat of
damaging the plant, it would be
shut down and inspected immedi-
ately.

"The fact is, any leakage that
we're seeing is well within toler-
ances for this plant," Gallagher
said. "And in the last week, the
leak has been basically one or two
gallons per day, it was four to five
gallons per day. So there really
isn't any trend."

9203310237-02

MAR 20 1990 03:29 NRC MILLS

NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406

Jul 10 1990

Docket No. 50-336

Northeast Nuclear Energy Company
ATTN: Mr. E. J. Mroczka
Senior Vice President - Nuclear
Engineering and Operations Group
P. O. Box 270
Hartford, Connecticut 06141-0270

Gentlemen:

Subject: Inspection Report No. 50-336/90-08


This letter refers to the routine inspection conducted by Mr. R. Winters and Mr. P. Habighorst of this office on April 25 - 27, 1990 at the Northeast Nuclear Energy Company office in Berlin, Connecticut and at the Millstone Unit 2 plant in Waterford, Connecticut. Mr. Winters discussed the results of the inspection with Mr. Wells in the corporate office, and Mr. Habighorst discussed the onsite portion of the inspection with Mr. Keenan of your staff at the conclusion of the inspection.

This inspection was directed at activities related to the results of the October 1989 inspection of the steam generators. Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,


Jacques P. Durr, Chief
Division of Reactor Safety

Enclosure. NRC Region I Inspection Report No. 50-336/90-08

~~9007240134~~

H128

Northeast Nuclear
Energy Company

cc w/encl:

W. D. Rumberg, Vice President, Nuclear Operations
 S. E. Scobe, Station Director, Millstone
 D. O. Nordquist, Director of Quality Services
 R. M. Kacich, Manager, Generation Facilities Licensing
 E. A. DeBarba, Station Director, Haddam Neck
 Gerald Garfield, Esquire
 Public Document Room (PDR)
 Local Public Document Room (LPDR)
 Nuclear Safety Information Center (NSIC)
 NRC Resident Inspector
 State of Connecticut

bcc w/encl:

Region I Docket Room (with concurrences)
 Management Assistant, DRMA (w/o encl)
 R. Bellamy, DRSS
 DRP Section Chief
 M. Conner, SALP Reports Only
 J. Shedlosky, SRI, Haddam Neck
 W. Raymond, SRI, Millstone
 K. Abraham, PAO (20) SALP Report and (2) All Inspection Reports
 J. Caldwell, EDO
 G. Vissing, PM, NRR

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Report No. 50-336/90-08

Docket No. 50-336

License No. PPR-65

Licenser: Northeast Nuclear Energy Company
P. O. Box 270
Hartford, Connecticut

Facility Name: Millstone Nuclear Power Station - Unit 2

Inspection At: Berlin, Connecticut

Inspection Dates: April 25-27, 1990

Inspectors:

R. W. Winters
R. W. Winters, Reactor Engineer, Materials &
Processes Section, EB, DRS

6/26/90
date

A. Lohreier
A. Lohreier, Reactor Engineer, Materials &
Processes Section, EB, DRS

6/26/90
date

P. Habighorst for
P. Habighorst, Resident Inspector, Millstone,
DRP, Region I

6/26/90
date

E. Murphy for
E. Murphy, Senior Engineer, NRR, Materials
and Chemical Engineering Branch

6/26/90
date

Reviewed by:

Jack Strosnider
J. Strosnider, Chief, Materials & Processes
Section, Engineering Branch, DRS, RI

7/2/90
date

Inspection Summary: Announced inspection from April 25-27, 1990
(Report No. 50-336/90-08).

Areas Inspected: The result of the eddy current examination of the steam generators performed during October 1989 was inspected with emphasis on the dissenting opinion expressed by one member of the licensee's staff regarding the acceptable period of operation for the steam generators.

Results: No violations or deviations were identified. One unresolved item concerning the trending of primary-to-secondary leakage was identified.

9007240136

DETAILS

1.0 Persons Contacted

Northeast Nuclear Energy Company

- * G. Alkire, Project Engineer, Piping Systems Engineering
- * F. Anderson, Senior Engineer, Nuclear Materials and Chemistry
- * P. Blasioli, Supervisor Nuclear Licensing
- * K. Colgan, Engineer, Nuclear Materials and Chemistry
- * D. Dube, Supervisor, Probabilistic Risk Analysis
- * J. Ely, Supervisor, General Engineering
- * J. Fackelman, Project Engineer, Nuclear Materials and Chemistry
- * W. Hutchins, Millstone Unit 2, Licensing
- V. Jones, Project Engineer, Nuclear Materials and Chemistry
- ** J. Keenan, Superintendent, Millstone Unit 2
- * M. Kupinski, Manager, Piping Systems Engineering
- * R. Linthicum, Engineer, Probabilistic Risk Analysis
- * R. Wells, Manager, Nuclear Materials and Chemistry

United States Nuclear Regulatory Commission

- * W. Raymond, Senior Resident Inspector, Millstone

* Denotes those attending the exit meeting in the Corporate Office.

** Denotes those attending the exit meeting at the site.

The inspectors also contacted other administrative and technical personnel during the inspection.

2.0 Follow-up of Structural Integrity Action Plan

Scope

The scope of this portion of the inspection was to review licensee actions taken as a result of the October 1989 steam generator eddy current testing at Millstone Unit 2 with emphasis on the licensee's action plan for evaluation of the steam generator tube structural integrity. The results of the October 1989 inspection and the status of the licensee's tube integrity evaluation were previously discussed at a meeting with NRC on February 22, 1990. At this meeting the licensee committed to perform additional testing and analysis of the cracked tubes removed from the steam generators during the October 1989 inspection. Also, as a result of newspaper articles reporting a differing opinion by an individual in the licensee organization, this inspection reviewed comments of this individual and the responses made by the licensee to determine if the individual's concerns were adequately addressed.

2.1 Tube Evaluation

The licensee has performed an evaluation of the 86 crack profiles of tubes found during the October 1989 inspection using the ASME Code, Section III, Appendix F acceptance criteria. The results of this evaluation were that 85 tubes met these requirements and one tube (L45R13) did not after the 170 effective full power days (EFPD) of operation prior to the October 1989 inspection.

Independent review by a licensee consultant of these 86 tubes using different analytic techniques identified the same tube as not meeting Regulatory Guide 1.121 safety margins after the 170 EFPD of operations.

The calculated factor of safety for low probability, postulated accident conditions (faulted conditions) did not satisfy the R.G. 1.121 criteria. Margin still existed against tube rupture under normal operating conditions.

Burst Testing

Burst testing of tube samples was performed by the licensee to ascertain the validity of the analytic methods used in predicting failure of tubes with varying crack geometries. Six tube samples containing manufactured flaws simulating actual crack geometries were pressure tested. Two tube specimens removed from the steam generator were also pressure tested. Based on these tests the licensee concluded that the analytical model was conservative.

3-Dimensional Finite Element Analysis of Tube L45R13

The analytical models used in the above tube evaluation did not explicitly consider crack ligament strengthening effects and tubesheet constraint. A 3-D finite element analysis of the L45R13 was performed to assess the effects. The results indicated that the above analytical models were conservative, but not over conservative.

2.2 Tube Life Calculations

The licensee has concluded that in the absence of an initiating event (main steam line break or main feedwater break) any tubes that fail will exhibit leak-before-break behavior. Under these circumstances, the licensee has concluded the existing leak detection systems will be adequate to allow corrective action before a tube rupture. However, based on the eddy current examination performed in October 1989, calculations show that after 170 EFPD there is a significant probability that stress in at least one tube could exceed the allowable level as required by Regulatory Guide 1.121 or ASME, Section III, Appendix F for faulted conditions. An independent analysis by a licensee contractor indicated that the 170 EFPD was a conservative estimate of the time at which a tube would reach an unacceptable stress level.

Inspectors Observations

The inspectors discussed this concern with the individual. The individual is satisfied that Probabilistic Risk Analysis (PRA) performed by the licensee's PRA Department accounts for uncertainty in the number of tubes which may develop significant cracking.

Concern 3

"Equivalent" depth should read "average" depth since time did not permit a calculation of all 85 crack profiles to determine "equivalent" crack depths. Based on a sampling of worst tubes the "equivalent" depth was on the order of 83 percent as compared to an average depth of 20 - 30 percent for the same crack and would result in a major change to the probabilistic model used in the safety assessment. The practice of using average depth as an indicator of tube acceptability is good for uniformly degraded tubes (uniform depth, 360° circumferential extent); however, it is an extremely poor method to assess tubes that challenge stability."

Inspectors Observations

The inspectors discussed this concern with the individual. The individual was satisfied with recalculations that were performed using the "equivalent" depth that included a bending component in the calculations. These calculations considered the basis of the actual geometry of the tube defects.

Concern 4

"The existing safety assessment assumes additional margins exist to rupture, based on data that is pressure based only. Potential external loads as a result of tube bowing, tube lockup (from denting), secondary internal loading during accident conditions, etc., have not been considered. An evaluation of these loads by Combustion Engineering for Millstone Unit No. 2 steam generators present conditions needs to be performed before we try to strip our analysis of any potential conservatisms."

Inspectors Observations

The inspectors discussed this concern with the individual. The individual is satisfied that a 650 psi pressure load adjustment has been retained in the analysis to account for these external loading effects. This value is an estimate but calculations by Combustion Engineering determined that this value is conservative.

Concern 5

"The limit load analysis performed for the most complex flaws is in a preliminary status with no independent review and approval being accomplished and forms a weak basis for subsequent safety assessment assumptions. Also, this analysis did not include Northeast Utilities (NU's) standard practice of including NDE error in the analysis (a practice Regulatory Guide 1.121 also requests) or Section XI equivalent flaw length to depth criteria for multiple flaws."

Inspectors Observations

The inspectors discussed this concern with the individual and determined that the individual accepts that the limit load calculations have now been completed, reviewed and approved in accordance with the licensee's procedures. The interpretation of the analysis results has been upgraded to reflect additional test results, revised interpretation of flaw geometry, and improved analytic methods provided by the independent contractor.

The individual has accepted the omission of inspection tolerance in the limit analysis because good correlation was found between the ultrasonic testing measurement and actual test values.

Concern 6

"NU has not performed a detailed Regulatory Guide 1.121 analysis for these tubes to date due to time constraints. Preliminary results identify that at least seven tubes will not meet this criteria."

Inspectors Observations

The inspectors discussed this concern with the individual and determined that the individual agreed that Regulatory Guide 1.121 analysis had been performed in full by the time of this inspection. In the revised analysis in accordance with the Regulatory Guide 1.121 it was found that one tube did not meet the regulatory guidelines after 170 EFPD.

Concern 7

"The present safety assessment identified a safety factor of 1.52, for tube L20/R22, between room temperature burst test information and the preliminary analytical results. Regulatory Guide 1.121 requires the burst strength be determined experimentally at operating temperature. Margins may not be present.

Evaluation of end of cycle (EOC) 8 pulled tube L25/R19, which leaked at 0.1 gpm in service shows zero margin between the analytical model and actual rupture point.

Inspectors Observations

The inspectors discussed this concern with the individual and determined that the individual believes it is acceptable to use room temperature test for determining rupture properties at operating temperatures because there are only small differences between the properties at these temperatures.

More recent testing has shown safety factors greater than 1.24 between burst test results and analytical predictions, compared to the 1.52 margin from initial testing.

Regarding tube L25R19, the crack may have exhibited further growth after it was plugged, but prior to its being removed from the field. The individual does not consider the size of the crack to have direct implications for the current operating cycle.

Concern 8

"The minimum calculated wall thickness of 77% was based on a flow stress of 69,000 psi. This flow stress was assumed to be conservative since this was considered to be a code based (3 Sm) number. A detailed review of Millstone Unit No. 2 certified material test reports identified that twenty-nine heats have flow stresses below this value. The minimum flow stress is 65,000 psi and results in a minimum wall thickness of 75%. This minimum wall thickness was not being utilized in the safety assessment submitted to the NRC prior to the February 22, 1990 meeting. The number determines a statistical interval used to arrive at the current safety assessment's conclusion."

Inspectors Observations

The inspectors discussed this concern with the individual and determined that the individual based his question regarding the results of analysis and testing on information available at the time of his question. Since that time however, new considerations and additional tests, analyses, and evaluations, have resulted in a somewhat different safety assessment with which he agrees.

Concern 9

"A review of tubes with uniform through wall cracks over 360° of the circumference was performed with a comparison to the 77 percent acceptance criteria. This review was not performed for the new 75 percent acceptance criteria due to time constraints."

Inspectors Observations

The inspectors discussed this concern with the individual and determined that the individual agrees with the method presently in use that includes provision for including total stress (with bending).

Concern 10

"EOC B leaking tube L25R19 exhibited a circumferentially predominate degraded region of 190° which resulted in a through wall crack of 35° and a leak of 0.1 gpm under normal operating conditions. The tubes presently being evaluated have regions greater than 190° and are UT determined to be 80% through wall. Longer term operation of tubes similar to these could provide for through wall cracks greater than 0.1 gpm at normal operating conditions."

Inspector Observations

The inspectors discussed this concern with the individual and determined that the individual agrees that as a result of the testing and evaluations the plant can operate for 170 EFPD before reducing the safety margin below Regulatory Guide and ASME limits.

2.4 Conclusions

Based on discussions with the individual who had expressed concerns about the length of time the steam generators should be operated, the inspectors concluded he now believes his concerns have been fully addressed and given due consideration by his management. Based on discussions with the engineer having the dissenting opinion and after reviewing the results of the investigations made by the licensee as a result of this dissenting opinion the inspectors concluded that the 10 concerns had been adequately addressed.

The licensee has performed a probabilistic assessment of tube rupture under faulted conditions in justification of operation through the end of the fuel cycle. Included in their assessment is the assumption that a leaking tube can be identified during normal operation. On the basis of the calculations and testing performed on tubes removed from the steam generators, the licensee stated that the conclusions expressed in the February 22, 1990 meeting are still valid and operation to the end of cycle 10 is justified.

3.0 Primary-to-Secondary Leakage Monitoring

Scope

A review of available licensee radiation monitoring and radiochemistry sampling process to detect primary-to-secondary leakage was performed to assess the adequacy of the licensee's program. Specifically, the inspector reviewed detection methods, procedures, administrative controls, and operator actions in response to applicable control room alarms, radiochemistry results, and licensee management awareness to the leakage program.

3.1 Detection Methods

The radiation monitoring instruments used at Millstone 2 to detect leakage from the primary-to-secondary are: (1) steam jet air ejector radiation monitor (RM-5099); (2) steam generator blowdown radiation monitor (RM-4262); (3) N-16 radiation monitors; (4) main steam line radiation monitors (RM-4299 A,B,C) and (5) alternate steam jet air ejector monitor. The radiochemistry analysis includes steam generator blowdown grab samples, secondary tritium calculations, and steam jet air ejector grab samples.

The steam jet air ejector radiation monitor (RM-5099) is located at the 14' 6" elevation of the turbine building. The monitor's required operability is based on technical specification (TS) 3.3.3.9. The design basis is to monitor noble gas activity in the condenser air removal system and to provide a control logic signal to close the steam generator blowdown valves to terminate discharge of blowdown to the circulating water canal. The control logic signal is to prevent 10 CFR 20 radioactivity limits from being exceeded to unrestricted areas. The licensee considers RM-5099 to be one of the first monitors to sense primary-to-secondary leakage.

The steam generator blowdown radiation monitor (RM-4262) is located on the 14' 6" elevation of the auxiliary building. RM-4262 monitors a combined blowdown activity from both steam generators. The monitor's operability is based in TS 3.3.3.9. The design basis is similar to RM-5099, except for the monitored location point. The licensee's radiological assessment branch review of RM-4262 indicates it is not a sensitive indication of primary-to-secondary leakage based on industry experience. Specifically, in actual past industry tube rupture events it often took up to 30 minutes for activities in the steam generator water to buildup to cause a monitor alarm.

The N-16 monitors are located on each main steam line on the 38' 6" elevation of the turbine building. The monitors were installed in July, 1989 under licensee inservice test 789-019. The licensee determined within the inservice test no unreviewed safety question per 10 CFR 50.59 existed. This monitor was installed as an independent action by the licensee and is not a regulatory requirement. Therefore, it is not required to be operable nor is it identified in the Final Safety Analysis Report. The monitors detect the presence of gamma radiation in the main steam lines. The digital leak rate calculations are based on high energy gamma radiation from the radioactive decay of Nitrogen-16 and the total counts per second readout display the detected low energy gamma. The monitors detect the presence of a steam generator leak, and identify the affected steam generator unlike RM-5099 and RM-4262 that do not isolate the source of the leakage.

The main steam line radiation monitors (RM-4299 A,B,C) are located in the 38' 6" east and west penetration rooms. The monitors are located on the main steam lines to detect primary-to-secondary leakage and quantify a postulated post accident release thru the main steam line safety valves and atmospheric dump valves. The operability of the monitors is prescribed in TS 3.3.3.6 and NRC Regulatory Guide 1.97.

The alternate steam jet air ejector monitor was installed on April 12, 1990 under authorized work order M2-90-03698. The monitor is located upstream of RM-5099, at the 14' 6" elevation of the turbine building. The monitor's primary function is a backup and verification of monitor RM-5099. No design basis or requirements exist for the alternate steam jet air ejector monitor.

The radiochemistry input into detector of activity in the steam generators is in part required by the technical specifications and further amplified by procedures and licensee administrative guidance. TS surveillance requirement 4.7.1.4 specifies the time interval for gross activity and dose equivalent iodine in the steam generators, and TS 4.11.1.1, radioactive liquid samples levels not to exceed 10 CFR 20 Appendix B, Table II, Column 2 for release from the site.

Procedurally, per SP-2833, "Secondary Coolant Analysis for Total Activity", the licensee samples steam generator blowdown grab samples and air ejector grab samples daily, and upon a RM-5099 or RM-4262 alarmed condition. In addition, the frequency is increased based on a calculated primary-to-secondary leakage. (i.e. SJAE grab samples three times per day when leakage exceeds .05 gallons per minute).

The leakage rate calculations are based on three methods identified in licensee procedure CP-2806Y. The calculation methods are based on Electric Power Research Institute (EPRI) NP-5980-SR "Primary Water Chemistry Guidelines." The methods implemented by the licensee consist of a tritium balance, air ejector gas method, and soluble liquid nuclei determination of steam generator leakage. The licensee employs the tritium analysis as a confirmation and backup to the air ejector gas method for leakage rate determinations. The air ejector gas method is the primary method implemented by the licensee. This method provides a rapid response to leak rate changes, however, the detection sensitivity is significantly less than the tritium samples, based on detectability of liquid scintillation vice the gamma spectrometry. The disadvantage of the tritium method is a relatively slow response in analysis acquisition and determination of time constant.

The licensee calculates, as a minimum, a daily leak rate calculation using the air ejector gas method.

3.2 Procedures and Administrative Controls

The inspector reviewed licensee's procedures and actions for a primary-to-secondary leak to assess the adequacy of required actions at the facility. Procedures reviewed are listed below:

- OP 2260 "Millstone 2 Emergency Operating Procedure (EOP) Users Guideline."
- AOP 2569 "SG Tube Leak"
- EOP 2534 "SG Tube Rupture"
- SP 2833 "Secondary Analysis for Total Gamma Activity"
- CP 2806Y "Calculating Primary to Secondary Leak Rates"

- DP 2316A Section 6.15 "Main Steam System"
- Plant Operations Night Order 7/14/89-1
- DP 2383A "Process Radiation Monitors Operation"

Inspector review identified adequate required operator response to alarms for the diagnostics of a primary-to-secondary leak, increased radiochemistry sampling in response to increases in leakage, and the licensee's process to evaluate radiochemistry data. In AOP 2569, the decision to continue plant operation with a known leakage resides with plant management, and if technical specifications for leak or SG activity are exceeded, a required shutdown of the plant is reinforced by procedure and in accordance with applicable action statement.

The present licensee procedures do not provide trending of leakage rates to take plant operational action prior to exceeding required TS limits or onset of a postulated steam generator tube rupture. The above enhancement program was addressed for information to Millstone 2 via NRC Bulletin 88-02 dated February 5, 1988. The inspector considers this issue open (90-08-01) and will follow licensee actions to this regard in future inspections.

3.3 Operator Actions to Applicable Radiation Monitor Alarms and Radiochemistry Results

Inspector observations of control room activities noted that, once RM-5099 or RM-4299 alarms and isolates the steam generator blowdown, control room operators request a chemistry department sample of either the steam jet air ejector or blowdown. The control room logs document the time of the alarm, automatic action, chemistry radioactivity samples, and N-16 radiation monitor readings. The above actions are in accordance with procedure DP 2316A and plant operations night order 7/14/89-1.

Control room alarms available to provide indication of a primary-to-secondary leak are "Main Steam Line High Radiation/Instrument Failure," Process Monitor Radiation High and local alarms at the RM-4262, RM-5099, and the N-16 monitors.

3.4 Licensee Management Awareness

Inspector observation at licensee daily work planning meetings indicates heightened awareness of leak rate calculations on a daily basis, and control room operators are cognizant of current leakage values. Utility management actions pursuant to current leakage rates include (1) implementation of alternate air ejector monitor (2) confirmation of leakage rates by tritium analysis and predictions (3) ratios of noble gas half-lives to determine an approximate time delay between primary and secondary systems, and (4) evaluation of air ejector radiation "spikes".

3.8 Conclusions

No deficiencies were observed in the licensee's primary-to-secondary leak rate monitoring program. The program includes monitoring capabilities not required in TS or other regulatory requirements and additional sampling actions by the chemistry department (i.e. tritium predictive analysis).

4.0 Water Chemistry

Millstone Unit 2 receives makeup water from the New London, Connecticut city water supply. This water is suitable for human consumption but contains impurities detrimental to the operation of the steam generators. The licensee treats the city water by filtering and ion exchange to remove most of the impurities. The next step is to use reverse osmosis to remove organic materials peculiar to the area, then another ion exchange for final treatment. The treated water is then stored in a stainless steel tank for later use. Makeup water is fed into the secondary system through the 'A' hot well of the main turbine condenser as needed to replace blowdown losses. This serves to remove any dissolved oxygen or other noncondensable gases through the steam jet air ejectors.

From the condenser hot wells the flow is through the condensate pumps, polishers, feedwater heaters, feedwater pumps, to the steam generators, as steam to the turbine and back to the condensers. In line chemical monitoring is done before and after the condensate pumps, and on the steam generator blowdown. Radiation detectors to monitor for steam generator tube leaks are at the steam jet air ejectors, and on the steam generator blowdown lines. In addition there is an N_{16} radiation monitor located in the main steam line between the steam generator and the turbine. Water flow through this system is on the order of 18,000 gallons per minute.

Chemical additions of ammonia and hydrazine are made downstream of the condensate polishers to adjust the pH and control oxygen respectively. These additions are made by continuous, automatic injection of solutions to the main flow. A boric acid solution is also injected downstream of the polishers by manual control of the injection pump. The boric acid is added to the secondary water in an attempt to eliminate the cracking the steam generator tubes have experienced at the top of the tubesheet.

During transients, the water chemistry undergoes changes. During these transients, special attention is required to maintain the chemistry at appropriate levels.

Conclusions

The licensee has developed an excellent system for the control of water chemistry. Purity is approaching the current technological limit of the ability to measure the impurities present.

5.0 Unresolved Items

Unresolved items are matters about which more information is required in order to ascertain whether they are acceptable items or violations. Unresolved items are discussed in paragraph 3.0.

6.0 Management Meetings

Licensee management was informed of the scope and purpose of the inspection at the entrance interview on April 25, 1990. The findings of the inspection were discussed with licensee representatives during the course of the inspection and presented to licensee management at the April 27, 1990 exit interviews (see paragraph 1 for attendees).

At no time during the inspection was written material provided to the licensee by the inspector. The licensee did not indicate that proprietary information was involved within the scope of this inspection.