

LICENSEE EVENT REPORT

EXHIBIT A

LER No. (50-368) 83-028/03X-1

Occurrence Date: 06/27/83

Cause Description and Corrective Actions (Continued)

counsel the involved personnel on T.S. required analyses, their frequencies, operating modes for which they are required, and the locations of the requirements within the T.S. To prevent recurrence, formal training for appropriate personnel on the T.S. requirements for R.C. analyses was conducted.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 18, 1984

2CANØ58414


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 83-028/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning failure to perform the Gross Activity Determination of the reactor coolant within the specified time requirements. This is a revision to a previous submittal dated July 21, 1983.

Very truly yours,


John R. Marshall
Manager, Licensing

JRM:RJS:ac

Attachment

cc: Mr. Richard P. Denise, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

IE22
11