

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

84 MAR 2 11:40

W. L. STEWART
VICE PRESIDENT
NUCLEAR OPERATIONS

March 27, 1984

Mr. James P. O'Reilly
Regional Administrator
Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303


Serial No. 132
NO/WDC:acm
Docket No. 50-280
License No. DPR-32

Dear Mr. O'Reilly:

We have reviewed your letter of February 27, 1984, in reference to the inspection conducted at Surry Power Station on January 3-31, 1984, and reported in IE Inspection Report No. 50-280/84-04. Our response to the specific infraction is attached.

We have determined that no proprietary information is contained in the report. Accordingly, the Virginia Electric and Power Company has no objection to this inspection report being made a matter of public disclosure. The information contained in the attached pages is true and accurate to the best of my knowledge and belief.

Very truly yours,


W. L. Stewart

Attachment

cc: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Mr. D. J. Burke
NRC Resident Inspector
Surry Power Station

8405300510 840522
PDR ADDCK 05000280
G PDR

RESPONSE TO NOTICE OF VIOLATION
INSPECTION REPORT NO. 50-280/84-04

NRC COMMENT:

The following violations were identified during an inspection conducted on January 3-31, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.11.B.4 requires that gross and particulate activity and flow rate be continuously monitored and recorded during the release of radioactive gaseous wastes to the process vent.

Contrary to the above requirements, the contents of the A waste gas decay tank were released to the process vent from 3:15 p.m. on January 10, 1984, until 9:22 a.m. on January 11, 1984, without continuously monitoring gaseous gross and particulate activity. Proper flow was not maintained to the process vent radiation monitors RI-GW-101 and 102 due to a failure of the air sampling pump. The redundant process vent effluent radiation monitor RI-GW-130-1 was also inoperable due to equipment failures.

This is a Severity Level IV Violation (Supplement I), and applies to Unit 1.

RESPONSE:

(1) ADMISSION OR DENIAL OF THE ALLEGED VIOLATION:

The violation is correct as stated.

(2) REASONS FOR VIOLATION:

This violation is primarily resultant from multiple equipment failure in that the process vent air sampling pump failed. This failure went undetected because of a malfunction in the flow fault detections/alarm circuit. To a lesser degree the violation is attributable to inadequate procedure because verification of proper operation of the process vent monitoring system is not performed immediately prior to release.

(3) CORRECTIVE STEPS WHICH HAVE BEEN TAKEN AND THE RESULTS ACHIEVED:

The process vent air sampling pump and flow fault detection circuit have been repaired and are functioning properly.

(4) CORRECTIVE STEPS WHICH WILL BE TAKEN TO AVOID FURTHER VIOLATIONS:

The operating procedure for releasing WGDT's is being improved to include local flow verification for the process vent air sampling pump immediately prior to releases. The procedure will be changed by April 6, 1984.

(5) THE DATE WHEN FULL COMPLIANCE WILL BE ACHIEVED:

Full compliance has been achieved.