

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

May 3, 1984

34 MAY 8 P 1:24

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: RII: WPK
50-413/84-28
50-414/84-16

Dear Mr. O'Reilly:

Please find attached a response to Violation No. 413/84-28-01, 414/84-16-01, as identified in the above referenced inspection report. Duke Power Company does not consider any information contained in this inspection report to be proprietary.

Very truly yours,

H.B. Tucker

Hal B. Tucker

LTP/php

Attachment

cc: NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

8405300652 840522
PDR ADOCK 05000413
PDR
G

A. Duke Power Company admits the Violation.

B(1) Cause of Violation, Part 1

Duke Power failed to amend Specification CNS-1211.00-00-0010. The requirement for review of welder qualification certification is a part of Duke's QA program of vendor approval, audit and surveillance. As such, Duke did not require submission of welder certifications to Duke. Due to oversight, the requirement was not removed from the Design specification.

C(1) Action

Specification CNS 1211.00-00-0010 has been revised to delete the requirement for welder certification submittal to Duke. Welder certifications have been obtained from the vendor and added to the QA documentation package.

D(1) Corrective Action

All other procurement specifications to Bahnson have been reviewed to assure no similar deficiencies existed.

E(1) Status

Full compliance has been achieved.

B(2) Cause of Violation, Part 2

The cause of welding deficiencies on these Bahnson air handling units was poor workmanship and weld inspection by Bahnson in violation of Bahnson's QA program. These deficiencies were not identified by Duke Power prior to installation of the equipment.

C(2) Action

A complete inspection of Bahnson's air handling units was conducted by Bahnson's Level III during the week of 2/27/84. Duke Power Company documented all welding deficiencies on NCIR #18132. These deficiencies were evaluated by Bahnson, Bahnson's seismic consultant, and Duke Power Design Engineering. All reports, analyses, and results of inspections are documented in NCIR #18132. Similar Bahnson units at other Duke locations were also inspected.

D(2) Corrective Action

No other orders for similar Bahnson equipment are in process; therefore, no specific corrective action for Bahnson AHU's is required. To assure that similar problems do not occur in other areas of Bahnson work, Duke QA has conducted audits and surveillances of Bahnson's QA program, with special emphasis on welding.

E(2) Status

All deficient welds have been inspected and results analyzed. All welds were structurally adequate and have been accepted by engineering "as is" with no repair. All documentation will be on file with completed NCI. Files should be completed by May 20, 1984.