

# Vepco

VIRGINIA ELECTRIC AND POWER COMPANY  
NORTH ANNA POWER STATION  
P. O. BOX 402  
MINERAL, VIRGINIA 20117

10 CFR 50.71

April 2, 1992

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Serial No. N-92-10  
NAPS:WCH  
Docket Nos. 50-338  
50-339  
License Nos. NPF-4  
NPF-7


Dear Sirs:

The Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to North Anna Units 1 and 2.

Report No. 50-338,339/92-007-00

This Report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Corporate Management Safety Review Committee for its review.

Very Truly Yours,

  
G. E. Kane  
Station Manager

Enclosure:

cc: U.S. Nuclear Regulatory Commission  
101 Marietta Street, N.W.  
Suite 2900  
Atlanta, Georgia 30323

Mr. M. S. Lesser  
NRC Senior Resident Inspector  
North Anna Power Station

9204070310 920402  
PDR ADDCK 05000338  
S PDR

IE22

111

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

DOCKET NUMBER (2) PAGE (2)  
05000338 1 OF 04

FACILITY NAME (1)  
North Anna Power Station Units 1 and 2

TITLE (4)  
MISSED SURVEILLANCES ON RCP BUS UV/UF TESTING AND SI INPUT TO REACTOR TRIP

EVENT DATE (6)				LER NUMBER (8)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME(S)	DOCKET NUMBER(S)
03	06	92	92	007	00	04	02	92	North Anna Unit 2	05000339
										05000011

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more of the following) (11)

OPERATING MODE (9)	1	20.402(b)	20.405(i)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10)	095	20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract)
		20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)	None (See Part 50.104)
		20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(iii)	

NAME: G. E. Kane, Station Manager  
 LICENSEE CONTACT FOR THIS LER (12)  
 TELEPHONE NUMBER (13)  
 AREA CODE: 703  
 NUMBER: 897-2101

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)  
 YES (spec. complete EXPECTED SUBMISSION DATE)  NO  
 EXPECTED SUBMISSION DATE (15)  
 MONTH: | DAY: | YEAR: |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 800 words) (16)  
 On March 6, 1992, with Unit 1 in Mode 1 and Unit 2 in Mode 6, an evaluation of surveillance requirements determined that the Unit 2 Reactor Coolant Pump (RCP) bus monthly undervoltage and underfrequency (UV/UF) channel functional tests were not performed in accordance with Technical Specification (TS) Table 4.3-1, Items 16 and 17. Upon further evaluation, documentation could not be located which ensured the Unit 1 "A" Station Service Bus UV circuit was fully tested during 18 month channel calibration testing (Item 16). As a corrective action, further TS surveillance reviews were performed, and it was found that tests of the Safety Injection (SI) input to Reactor Trip for both units were not performed monthly (Item 19). These events are reportable pursuant to 10CFR50.73 (a) (2) (i) (B).  
 The cause of these events was personnel errors resulting in failure to develop appropriate procedures to satisfy TS surveillance requirements.  
 These events posed no significant safety implications because subsequent testing of the Unit 1 UV/UF channels and previous bi-monthly testing of the SI input to Reactor Trip circuitry demonstrated that all circuitry was capable of performing its intended function. Testing will be performed on Unit 2 prior to startup. In addition, a review of the operating history for both units revealed that the RCP bus UV/UF protection circuitry has not been challenged. Therefore, the health and safety of the general public was not affected at any time due to these events.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-580), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  North Anna Power Station Unit 1 and 2	DOCKET NUMBER (2)  0200033892	LER NUMBER (3)			PAGE (3)  2 of 4
		YEAR	SEQUENTIAL NUMBER	REPORT NUMBER	
		92	007	00	

TEXT (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

1.0 Description of the Event

On March 6, 1992, during a Unit 2 refueling outage with Unit 1 operating at 95% power, an evaluation of station service bus surveillance requirements determined that the Unit 2 Reactor Coolant Pump (RCP) (E118 AB-P) power supply bus monthly undervoltage and underfrequency (UV/UF) protection channel (E118 JC-CHA) functional tests were not being performed in accordance with Technical Specification (TS) 4.3.1.1.1 Table 4.3-1 Items 16 and 17. Upon further evaluation, documentation could not be located which ensured the Unit 1 "A" Station Service bus UV reactor trip circuit was fully tested during 18 month frequency channel calibration testing as required by Item 16. As a corrective action, further TS surveillance reviews were performed, and it was found that channel functional tests of the Safety Injection input to Reactor Trip for both units was not being performed monthly in accordance with Item 19. These events are reportable pursuant to 10CFR50.73 (a) (2) (i) (B).

The North Anna Units 1 and 2 TS Surveillance 4.3.1.1.1 requires that each reactor trip system instrumentation channel be demonstrated operable by the performance of periodic tests at frequencies shown in Table 4.3-1. The Unit 2 Table 4.3-1 requires that RCP bus UV/UF protection channel functional tests be performed on a monthly frequency while in Mode 1. Unit 1 does not have a monthly UV/UF functional test TS requirement. The Surveillance Test/Technical Specification Cross-Reference Document currently states that the Unit 2 monthly surveillance requirements of Table 4.3-1 Items 16 and 17 are performed by PT-36.1A and PT-36.1B. These procedures actually perform an automatic trip logic test, which includes a portion of the UV/UF circuitry, on a "staggered test basis" (once every two months) to satisfy the requirements of Item 22 of Table 4.3-1. Since a monthly channel functional test has not been performed, the surveillance requirement has not been satisfied for items 16 and 17. An "information only" Action was entered on Unit 2 to ensure the testing will be completed before restart.

TS Table 4.3-1 for both units also requires RCP bus UV/UF channel calibrations during each refueling outage. The combination of "overlapping" tests which perform this surveillance were reviewed to determine if the procedures adequately provide verification of the entire circuit as required for a channel calibration. The overlapping test procedures did not require documentation that the UV alarm circuitry was operable as required by a channel calibration. Historical computer printouts from UV testing performed during the previous Unit 1 outage document that all station service bus alarm circuits functioned with the exception of the "1A" bus UV protection. Since documentation which ensures that the entire "1A" bus UV protection circuit had been tested could not be located, it was conservatively assumed that the surveillance had been missed, and TS 4.0.3 was entered.

Item 19 in TS Table 4.3-1 requires a monthly channel functional test of the Safety Injection (SI) input to Reactor Trip. This test has been incorrectly performed on a staggered test basis which tests each train every 62 days. Therefore, this surveillance has also been missed during previous

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (5150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  North Anna Power Station Unit 1 and 2	DOCKET NUMBER (2)  058003318	LER NUMBER (3)				PAGE (3)  03 OF 04
		YEAR 92	IDENTICAL NUMBER 007	REVISION NUMBER 00		

TEXT (If more space is required, use additional NRC Form 306A) (17)

1.0 Description of the Event (continued)

operating cycles. Unit 1 did not enter TS 4.0.3 due to this event because 31 days had not elapsed since the last test. The Surveillance Test/Technical Specification Cross-Reference Document does not specify a monthly procedure for this surveillance requirement.

2.0 Significant Safety Consequences and Implications

These events posed no significant safety implications because subsequent testing of the Unit 1 UV/UF channels and previous staggered testing of the SI input to Reactor Trip circuitry demonstrated that all circuitry was capable of performing its intended function. Testing will be performed on Unit 2 prior to startup. In addition, a review of the operating history for both units revealed that the RCP bus UV/UF protection circuitry has not been challenged. Therefore, the health and safety of the general public was not affected at any time due to these events.

3.0 Cause of the Event

The cause of the events was personnel error resulting in failure to develop appropriate procedures to satisfy the surveillance requirements.

4.0 Immediate Corrective Actions

Due to the undocumented surveillance of the entire Unit 1 "A" RCP bus UV protection circuit, Unit 1 entered TS 4.0.3 which allows 24 hours for surveillance testing. A channel calibration procedure was written, and the test was completed satisfactorily within the 24 hour limit. Since Unit 2 was in a refueling outage, no immediate testing was required.

5.0 Additional Corrective Actions

Temporary changes to current channel calibration tests were developed and performed for all RCP bus UV/UF protection circuits on Unit 1 as a good practice.

An Engineer/SRO has performed an in-depth study of the North Anna TS Surveillances required by TS 3.3.1.1 and 3.3.2.1 for both units to verify that the existing procedures fully meet the requirements. Documents were reviewed to ensure continuity through entire instrumentation loops was tested as required by the appropriate surveillance requirement. The SI input to reactor trip missed surveillance was found during this review.

An additional review of other complex instrumentation/electrical surveillance requirements will be performed to verify TS surveillance requirements are fully met.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  North Anna Power Station Unit 1 and 2	EVENT NUMBER (2)  0   5   0   0   3   3   8	LER NUMBER (3)				PAGE (3)  0   4   OF   0   4
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
	9   2	0   0   7	0   0			

TEXT (If more space is required, use additional NRC Form 3054s) (17)

6.0 Actions to Prevent Recurrence

Functional test procedures for monthly RCP UV/UF protection circuitry of the Unit 2 RCP busses will be developed and performed prior to entering Mode 1 following the current refueling outage to completely satisfy the 18 month calibration requirement. An "information only" Action was entered on Unit 2 to ensure the testing will be completed before restart. These procedures will then be performed on a monthly frequency.

18 month RCP bus UV/UF protection channel calibration procedures for both units will be enhanced to permanently incorporate changes that verify the entire circuits are tested as required by a channel calibration.

The SI input to Reactor trip channel functional test procedures will be performed monthly as required by the TS.

A TS change package will be submitted to require the SI input to reactor trip surveillance on a bi-monthly frequency.

7.0 Similar Events

LER N1/2-90-009-02 described an event where full response time testing of the Source Range Neutron Flux Reactor Trip preamplifiers, the Power Range Neutron Detector isolation amplifiers and the Overtemperature Delta Temperature Reactor Trip lag and lead/lag cards was not performed due to incorrect TS interpretation.

LER N2-91-001-00 documents an event where a set of contacts and associated wiring on the control room bench board switch for the Train A power operated relief valve (PORV) over pressure control circuitry had not been tested as required by TS surveillance requirement 4.4.3.2.1.b. The cause of the event was the incorrect interpretation of TS 4.4.3.2.1.b. Previous interpretations did not require testing of the contacts and associated wiring for the PORV control circuitry.

7.0 Additional Information

None.