

Deen L Quamme Site Manager Midland Project

Midland Project: PO Bux 1963, Midland, MI 48640 • (517) 631-8650

March 15, 1984

Mr John J Harrison Chief, Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020
PROGRAM FOR RESUMPTION OF ASME III CODE AND NON-CODE DIESEL GENERATOR MECHANICAL EQUIPMENT INSTALLATION File: 0487.4 UFI: 00234(S) Serial: CSC-7468
M-18 42\*10\*06

The purpose of this letter is to request NRC concurrence with the program discussed at the meeting, March 7, 1984 and attached herein. In attendance at that meeting were the following persons:

| NAME              | TITLE                            |
|-------------------|----------------------------------|
| H. Livermore      | NRC Site Supervisor              |
| Jon S. Kreple     | CPCo SMO                         |
| Bruce H. Peck     | CPCo SMO-Construction            |
| Morris Rubenstein | MPQAD QA Engineer                |
| T. A. Parker      | Stone & Webster Michigan, CIO    |
| Bruce Harshe      | CPCo-Project Engineering         |
| J. Harrison       | NRC, Section Chief               |
| B. Burgess        | NRC, Resident Inspector, Midland |
| P. Hiland         | NRC, Resident Inspector, Midland |

Consumers Power Company is proposing a program independent of the Construction Completion Program (CCP) for the resumption of ASME, Section III and non-code mechanical work on the portion of the Emergency Diesel Generators where the vendor, Trans-america DeLaval, Inc. (TDI), has the responsibility for the design and installation of the components.

It is our opinion that this proposed program is more stringent than the CCP and can therefore be independent from it.

The evolution of this program is based on the fact that TDI supplied a component in a system. The size of the component required that it be shipped in pieces and reassembled on the site. The reassembly was the responsibility of TDI with Bechtel crafts doing the work. Audits done to TDI QA Program revealed that their N stamp did not extend outside their fabrication facili-

OCO384-0002A-CN01

ties. Transferring of the N stamp responsibility to Bechtel was done by revisions to TDI procedures, generation of a new Code Effective Dates Specification, a SAR change clarifying the ASME criteria and an ASME audit for the purpose of adding authorization to fabricate and install ASME Section III NF supports. The ASME audit is scheduled for June 27-29, 1984. An NCR was written against the assembled component. The NCR states that the violation of ASME Section III and the lack of ANI involvement in the reassembly process requires that all ASME Code pieces be disassembled, inspected to the ASME Code requirements and reassembled. Review of component piece documentation will be done back to its receipt inspection. It is our opinion that this program is more stringent that the CCP and therefore can be used in lieu of it.

Specific elements of the program to do TDI ASME code work include:

°All mechanical work to be done under the direction of TDI technical representative to TDI procedures.

"Quality control inspections are to be done by MPQAD QCE's to PQCI's developed specifically for the Diesel Generators. The PQCI's are listed to describe their function.

- P2.11 Pipe Component Support Installation
- PF1.11 Pipe Flange Installation and Rework for Diesel Generator Piping Systems
- P1.01 Piping Completed Line Inspections Emergency Diesel Generators
- PI1.41 Installation of ASME III Diesel Generator Instrumentation and Tubing Systems
- PW1.01 Fabrication, Welding, Heat Treating and Non Destructive Examination of ASME III Piping of the Emergency Diesel Generator Complex.
- T1.01 Pressure Testing of ASME ITI Piping and Instrumentation System Designed by Transamerica DeLaval, Inc.
- "The Bechtel Authorized Nuclear Inspector has reviewed and approved the PQCI's and will be responsible for inspection overview.
- °MPQAD has specifically designated Quality Control Inspectors to work on the Diesel Generators.
- °MPQAD will conduct a complete review of all open and closed PQCI Inspection Reports.

Specific elements of the non code related mechanical work include:

"Technical direction by TDI

- \*Quality Control Inspections will be done by TDI Quality Control Inspector to TDI Quality Control Program.
- \*Inspection Reports will be developed by TDI Quality Control Inspector in accordance with their program.
- \*MPQAD will provide in line review function of the Inspection Reports and will monitor the work on a regular basis.

Bechtel has committed system team 19 to work exclusively in the Diesel Generator Building. The physical work will be done by Bechtel craft utilizing the construction work package program that was developed as part of the CCP.

Stone and Webster has committed to provide third party overinspection for this program.

This proposed program is independent of Consumers Power Company involvement in the TDI Users Group Task Force to solve the generic problems that have arisen on TDI diesel engines at other nuclear facilities. It is our desire to have as much of the construction complete as possible prior to addressing the modifications that come out of the Users Group Reviews.

kflan Jamme

DLO/JSK/klw

CC BLHarshe, P24-618
RAWells, MPOAD
RJCook, Midland Resident Inspector
DSHood, USNRC
JGKeppler, Regional Administrator, Region III

BCC JWCook, P-26-336B SHHowell, M-1180B TABuczwinski, Midland-207 LGraber, LIS JNLeech, P-24-506 DFLewis, Bechtel FJLevandoski, B&W GALow, P-12-237A DASommers, P-14-106 PrSteptoe, IL&B, Chicago DJVandeWalle, P-24-614B BJWalraven, P-24-517 RAWells, Midland FCWilliams, IL&B, Washington, DC DTPerry, Midland NRC Correspondence File, P-24-517 UFI, P-24-511 CMS-Midland

> RC DMBudzik, P-24-517A RJErhardt, P-14-113A LSGibson, P-24-618A P-24-505 (Last)



James W. Cook
Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Farnell Road, Jackson, MI 49201 • (517) 788-0453

February 28, 1984

Mr J G Keppler, Regional Administrator US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND NUCLEAR COGENERATION PLANT DOCKET NOS. 50-329 AND 50-330
ITEMS FOR NRC CLOSURE
FILE 0.4.2 SERIAL 27328

In accordance with your request, we are submitting the attached list of items which have been reviewed by CP Co and have been determined to be ready for review and closure by the NRC.

This is a complete list which includes the items that were transmitted on October 4, 1983 that have not been closed subsequent to that time. The items marked with an asterisk (\*) have been reviewed by the Region III Inspectors and will be removed from the list when closed in an inspection report.

CC WRBird, P-14-418A
DMBudzik, P-24-517A
RCook, NRC-Midland
JFFremeau, Midland
JHarrison, NRC
JNLeech, P-24-507
DLQuamme, Midland
JARutgers, Bechtel-AA
RAWells, Midland
REWhitaker, Midland

MAR 2 1984

tames W. Cert

8403080171

OC0284-0001A-0L02

# NRC Inspection Report Items

### Miscellaneous Items Ready For Closure

| Item         | Туре       | Subject  | Closure Location |
|--------------|------------|--|------------------|
| 79-12-05     | Unresolved | Pressure Test of Pressurizer Relief Valve                                    | Site             |
| 80-09-01     | Deficiency | Leveling of Internal Core Support Structure                                  | Site             |
| *80-30/31-01 | Unresolved | Battery Rack Acidic Environment  | Site             |
| 81-12-09/10  | Violation  | Lack of Approved Procedures Covering Rework                                  | Site             |
| 81-20-01     | Unresolved | Cable Tray Dividers  | Site             |
| 82-05-01     | Deviation  | QA Staffing  | Site             |
| 82-06-02     | Violation  | Cable Pulling  | Site             |
| 82-18-02/01  | Violation  | Dewatering Fines Monitoring  | Site             |
| 82-18-03/02  | Violation  | Slope Layback  | Site             |
| 82-20-01     | 0pen       | Training of RMS Personnel for Emergency<br>Procedures and Training of Crafts | Site             |
| 83-03-02     | Unresolved | Expansion of Excavation Permit System to<br>Underpinning                     | Site             |
| 83-13/14-03  | Deviation  | Slope Layback in the Drifts  | Site             |

#### NRC Inspection Report Items

#### Items Dealing With Hanger Design

The following items all were initiated by I Yen, and need to be resolved by a scheduled trip to Ann Arbor with a possibility of going to ITT Grinnell in Providence.

| Item        | Type | Subject  |     | Closure Location    |
|-------------|------|--|-----|---------------------|
| /8-19-02    | URI  | Locking Devices on Bolts used in ITT Grinnel                                     | Ann | Arbor               |
| 78-19-03    | URI  | ITT Grinnell Evaluation of Bolt Holes Near<br>Edge of Plate                      | Ann | Arbor               |
| 79-01-02    | URI  | Adequacy of Drawing Hanger Review  | Ann | Arbor               |
| 79-05-02    | URI  | Additional reviews of ITT Hanger Design  | Ann | Arbor or Providence |
| 79-05-03    | URI  | Bechtel System for Design Interface of Hanger<br>Loadings on Existing Structures | Ann | Arbor               |
| 80-11/12-01 | URI  | Bolted Joints  | Ann | Arbor               |
| 82-07-01    | URI  | Review of Other Disciplines for Handling of CPDC's                               | Ann | Arbor               |

# 50.55(e) Reports Ready For Closure

| NRC Number | No       | Description   |
|------------|----------|---|
| 77-03      | 0.4.9.12 | ITT/Grinnel Pipe Supports                             |
| 78-01      | 0.4.9.13 | RCP Motor Flange                                      |
| 78-06      | 0.4.9.18 | Smali Break Analysis                                  |
| 81-05      | 0.4.9.53 | Shear Reinforcement at Major Containment Penetrations |

# Bulletins - Circulars - Notices Ready For Closure

| *BULLETIN | 73-01          | Faulty Overcurrent Trip Delay Device in Circuit Breakers for Engineered Safety System   |
|-----------|----------------|---|
| *BULLETIN | 74-01          | Valve Deficiencies  |
| *BULLETIN | 74-06<br>74-08 | Defective Westinghouse Type W-2 Control Switch Component Deficiency in ITE Molded Case Circuit Breakers, Type HE-3                      |
| *BULLETIN | 74-09          | Deficiency in General Electric Model 4kV Magna-Blast Breakers   |
| *BULLETIN | 74-12          | Incorrect Coils in Westinghouse Type SG Relays at Trojan  |
| *BULLETIN | 74-15          | Misapplication of Cutler-Hammer Three Positioned Maintained<br>Switch, Model 10250T   |
| BULLETIN  | 74-16          | Improper Machining of Pistons in Colt Industries (Fairbanks-Morse) Diesel Generators  |
| BULLETIN  | 78-12          | Atypical Weld Material in Reactor Pressure Vessel Welds   |
| BULLETIN  | 80-16          | Potential Misapplication of Rosemount, Inc Models 1151 and 1152 Pressure Trans-<br>mitters with either "A" or "D" Output Codes.         |
| BULLETIN  | 82-01          | Alteration of Radiographs of Welds in Piping Assemblies.  |
| BULLETIN  | 82-03          | Stress Corrosion Cracking in Thick-Wall, Large Diameter, Stainless Steel, Recirculation System Piping at BWR Plants.                    |
| BULLETIN  | 82-04          | Deficiencies in Primary Containment Penetration Assemblies.   |
| BULLETIN  | 83-02          | Stress Corrosion Cracking in Large Diameter Stainless Steel Recirculation System Piping at BWR Plants.                                  |
| CIRCULAR  | 76-01          | Crane Hoist Control Circuit Modifications   |
| CIRCULAR  | 76-05          | Hydraulic Shock and Sway Suppressors Maintenance of Bleed and Locking on ITT Grinnell's Model Number Figure 200 and 201 Catalog PH-74-R |
|           |                |   |

| *CIRCULAR | 77-02 | Potential Heavy Spring Flooding  |
|-----------|-------|--|
| CIRCULAR  | 77-06 | Effects of Hydraulic Fluid on Electrical Cables  |
| CIRCULAR  | 78-05 | Inadvertent Safety Injection during Cooldown   |
| *CIRCULAR | 78-13 | Inoperability of Multiple Service Water Pumps  |
| CIRCULAR  | 78-15 | Check Valves Fail to Close in Vertical Position  |
| CIRCULAR  | 79-05 | Moisture Leakage in Stranded Wire Conductors   |
| CIRCULAR  | 79-11 | Design/Construction Interface  |
| CIRCULAR  | 79-12 | Potential Diesel Generator Turbocharger Problem  |
| CIRCULAR  | 80-16 | Operational Deficiency on Rosemount Model 510DU Trip Units and<br>Model 1152 pressure Transmitters |
| CIRCULAR  | 80-17 | Fuel Pin Damage to Water Jet from Baffle Plate Corner  |
| CIRCULAR  | 80-21 | Regulation of Refueling Crews  |
| CIRCULAR  | 81-05 | Self-Aligning Rod End Bushings for Pipe Supports   |
| CIRCULAR  | 81-06 | Potential Deficiency Affecting Certain Foxboro 10 to 50 Milliampere Transmitters                   |
| CIRCULAR  | 81-07 | Control of Radioactively Contaminated Material   |
| CIRCULAR  | 81-08 | Foundation Materials   |
| CIRCULAR  | 81-09 | Containment Effluent Water Heat Bypasses Radioactivity Monitor                                     |
| CIRCULAR  | 81-11 | Inadequate Decay Heat Removal During Reactor Shutdown  |

| CIRCULAR | 81-12 | Inadequate Periodic Test Procedure of PWR Protection System   |
|----------|-------|---|
| CIRCULAR | 81-14 | Main Steam Isolation Valve Failures to Close  |
| NOTICE   | 79-06 | Stress Analysis of Safety-Related Piping  |
| NOTICE   | 79-09 | Spill of Radioactively Contaminated Resin   |
| NOTICE   | 79-11 | Lower Reactor Vessel Head Insulation Support Problem  |
| NOTICE   | 79-12 | Attempted Damage to New Fuel Assemblies   |
| NOTICE   | 79-13 | Indication of Low Water Level in the Oyster Creek Reactor (BWR)   |
| NOTICE   | 79-16 | Nuclear Incident at Three Mile Island   |
| NOTICE   | 79–17 | Source Holder Assembly Damage from Misfit between Assembly and Reactor Upper Grid Plate (Westinghouse Units only) |
| NOTICE   | 79-18 | Skylab Reentry  |
| NOTICE   | 79-28 | Overloading of Structural Elements due to Pipe Support Loads  |
| NOTICE   | 79-29 | Loss of Nonsatety-Kelated Reactor Coolant System Instrumentation during Operation.                                |
| NOTICE   | 79-32 | Separation of Electrical Cables for HPCI and ADS (BWR only)   |
| NOTICE   | 79-37 | Cracking in Low Pressure Turbine Discs  |
| NOTICE   | 80-04 | BWR Fuel Exposure in Excess of Limits   |
| NOTICE   | 80-06 | Notification of Significant Event and Supplement  |

ж

| NOTICE | 80-17 | Potential Hazards Associated with Interchangeable Parts on Radiographic Equipment   |
|--------|-------|---|
| NOTICE | 80-20 | Loss of Decay Heat Removal Capability at Davis-Besse Unit I while in Refueling Mode   |
| NOTICE | 80-22 | Breakdowns in Contamination Control Programs  |
| NOTICE | 80-23 | Loss of Suction to Emergency Feedwater Pumps  |
| NOTICE | 80-24 | Low Level Radioactive Waste Burial Criteria   |
| NOTICE | 80-25 | Transportation of Pyrophoric Uranium  |
| NOTICE | 80-27 | Degradation of Reactor Coolant Pump Stude   |
| NOTICE | 80-29 | Broken Studs on Terry Turbine Steam Inlet Flange  |
| NOTICE | 80-30 | Potential for Unacceptable Interaction between the Control Rod Drive<br>Scram Function and Nonessential Control Air at Certain G E BWR Facilities |
| NOTICE | 80-33 | Determination of Teletherapy Timer Accuracy   |
| NOTICE | 80-35 | Leaking and dislodged Iodine-125 Implant Seeds  |
| NOTICE | 80-37 | Containment Cooler Leaks and Reactor Cavity Flooding at Indian<br>Point 2   |
| NOTICE | 80-45 | Potential Failure of BWR Backup Manual Scram Capability   |
| NOTICE | 81-02 | Transportation of Radiography Devices   |
| NOTICE | 81-04 | Cracking in Main Steam Lines  |
| NOTICE | 81-06 | Failure of ITE Model K-600 Circuit Breaker  |

| NOTICE | 81-07 | Potential Problem with Water Soluble Purge Dam Materials used during<br>Inert Gas Welding                                   |
|--------|-------|---|
| NOTICE | 81-08 | Repetitive Failures of Limitorque Operator SMB-4 Motor-to-Shaft Key   |
| NOTICE | 81-10 | Inadvertent Containment Spray due to Personnel Error  |
| NOTICE | 81-11 | Alternate Rod Insertion for BWR Scram Represents a Potential<br>Path for Loss of Primary Coolant.                           |
| NOTICE | 81-12 | Guidance on Order Issued January 9, 1981, Regarding Automatic Control Rod Insertion on Low Control Air Pressure (BWR only). |
| NOTICE | 81-13 | Jammed Source Rack in a Gamma Irradiator  |
| NOTICE | 81-14 | Potential Overstress of Shafts on Fisher Series 9200 Butterfly Valves with Expandle T-Rings                                 |
| NOTICE | 81-15 | Degradation of Automatic ECCS Actuation Capability by Isolation of Instrument Lines.  |
| NOTICE | 81-16 | Control Rod Drive System Malfunction (BWR only)   |
| NOTICE | 81-17 | Never Issued  |
| NOTICE | 81-18 | Excessive Radiation Exposure to Fingers   |
| NOTICE | 81-19 | Lost Parts in Primary Coolant System  |
| NOTICE | 81-20 | Test Failures of Electrical Penetration Assemblies  |
| NOTICE | 81-21 | Potential Loss of Direct Access to Ultimate Heat Sink   |
| NOTICE | 81-22 | Section 235 and 236 Admendments to the Atomic Energy Act of 1954  |

| NOTICE | 81-23 | Fuel Assembly Damage due to Improper Positioning of Fuel Handling Equipment  |
|--------|-------|--|
| NOTICE | 81-24 | AFW Pump Turbine Bearing Failures  |
| NOTICE | 81-26 | Compilation of Health Physics Related Information Items  |
| NOTICE | 81-27 | Flammable Gas Mixtures in the Waste Decay Tanks in BWR Plants.   |
| NOTICE | 81-28 | Failure of Rockwell-Elward Main Steam Isolation Valves   |
| NOTICE | 81-29 | Equipment Qualification Testing Experience   |
| NOTICE | 81-30 | Velan Swing Check Valves   |
| NOTICE | 81-31 | Failure of Safety Injection Valve to Operate Against<br>Differential Pressure.   |
| NOTICE | 81-32 | Transfer and/or Disposal of Spent Generators   |
| NOTICE | 81-33 | Locking Devices Inadequately Installed on Main Steam Isolation Valves  |
| NOTICE | 81-34 | Accidental Actuation of Prompt Public Notification System  |
| NOTICE | 81-35 | Check Valve Failures   |
| NOTICE | 81-36 | Replacement Diaphrams for Robertshaw Valve (Model No VC-210)   |
| NOTICE | 81-37 | Unnecessary Radiation Exposure to Public and Workers during Events<br>Involving Thickness and Limit Measuring Devices. |
| NOTICE | 81-38 | Potentially Significant Equipment Failures Resulting from Contamination of Air-Operated Systems                        |
| NOTICE | 81-39 | EPA Crosscheck Program Low-Level Radioiodine in Water Intercomparison Study  |

. . . . . . . . .

| NOTICE | 82-01 | AFW Pump Lockout Resulting from Westinghouse W-2 Switch Circuit Modification                      |
|--------|-------|---|
| NOTICE | 82-02 | Westinghouse NBFD Relay Failures in Reactor Protection Systems at Certain Nuclear<br>Power Plants |
| NOTICE | 82-03 | Environmental Tests of Electrical Terminal Blocks   |
| NOTICE | 82-04 | Potential Deficiency of Certain Agastat E-7000 Series Time Delay Relays                           |
| NOTICE | 82-05 | Increasing Frequency of Drug-Related Incidents  |
| NOTICE | 82-07 | Inadequate Security Screening Programs  |
| NOTICE | 82-09 | Cracking in Makeup Coolant Lines at B&W Plants  |
| NOTICE | 82-10 | Following Up Symptomatic Repairs to Assure Resolution of the Problem                              |
| NOTICE | 82-11 | Potential Inaccuracies in Wide Range Pressure Instruments Used in Westinghouse Designed Plants    |
| NOTICE | 82-12 | Surveillance of Hydraulic Snubbers  |
| NOTICE | 82-13 | Failure of General Electric Type HFA Relays   |
| NOTICE | 82-15 | Notification of Nuclear Regulatory Commission (NRC)   |
| NOTICE | 82-16 | HPCI/RCIC High Steam Flow Set Points  |
| NOTICE | 82-18 | Assessment of Intakes of Radioactive Materials by Workers   |
| NOTICE | 82-19 | Loss of High Head Safety Injection Emergency Boration and Reactor Coolant<br>Makeup Capability    |
| NOTICE | 82-20 | Check Valve Problems  |
|        |       |   |

| NOTICE | 82-21 | Buildup of Enriched Uranium in Effluent Treatment Tanks   |
|--------|-------|---|
| NOTICE | 82-22 | l ilures in Turbine Exhaust Lines   |
| NOTICE | 82-23 | Main Steam Isolation Valve Leakage  |
| NOTICE | 82-24 | Water Leakage from Uranium Hexafloride Overpacks  |
| NOTICE | 82-26 | RCIC and HPCI Turbine Exhaust Check Valve Failure (BWR only)  |
| NOTICE | 82-27 | Fuel Rod Degradation Resulting from Water-Jet Bairle Impingement  |
| NOTICE | 82-28 | Hydrogen Explosion while Grinding in Vicinity of Drained and Open RCS   |
| NOTICE | 82-29 | Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse<br>PWR (Westinghouse Plants only)           |
| NOTICE | 82-30 | Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Plants  |
| NOTICE | 82-31 | Overexposure of Diver during Work in Fuel Storage Pool  |
| NOTICE | 82-33 | Control of Radiation Levels in Unrestricted Areas Adjacent to Brachytherapy<br>Patients (Medical Institutions only) |
| NOTICE | 82-35 | Failures of Three Check Valve on HPI Lines to Pass Flow   |
| NOTICE | 82-36 | Respirator Users Warning for Certain 5-Minute Emergency Escape<br>Self-Contained Breathing Apparatus                |
| NOTICE | 82-37 | Cracking in the Upper Shell to Transition Cone Girth Weld of a Steam<br>Generator on an Operating PWR               |
| NOTICE | 82-38 | Change in Format and Distribution System for IE Bulletins, Circulars and Information Notices                        |
|        |       |   |

| NOTICE | 82-39 | Service Degradation of Thick Wall Stainless Steel Recirculation System Piping at BWRs                                    |
|--------|-------|--|
| NOTICE | 82-40 | Deficiencies in Primary Containment Electrical Penetration Assemblies  |
| NOTICE | 82-41 | Failure of Safety Relief Valve to Open at a BWR  |
| NOTICE | 82-42 | Defects Observed in Panasonic Model 801 and Model 802 Thermoluminiscent Dosimeters                                       |
| NOTICE | 82-43 | Deficiencies in LWR Air Filtration/Ventilation Systems   |
| NOTICE | 82-44 | Clarification of Emergency Plan Exercise Requirements  |
| NOTICE | 82-45 | PWR Low Temperature Overpressure Protection  |
| NOTICE | 82-46 | Defective and Obsolete Combination Padlocks  |
| NOTICE | 82-51 | Overexposure in PWR Cavities   |
| NOTICE | 82-52 | Equipment Environmental Qualification Testing Experience - Update of Test Summaries Previously Issued in IN 81-29        |
| NOTICE | 82-54 | Westinghouse NBFD Relay Failures in Reactor Protection Systems   |
| NOTICE | 82-55 | Seismic Qualification of Westinghouse AR Relay with Latch Attachment used in Westinghouse Solid-State Protection System. |
| NOTICE | 83-01 | Ray Miller, Inc.   |
| NOTICE | 83-07 | Nonconformities with Materials Supplied by Tube-Line Corp  |
| NOTICE | 83-09 | Safety and Security of Irradiators   |
| NOTICE | 83-12 | Incorrect Boron Standards  |

| NOTICE | 83-13 | Design Misapplication of Bergen Patterson Standard Strut Restraints   |   |
|--------|-------|---|---|
| NOTICE | 83-14 | Dewatered Spent Ion Exchange Resin Susceptability to<br>Exothermic Chemical Reaction                                |   |
| NOTICE | 83-15 | Falsified Pre-Employment Screening Records  |   |
| NOTICE | 83-16 | Contamination of Auburn Steel Company with Cobalt-60  |   |
| NOTICE | 83-20 | ITT Grinnel Figure 306/307 Mechanical Snubber Attechment Interferences  |   |
| NOTICE | 83-21 | Defective Emergency Use Respirators   |   |
| NOTICE | 83-22 | BWR Safety/Relief Valve Failures  |   |
| NOTICE | 83-26 | Failure of Safety/Relief Valve Discharge Line Vacuum Breakers   |   |
| NOTICE | 83-29 | Fuel Binding Caused by Fuel Rack Deformation  |   |
| NOTICE | 83-32 | Rupture of Americium-241 Source(s) Contained in Well Logging Device   | , |
| NOTICE | 83-34 | Event Notification Information Worksheet  |   |
| NOTICE | 83-35 | Fuel Movement with Control Rods Withdrawn   |   |
| NOTICE | 83-37 | Transformer Failure Resulting from Degraded Internal Connection Cables  |   |
| NOTICE | 83-39 | Failure of Safety/Relief Valves to Open at a BWR - Interim Report   |   |
| NOTICE | 83-42 | Reactor Mode Switch Malfunction   |   |
| NOTICE | 83-44 | Potential Damage to Redundant Safety Equipment as a Result of Backflow through the Equipment and Floor Drain System |   |
| NOTICE | 83-52 | Radioactive Waste Gas System Events   |   |
|        |       |   |   |

| NOTICE | 83-53 | Primary Containment Isolation Valve Discrepancies  |
|--------|-------|--|
| NOTICE | 83-54 | Common Mode Failure of Main Steam Isolation Nonreturn Check Valves                             |
| NOTICE | 83-55 | Misapplication of Valves by Throttling beyond Design Range                                     |
| NOTICE | 83-59 | Dose Assignment for Workers in Non-Uniform Radiation Fields                                    |
| NOTICE | 83-60 | Falsification of Test Results for Protection Coatings  |
| NOTICE | 83-61 | Alleged Use of Stand-Ins for Welder Qualification Tests  |
| NOTICE | 83-62 | Failure of Redundant Toxic Gas Detectors Positioned at Control Room<br>Ventilation Air Intakes |
| NOTICE | 83-63 | Potential Failure of Westinghouse Electric Corp Type SA-! Differential Relays                  |
| NOTICE | 83-64 | Lead Shielding Attached to Safety-Related Systems without<br>10CFR50.59 Evaluations            |
| NOTICE | 83-66 | Fatality at Argentine Critical Facility  |
| NOTICE | 83-67 | Emergency Use Respirator Material Defect Causes Production of Noxious Gases                    |
| NOTICE | 83-68 | Respirator User Warning - Defective Self-Contained Breathing Apparatus Air Cylinders           |
| NOTICE | 83-73 | Radiation Exposure from Gloves Contaminated with Uranium Daughter Products.                    |
| NOTICE | 83-74 | Rupture of Cesium-137 Source used in Well-Logging Operations                                   |
| NOTICE | 83-80 | Use of Specialized "Stiff" Pipe Clamps   |
| NOTICE | 83-82 | Failure of Safety Relief Valves to Open at BWR - Formal Report                                 |
|        |       |  |

NOTICE 83-84 Cracked and Broken Piston Rods in Brown Boveri Electric Type 5HK Circuit Breakers



April 9, 1984

For the past several weeks we have seen a large amount of speculation and suggestions from the media and various government officials and other organizations concerning the future of the Midland Ruclear Plant. Because of the variety of organizations involved in one way or another in issuing public statements about Midland, there has been some confusion.

The Company has been meeting for several weeks with representatives of the attorney general and the staff of the Michigan Public Service Commission. These meetings, which have involved discussing various scenarios relating to completion of the Midland Plant, resulted from an agreement between Consumers Power Chairman John D Selby and Attorney General Frank Kelley. No other parties have been involved in these talks and no firm proposals have been made by either side.

Company officials met last week with representatives of large industrial customers to brief them on our forecasts which show the need to complete Midland. Although participants in that meeting included members of the industrial customer organization called ABATE, the session also included major customers who do not hold membership in that organization.

The only concrete proposal offered to the Company by any outside party was a so-called "survival plan" which was proposed by a coalition that included some of the above-named parties along with the Michigan Citizens' Lobby. That proposal, which was studied, was rejected in its entirery because it was designed as a blueprint for disaster for the Company.

For some months, the Company has been conducting a study of a new schedule for completion of Unit 2. The results of that study will include an initial cost estimate for completing the unit. The Company's board of directors will be presented with the results of that study prior to the Company's annual meeting on Tuesday, April 10. The results of any board action are scheduled to be announced at the annual meeting. We plan to communicate that information to all Midland workers as quickly as possible.

The major issues to be reviewed by the board include:

"Schedule and cost for the Midland Nuclear Flant \*Action on the payment of the Company's common stock dividend

180

During the secting itself, stockholders will vote on a proposal submitted by an individual shareholder that would halt construction of the plant for one year.

Time limitations Tuesday afternoon will now allow us to give you an immediate detailed analysis of the decisions and their impact on Midland. We will provide this full accounting to you as soon afterwards as possible.

Amid the pages of newspaper publicity and hours of radio and television coverage of the Midland Nuclear Plant, we should not lose perspective of cur individual jobs and roles to successfully complete this project. The site-wide role and responsibility is clear: we need to continue with the progress we are accomplishing in completing our task.

The Midland completion schedule is schievable. It will be accomplished not by the board of directors or government officials in Lansing; it must be made by all workers vanting to share it the success of Midland.

\*\*\*

LEGAL DEPARTMENT THE VERSON

DATE - LETS DENCE



MAR -9 P4:42

General Offices: 212 West Michigan Avenue, Jackson, MI 49201 + (517) 788-0550, 574 v. 1 BRANCH Writer's Direct Dial Number + (517) 788-1257

March 7, 1984

Dr. Frederick P. Cowan 6152 N. Verde Trail Apt. B-125 Boca Raton, FL 33433

PRINCIPAL

Mr. Charles Bechhoefer, Esq. Atomic Safety & Licensing Board Panel U.S. Nuclear Regulatory Commission East-West Towers Room E-413 4350 East-West Highway Bethesda, MD 20014

Dr. Jerry Harbour Atomic Safety & Licensing Board Panel U.S. Nuclear Regulatory Commission East-West Towers Room E-454 4350 East-West Highway Bethesda, MD 20014

Dear Board Members:

At Tr. 22401 Robert Wheeler offered to provide information concerning certain work which was performed in connection with an underground fireline at the Midland site. Mr. Wheeler has been able to determine that after NRC Staff approval was obtained, physical connections were made to the fireline in question on or about October 16, 1982 to restore fire service to portions of the jobsite. The physical connections were a mechanical operation not involving excavations or backfilling. The entire fireline excavation was backfilled at a later date, pursuant to NRC authorization under the Region III work authorization procedure.

Very truly yours,

James E. Brunner

Attorney for Consumers Power Company

CC OM/OL Service List

amu & Thurren

PDR ADOCK 05000

1503

where is in inter

#### OM/OL SERVICE LIST

Mr. Frank J. Kelley, Esq.
Attorney General of the
State of Michigan
Ms. Carole Steinberg, Esq.
Assistant Attorney General
Environmental Protection Div.
720 Law Building
Lansing, MI 48913

Mr. Myron M. Cherry, Esq. Cherry & Flynn 3 First National Plaza Suite 3700 Chicago, IL 60602

Mr. Wendell H. Marshall 4625 S. Saginaw Road Midland, MI 48640

Mr. Charles Bechhoefer, Esq.
Atomic Safety & Licensing
Board Panel
U.S. Nuclear Regulatory Commission
East-West Towers
Room E-413
4350 East-West Highway
Bethesda, MD 20014

Dr. Frederick P. Cowan 6152 N. Verde Trail Apt. B-125 Boca Raton, FL 33433

Mr. Michael Miller, Esq. Isham, Lincoln & Beale 3 First National Plaza Suite 5200 Chicago, IL 60502

Mr. D. F. Judd Senior Project Manager The Babcock & Wilcox Company P.O. Box 1260 Lynchburg, VA 24505

Ms. Barbara Stamiris 5795 North River Road Route 3 Freeland, MI 48623 Mr. Steve Gadler 2120 Carter Avenue St. Paul, MN 55108

Atomic Safety & Licensing
Appeal Board
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. C. R. Stephens, Chief Docketing & Services U.S. Nuclear Regulatory Commission Office of the Secretary Washington, DC 20555

Ms. Mary Sinclair 5711 Summerset Street Midland, MI 48640

Dr. Jerry Harbour
Atomic Safety & Licensing
Board Panel
U.S. Nuclear Regulatory Commission
East-West Towers
Room E-454
4350 East-West Highway
Bethesda, MD 20014

Atomic Safety & Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, DC 20355

Mr. William D. Paton, Esq. Counsel for the NRC Staff U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. Frederick C. Williams Isham, Lincoln & Beale 1120 Connecticut Ave., N.W. Suite 325 Washington, DC 20036

Ms. Lynne Bernabei
Government Accountability
Project of the Institute
for Policy Studies
1901 Q Street, N.W.
Washington, DC 20009

OM/OL Service List (Cont'd.)
Page 2.

Mr. John DeMeester, Esq. Dow Chemical Building Michigan Division Midland, MI 48640 Mr. James E. Brunner, Esq. Consumers Power Company 212 West Michigan Avenue Jackson, MI 49201



# UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD

GLEN ELLYN, ILLINOIS 60137

Warnick

APR 9 1984

MEMORANDUM FOR:

D. G. Eisenhut, Director, Division of Licensing

FROM:

C. E. Norelius, Director, Division of Project and

Resident Programs

SUBJECT:

RECOMMENDATION FOR NOTIFICATION OF LICENSING BOARD -

FCR/FCN STOP WORK STATUS AND NRC MIDLAND STAFFING CHANGES.

In accordance with present NRC procedures regarding Board notifications, the following information is being provided as constituting new information relevant and material to the Midland OM/OL proceedings.

#### Design Control Stop Work Status

On January 31, 1984, Region III notified you of the status of the stop work orders regarding the design control (FCR/FCN) problems at Midland. On February 14, 1984, a Supplemental Board Notification (BN 84-023) forwarded this information to the Hearing Board. Following this notification the licensee lifted the remaining stop-works by area engineering discipline. On March 23, 1984, at 7:30 a.m., the final stop work was lifted. Attached you will find a copy of a matrix developed by Consumers Power Company that identifies key dates for various releases including Stone and Webster releases and CPCo final release.

As a result of the design control stop work orders and the resultant review of approximately 60,000 documents by Consumers Power Company, 12 nonconformance reports were issued. Attachment 2 identifies the nonconformance reports issued by number, engineering discipline, and a description of the nonconformance. The licensee has determined that the nonconformances have no significant impact on hardware.

The NRC staff plans to perform an inspection on the FCR/FCN area later this year to review the new design control system, problems identified by the licensee, and corrective actions taken. The Board will be informed of the results of this inspection via a copy of the inspection report when issued. This will complete all required followup action by the NRC.

8405020262

APR 9 DO

D. G. Eisenhut

#### NRC Staffing Status

The NRC staff assigned to perform inspections at the Midland facility has been increased this fiscal year. The increase is in accordance with the Region III staffing plan and is due to the backlog of open inspection items and the increased inspection workload associated with the Construction Completion Program.

The NRC now has three resident inspectors located at the Midland site, an additional three individuals in the Region III office assigned full time to the Midland project, and three inspection specialists from the Region III Division of Engineering who spend time onsite as needed. Additionally, an NRC Resident Site Supervisor has been selected for Midland and will report to the site in the near future.

NRC is in the process of approving a contract with a national laboratory for assistance with the technical inspection program at Midland, approximately two and one-half man-years of effort. In the interim, two Argonne contract engineers, formerly assigned to Zimmer, have been temporarily assigned to provide inspection assistance at Midland.

With the announced decision by the owners of the Zimmer plant to not complete it as a nuclear facility, Region III dissolved the Zimmer Section and the Office of Special Cases and transferred the Midland Section together with all its people to the Division of Project and Resident Programs (DPRP). The Director of the Office of Special Cases was reassigned as Chief, Projects Branch 1, DPRP, with responsibility for RIII plants under construction, including Midland.

We believe the increased NRC staffing will help to reduce the backlog of open inspection items and will enable RIII to better monitor the ongoing plant activities. The organization changes should have no impact on NRC inspection activities at Midland. No followup actions are required.

for C. E. Norelius, Director Division of Project and Resident Programs

Enclosures: As stated

cc w/encls: J. G. Keppler

#### STOP WORK RELEASE SUMMARY STOP WORK ORDERS FSW-33 THROUGH 41

| STOP WORK NO.                               | FSW-33  | FSW-34                       | FSW-35                        | FSN-36  | FSW-37  | F::W-38  | FSW-39   | FSW-40   | FSW-41  |
|---|---|------------------------------|-------------------------------|---|---|--|--|--|---|
| SUBJECT                                     | HVAC Zack<br>& MPGAD-<br>HVAC In-<br>spection | MPGAD Hanger<br>Reinapection | GEO Construc-<br>tion Testing | Procurement   | B&W Fabrica-<br>tion, Instal-<br>lation & In-<br>spection<br>(Utilizing<br>BPCo Spec's<br>& Dwgs. | Soils Q-<br>Related<br>Work Fabri-<br>cation, In-<br>stallation,<br>construction<br>& Inspection | Standish<br>Fabrication<br>Facility<br>Fabrication<br>Inspection | GSO Fabri-<br>cation &<br>Installa-<br>tion; MPQAD<br>Inspection<br>in support<br>of GSO | Balance of Plant Q-relat- ed work includ- ing CCP Status Assens- ment & QVP Act.  |
| PARTIAL RELEASE                             | N/A   | H/A                          | N/A                           | Ann Arbor<br>Procurements<br>(Only) Veri-<br>fied as not<br>affected<br>11-3-83<br>11-20 a.m. | N/A   | N/A  | N/A  | N/A  | N/A   |
| PARTIAL RELEASE FOR FCN/FCR PROCESSING      | 12-9-83<br>6:10 p.m.                          | 12-9-83<br>6:19 p.m.         | 12-9-83<br>6:20 p.m.          | 12-9-63<br>6:09 p.m.  | 12-9-83<br>6:20 p.m.  | 12-9-83<br>6:12 p.m.   | 12-9-83<br>6:21 p.m.   | 12-9-83<br>6:22 p.m.   | 12-9-83<br>6:21 p.s   |
| STONE & WERSTER<br>ARCHITECTURAL<br>RELEASE | 1-20-84                                       | 1-20-84                      | 1-20-84                       | 1-30-84   | 1-20-84   | 1-20-84  | 1-20-64  | 1-20-84  | Dwg only at Sta- tion 14 12-11-8; (Verbal) Dwg & Specs. DCC Sta- tions 14, 48a, b&d & 55; 12-13-8; Print concept & Sta- tion 59 1-20-84 |

Rev. 2 3-23-84 D & Taggart

| STOP WORK NO.  | F34-33   | 15-53   | PSW-35  | PS#-36                                       | F34-37  | F.W-38   | F34-39   | FSW-40   | F5#-#1  |
|--|--|---|---|--|---|--|--|--|---|
| PARTIAL RELEASE FOR G-RELATED WORK ARCHITECTURAL DOC'S | 2-9-89<br>11-25 4-8-<br>8 Statton<br>99 (FDSC) | 1.20-84<br>11:17 a.m.<br>F Station<br>59 (FDBC) | 2-9-84<br>2:46 p.m.<br>5- (PDDC)              | 11:16 a.a.<br># Station<br>59 (FDBC)         | 2-8-84<br>3:48 p.s.<br>6 Station<br>59 (PDDC) |  | 1-20-84 11:15 a.m. # Station 59 (FDEC) NOTE: Pab- rication, Imapection, a related work in support of Soils re- leased via SwD FSM-38 | 1-20-84<br>11:18 a.m.<br># Station<br>59 (FDDC)  | 12-11-83<br>3:00 p.m.<br>bug only<br>e Station<br>14<br>12-13-83<br>9:15 c.m.<br>bug 4<br>Spec's<br>bug 4<br>Spec's<br>bug 4<br>Spec's<br>1000 Station<br>430, Ned<br>4 55<br>11:15 a.m.<br>111:15 |
| STONE & VERSTER  | 1-20-84  | 1-20-84   | 1-20-84                                       | 1-27-84                                      | 1-20-84                                       | 1-19-84  | 1-20-84  | 1-20-84  | 1-20-84   |
| MORK CIVIL DOC'S                                       | 2-9-84<br>11:25 a.m.<br># Station<br>59 (FDGS) | 1-20-84<br>11:37 a.m.<br># Station<br>59 (PSDC) | 2-9-84<br>2:48 p.m.<br># Station<br>59 (FDDC) | 1-3-64<br>11:16 a.m.<br># Sation<br>59 (PDC) | 2-8-84<br>3:48 p.m.<br># Station<br>59 (FDDC) | 1-19-84<br>9:40 a.m.<br>5011a DCC<br>5011a DCC<br>512110na<br>8,10,13,24<br>6.64 | 1-20-84 11:15 a.m. # Station 59 WOTE: Fabrication, Inspection, a related work in auppoort of Soils re- leased via SWO FSW-38         | 11.20-84<br>11.18 a.m.<br># Station<br>59 (FDGC) | 1-20-84   |
| STONE & WEBSTER  | 1-24-84  | 1-24-84   | 1-24-84                                       | 1-24-84                                      | 1-24-84                                       | 1-24-84  | 1-24-84  | 1-24-84  | 1-24-84   |

3-23-64 SM

| STOP WORK NO   | FSN-33   | FSW-34  | FSW-35 '                                      | FSW-36  | FSW-37  | FSW-38   | FSW-39  | FSW-40  | FSW-41                                       |
|--|--|---|---|---|---|--|---|---|--|
| PARTIAL RELEASE<br>FOR Q-RELATED<br>WORK IAC DOC's*          | 2-9-8%<br>11-25 a.m.<br># Station<br>59 (FDDC) | 1-24-84<br>12:32 p.m.<br># Station<br>59 (FDDC) | 2-9-84<br>2:48 p.m.<br># Station<br>59 (FDDC) | 1-24-84<br>12:30 p.m.<br># Station<br>59 (FDDC) | 2-8-84<br>3:48 p.m.<br>@ Station<br>59 (FDDC) | (Soils G<br>Series to<br>support<br>Civil Soils<br>released<br>1-24-84<br>e 11:55 a.m. | 1-24-84<br>12:32 p.m.<br># Station<br>59 (FDDC) | 1-24-84<br>12:33 p.m.<br>& Station<br>59 (FDDC) | 1-24-84<br>12:35 a.s                         |
| STONE & WEBSTER<br>ELECTRICAL<br>RELEASE                     | 1-26-84  | 1-26-84   | 1-26-84                                       | 1-26-84   | 1-26-84                                       | 1-26-84  | 1-26-84   | 1-26-84   | 1-26-84                                      |
| PARTIAL RELEASE FOR Q-RELATED WORK ELECTRICAL DOC's.         | 2-9-84<br>11:25 a.m.<br># Station<br>59 (FDBC) | 1-26-84<br>2:36 p.m.<br># Station<br>.59 (FDDC) | 2-9-84<br>2:48 p.m.<br># Station<br>59 (FDDC) | 1-26-84<br>2:3' , m.<br># Scation<br>59 (7DDC)  | 2-8-84<br>3:48 p.m.<br># Station<br>59 (FDDC) | 2-6-84<br>1:20 p.m.<br>Stations<br>8 & 10  | 1-26-84<br>2:38 p.m.<br># Station<br>59 (FDDC)  | 1-26-84<br>2:39 p.m.<br># Station<br>59 (FDDC)  | 1-26-84<br>2:12 p.e<br># Static<br>59 (FDDC  |
| STONE & WEBSTER<br>MECHANICAL<br>RELEASE                     | 2-8-84   | 2-8-84  | 2-8-84  | 2-8-84  | 2-8-84  | 2-8-84   | 2-8-84  | 2-8-84  | 2-8-84                                       |
| PARTIAL RELEASE<br>FOR Q-RELATED<br>WORK MECHANICAL<br>DOC'S | 2-9-84<br>11:25 a.m.<br># Station<br>59 (FDDC) | 2-8-9%<br>3:47 p.m.<br># Station<br>59 (FDDC)   | 2-9-84<br>2:48 p.m.<br>@ Station<br>59 (FDDC) | 2-8-34<br>3:47 p.m.<br># Station<br>59 (FDDC)   | 2-8-84<br>3:48 p.m.<br>@ Station<br>59 (FDDC) | 3-23-84<br>7:30 a.m.<br># Stations<br>8 & 10   | 2-8-84<br>3:48 p.m.<br># Station<br>59 (FDDC)   | 2-8-84<br>3:49 p.m.<br>@ Station<br>59 (FDDC)   | 2-8-84<br>3:45 p.m<br># Station<br>59 (FDDC) |
| FINAL COMPLETE<br>RELEASE                                    | 2-9-84<br>11:25 a.m.                           | 2-8-84<br>3:47 p.m.                             | 2-9-84<br>2:48 p.m.                           | 2-8-14<br>3-47 p.m.                             | 2-8-84<br>3:48 p.m.                           | Soils Pri-<br>mary re-<br>lease<br>1-19-84<br>9:40 m.m.                                | 2-8-84<br>3:48 p.m.                             | 2-8-84<br>3:49 p.m.                             | 2-8-84<br>3:45 p.m                           |

\*NOTE: G Series documents were included # I & C Doc's, G-Doc were released in conjunction as when the discipline was released starting 1-24-84.

Rev. 2 3-23-84 D A Taggart