

Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

July 5, 1995

TELEPHONE
714-366-6255

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362
30-Day Report
Licensee Event Report No. 95-011
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to 10 CFR 50.73(d), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving inoperable fire dampers in Units 2 and 3. Since this occurrence involves similar systems, cause, and corrective actions applicable to Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,



Enclosure: LER No. 95-011

cc: L. J. Callen, Regional Administrator, NRC Region IV
A. B. Beach, Director, Division of Reactor Projects, Region IV
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC
Region IV
J. Sloan (USNRC Senior Resident Inspector, Units 2 and 3)
M. B. Fields, NRC Project Manager, San Onofre Units 2 & 3
Institute of Nuclear Power Operations (INPO)

710000
9507110130 950705
PDR ADOCK 05000361
S PDR

FE22
11

LICENSEE EVENT REPORT (LER)

Facility Name (1) SAN ONOFRE NUCLEAR GENERATING STATION (SONGS), Unit 2	Docket Number (2) 0 5 0 0 0 3 6 1	Page (3) 1 of 0 1
--	--	------------------------

Inoperable Fire Dampers

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
Month	Day	Year	Year	/// Sequential Number	/// Revision Number	Month	Day	Year	Facility Names	Docket Number(s)
0 6	0 5	9 5	9 5	0 1 1	0 0	0 7	0 5	9 5	SONGS Unit 3	0 5 0 0 0 3 6 2

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)	
POWER LEVEL (10) 0 9 9	<input type="checkbox"/> 20.402(b) <input type="checkbox"/> 20.405(a)(1)(i) <input type="checkbox"/> 20.405(a)(1)(ii) <input type="checkbox"/> 20.405(a)(1)(iii) <input checked="" type="checkbox"/> X <input type="checkbox"/> 20.405(a)(1)(iv) <input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 20.405(c) <input type="checkbox"/> 50.36(c)(1) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.73(a)(2)(i) <input type="checkbox"/> 50.73(a)(2)(ii) <input type="checkbox"/> 50.73(a)(2)(iii)
	<input type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 73.71(b) <input type="checkbox"/> 73.71(c) <input type="checkbox"/> Other (Specify in Abstract below and in text)

LICENSEE CONTACT FOR THIS LER (12)

Name R. W. Krieger, Vice President, Nuclear Generation	TELEPHONE NUMBER AREA CODE 7 1 4 3 6 8 - 6 2 5 5
---	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS
X	V	-	D M P A 1 2 4	N					

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> Yes (if yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	Expected Submission Date (15) 1 0 0 5 9 5
---	-----------------------------	--

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During routine 18-month surveillance testing conducted from 5/9/95 through 6/15/95 with both Units in Mode 1 at about 99% power, Edison drop tested 44 fire dampers and 26 failed. On 6/5/95, Edison concluded, due to the number of failures observed at that time, it was likely the dampers had been inoperable for longer than the one hour Technical Specification out of service time limit without a compensatory fire watch. Edison is reporting this condition in accordance with 10CFR50.73(a)(2)(i).

Edison established a fire watch for the affected areas and initiated repair of the dampers. Edison is conducting a Root Cause Evaluation and will submit a supplemental report to discuss the cause, planned corrective actions, and safety significance of this occurrence.

The failed fire dampers are located in 2 and 3 hour rated fire barriers. Edison believes the damper failures did not significantly reduce the effectiveness of the fire protection program at SONGS.

Edison has submitted three LERs involving fire protection systems in the last three years: 2-94-002 and 2-94-003 for missed surveillances; 2-95-004 for an inoperable fire sprinkler system. These previous LERs did not involve fire dampers.