



Log # TXX-91463
File # 10110
903.8
Ref. # 10CFR50.55(e)

William J. Cahill, Jr.
Group Vice President

December 13, 1991

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

SUBJECT: MANCHE PEAK STEAM ELECTRIC STATION (CPSES) - UNIT 2
D. KET NO. 50-436
CORRODED HILTI BOLTS
SDAR CP-91-003 (INTERIM REPORT)


Gentlemen:

On June 11, 1991, TU Electric orally notified the NRC of a deficiency involving the corrosion of installed Hilti Kwik Bolts (HKB). This condition was identified when an HKB on a floor mounted pipe support broke during retorquing. Examination of the broken bolt identified a significant reduction in cross sectional area due to corrosion. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e). Our last interim report on this issue was logged TXX-91343 dated September 17, 1991.

We are continuing our evaluation of this issue in accordance with our Procedure 2IM-5.24 "Selection, Inspection and Evaluation of Hilti Anchors in Potentially Flooded Areas in Unit 2". The next report on this issue will be provided by January 30, 1992.

Sincerely,

William J. Cahill, Jr.

By: 
D. R. Woodlan
Docket Licensing Manager

CLW/grp

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (2)
Mr. M. B. Fields, NRR

9112190421 911213
PDR ADCX 03000446
S PDR