tebruary 5, 1982 Mr. Dennis Saunders P.O. Box 2101 midland, MI 48640 lear Mr. Saunders: Mr. Bert Danis, Deputy Regional administrator of the NRC Region II office stated that you were interested in any followup action that has transpired since our Notice of Violation. Attached is a copy of all the correspondence that is anailable relating to the Notice of Violation We hope we have resolved your concern. of we can be of any further assistance, I please let as theman. Mar Marin Littlaniz fon Chief, Materials & Process 8406050040 840517 PDR FOIA RICE84-96 PD THE AS PDR 1 - ----



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN. ILLINOIS 80137

OCT 2 8 1981

ipen

Docket No. 50-329 Docket No. 50-330

Consumers Power Company ATTN: Mr. James W. Cook Vice President Midland Project 1945 West Parnall Road Jackson, MI 49201

Gentlemen:


Thank you for your letter dated September 9, 1981, informing us of the steps you have taken to correct the item of noncompliance which we brought to your attention in Inspection Reports No. 50-329/81-14; 50-330/81-14 forwarded by our letter dated August 7, 1981.

We disagree with the statement in your letter that, "we believe that the item of noncompliance as stated does not exist". Our conclusion was based on the findings stated in Paragraphs 2.a., b., and c. of the above RIII

- From March 1979 to November 1980, there was no procedure for a., engineering review of redline drawings.
- At the time of inspection, the engineering procedures for the b. review of red line drawings were considered to be inadequate.
- At the time of inspection, the site design engineers were designing c.

hangers and restraints without confirmed preliminary design loads. Since our review of your response did not change our position that this is a Severity Level V violation, we do not consider your letter to be

fully responsive in that you failed to document (1) corrective action to be taken to avoid further noncompliance, and (2) the date when full com-



Consumers Power Company

We further disagree with your statement that, " - 2 we further disagree with your statement that, "... in-depth investiga-tions, both by Consumers Power Company and Bechtel, have shown no evidence of technical deficiencies relating to redlines" You reported seven of technical deficiencies as the result of your in-denth review of the of technical deficiencies relating to redlines". You reported seven significant deficiencies as the result of your in-depth review of the engineering Asguiricant dericiencies as the result of your in-depth review of design analysis and calculation packages, including the engineering reviews of redline drawings for small bore mining systems, since the design analysis and calculation packages, including the engineering reviews of redline drawings for small bore piping systems, since the issuance of our Immediate Action Letter dated May 22, 1981. Details of vour findings are documented in Paragraph 1. Item 6 of the RIII issuance of our immediate Action Letter dated hay 22, 1981. Detail of your findings are documented in Paragraph 1, Item 6 of the RIII inspection reports listed above inspection reports listed above. As discussed during the management meeting held at the site on July 24, 1981, please advise this office of the results of your investigation As discussed during the management meeting held at the site on July 1981, please advise this office of the results of your investigation efforts to identify whether or not there are similar problems existing Tyol, Please advise this office of the results of your investigation efforts to identify whether or not there are similar problems existing in other site activities in other site activities. We request that you provide written response within 25 days of the date of this letter to this office addressing the matters discussed above. we request that you provide written response within 25 days of the day of this letter to this office addressing the matters discussed above. Your cooperation with us is appreciated. Sincerely,

Original signed by A. Bert Davis

v/ltr dtd 8/7/81: Document Control Desk (RIDS) dent Inspector, RIII ld Callen, Michigan lic Service Commission rbara Stamiris

RIII RIII RIUD Danielson Williams Boyd offes 23-81 10/23/81 RIII 10/2/11 1926/2 RIII Morestas RILL 1 10/20/81 10/27 Keppler

C. E. Norelius, Director Division of Engineering and Technical Inspection



James W Cook Vice President - Projects, Engineering and Construction

1.2

General Offices: 1945 West Parnall Road, Jackson, MI 49201 + (517) 788-0453

September 9, 1981

Mr J G Keppler, Regional Director Office of Inspection & Enforcement US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND PROJECT -INSPECTION REPORT NO 50-329 AND 50-330/81-14 FILE: 0.4.2 SERIAL: 13664

Reference: J G Keppler letter to J W Cook. dated August 7, 1981

This letter, including all attachments, provides Consumers Power Company's response to the referenced letter which transmitted the subject Inspection Report and which requested our written statement regarding one item of noncompliance described in Appendix A of the reference.

Consumers Power Company

James W. Cook

S.orn and subscribed to before me this 9th day of September, 1931.

Beverly A. Avery

Notary Public, Jackson County, Michigan My commission expires January 16, 1985

WRB/1r

CC: RJCook, USNRC Resident Inspector Midland Nuclear Plant

8111020535

SEP 1 4 1981

CONSUMERS POWER COMPANY'S PESPONSE TO NOTICE VICLATION DESCRIBED IN NEC INSPECTION REPO DOCKET NO 50-329/81-14 AND 50-330/81-14 Attachment Seriel 13664 Appendix A (Item of Noncompliance 329/81-14 and 330/81-14) states in Part, "Contrary to the above, procedures used by your resident engineers to Fart, AFPendix A (Item of Noncompliance 329/81-14 and 330/81-14) states in Part, "Contrary to the above, procedures used by your resident engineers in Part, and approve field initiated redline drawings for small bore mining and Contrary to the above, procedures used by Your resident engineers to and approve field initiated redline drawings for small bore piping and and wish your riald Change Reduces to a and approve field initiated redline drawings for small bore piping piping supports were not in accordance with your Field Change Piping and procedures, and as a result, field initiated redline drawings deguest ware not piping supports were not in accordance with your Field Change Request procedures, and as a result, field initiated redline drawings were not receiving ission control reviews commanguments with those annial to the Frocedures, and as a result, field initiated redline drawings were not receiving issues commensurate with those applied to the Consumers Power Company's Response It is agreed that the procedures used by resident engineering for review and approval of redlines are not in agreement with the field change reque It is agreed that the procedures used by resident engineering for review and approval of redlines are not in agreement with the field change review are new are new and in accordance with the field change request and approval of redlines are not in agreement with the field change required in accordance with the applicable redline main and discussed in our July 24, 108; massing which are redline which are an additioned on the second sec procedure. They are reviewed in accordance with the applicable reduces as we discussed in our July 24, 1981, meeting. This procedure reduces by revising the original design documents of the original design documents. Procedure as we discussed in our July 24, 1981, meeting. This Procedure requires incorporation of redlines by revising the original design document All revisions to drawings require reviews commensurate with those applied. requires incorporation of redlines by revising the original design documents of the original design As noted in our response above, we believe that the item of noncompliance As noted in our response above, we believe that the item of noncompliance as stated does not exist. We therefore request that you reconsider the reconsider the as stated does not exist. We therefore request that classification of this as an item of noncompliance. Section II of the Inspection Report addresses the review conducted in resards of field change rediining procedures. The three observations described on Section II of the Inspection Report addresses the review conducted in refar to field change redlining procedures. The three observations described in refar age 7 are addressed as follows: Item 2a - Inspection Report Fage 7 states, "From March 1979, since the formation of the Site Small Pine group, to November 1080, these was no Item 2a - Inspection Report Fage 7 states, "From March 1979, since the stabilished procedure for handling the review and approval of FT redited approval of FT redited approval of FT redited approximation. formation of the Site Small Pipe Group, to November 1980, there was no established procedure for handling the review and approval of review and approval of review and approval of review and approval of review and review and approval of review and rev established procedure for handling the review and approval of FI red drawings that were issued per FIP 1.112 and FIP 1.110 requirements. Consumers Power Company's Response e agree with this statement; however, it should be noted that this deficiency is noted by Sechtel and corrective measures were taken to document the e agree with this statement; Lowever, it should be noted that this statement; Lowever, it should be noted that this definition of the sine in a format proceedure implemented on vovember the sine in a format proceedure implemented on vovember the side in the side of the actice at the time in a formal procedure implemented on November 7, 1980. actice at the time in a formal procedure implemented on Movember 7, 1960. Should further be noted that in-depth investigations, both by Consumers is a common of technical deficiencies. should further be noted that in-depth investigations, both by Consumers er Company and Bechtel, have shown no evidence of technical deficiencies ting to redlines. 2b - Inspection Report Page 7 states, "The present EDPI-4.46.9 used to review and approve redline drawings does not distinguish harvess D - inspection deport rafe / states, the present instances with to review and approve redline drawings does not distinguish between on minor design changes. To provide and changes and signisions. to review and approve redline drawings does not distinguish between or minor design changes. If FT requested changes are significant should not sign off the redline drawings for construction, but sho or minor design changes. If it requested changes are significant, should not sign off the redline drawings for construction, but should to the appropriate angingentine official as mentioned. should not sign our the redline drawings for construction, but should FCRs to be approved by the corporate engineering office, as required

Consumers Power Company's Response This procedural enhancement was agreed upon in our July 24, 1981 meeting and the procedure has been revised and submitted for your review. This This procedural enhancement was agreed upon in our July 24, 1981 meeting and the procedure has been revised and submitted for your review. 1981 meeting revision includes the oritaria to distinguish between major and minor This and the procedure has been revised and submitted for your review. The design changes and instructions on proper disposition of major and minor and revision includes the criteria to distinguish between major and minor design changes and instructions on proper disposition of major and minor design changes. In accordance with our past prectice, we agree that design changes and instructions on Proper disposition of major and minor significant changes initially identified on redline drawings will be processed in EDPI 4.46.9, which include Processed significant changes initially identified on redline drawings will be process in accordance with the options described in EDPI 4.46.9, which include Process. Item 2c - Inspection Report Page 7 states in part, "The Small Fipe Group REs did not recognize that some of the redline hanger drawings without C. Item 2c - Inspection Report Page 7 states in Part, "The Small Fipe Group of the redline hanger drawings without confirmed design loadings supported by the nipe system stress cphcs year REs did not recognize that some of the redline hanger drawings without confirmed design loadings supported by the pipe system stress without in violation of EDPI-4.46.0 Paragraph 2. "Definition." which states that. confirmed design loadings supported by the pipe system stress CPDCs vere in violation of EDPI-4.46.9 paragraph 2, "Definition," which states CPDCs vere "A redline is a field mark-up work print which is transmitted from broised in violation of EDPI-0.46.9 Paragraph 2, "Definition," which states that "A redline is a field mark-up work print which is transmitted from states that is transmitted from project engineering to request a change in project approved "A redline is a field mark-up work print which is transmitted from project engineering to request a change in Froject approved drawing, there should be documented CPDCs per Bechtel EDF-4.37, MED 4.37-0. engineering drawings." In order to issue a project-approved engineering drawing, there should be documented CPDCs per Bechtel EDF-4.37, MED 4.37-6 (See Region III Inspection Reports No 50-329/81-12; 50-330/8 drawing, there should be documented CPDCs per Bechtel EDF-4.37, MED 4.37-0, and MED 4.37-6 (See Region III Inspection Reports No 50-329/81-12; 50-330/81-12; The present practice of the RE reviewing hanger structural calculations and MED 4.37-6 (See Region III Inspection Reports No 50-329/81-12; 50-32 The present practice of the RE reviewing hanger structural calculations resulting from redline changes is questionable. For some of the hangers The Present Practice of the RE reviewing hanger structural calculations resulting from redline changes is questionable. For some of the hangers, the hangers, the resulting from redline changes is questionable. For some of the hangers, the structural assembly design." established prior to structural assembly design." Consumers Power Company's Response Puring the NRC inspection of the site small pipe design activities the week May 16, it was recognized that there was a lack of procedural controls. Juring the NRC inspection of the site small pipe design activities the vest immediate action letter was issued on May 22, 1961, and remedial controls. iertaken and the situation was subsequently corrected. We agreed that immediate action letter was issued on May 22, 1901, and remedial action was subsequently corrected. We assed action was subsequently corrected. We assed action the handers, the design loads were without documented hasis Some of the situation was subsequently corrected. We agreed that a some of the handers, the design loads were without documented that a system oppo had not been established prior to structural assembly assembly Some of the handers, the design loads were vithout documented basis ce a system CFDC had not been established prior to structural assembly in Pine support load sheets had been prepared for the banges design. ce a system CFDC had not been established prior to structural assembly inne stress analysts although a mining stress opport the hanger designs not have aviant iping support load sheets had been prepared for the hanger designs a piping stress analysts although a piping stress CFDC may not have designs to the loads were based either upon Specification 70000M at stated iping stress analysts although a piping stress CFDC may not have exist and anang. or were calculated but inadequately documented. rehensive and intensive program was established to provide CFDC's the piping isometrics. The details of this program and the the piping isometrics. The details of this program and the income sources of the details of this program and the income sources and the i LAS OF its completion has been july disclosed to the second state of the second state of the second state of the second states the seco ussion and formal correspondence. Mesident engineering recog-te implications of redlines during the early stages of the CFDC form is that time additional restrictions were blanded on the e implications of redlines during the early stages of the cruc fort. At that time, additional restrictions were placed on the engineering redline review process to ensure that the intent of fort. At that time, additional restrictions were placed on the diate action letter of May 22, 1961, was met. The policy of the subject van was discussed with the Region III Staff when the subject vas If reised, we believed that our interim practice and the Ly raised, we believed that our interim practice and the formation of that practice net with your satisfactice based on the analysis understanding of addition on ci that practice met with your satisfaction based on the ci meeting including the specific understandings of additional to the reduining procedures as incumented in our to be added to the redlining Frocedures as documented in our

The completion of the calculational reviews and the establishment of the CPDC's has provided evidence of the design adequacy of the small pipe supports. As the stress CPDC's were being completed, new support load pipe a hanger required due to the original designs. In no case was a physical change the this demonstrates the adequacy of controls and the viability of the set of the site design effort.

3

大田

JAN 26 191.

Docket No. 50-329 Docket No. 50-330

Consumers Power Company ATTN: Mr. James W. Cook Vice President Midland Project 1945 West Parnall Road Jackson, MI 49201

Gentlemen:

Thank you for your letter dated November 20, 1981, providing us additional details regarding the steps you have taken to correct the noncompliance which we brought to your attention in Inspection Reports No. 50-329/81-14; 50-330/81-14 forwarded by our letter dated August 7, 1981. We will examine these matters during a subsequent inspection. At that time we will thoroughly examine the contents of your indepth review of design and calculation packages and respond to the request in Paragraph 2 of your letter requesting us to reconsider our position on the technical deficiencies identified during your indepth review.

Your cooperation with us is appreciated.

Sincerely,

"Driginal Gigned by C.E. Horetime .

C. E. Norelius, Director Division of Engineering and Technical Inspection

cc w/ltr dtd 11/20/81: DMB/Document Control Desk (RIDS) Resident Inspector, RIII Ronald Callen, Michigan Public Service Commission Myron M. Cherry Barbara Stamiris Mary Sinclair Wendell Marshall

8202010318

RIII + Yin/so 12/1/81	RIII Jones 1-25 82	Boyd I-15-12	RIII L7#4 Danielson 1/23/41	RIJI Williams	RIII Norelius 1/2 5/8L	
				127102		



James W Cook Vice President - Projects, Engineering and Construction

500

General Offices: 1945 West Parnall Road, Jackson, MI 49201 + (517) 788-0453

November 20, 1981

(cet

Mr J G Keppler, Regional Director Office of Inspection & Enforcement US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND PROJECT -INSPECTION REPORT NO 50-329/81-14 AND 50-330/81-14 FILE: 0.4.2 SERIAL: 14618

References: 1. NRC letter, C E Norelius to J W Cook, dated October 28, 1981

- 2. Consumers Power letter Seriall 13664, J W Cook to J G Keppler, dated September 9, 1981
- 3. NRC letter, J G Keppler to J W Cook, dated August 7, 1981

This letter, including all attachments, provides Consumers Fower Company's response to Reference 1, which rejected portions of our response (Reference 2) to one item of noncompliance described in Appendix A of Reference 3.

Consumers Power Company

James W: Croh

Sworn and subscribed to before me on this 20th day of November, 1981.

Burly a. avery Edicity A. Avery Notary Public, Jackson County, Michigan My commission expires Jan 16, 1985

WRB/1r

CC: RJCook, USNRC Resident Inspector Midland Nuclear Plant (1)

NUN 2 3 1951

8262010325

CONSUMERS POWER COMPANY'S RESPONSE TO US NUCLEAR REGULATORY COMMISSION, REGION III LETTER DATED OCTOBER 28, 1981 DOCKET NUMBERS 50-329 AND 50-330

1. The second paragraph of the Region III letter of October 28, 1981, - states:

"We disagree with the statement in your letter that, 'we believe that the item of noncompliance as stated does not exist.' Our conclusion was based on the findings stated in Paragraphs 2a, 2b and 2c of the above RIII inspection reports as paraphrased below:

- a. From March 1979 to November 1980, there was no procedure for engineering review of redline drawings.
- b. At the time of inspection, the engineering procedures for the review of redline drawings were considered to be inadequate.
- c. At the time of inspection, the site design engineers were designing hangers and restraints without confirmed preliminary design loads.

Since our review of your response did not change our position that this is a Severity Level V violation, we do not consider your letter to be fully responsive in that you failed to document: 1) corrective action to be taken to avoid further noncompliance, and 2) the date when full compliance was or will be achieved."

CONSUMERS POWER COMPANY'S RESPONSE

Upon further review and consideration of the detailed findings set forth in Paragraphs 2a, 2b and 2c of Inspection Reports 50-329/81-14 and 50-330/81-14, it is acknowledged that the described conditions do constitute an item of noncompliance as stated in these Inspection Reports. Accordingly, as requested, the following information concerning the actions taken to correct those described conditions and the item of noncompliance is provided:

A. Item 2a, page 7 of Inspection Report 50-329/81-14 and 50-330/ 81-14 states:

"From March 1979, since the formation of the Site Small Pipe group, to November 1980, there was no established procedure for handling the review and approval of FE redline drawings that were issued per FIP 1.112 and FIP 1.110 requirements."

Corrective Action Taken

Bechtel Management audit AAMA-2, conducted in August of 1980, initially identified this deficiency. As a result of that audit, EDPI 4.46.9 was initiated to document the redline practices in effect at the time. This deficiency was corrected with the issue and implementation of Revision 0 of EDPI 4.46.9 on November 7, 1980. B. Item 2b, page 7 of Inspection Report 50-325/81-14 and 50-330/81-14 states:

"The present EDPI-4.46.9 used by RE to review and approve redline drawings does not distinguish between major or minor design changes. If FE requested changes are significant, the RE should not sign off the redline drawings for construction but should request FCRs to be approved by the corporate engineering office, as required by EDPI-2.14.1."

Corrective Action Taken

As was agreed in our July 24, 1981, meeting, EDPI 4.46.9 has been revised to include definitive criteria for distinguishing between major and minor design changes and to provide instructions to Resident Engineering for dispositioning each such category of change. These instructions do not permit Resident Engineering Small Pipe and Hanger Group approval of proposed redline changes which are categorized as major; rather, three alternate methods of proceeding, including the processing of an FCR, are provided. Revision 2 of EDPI 4.46.9, incorporating the above described changes, was issued and implemented on August 24, 1981.

C. Item 2c, page 7 of Inspection Report 50-329/81-14 and 50-330/81-14 states:

"The Small Pipe Group did not recognize that some of the redline hanger drawings without confirmed design loadings supported by the pipe system stress CPDCs were in violation of EDPI-4.46.9, Paragraph 2, 'Definition,' which states that:

'A redline is a field mark-up work print which is transmitted from project construction to project engineering to request a change in project-approved engineering drawings.'

In order to issue a project-approved engineering drawing, there should be documented CPDCs per Bechtel EDP-4.37, MED 4.37-0, and MED 4.37-6 (see Region III Inspection Reports No 50-329/ 81-12; 50-330/81-12). The present practice of the RE reviewing hanger structural calculations resulting from redline changes is questionable. For some of the hangers, the design loads were without documented basis since a system CPDC had not been established prior to structural assembly design."

Corrective Action Taken

We understand the basis of the above described concern with redline drawings to be the fact that several of the small bore pipe and piping suspension system designs performed at the site had not been prepared, reviewed and approved in accordance with established design control procedures. Specifically, it was found that some drawings had been issued for construction without the required Committed Preliminary Design Calculations (CPDCs). This procedural violation was identified during the NRC inspection of May 18-22, 1981, and was the subject of the NRC Immediate Action Letter dated May 22, 1981.

Based on the Immediate Action Letter of May 22, 1981, remedial action was undertaken. A comprehensive and intensive program was established to provide CPDCs for all the piping isometrics. The details of this program and the scheduling of its completion has been fully disclosed to the NRC, both by discussion and formal correspondence. Resident Engineering recognized the implications of redlines during the early stages of the CPDC review effort . At that time, additional restrictions were placed on the resident engineering redline review process to ensure that the intent of your Immediate Action Letter of May 22, 1981, was met. In addition, on July 27, 1981, a hold was placed on installation of small bore piping whose isometric drawing was not supported by a CPDC. The policy of redlining was discussed with the Region III staff when the subject was subsequently raised. We believed that our interim practice and the documentation of that practice met with your satisfaction based on the July 24, 1981, meeting, including the specific understandings of additional specificity to be added to the redlining procedures as documented in our letter to you dated July 27, 1981.

The remedial program of calculational reviews and the establishment of CPDCs for all piping isometrics was completed on August 5, 1981. Consequently, the review of hanger structural calculations resulting from redline changes are based on design loads documented by the system CPDC in all cases.

Based on the actions taken in 1A, B and C on the previous pages, we consider the plant has been in compliance on this matter since August 24, 1981.

 The second paragraph of the Region III letter of October 28, 1981, states:

"We further disagree with your statement that: "...indepth investigation, both by Consumers Power Company and Bechtel, have shown no evidence of technical deficiencies as the result of your indepth review of the design analysis and calculation packages, including the engineering reviews of redline drawings for small bore piping systems, since the issuance of our Immediate Action Letter dated May 22, 1981. Details of your findings are documented in Paragraph 1, Item 6 of the Region III inspection reports listed above."

CONSUMERS POWER COMPANY'S RESPONSE

We believe there may be a minor misunderstanding on this matter. As indicated, seven significant discrepancies were identified as the

result of our indepth review of the design analysis and calculation packages and were reported to you in accordance with the Immediate Action Letter dated May 22, 1981. However, it is important to note that none of these discrepancies were related to the redlining of drawings; all were related to other issues. This fact was brought to your attention during our July 24, 1981, meeting. Accordinglys we consider our statement to be a true and accurate representation of the situation and request you to reconsider your position on this matter.

 The fourth paragraph of the Region III letter of October 28, 1981, states:

"As discussed during the management meeting held at the site on July 24, 1981, please advise this office of the results of your investigation efforts to identify whether or not there are similar problems existing in other site activities."

CONSUMERS POWER COMPANY'S RESPONSE

Three audits were conducted at the site between June and November 1981 of all Site design activities. Two other areas on site were identified as having similar problems. The first was the Instrument Tubing Support Group, which was identified by Consumers Power as not having adequate procedures to govern the Field Engineering preparation and Resident Engineering's review of calculations and drawings. Work was stopped in this area until approved procedures to prepare and review calculations and drawings for instrument tubing and supports were generated. It should be noted that the audit was timed to review these activities just as they were being initiated. The second area was the site Resident Engineering Civil Group. It was identified by Bechtel Quality Engineering that calculations had been performed as back-up informat.on, but they had not been formally approved All of the calculations involved were subsequently reviewed and necessary approvals were given. It should be noted that no procedural changes were initiated as a result of this deficiency since the audit finding was for a procedural violation. Our investigation revealed no other similar problems.

Design activities being conducted in the other Resident Engineering groups were found to be done in accordance with the EDPs, and the procedures were also found to be adequate.