Georgia Power Company Post Office Box 439 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444



Edwin I. Hatch Nuclear Plant

June 1, 1984 GM-84-470

PLANT E. I. HATCH Special Report Docket No. 50-321

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II Suite 3100 101 Marietta Street Atlanta, Georgia 30303

ATTENTION: Mr. Sames P. O'Reilly

Attached is Special Report No. 50-321/1984-006. This report is required by Hatch Unit 1 Technical Specifications Section 3.13.2, ACTION b.1 and Hatch Unit 2 Technical Specifications Section 3.7.6.1, ACTION b.2.c.

H. C. Nix General Manager

HCN/SBT/djs

xc: R. J. Kelly

G. F. Head

J. T. Beckham, Jr.

P. D. Rice

K. M. Gillespie

S. B. Tipps

R. D. Baker

Control Room

Document Control

IE22

Special Report 50-321/1984-006

LICENSEE : GEORGIA POWER COMPANY

FACILITY NAME : EDWIN I. HATCH

DOCKET NUMBER : 50-321

On May 21, 1984, at approximately 0945 CDT, with Unit 1 in steady-state operation at 2434 MWT (approximately 100% power) and Unit 2 in a recirculation pipe replacement outage, the level in both fire water storage tanks dropped to approximately 265,000 gallons each.

While personnel were performing maintenance on a deluge valve just outside of the valve house on the north end of "B" Cooling Tower on Unit 1, they accidently activated a deluge valve which started spraying down the cooling tower. This pressure drop on fire water system automatically started the electric fire pump and one diesel fire pump which maintained fire water pressure at approximately 100 PSIG. After personnel reset the activated deluge valve, they reported that fire water tank level had dropped to approximately 265,000 gallons in each tank. Thus, the 270,000 gallons requirement of Unit 1 Tech. Specs. section 3.13.2.b and Unit 2 Tech. Specs. section 3.7.6.1.b was exceeded before the deluge valve could be reset.

The cause of this event was personnel accidently activating a deluge valve. Personnel investigating this event found the deluge valve which was activated, reset it, and restored fire water storage tank levels to within Tech. Specs. limits in approximately 10 minutes.