

DOCKETED  
USHRC

'95 JUL 27 A9:56

OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

Need to push to find FW ISOLATION resolved  
so lighting can make couplings and stroke MFIV's

check valves 032, 036 why do we not want to  
weld these valves. They checked OK so far as finish.  
Bet you the marriage they leak.

0700

MBK asked if transfer tube flanges were on  
and if sum, flanges are removed. Need to  
be on.

730 AM  
Tension start

Mode 3 circuit

Set with WH &amp; 5th wind blind

Cir Diesel Turb

copy everything from Plant Room (projector close at 8:45 Hatch Thursday,  
continue welding activities

continue, large activities

Blinds on SHPC, restrictions

\* Unit 2 Re Trip at 9:22 AM. <sup>EST</sup> Dumb Truck Driver blocks  
into my yard in Encampment - DONNIE WILLWHITE

\* Head tensioning on Re Vessel was stopped at 9:15 AM by Ops. A question  
as to the operability of A Diesel came up. Ops looking into this

\* Site Area Alert DECLARED AT  $\approx$  9:50 AM <sup>EST</sup> "A" DIG Failed to run on  
DE-Graded to ALERT at  $\approx$  10:30 <sup>EST</sup> Unit 1 WAS MANUALLY  
STARTED AFTER 15 MINUTE

\* Unit 2 'B' DIG started up and ran as designed.

\* As of 3:30pm, CL. Coursey was relieved as dayshift outage  
superintendent. MR. HARVEY Handfinger assumed his duties.  
MR. Coursey is assigned to the ~~\*@@\*~~ critique committee.

\* When Site Area Alert was declared, immediate action was taken on the following  
items:

- 1) ALL CONTRACT / NON ESSENTIAL PERSONNEL WERE EVACUATED FROM PESB.
- 2) 1-HV8888D - Valve was ~~tight~~ already re-assembled, but not torqued. Went  
down and tightened bonnet bolts.

NUCLEAR REGULATORY COMMISSION	
Docket No. 50-424/425-OLA-3 EXHIBIT NO. I-123	
In the matter of Georgia Power Co. et al., Vogtle Units 1 & 2	
<input type="checkbox"/> Staff	<input type="checkbox"/> Applicant
<input checked="" type="checkbox"/> Identified	<input type="checkbox"/> Received
<input type="checkbox"/> Rejected	<input type="checkbox"/> Other
Reporter	CR
Date 07-17-95	Witness S. Strickland

- 4  
• 1 holds →  
(1) why did the relay try  
(2) evaluate "B" RAT  
(3) short-dash test on "C",  
(4) noise in thrust bag

- Chemistry is a problem to extract  
• Need to see how long turb needs +  
off lube oil and pulling?  
• Uncouple "B" Ccc w/o pump, check left, then run motor & check vibration

3/20/80  
7:30 PM

Unit 1

- why alignment of "A" bus before open up equipment hatch or 035 ch valve
- Don't do any troubleshooting on "A" D/G until get "B" operable
- Run "B" tonight (8 hr run)

need following chs released to do special test on "B" (and D/G)  
Ch 15021 "CS B"  
Ch 15496 "ESF Chiller B"  
Ch 1585 "SI B"

- Will need to run "A" D/G to reconfigure "A" bus to "A" RAT
- Sequence locking & socket w/o gear needs to be worked before opening equip hatch and returning midloop work
- Want as operable D/G and "A" & "B" RAT's back before returning midloop work
- Need 1 D/G operable to enter Mode 5 (tension load)  
down to hot pass on tensioning head
- Try to contact sequence vendor tonight, also try to get Steve Stewart tonight (HMI/MSL)
- Focus on "A" D/G socket w/o problem

- Ran "A" D/G for long period of time (over 30 minutes). Everything tested good. Ran it 3 times, no indication of a problem either time

- Got "A" RAT lined back up to "A" bus and "B" RAT is lined up to "B" bus (12:30 pm). Relaxed to go back to work on midloop. Ops says sample problem. Said Ch 15496 aligned (HIV-B008D) and Ch 15021 hung (1-1204-24-104). Notified supervisor to tension "2 + 3" pulleys and remove "2 cold by". Explained socket and tension. Told them to have Ops make sure there is no w/o on the channel head before removing necessary

168 Tuesday night  
3/20/80

• We're having a real good time tonight trying to get anything out of Ops. We've had to lead them by the hand and encourage them work for them.

• Ben trying to get Ops to line up NSCA so we can run "B" site for at least an hour now

• Notified control room @ 3:30 am that the last 2 truck cards go back on turning gear. Was soon the switched.

• Shaded the PCT's that were down on plant 2 at approx 3:00 am

• Gave Ops 106A bat @ midnight tonight (reduced site) however CPC elect still working on 8807-82 (feeder site)

• Everything that can be done on DCP 115 is complete until we get the disconnect here

• Augusta Inv 1 Fast Pack so pissed about being jacked around that they are going to try the double bat tonight if we can get everything ready. Authorized our in to do bat 4:15 am

• AMR talked to Cle 1 Tagging @ 4:00 am. They had 15478 in pull but it is still a ways from being reduced. They are trying for end of night shift and let dayshift hang 15019 (which is a large site). Will be lucky if they are ready for us to work 1-1204-04-144 check where when we return tonight

• Talked to MHS about game plan on MHS's. PCT worked HV-2628A & HV-2628B tonight. Will be ready for him to work HV-2628A and HV-2628B on dayshift. Then we will come in tonight and work HV-8808D. The MOVAT on 8808D is not tied to holding. We just have to make sure we get the MOVAT done before they fall accumulators.  
#4

Day 5  
Wed, 3/26/80

- \* Encountered problems trying to weld 007 valve. Need to clean valve seat weld area before weld can be made. Revising pkg. to back out on thread engagement.
- \* Started Ccc winter - Removing piping to re-check pump lift. Pump checks out O.K. NEED TO SET LIFT AND COUPLE.
- \* Rec'd. Sisu on IFC batteries at 1:15pm. This will be critical path for going to MODE 5. Working in parallel. - Doing early. At 4:00pm. complete at 4:30pm.
- \* UIC 'B' will be run with an abbreviated EDFAS type operability test. CR. will remain on #2 RCP Pmp. NEED TO COUP. D.SCH. Valve work & mount.
- \* #3 RCP slv. null alignment check was good. Notified IFC to install dev. probes. Working alignment check on #2.
- \* CPS filling & cooling RCS systems. Requested we work Muc's 1890.024 & 25. with, on IFC support, notified M. Leckey.
- \* Design for restraints on RHR 'B' Pmp are due in tomorrow morning. Mike Chance says parts on site
- \* NEED TO Implement MWD 1900706 - TEMP MOD on containment lighting so INBR can come down for torquing. INBR scheduled to come down at  $\approx$  9:00 pm.
- \* Containment Purge - Mount's complete on 1HV2626A & 2629A.
- \* DCP 89-036 - MWD 19000159 - Thad Harkins informed me today that there was mech. work involved to install a roller on WEST WALL OF CONTAINMENT. THIS work will require A. scaffold.
- \* MWD 1900640 - DCP 101 - Returned to WPG. WING, ENG, to Supply FER to close pkg.
- \* WAR Room says we can start on Head Tensioning at 6:00pm. WING, OPS to clean up paperwork.
- \* MWD 18900429 - 1120144007 - Tried to TEG web & STEEL WELD. Unsuccessful. Review skin to disassemble valve.

Led night  
3/21/90 173

NOTE 6 ENTRY #63 covering

Ran 1B Diesel

111.8 loop test

WHT

VAT's Tested good / return in progress

Relay replacement on Diesel - urgent now

ACTIONS TONIGHT

- (1) Get Unit 2 on Line
- (2) whatever critique committee needs
- (3) outage

? NRC people here tonight, 7 more tomorrow

• Restoring shutdown, Unit 2 critical, vacuum pulled

Chart 1

- Need to be reconnected so can restore left pump on RCP's
- PR-4SSC boundary when going into seat, probably because system a dry
- When I&C completes screw range cable, will start start taxonomy hand
- 036  $\Rightarrow$  continental feeds to take out on format, then start assessment
- 007  $\Rightarrow$  disassemble, clean, assemble
- 144  $\Rightarrow$  why system to drain

• Taking NRU down @ 9:45 pm to begin bus. This was closest prior to the outage

• Has everybody lined up to run "P" DTC, now asas has duty eng  
set up cleaning equipment for changing seats on Unit 2. Saying  
will be at least 10:00 pm before he is free. Hh!

Takes on us. When we got the duty eng, he gave procedure  
to PRH and said go ahead. Got into the test, then after  
we went to wait the over-speed test, it would do it thing.  
Called and called States to no avail, beeper and no response  
Called Paul Kochay, he said he had some prints in his office,  
he was too tired to come out, he would see us in the am.  
Duty Eng was no help - he was the one that gave procedure

Wed Night  
3/21/90

to PRH to do. PRH and ITC went back to DCP 115 and kept looking. Finally found a breaker that was open that should have been closed. Ready to run but will wait till 6:00 when next INR Delaval cow comes in. Night shift crew was sent home when we ran into trouble and could not get in touch with Stokes.

• Start 2  $\Rightarrow$  went into Mode 1 @ approx 3:40 am

• Was ready to run Start 2 Cess w/o pump "B" at approx 2:30 am. Still waiting for Ops to run at 4:30 am. Cle for been released (except for a handswitch)

• Manning transducers set up on pipe

• Need DC to go look at equipment tank o-ring was

• "A" Condenser <sup>Hobwell</sup> <sup>& Clear</sup> ~~approx~~ complete, need o-rings to blow air over close it up

• "B" Condenser Hobwell ~~approx~~ continues today, should complete today

• Cut paperholes to well containment line in flow elements in north valve room

• Laying off 3 balances (core) on night shift this morning - 5 remain

• Have 9 balances still on dayshift - need a layoff Friday

• Go to 4 Ironworkers max on each shift after Friday (3/23)

• DCP 115 has wrong kind of filter installed in containment. But has got with engineering and got resolution

• INR should complete by end of night shift

7:30 AM MEETING

- Unit 2 in Mode 1, 25% power
- Core water pump in service
- watch Chemistry on Unit 2 today - demins

Unit 1

- 4 hrs behind schedule
- Expected Mode 5 @ 0403 EST
- Would like to close "A" condenser today
- Close "B" & "C" Condenser & Natural Draft or Set
- 166.9 mwh/Sec
- Mainloop Work
  - 036 valve  $\Rightarrow$  final torque complete, QC wanted area where cap was welded cleaned up for PT. Apparently the weld that was grinding it, ground in the body of the valve. Plant Engg noticed - NEED TO PUSH RESOLUTION!
  - 007 valve  $\Rightarrow$  total cluster, new plan is to clean the threads of the area that is presently exposed (bonnet =  $\frac{1}{4}$  way up), reassemble bonnet and attempt another seal with
  - 144 valve  $\Rightarrow$  still draining water across across seat. Asked GHT to go look at putting an expandable plug in the line to stop water so can try seat
- All MOVATS on containment page complete - closing page ITC close to do LLRT's
- Make sure MOVAT on 8808D gets done today
- Push Lacy/Bailey for 8809A MOVAT for night shift tonight update - no go! - Waiting full review of RCS.

- 11:00 NRC ENTRANCE for Augmented Inspection Team today
- All members of critique team needs to attend, ~~so does the~~ Dept heads also need to attend



→ HATCH CLOSES FOR LAST TIME FRIDAY

- Plan to support a test on the "M" D/S and sequence. Set to try to recreate the event Tuesday

- LLRT on personnel see back Thursday night @ 9:30 pm

177  
Thursday Day flight  
3/22/90

- ~~CX~~ X73 jury rig off 200 ft apart & 3 separate to handle.
- Forklift always needed, make a large freshwater tank on container ship. - 10000 liters. Ed Barron people need to stay until done.
- Take oil switch + small T-type D. Street. Switch position not important.

### 144 Purple

Priorities for tonite

- ① Fill & Vent RCS
- ② A Diesel
- ③ B Diesel

DO NOT TO proceed on personnel hatch

Engineering wanting to roll over and play dead on seal well.

Tag all your tools etc. in containment or they will get jettisoned out

Darley crying for help on CCRG

Decision made on CO<sub>2</sub> valve  $\Rightarrow$  plan to cut valve out and weld in pipe in its place (socket weld). Have located 2" schedule 40 pipe, couplings and 90's if needed.

Rowing phy 14000429 to cut CO<sub>2</sub> valve out. Checked with Ong in the room and laid out the plan. Had conference call with Ong at 2:00 am to make sure they were putting the DSS together in such a manner as to support our plan.

Received phy @ 2:30 am to cut valve out. Sent man to ALKA barge at 3:00 am to cut valve out.

drugs for opium users held  
by the "Red Guard" for sale.

out Sunday in out shift  
working full shift of manufacture and distribution. It's only the 7

in safe sets  
to the limit. Doubtless should tell him from 3 days to the  
TH estimate will take 2 days which is same if we pull thru  
as can out the following note  
of the "Planning to do the 1st 1000 boxes as  
not hard task from me. He is also returning to us  
as will start manufacture early next day at 11:00 am down  
Mile road to Chia Ho to see if they really believe with  
it possible to do this in four days of continuous  
effort a series of cars down 5th N. W. K. Road between  
in one day to cover all the "Red Guard" members  
and estimate 3 days with 15 times difference

18906455

night shift Tuesday before we leave. Also need to work  
tomorrow, suitable pre manning and clean hotel by end of  
week shift after today. Need to pack up car & continue  
. Notified Mr. Li that we want to cut distribution to 0 in

order

each shift after today (Friday). Will send no communiques for  
. Notified Mr. Li that we want to cut distribution to 0 in

depth: Sheld. M. @ 4:00 am

tell the operator rate of M. and sum of (864 m)  
summarize to now M. @ 3:00 m to check for total, then  
MSIV, summarizing M. @ 2:00 am the 16 2K. also  
As of 3:30 m, tell how to do support for sheld.

1890646 = 031 chkd well, or longer off. No rework

3/28/80  
FBI - NY

Thursday Night 179  
3/22/80

- Told Mike Dye to layoff all barometers on day shift except 4. Work all 4 of them Sat, zero on Sunday. Keeping these 4 to do the Eagle story over the hatch.
- 19001493 ⇒ now for DCP 90-132 for OOT value in field for pre-fab at 6:00 AM. Value is cut out. Will start <sup>our</sup> dayshift now on pre-fab, another cover will be sent to ALARA briefing for field values.
- Temp Prod is in place for "B" train outage (19000378)
- DCP 115 ⇒ fix, closing gap.
- Starting "B" D/L (at 6:07 AM)
- Found 2 10 minute looks on "A", IFC requiring
- All 4 RCP Lift Pumps back on permanent gear. Scaffold needs to come down on RCP's 1, 3, 4. Still need to kill RCP's when seal injection is ~~over~~.
- Need cles on mon's baulk ⇒ need 15522, 15523, 15479, 15478
- Layoff running field at end of shift today  
Layoff Steve Young at end of day shift today  
Layoff Mike Dye at end of night shift tonight } NOTIFY PERSONNEL THIS AM!!
- Need to bring in 4 barometers / 4 thermometers on dayshift to clean hatch.

7:30 AM MEETING

- Out processing available 5:00 AM - 10:00 PM 7 days/week
- \* • ILRT meeting in other Rm (at 10:00 AM - ALL DEPTS TO ATTEND)
- DCP 90-132 due in by 8:00 AM
- DCP 90-130 EHR Starts
- NOTICE • Does not look like we will get "B" switchgear until Sat night. WORK NORMAL SHIFT SAT -  $\frac{1}{2}$  PERSONNEL ROD
- Need to suggest start 2 problems with the drain pumps

PRIORITIES

- (1) OOT James Bond episode
- (2) Fill & vent
- (3) has "A" OK
- (4) ILRT support

Thursday Night  
3/22/90

- GPC Panel or Contact for NRC Review
- Tom D'Amico
- Ken Holmes
- George Frederick
- Tim Roberts
- Robert Maye
- Paul Kochary
- Tim Szwedzinski

If you get contacted by the NRC, be sure you notify the appropriate GPC people of your conversation with the NRC

- Should have DCP 90-152 ready for PRB by 10:00 am. Need to get Billy Baker to ensure the met'l is suitable for this DCP before it is installed
- Unit 1 "A" D/G
  - explored all 3 tube at press ends last night
  - found approx 10 very narrow cracks
  -
- NEED Randy Black to sign off CIR. 190-15198 Rel. MWD 18906604. 50 CIRC. WATER PUMP CAN RUN. (full system).
- NEXT TIME 'A' D/G (unit 1) RUNS, NOTIFY CLC PRIOR. Critique ~~committee~~ is to be present.
- Released to install ~~the~~ PRESSURIZER MANWAY AT 12:00 noon.
- MWD 18906359 - Access to NSCW Doghouse - IEC would like to work <sup>Sunday</sup> ~~Monday~~ - We NEED to grind welds on BARRIER early in morning I have Security Comp. Post established.
- Per Burnister, 1BA03 will come down tomorrow. Hinges on completion of A & B D/G TEST. PLAN TO BRING Elects. in on Sun. 13 hrs.
- NSCW 'B' TRN. - IEC and Security ARE lined up for work Sun. morning. (MWD 18900452) will require GPC mech. support to remove BARRIER. NO I/W's will be here.

Friday Day  
3/23/90

181

- DCP for CCN valve deletion not received until 2:35PM.  
MWD in Revision 1 piping. Found indication on pipe (far fab). Checking to see if cracked. Pipe was cracked. Getting new pipe & couplings.
- Plan to determine Cont. Equip. Hatch Hoist last item before closing Hatch.  
NEED to get B/m's to drop Hoist and removed from containment.  
NOTE: ELECT TO DETERM MOTORS PRIOR TO REMOVING.
- ~~WORK~~  
~~Need to VTECI. CREW THAT HAS BEEN WORKING SIGMA CONSOLE~~  
~~DEP. (W) vendor rep is working Amputator~~
- Mark Seymour is working on ILRT pre req's.
- IPV300 - NEED to weld repair press. SCIL AREA & RE-MACHINE.  
MNG getting letter from vendor for concurrence. NEED TO HAVE ~~MACHINERIE~~  
~~Welding~~ welding completed this weekend so Cont. Field can machine this coming MONDAY.
- NEED OPS to release Back Feed clearance & restore to normal configuration.
- Seal Inj. on RCP's should happen sometime tonight. NEED TO Roll Paps. to flush seals.
- NEED OPERATOR FOR MSIU STROKING.

7:30 p.m. MTG.

Unit 1 will not go critical until Regional NRC gives go ahead.  
I-ESP testing will not be conducted until NRC is notified  
and consens. Since Av logic Board testing, Sequencer testing,  
Input interviews and Re-interviews of plant staff associated  
with event.

Identify OSOS prior to starting weld on 207

Fall / Start

Directs

ILRT / ILRT  
111511

Meeting 10:00A / 1000p LRT/LRT  
Ref from E&I Dept

92 PROJECT  
030478

- Passenger manway is open & transposed, insulation going in
- Did hot torque on "IB" D/G. Had one air start valve bolt to move. Plan to start D/G back up at 2:00 am and shutdown at 6:00 am. Day shift IMO will be standing with torque wrench in hand at 6:00 am
- Started "IB" again 2:00 am. Got "Hi Tach w/o Temp" alarm in. Went over breaker to jacket w/o heat each temp's, inlet and outlet was both well within spec. Checked engine cel panel and found IB <sup>standard</sup> varying. When IB <sup>standard</sup> starts, engine should start trip. When ~~99 cents~~ IT DIDN'T TRIP. MH had control room shut engine down. Now we've really got a mess. Both D/G's are questionable!
- DCP 90-130 on "B" RHR motor sitting in water collecting dust. MAKO in with DCP, but nobody up there knew anything about it and was not pressuring it. Must not be important any more!
- Started a third HSV. This one was one that we didn't bring to the shop during 1A2. It has the same thing. Reverts the pump side from the cel in and the non-pump side activates in the field and vice-versa
- Will not be ready to leave earliest from agency hotel at 5:30 am. Still have several things need to get out of confinement they hold the ironworkers over till 2:00 am. If not early by then, will let CR machine pull the earliest out, and day shift bathhouse close hotel
- Having a hard time getting HV-~~37901~~ (Eric Mottram valve) to pass LLRT. Has failed twice. IFC trying to shoot static value and see if it will pass. 3<sup>rd</sup> CLAT I/P - It FAILED! HV-10950 (Valve value) failing LLRT unbalance bad. must be fixed. Doing LLRT from back side to see of pass. If it does, it is a good indication the valve is seated in the line backwards, which is ~~a big difference~~
- Spring coil on RHR B pump installed, set and brought off by SC @ 4:00 am

Friday Night  
3/23/90

185

- Need to get rid of the 3 guards on the fire deck. Everything is buttoned up. Don't need controlled access any more

Don't want any paperless on night shift no more, GE was told to lay them off tonight but they didn't. I'm having Security pull these badges. GE has been told to bring them back in Monday morning and lay off

Also, DEC is telling GE to terminate on ADA night shift at end of shift Sunday night. Remaining work can be done on days

Op needs to start filling tube oil reserve Sunday morning

• On the D/K problems, RCH, PRH, James Simpson and myself suggest you get Sheldon Ongoyang back in there. He had already been released and is in Calif. Lance Black trying to locate him this morning. Lance wants us to use word Bob Johnson and call Sheldon for advice as needed. We all recommend Sheldon. I believe Engg should issue a change order to one PO to get Sheldon to help them. They need him whether they admit it or not

• Control fm called - having problems with LDR 1N908-05. Found broken secondary disconnect  $\Rightarrow$  rolling to days

• Back feed complete, need to reinstall ground

• Please put's on N<sub>2</sub> are used backwash. ART has now going them. Should be ready for crew Sunday night

7:30 AM MEETING

- 12 hrs behind sched, last 16 hrs in last 24 hrs
- Need to hand roll RCP's today
- Fill & vent in progress, sched to last 24 hrs
- Expect to close aqmp hatch this morning
- ILRT meeting @ 10:00 AM
- Look at the long pr boards still in containment, need to come out aqmp hatch before it closes

186 Sat Day Shift  
3/24/90

breakouts

- Bandit may state, Bandit now uses Cont 5 (one closest to Simulite). No one else should use Cont 5 until further notice.
- Security D/S → CB wants greater base run to it so if need to start, can fill it with water.

Mount

- "B" Logue banded - get Shadron & Morris Lowrey on site
- Cobb jacket w/o temp probes - in shop IHO now
- Test "B" sequences with vendor, notify NCC fast, don't work till after fill & vent.

NOTICE →

- Then LOSP on "B" D/S
- Start working favorably on "B" A/H struts
- DCP coming that will make LOSP signal to D/S the same as SI signal

- We have a lot of equipment that come out of the car and is in incubate outside the hotel. This needs to be moved around to the east end bay before it starts raining. Forecast is for rain the weekend (so I've been told).

- The 3 MWs which core filters had were issued to ~~EE~~ NNI. Only 3 NNI TECHS here today, Rowell said if day shift couldn't work them, his people would.

- MWI 18905032 - received Pk's. for 11610 & 11625 about eleven o'clock.

- MWI 18906163 - Ops using hose for venting, would not allow us to remove at this time.

- Contacted AAJ and got permission to release sls's 15000, 01, & 03 on RCP's for hand roll / flush and prep. for runs.

Dusty,

Please ask Monty to write a brief letter to plant personnel explaining the events (as they are known) that took place Tuesday, the events since that time, the NRC inspection team, etc. People in the shop are very curious and have little info. They are being asked a lot of questions by their neighbors and friends and they feel embarrassed because they can't answer any answers. I think this is very important that we give them some answers. Otherwise, they will start feel we are hiding things from them.

SAP  
3/24/90

- Sched. to close Equp. Hatch at 1:00pm.
- I've heard Leak Repair is coming up to repair leak on Unit 2 A Hr. Dev. Pmp. - if so, we may want to I.D. any other leaks we may want them to work while they are here. If we know of any, we need to let WPG know to prep pkgs. for them.
- Mike Lackey requested we take a look at the switch gear we have sched. to clean and see if we can delete any of those. He feels our present sched. will run into critical path.
- After conversations with Tom Green, 1BA03 will not come down tomorrow. My feelings after this conversation are that it won't come down at all. We are scrapping up electrical work now.
- #WD 19001358 - found problem with leakage to ~~be~~ be at bonnet, trying to face up Monty Edwards to make weld. If not, may use Cimer pipe fittings.
- • Paul Kochrey is the man to notify before any work is done on Diesels. (Beeper 126) 4 hrs. prior notice is required.

TCP 100 complete.

Isolator latch closed.

May need ext. work (Ball Nose type) for T CRT approach.

Sat Night  
3/24/80

189

Restoration in progress on pen 83. Pen 84 complete.  
No word yet on I&C set up & test of F.P. Valve  
on pen 40.

No extra electrical personnel needed as B train  
SWR Not coming Down.

MWD 1-90-0330 re restoration of temp mod  
on Backlead is with MOWB. Not a mad rush  
but he is working it.

Westby wrote HPH a memo explaining that  
there's no problem with MSIV circuitry.  
Copy attached. →

Memo also attached from Lance Block detailing  
Coopers terms and pricing for Investigation  
Support. If any of the shit were going thru  
turns out to be the result of their activities  
do we have any recourse? YES →

MWD 1-90-00541 / 1HV-8438 (leakage between charging pumps)  
Saying water was spraying from packing. RMR has looked  
at this valve and there is very little leakage. There  
is plenty of adjustment left but it is a MOVAT valve.  
Not worth the additional testing. Not to mention  
it will be a bitch to get charging taken out  
of service.

Will complete on Sample valve at 11:55 p. CR must bug  
off. I&C notified to start their retest. We may have  
to cut this valve out as I&C is telling me it  
tests good in reverse. If this is the case  
we need to get engineering concurrence and  
wake J. Davis up

1-1204-04-077 - still can't get water to stop. Ops  
trying to get it to stop.

Memo—Long Form

PAGE 1 of 2

DATE  
3/24/90

FROM	LANCE R. BLOCK (COOPER INDUSTRIES)
TO	RAY HOWARD
TO	HARVEY HANDFINGER
TO	
TO	

- NOTE AND FILE
- PRIORITY REPLY FOR MY SIGNATURE
- NOTES AND RETURN TO ME
- TAKE APPROPRIATE ACTION
- RETURN WITH MORE DETAILS
- PER YOUR REQUEST
- NOTE AND SEE ME ABOUT THIS
- SIGNATURE
- PLEASE ANSWER
- FOR YOUR INFORMATION
- FOR YOUR APPROVAL
- INVESTIGATE AND REPORT

COMMENTS

FOLLOWING ARE THE COOPER INDUSTRIES TERMS FOR THE SERVICES OF CONTROL ENGINEERS S. OWYOUNG AND D. PESOURT FOR THE PURPOSE OF INVESTIGATING THE UNIT 1 DIESEL/GENERATOR CONTROL SYSTEM:

① FOR 72 HOUR EMERGENCY CALLOUT:

\$ 187.00 PER HOUR FOR FIRST 72 HOURS AND THEN \$ 125.00 PER HOUR FOR EACH ADDITIONAL HOUR.

HOURS NOT TO EXCEED 16 HOURS PER DAY OR 72 HOURS PER WEEK.

ADDITIONALLY, CUSTOMER TO PAY TRAVEL EXPENSES (INCLUDING AIRLINE, RENTAL CAR), TRAVEL TIME WHICH SHALL NOT EXCEED 8 HOURS PER DAY, HOTEL ACCOMMODATIONS, AND MEALS WHICH SHALL NOT EXCEED \$ 25.00 PER DAY.

IF GEORGIA POWER WISHES THE SUPPORT SERVICES OF MECHANICAL ENGINEER, ROBERT JOHNSTON, THE FOLLOWING TERMS SHALL APPLY:

\$ 125.00 PER HOUR, HOURS NOT TO EXCEED 16 HOURS PER DAY OR 72 HOURS PER WEEK.

ADDITIONALLY, CUSTOMER TO PAY TRAVEL EXPENSES (IF SEPERATE FROM S. OWYOUNG AND D. PESOURT), TRAVEL TIME WHICH SHALL NOT EXCEED 8 HOURS PER DAY, HOTEL ACCOMODATIONS.

Memo—Long Form

FROM

TO

CC

RE:

COMMENTS

LANCE A. BLOCK (COOPER INDUSTRIES)

RAY HOWARD

HARVEY HANDFINGER

PAGE 1 OF 2

DATE  
3/24/90

- |   |   |
|---|---|
| <input type="checkbox"/> NOTE AND FILE              | <input type="checkbox"/> PREPARE REPLY FOR MY SIGNATURE |
| <input type="checkbox"/> NOTE AND RETURN TO ME      | <input type="checkbox"/> TAKE APPROPRIATE ACTION        |
| <input type="checkbox"/> RETURN WITH MORE DETAILS   | <input type="checkbox"/> PER YOUR REQUEST               |
| <input type="checkbox"/> NOTE AND SEE ME ABOUT THIS | <input type="checkbox"/> SIGNATURE                      |
| <input type="checkbox"/> PLEASE ANSWER              | <input type="checkbox"/> FOR YOUR INFORMATION           |
| <input type="checkbox"/> FOR YOUR APPROVAL          | <input type="checkbox"/> INVESTIGATE AND REPORT         |

FOLLOWING ARE THE COOPER INDUSTRIES TERMS FOR THE SERVICES OF CONTROL ENGINEERS S. OUYOUNG AND D. PESONT FOR THE PURPOSE OF INVESTIGATING THE UNIT 1 DIESEL/GENERATOR CONTROL SYSTEM;

IF FOR 72 HOUR EMERGENCY CALLOUT:

\* \$187.00 PER HOUR FOR FIRST 72 HOURS AND THEN

\* \$125.00 PER HOUR FOR EACH ADDITIONAL HOUR.

HOURS NOT TO EXCEED 16 HOURS PER DAY OR 72 HOURS PER WEEK.

ADDITIONALLY, CUSTOMER TO PAY TRAVEL EXPENSES (INCLUDING AIRLINE, RENTAL CAR), TRAVEL TIME WHICH SHALL NOT EXCEED 8 HOURS PER DAY, HOTEL ACCOMMODATIONS, AND MEALS WHICH SHALL NOT EXCEED \$25.00 PER DAY.

IF GEORGIA POWER WISHES THE SUPPORT SERVICES OF MECHANICAL ENGINEER, ROBERT JOHNSTON, THE FOLLOWING TERMS SHALL APPLY:

\* \$125.00 PER HOUR, HOURS NOT TO EXCEED 16 HOURS PER DAY OR 72 HOURS PER WEEK.

ADDITIONALLY, CUSTOMER TO PAY TRAVEL

EXPENSES (IF SEPARATE FROM S. OUYOUNG AND D. PESONT), TRAVEL TIME WHICH SHALL NOT EXCEED 8 HOURS PER DAY, HOTEL ACCOMMODATIONS.

Memo—Long Form

PAGE 2 OF 2

DATE  
3/24/90

FROM	LANCE R. BLOCK (COOPER INDUSTRIES)
TO	RAY HOWARD
TO	HARVEY HANDFINGER
TO	
TO	
COMMENTS	AND MEALS WHICH SHALL NOT EXCEED \$25.00 PER DAY.

- |   |   |
|---|---|
| <input type="checkbox"/> NOTE AND FILE              | <input type="checkbox"/> PENDING REPLY FOR MY SIGNATURE |
| <input type="checkbox"/> NOTE AND RETURN TO ME      | <input type="checkbox"/> TAKE APPROPRIATE ACTION        |
| <input type="checkbox"/> RETURN WITH MORE DETAILS   | <input type="checkbox"/> PER YOUR REQUEST               |
| <input type="checkbox"/> NOTE AND SEE ME ABOUT THIS | <input type="checkbox"/> SIGNATURE                      |
| <input type="checkbox"/> PLEASE ANSWER              | <input type="checkbox"/> FOR YOUR INFORMATION           |
| <input type="checkbox"/> FOR YOUR APPROVAL          | <input type="checkbox"/> INVESTIGATE AND REPORT         |

COOPER INDUSTRIES PERSONNEL SHALL PRESENT ALL EXPENSE REPORTS AND TIME SHEETS TO GEORGIA POWER FOR APPROVAL.

ABOVE TERMS ARE PER VERAL DISCUSSION WITH DUSTY ADAMS.

*Lance R. Block*  
LANCE R. BLOCK  
PROJECT MANAGER

190 *Ent 1/21<sup>st</sup>*  
3/24/90

Sam	Harvey
J. H.	

3-24-90

- |  |  |
|--|--|
| <input type="checkbox"/> ADDITIONAL INFORMATION      | <input type="checkbox"/> PRIORITY REQUEST FOR SITE INVESTIGATION |
| <input type="checkbox"/> PHOTOGRAPH                  | <input type="checkbox"/> FOR YOUR REQUEST                        |
| <input type="checkbox"/> RETURN WITH MORE DETAILS    | <input type="checkbox"/> OBSERVATION                             |
| <input type="checkbox"/> PHOTO AND SEE IF ABOUT THIS | <input type="checkbox"/> FOR YOUR INFORMATION                    |
| <input type="checkbox"/> PLEASE ANSWER               | <input type="checkbox"/> INVESTIGATE AND REPORT                  |
| <input type="checkbox"/> FOR YOUR APPROVAL           |  |

COMMENTS

During functional testing of Unit 1 MSIV's it was noted that the control room test switch labelled "Main" operated the non-pump side test solenoid and the switch labelled "Back-Up" operated the pump-side test solenoid. Although somewhat confusing, this is the correct function of the test switches. The MSIV non-pump side hydraulic manifold is considered the "Main" system. This can be verified by cross-referencing the junction box numbers feeding the solenoids in the field to the elementary diagrams. The non-pump side solenoids are shown in the "Main System" portion of the elementary

DRIVE B&W COPY ATTACHED

MOB - Lured Security a gas welder to be used at Bartlett entrance. Security has been told they are not to leave it unattended

Sunday Morning  
3/25/80 193

- Need to limit traffic in containment ~~today~~ today
- Still trying to draw "3 accumulators to work on 1-1204-04-077  
Be careful when you go in to do this work

Breakout

- Fuel Truck driver for air compressors (ILRT) was sent home at 9:00 AM and told to come back at 4:30 AM, unless notified otherwise. Beep 391 if this changes.
- Finally got to start on INB02 At 11:15 AM.
- Decision has been made to give the Diesels precedence over ILRT. 'B' D/G troubleshooting sequence will be as follows:

'B' Diesel

- 1) Logic testing 'B' 10-12 hrs.
- 2) Emergency start 'B', Leak checks of various switches 6-8 hrs.
- 3) UV test on 'B' 6-8 hrs.

'B' Sequence

- 1) Sequence test 2 hrs.
- 2) Operability test 1 hr.
- 3) UV test on 'B' sequencer 6-8 hrs. (work in conjunction with Dies.)
- 4) DCP functional test (dead bus) 1 hr.

APPEARS ILRT could be delayed by 2 days or more. Also, work in containment will be minimize due to ILRT equip. in place.

- Reducing actual seating area on fire protection valve to try to increase pressure on mating surfaces. Did not work.
- INB11 is supposed to come down as soon as INB02 comes back up. This is for surge arrestor work. We have staged a temp. pump to take water from SOUTH SWAMP TO NORTH SWAMP. This is because South Swamp will be down during time INB11 is down. <sup>update</sup> Change in plan; now we NEED to pump to waste water retention basin. DAS is setting up temp. pump.

Sunday 19  
Days 3

- MWD 19000395 - INBO2 Ready for Funct. Test. Also need to work MWD 18804321 before bringing INBO2 back up.
- Logic Testing in progress on 1B DIG. Plan to work to 12:00pm midnite if necessary. If not completed, will work again tomorrow.
- Going down to tighten J-7 on seal table AGAIN. If leakage can't be stopped, secondary plan is to freeze seal. B. Baker/Howard Davis working on paper end. Mike Cagle came in around 4:30p and should be of assistance on this. He has gone down and identified leak. Leak has appeared to have stopped after tightening. May want to check again later this evening.

7:50 p.m. meeting /

- Clean up E&RT Prep activities
- B-Diesel testing
- E&RT Valve run 40
- Met tower Barrier Taped per HMT Request.
- Venting of Caissons on Sigma, Polar Crane
- 077 Valve still drumming Ops to expand CLR Boundary

Diesel logic testing on B is through for the night. Consensus is P3 is problem and I&C is to change out this am MWD 1-90-1511. PRH had door to B. Deactivated RCH or Hawk can have it activated this am. Logic testing MWD "1537"

Seal table has been inspected by Cagle and Withrow. Last inspection was at approx. 350 psi. No leak. Decon is supposed to start, they are to use hot water per HMT. This has been relayed to that supervisor thru Curtis Peters.

Sunday night 197  
3/05/70

The following is a list of recommended inspections for both Train A and B D16's to achieve operability status. These items are recommended by Cooper Energy Services personnel and myself:

- 1) I+C to obtain from the Warehouse all replacement parts (due to O-Ring Service Life) and calibrate.
- 2) Test main bearing temperature detector lines for air leakage.
- 3) Change out eutectic trip devices, verify rod is even with the top of guide tube.
- 4) Repeat Step 2.
- 5) Perform Engine logic Test per 275b3-C
- 6) Run engine in Emergency mode, check for leakage on each line to eng. trips.
- 7) Replace other required engine components (due to O-Ring Service Life)
- 8) Repeat Step 6
- 9) Perform 3 engine normal Control Room Starts and on the 3rd run engine ~~at~~ at 6kW for ~ 1/hr.
- 10) Perform U,V,

\* ATT # 8965 written by ATT on annunciation problems on MSIV's. MWD will go to ITC. Should be out by 3:00 am. MWD going to Phil Lubenberger

\* When IDW gets off site for OTT value, need functional on 1 value - 245 ± on site

\* Ops (Chester Sotke) won't hang site for sk and lay up pumpers. Let on this to vent for SCRT. Assigned meeting between Rick Wright and Jeff Gossen to resolve. No resolution ⇒ need Jeff Davis to resolve

\* MWD continues to work restoration of negative bus. Only have 2 circuit working. Invert P-11. vol 4 ohm 1111 - 110 L March 12

200Z  
Monday  
Days:  
3/26/90

- Need I.D. Wilkes to expand clearance points on Clearance 15007. We need to disassemble valve 1-1301-U4-264 to perform hydro on bonnet. Right now this valve is tagged as a boundary point. (REF. MUO 18705795)
- 'B' Condenser Water Box - 2 lower manways on South side NEED to stay open until re-coating of area where anodes were recently welded in is repaired. Bill Lampkins has pkgs. and is now waiting on coating material.
- Keith Hinchett, Teacy Atchley, Monty Edwards assigned to "B" RHR party on dryshaft. WKA has been talking to ergo & lot about different ways to accomplish this. Maybe he make some progress. ERK needs to assign a foreman and two welders to this tonight. According to Mike Charca, Bruce Kaplan is your man on night to issue RHR as needed. Probably will need two welders and two mechanics on each shift to help
- 19001398 (DAS) → ctel needs stethes (has something to do with Restokes) Called MES, he hasn't stocked → RCS has in field now as of 1:30 pm
- Put <sup>new</sup> PB switch in "B" SIC and did logic test, it triggered. Changed out shutdown logic board, repeated logic test, still logic trigger. Took scabbing time. Tried to make it fast, it didn't
- DAS Duthy to call DPB around 3:00 pm and tell him to come in on dryshaft tomorrow and be ready to hand up work on split mechanical seal on TPCW pump and beg replacement. Called DPB at 4:00pm.
- Berkley called about outstanding work on 5GWD. Only MWD open against to the clk he was interested in was 18708630. Luechett has relief who pulled. All other work is complete against that clk.

Days 3/26/90

Monday

- Apparently Keith was able to steake the guys from Bham.  
Now we can install more suitable restraints. We can fab what we want and get an ABN from Vince Stewart.
- Main Feed Pmp A/C oil Pump High Press. Discharge Flange was found to be cracked 180° around. Johnny has found one and should be on site tomorrow.
- INBF & INBE CAN COME DOWN DURING ILRT FOR CLEANING.  
ALSO INBOS CAN COME DOWN FOR ARRESTORS.

Nights 3/26/90

7:30pm Attnq.

Unit 1

- Continuing 'B' D/C logic testing - will not complete tonight
- ILRT Prep. continuing - Attnq. sched. for 12:00 midnight
- Main Turb. L.O. - ops will try to fill tonight
- Outage END DATE CHANGED TO 4/11/90 AT 12:00 noon.

Leak on Canopy weld on Head. Painter, withdraw and 2 Mechanics going in to look at and determine exactly where leak is coming from.

2A HTR Drain Pump Vits now at .32 in per sec  
Maint Engineering wants to shut down.

B Diesel is scheduled to run at 10 AM this morning  
I&C doing some recalls in prep for this run.

B-RHR Engineering has pkg and they are redesigning and evaluating tying Hand Shuts to Mezz structure. WKH go engineering in the room and apparently disliked them. If engineering had listened to my ass in the damn first place we could be putting this in instead of waiting on their ass. They say we will have a design by morning. They did not say which day. I guess this is progress.

2nd Monday Night  
3/26/80

\* Penetration 40  $\Rightarrow$  PASSED! Good Job ~~██████████~~

\* Jacket Wt Temp Sets - 2 of 3 appeared bad, got 2 out of water and tested. 1 had o-ring seal missing off cap, the other would not stop leaking. Went to get 2 more set's and are testing them now. NO MORE SPARE JACKET WTR TEMP SET'S IN WSNE.

Have also started test tube oil temp switches. Also, setting up recorder's for UV test

\* Insulators working 5-8's

Insulators working 6-12's

\* CEMCO complete with these part of INOB1 MCB working in tanklast INOB19 will be next

\* Need PCL for DCP 45 19000509 Av.1/John King/Stan Bailey

\* Need PCL for DCP 290 Bob Bryant

\* IHS - INAO409 Electroswitch 3276 CM - 105

S/N 59070-00015625 GPES- 906813

Loc A-57-I

\* Changed out 2 of 3 Jacket Wt Temp sets yesterday on dayshift. Turned to night shift to cable. See above for night shift details.

Engen 60 Temp set also appears to be leaking. Need PCL to disposition DC's on the two cables so can use for parts

FEST 12:00 to complete cable

\* Removing strand in head so can clear up boson deposit, approx 5-10 lbs of boson. Appears to be an old leak by the levels of contamination. Leak is at the 3<sup>rd</sup>

208 Tuesday Day  
3/27/90

- GO wants vendor here on Cetcon switches for 3/6 of one event
- 2 secondary events in past 24 hrs

Leakout on Convey Sst wth leak

- Continue to remove shroud so can get to the sst weld
- W has a unique technique that would not require draining down
- Need to look at coil stack and connectors closely to ensure boson isn't effected there
- PT has a welder qualified to make this weld
- This particular weld is a shop weld, it is not the weld <sup>x 3/10/90</sup>  
W has experienced problems with at other sites
- Need to determine if need to remove coil stack to facilitate welding
- DC inspected lower convey sst welds and did see boson. Documented in inspection report, reported to Sing Lee. He wrote memo to inspect and clean boson and PT 3 convey coils (lower). Boson that was present was believed to have been from the concrete leak
- In future, we if we find any boron acid, we clean all boson (after completing good inspection). Should have done this while head was in shroud
- Conference call with W from M. Lackey's office at 9:30 AM

Final outcome of call as to needs prior to weld repair.

- Remove necessary shroud to access area for Decon and inspection
- After inspections, Remove missile shield and coil stacks in the immediate area of Leaker to allow access by the welder
- W recommended drain down below the leak area prior to welding and preheat to dry out
- W also recommended megger test on coils that are removed.

- 19015271  
4 880160

Tuesday Night  
3/01/90

211

Let Menus know what we intend to do in Cum (Nothing)  
⑥ Leak expect to be here this AM, Need to talk with them to determine just exactly what equipment they will need. The use of a foot control would be almost impossible

MSE is proceeding on Freeze Seal on 087 valve still have no parts. MWG still says perform inspection this was not changed as I was told. We will establish seal and break into valve. If problems are encountered it will be interesting

INB19 is down and electrical is working on Arrestors and cleaning will work them thru to completion. They should be done by 2:30 / 3:00.

Mr. Hudson got a letter from Cooper saying not a concern that Diesel need not be run continuously in order to perform hot retorques.

MARCH 27, 1990


To: MR. RAY HOWARD  
GEORGIA POWER COMPANY  
VOGEL ELECTRIC GENERATING PLANT

From: ROBERT JOHNSTON  
COOPER ENERGY SERVICES  
ENTERPRISE ENGINE SERVICES

Subject: ENTERPRISE ENGINES IN 76021/24  
Hot Fastener Retorque

Reference: My memo to you dated 3/21/90 regarding  
hot fastener retorques.

To clarify the referenced memo, the time interval of operation between hot retorques need not be constant operation, it can be satisfied by accumulative operating hours from multiple start-stop cycles. The generator load during those periods of operation is not critical.

  
Robert Johnston  
Project Engineer

C<sup>2</sup> Ken States  
Paul Hudson  
Lance Blatt

Tuesday Night  
3/07/90

Got copy of (W) weld procedure for repair of canopy weld. Given to Howard Davis to Review

Diesel testing going good. Cooper personnel gone to motel after normal trip testing completed.

Diesel started and loaded when UV signal given running to get time required for hot torque. 4 hr. cool downs. Cold start and should be home free.

ILRT could start as early as 6:00AM if Rick Vough can get all the snapshots he needs and Ops don't have any problems with their surveillance Rent.

Ops has filled LO Reservoir to Roll Spectral flanges

RMR checking on gasket for a HTR DRN Pmp on unit. also ~~scaffolding~~ scaffold building should be complete by morning. I figured better build scaffold while you can still get close to it.

No gasket on site!

Weld on TEE under Generator in progress. I don't know who has been welding on this job but they need their certs posted.

Ops left drain valve open on Accumulator #3. Been filling and draining at same time. the fill and the instrument air clearance looks like will be the hold up to ILRT

Casing Gasket SN 43030-0002212 LOC 14-48-F  
Shaw 3 on Hand can not locate  
GP 25-906586 S ordered on 1-29-90  
Due date 2-29-90. Need to resolve before we work Heater Drain Pump.

Tuesday night  
5/27/90

213

DCP 90-130 B'ham Engineering is supposed to be addressing problems with SIZE Discrepancies of welds. Adding welds which are needed but not shown and including a 13M which has been agreed to but not shown in pkg. Keyton is talking to Horton. FFLs are to be generated here on site and issued by 1000AM.

INBA is complete. Paper needs to close. Electricians gone at 3:30. INB08 remains to be done

- Started "10" D/C at 5:03. Have to gradually load up to 100% for the then gradually decrease load. Should have been completed by 7:30 morning
- INB09 complete, Op being backup
- Need plant Eng to help resolve vibration problems on stator cooling fan. Right fans vibration is skin induced, not in bags
- Need to continue work on THW tee under generator (Cimco)
- Cimco to continue working on PW-3000 today
- Need FCR on DCP 89-051 add hanger w/ bolt (Ken Godfrey)  
• Still wty on FCR on DCP 89-290 to delete tubing (Bob Blaum)  
" " " FCR on DCP 89-045 (mws 14000509) (Steve Early)
- Need Cimco to work valve/pack set on A9000352
- Starting DCP 43 => 18905282      } Have 4 days from this morning to complete  
DCP 49 => 18905278      }  
                  18905280 }
- Still need to get LSC wte screens installed today (mcs)
- Shut "10" D/C down at approx 6:40 AM. Carbon vendor is suppose to be here this morning
- Got hot mws 5230 coupled yesterday. Need to fit stake 5230 today if yet found in 5229 can fit stake it today. Still having problem w/ mws numbers: i.e. tel em

92 PROJECT  
030496

225 WED dayshift  
3/28/70

- North Valve Run
- { 3016B - good
  - 3016A - has bad air leak, found solenoid not put together correctly  
have MWD in ATT's hand to replace tonight
  - 3026B - good mech/elect except relief valve. waiting MWD to replace
  - 3026B - bad handset, bad contact (WLT 8944) on relay. will work  
tonight if get MWD prepared
  - 3006B - did not work last night
- South Valve Run

- Marcus Edson is on site for MWF. All that remains is PT  
from freeze seal. If need be, can sign him off.
- Had another retaining ring on the a balance isolation valve  
come off last night. Should this happen, on both sides  
when you close the isolation valve for maint, you would  
not be able to close the valve. It would not serve  
its safety function if reg'd. Told MSC to wait DC  
I will discuss with MSC before we turn it in.
- Lachey called <sup>mid</sup> ask if we wanted MWF today. I told him  
yes

7:30 AM MEETING

- 72 hrs behind sched, lost 10 hrs in past 24 hrs
- Filling case w/o basin today after decontamination
- Total Scope MWD's  $\Rightarrow$  1685
- Completed MWD's  $\Rightarrow$  1275
- Staff Davis can take except to accommodate "3 being filled".  
Ops has been instructed to isolate west area  
IEC to do UERT on personnel and lock  
Door at 12:00 noon to start test
- Coming in today to finalize plan for removal of canopy seal  
will have to remove 3-4 cont stats to do this repair
- Closing pipe on '10" diff to declare it operable
- Having problem on Unit 2 with 1 phase from generator heating  
up. Presently @ 175°F, alarm set point is 185°F. will  
have to reduce load of another 185°F
- Can take MWF down after IEC test, must have back before  
take 1BAA03 down (after it is declared operable)
- 184.5 problem to date

7:30 am MEETING MINUT

**NOTICE**

- 29000415 "B" powder vessel on Client 2 needs to be worked
- Another DC in missed DC hold pt's. Second one in 2 days
- ISC needs to continue to work on getting ~~the~~ Not Towed back on the ORF computer
- CB wants all DC's on missed DC hold points completed and reinserted. Then we need to discuss with NRC resident as to what we are doing to correct this

**NOTICE!**

- Need to remove temp mod from INOT to "B" Train reformer and reinsert. Then install the same temp mod on "A" Train reformer so when do UV test in "A" DC, the turbines will not come into play. Once work is complete in "A" DC, we will need to pull temp mod back to "B" Train or can take down "B" Train edge. HBA is pushing man's to do this. When take INOT down (after DLT start) just have back up before take 10103 down
- Appears temp problem on Client 2 isophore is a thermocouple problem. Mike Duncan should know by 12:00 noon of that is the case. CB wants us to use our infrared equip to determine if we're overheating of ISC takes longer than noon to determine of the problem
- CB called wanting to know if "B" PHR work could be completed by tomorrow. Told him would be Friday at earliest before would complete
- Cakon vendor to be on site today at noon.
- CORE Boltremoval are being laid off tomorrow. The Oagle design over the equip hatch will have to be completed by GR workers when we can get back in containment
- CORE Insulators/Sheetmetal go on 10 hrs/day starting tomorrow (~~Thursday~~) will lay off 4 insul/4 sheetmetal Friday
- CORE Insulators go will lay off 2 on each shift today. Will have
- Mike arrangement w/ Shirley Parker on letting OR craft work 8 hrs every other day (if they want, and depending on the job they are working). This is effective today. See sched on the board behind you

- B D/G is now operable. NRC QUARANTINE is lifted on 'A' D/G at 3:30 pm today. PKgs are being prepd to start UV test at 8:00pm tonight. Next series of testing will be Logic Test, Sensory Test, Emergency Starts, UV Test, ? Lastly Ops Surveillance.
- NEED 1 MECH. TO SUPPORT AIR COMPRESSORS FOR ILRT tonight. DAY SHIFT MAN NEEDS TO BE RELIEVED IN FIELD.
- Received MODE 4 Restraint List of MW's -

ILRT - press up showed Drop in PZR Level  
Lube oil up and Running

T-mov - ensure B-train pulled, MWs closed, (Man to ops 1-90-0480)  
No A-train Diesel testing can be done until FBF gets 888528 (1-88-07879) operable, This valve is discharge B-OPP which is ops Boration Flow Path. This will take until morning/lunch to complete.

ILRT pressurization in progress. Fuel truck coming in.

Cimco Electricians decided not to show up for work tonite, 2/3 of crew for Nites did not come in.

Show

SG Harper

CT Dugger

DF Woods

BT Williams

HD Crowell

MN Toler (Foreman)

C Cooper (G Foreman)

NO-Shows

GW Jackson (Foreman)

FL Washington

RL Walker

ML Murry

AR Hammond

PR Goodale

EM Gleaton

KB Rastberry

AG Jackson

P.C. King.

This is a help to the Budget but we could have used their help tonite.

RD Phillips Left site with his Badge. He brought it back and completed a report with Security.

Thursday Days

3/29/90

- George wants RHR completed by Fri AM. State is we will do it right.
- FORM must SCREW  $\Rightarrow$  1700  
FORM COMPLETE  $\Rightarrow$  1822
- Starting Monday, JEL NEEDS 2 millwrights & 1 operating eng. to clean up Turbine Deck & Turbine Test Room. We NEED to use CIMCO FOR this.
- HARVEY said to <sup>support</sup> give Stoney <sup>with</sup> 3 laborers for Containment cleanup after ILRT. If he wants more, and he will, he needs to talk to MR. Finger. These men will report/work for Rushy Knuckles not Stoney.
- It appears we will supply a carpenter (or someone) to log tools in and out of Containment after ILRT. (HMH says core will cover)
- Fisher Rep., Daniel Watts, is here today. He will be working on Re-build of ILV 4333 & ILV 4334.
- Work on 'B' RHR was suspended by Cps. Concern was due to only cooling flow path available. HARVEY tried to help remove this obstacle, but was unsuccessful. It is APPARENT Cps feels we are a bunch of -yard apes and will disable pump if we are in the room. This will delay completion of the work!
- Clock for 8hr. hold on ILRT will start at 11:30AM. Presently, in stabilization period. Blow down/DEPRESSURIZATION is expected to take 14 hrs. (i.e. before re-enter into containment).
- "A" D/G worked like a charm when subjected to UV test. Will now go start logic testing.
- HMH says can go back to work on 'B' RHR @ 1:30pm WIRING
- Ops will be running 'B' D/G 3 times a week for at least the next 3 wks. We will need to perform Borescope inspection on Heads within 48 hrs. of each of these runs. Ops will run D/G on Sunday, Tuesday, & Friday. We can do our surveillance on Mon, Wed., & Friday afternoons & Saturday.

• She Run on A DIG started at 12:00am. HAVEN't experienced any problems AS OF yet.

• Finally got release to go back in at "D" LTR @ 2405 pm.  
Radiation fields are higher with pump running. Night shift needs to ensure they have adequate # of people available to shuffle in/out of room tonight. 3:35

• Dayshift doing 14805 & 14808. Both will be turning to night shift. Also looking at taking down 14805 (no mistake, this is "A" Train) tonight. FST 2:00 am to complete 14805 & 14808 5 min's on 14805, may decide to also clean once you get into gear. • CINCO did not finish alignment of static cooling pump. now is LTR on table. Need to get SPC night shift mechanics to work this. PLEASE!

• Laying off ½ the CINCO millwrights tomorrow

• Jewett Kitchens should be bringing you a packed up copy of their plate & cutlery tonight. Have Debbie or someone type this in the "Faceman Comments" of the NMIS file, not the "Plant Activities File". We have a meeting Friday afternoon to discuss all Plate & MW's. See junction on table sorted by faceman. Be sure you get update from night shift people, "FBE, MEE, MEP, MOC, WME" already you there to Edmonds, read update back and input into NMIS "Faceman comments"

• Try to keep "2P/1P" box empty.

• Trudeau finally on turning gear at 5:20 pm

• End problems with weld on HV 3000. It looked like sit city. Having to machine back down and go again. Be sure you have your bat to work on this.

7:00 AM Thursday Drag  
3/29/90

- Vic talked to IBEW and the International BA. Seems Plant Hatch had a much bigger problem last night and today than we did. BA's are supposed to have our problem resolved. If you have a similar problem tonight, keep me and Vic

- PCT to be depressurized by noon tomorrow from ILRT. Need to ensure we get the cables off the poles crane as soon as containment entry is altered. This will free the poles crane to support the canopy seal until repair.

} DRB is the field prep for the canopy seal weld job. DRB has tried to assign Stoney this position. HART told DRB him we have one on field groups. RADM/Nathan are the right field prep, however I believe RADM is closing on a house in Macon Friday @ 4:30 pm. Suggested to DRB that he get Cagle to come in on night shift Friday night

- MWD's on DCP 89-049 (18905278/18905280) and DCP 89-043 (18905282) are PWIC, w/o punches. These are the DCP's started yesterday that we had flagged for system outages. Trying to milk Ops into letting us start work on DCP's 89-042 (18905537) and 89-058 (18905535/18905536). Steve Chestnut is suppose to meet w/ CO's tonight so can start work tomorrow. PCT can have all three MWD's completed by Monday morning (lot of fudge in this, especially of work both shifts)

Thursday Nights  
3-29 7:00 p

- (100%)
- Depress ILRT
  - Check CDR Holders on TPCW Ops wants to put in Service
  - Diesel testing
  - B-RHR
  - A train switch.
  - CK on Carpenters to be 1500 Av tool accountability  
use 20427C to track.
  - Get with Rick on whom we will be depress'd  
so we can free up Polar Crane

26A Thursday Night  
3/24/92

INB08, INB05 should complete by ~~5:50 A.M.~~<sup>5:50</sup>, TAB-5 was cleared at midnite. This will probably not complete until lunch or after.

1-90-00942 Hatch Rigging pkg needs to work when can opens.

RMR has all obstructions out of way ON HTR DEN APP 2A. This Motor will more than likely have to be reworked. ARE there any plans to send to Forest Park?

DEC 408 - HP will not allow cutting grinding or welding until Cavity Vent Fans can be placed in service. IFC need to install their flow switches so work can progress

I ask you to consider Mr Withrow as Field Foreman on Back shift he is more than qualified and this would let the man know we have confidence in his ability. RAM is apparently not coming back in until Sunday nite. Cagle said that he really didn't want to work Saturday nite.

got go ahead from Ops to proceed on welds on av B-RH12 motor. Should be in short rows by end of shift.


A-tram Diesel testing should resume at 8:00 AM per P. Hart

If B-tram SWGR window opens Need to consider electrical support for week end.

Containment pressure at 14 psi. Hopefully be completely depressurized by end of shift.

Communications for Polar Crane are in LNT's office

Freddy Days  
3/30/90



230

Friday Night  
3/20/79

Weld Filler Material at WHSE at 2210 per Har  
ATKINS. Per DPB/JW they can process them in at 6.

ARE WE going to send HHR DRN PMP Motor to  
Forest Park? We don't have Bearings and from  
looking at this contraption move the bearings are  
going to be shot!

CRDM Oals will have to be replaced per withdraw  
No details yet. 39 is eaten up pretty bad. Meggered  
bad earlier. IFC making their checks on New Coil  
stack in Shop

Jacket wtr Temp sensor went tits up. IFC has located  
a kit to rework leaking sensor. Testing continuing &  
will be stopped at UV Test.

Initial vibration readings taken on B-124R. Proceed  
with Strut installation and tensioning. Will Run  
Pump and try and get it operable.

Tygon installed per Bill Dunn floating down. As soon  
as Pressure test can be completed.

- A-Diesel testing suspended when Jacket water to  
switches started screwing up. No Spares to replace

Work on DDP-408 slowed by Roy Gasters presence  
on CIR 15152. FANS are now running and work S.  
Finally!

FRF got clearances and shall have a productive  
nite

Not Bringing any Electricians in on or contract or G  
since Diesel work will probably drag on well in  
SAT nite / Sun morn.

Sat Day  
3/31/90

23.

RHR room can be cleaned up. No testing remaining

SAP will not be in today. He is going to be out of town but will call in with a # he can be reached at

Req # for Jacket Water Temp. Sensors

Req GP25-907407

S/N 29200-26237

Due in at 10:00 AM this morning.

Days Sat.

3/31/90

7:00A MTG

- Open Equipment Hatch / CRDM Coils in / Close Equipment Hatch.
- Drain Down to 203 to support canopy weld.
- When Jacket WTR Sns. get on site and Calibrated testing can resume on 1A Diesel
- Welding to write and process MWS for Equip Hatch.
- 1A Diesel Critical path.
- DCP-408 - Needs to push
- 11:00A MTG. to go over mode 4 punchlist
- Harvey asked me to look for MWS to Magger Generator His concern was the length of time without Stator Coating. Could not find, talk to Montgomery cause I feel this is where his concern come from.

B train outage to start Day shift Sunday.

- Have ask ops to run Stator Coating Pump 'A'. Mike Edmonds is releasing clk. 15071 so this can happen.
- I/w's supporting Equip. Hatch opening by Rigging. GPC will unbolt Hatch. Don't see any NEED for I/w's or laborers til Monday.
- NEED TO CLOSE MWS ON RHR STRUT WORK TONIGHT. Day shift felt more comfortable with nightshift QC buying welds. Welds should be stenciled by nightshift.

DAYS  
SM. 3/31/90

- Equip. Hatch open at 4:45 pm. Moving CRDM in, bad one out. BAD ONE will be put into FHB RAILBAY. Still preping for weld REPAIR.
- NEED CENTRAL WAREHOUSE OPEN TOMORROW - NEED BOLTS FOR DCP 90-098. BEEPED STYSLINGER BUT NO RESPONSE. TRIED TO CALL 2 GUYS ON CALL OUT LIST, BUT NO RESPONSE. WILL CONTINUE TOMORROW.
- CLEARANCE FOR STATOR COOLANT PUMP WAS RELEASED AT 8:30 AM THIS MORNING. MEGGER TEST ON GENERATOR WAS COMPLETED, AND READINGS WERE GOOD. NOW OPS WANTS TO WAIT 'TIL MONDAY TO RUN STATOR COOLING.
- CALLED P. HUDSON AT 4:45 pm TO HAVE HIM COME IN. TESTING ON DIG TO START WITHIN NEXT HOUR OR SO PER PAUL KOCHERY.
- I/W's spent most of day supporting Equip Hatch & MOVEMENT of CRDM COIL PACK. Night shift will probably be tied up with Equip. Hatch & MISSILE SHIELD. I TOLD THEM NOT TO WORK ON SUNDAY. THEY CAN WORK ON CABLE DESIGN MONDAY.
- Purge on CANOPY WELD REPAIR WAS STARTED AT 5:15 pm<sup>EST</sup>. MAY HAVE ANOTHER BAD CRDM, WAITING J. GREENWOOD to look at readings. Greenwood says readings will improve if we dry it out. Question now is do we bake this one for 12 hrs. and see if readings improve, or just go ahead and change it.  
DECISION MADE TO REPLACE CRDM STACK 44. Wtng. MWU# to buy NEW ONE. Holding off on Equip. Hatch until AFTER swap out. Up Date - (W) looking into buying 44 off AS IS. Should know something in 7:30 after.
- MWU 19000381 CAME BACK TO BBR. Coating REPAIR is complete. Waterbox CAN be closed up. DOORS ON SOUTH SIDE OF 'B' waterbox ARE THE ONLY ONES which ARE open. THEY CAN BE CLOSED AFTER 10:00 PM. THIS WILL HAVE ALLOWED SUFFICIENT TIME FOR COATING TO CURE.

Sat Day  
3/31/80

235

- \* Jim Montgomery called and requested either Sonny or [redacted] call him tonight. (863-7575).

7:30pm Mtnq.

- \* Steve Chestnut will be replacing MAC - (Chestnut Beeper 302) on nightshift.
- \* Unit 2 - 100% pure Still plan to run Htr. Dov Pump Sun. night
- \* Testing of A' D/G will continue this night & tomorrow.
- \* ANAO2 - TO COME DOWN TONIGHT - PA ANNOUNCEMENT WILL INFORM.
- \* Purge clock started at 6:00pm - Welders coming in at 7:00AM
  - \* PT after weld (should complete around noon)
  - \* UT at 40 psi (missed)
- \* Beware of presence of ARGW in lower elevation of cavity.
- \* Will REV original pkg. for CRDM STACK TO INCLUDE 44. (MADL475)
- \* LLRT will be required after Equip. Hatch Closes.
- \* DCP 134 - should rec paper tonight - Will be hot! MWU 19001692 now in hand.

Game plan is to get CRDM for 44 into Cav and remove questionable one and move it to FHB Then Start Closing the Hatch. DRPI going in with it.

Welder will be in at 5:00A

Setting up to do UV Test on 1A Diesel. M Chance and B. Nystrom getting ready at the sequencer.

CR 15071 pulled at 8:30A Ops doesn't want to run pump and I am not pushing it now. May try later in shift if manpower comes free.

Waiting to close hatch until IfC can get resistance readings bought off as good. CRDM and DRPI readings were just outside acceptance criterion. This shit is unreal!

UV Test on Diesel-A is SAT. Should start Operability run at 5:30A EDST. Tried to milk them into 4:30 after time changed but ops was so smart they left it at 1:15

3rd night 237  
3/31/90

A Diesel running for the money. Ops Surveillance started at 5:25 A.

Electronics (GPC) were not happy about having to work Sunday. I Don't look for all of them to be here.

Joe Thompson will be in Badge training Monday Morning. They pulled his Badge at the witching hour tonite.

Security did not Reset their alarm when Missile shield was put in place. The Stupid Bastards call in here an hour after all the work is done wanting us to remove it. [REDACTED] them!

1-90-00137 - To WPG for Parts

1-89-06395 - To WPG for CLR. (Will have to drain CVCs-E)

A-90-00296 - To WPG for Parts (Elbow)

ALL THE OLD CRAMES and DRIE coils are IN FHS

3-30-90

7	8A03-01, 04, 09, 18	
①	8B07-01 - Main	✓
①	8B16-01 - Main	✓
①	N810-01 - Main	✓
①	8B07-05 - BBC	✓
①	8B16-09 - BBB	✓
①	N810-12 - NBO	✓
①	8B07-09	✓
①	8B07-12	✓
①	8B07-13	✓
①	8B46-04	✓
①	8B46-12	✓
①	8B46-14	✓
②	1B01-01	✓
②	1B01-05	✓
②	1B01-09	✓
②	1B01-11	✓
②	1B01-04	✓
②	1B01-10	✓

Follow this scheme for RKE Testing. Dick Shadid also follow this scheme for Cleaning and inspecting

GOOD LUCK!

Sunday Days 239  
4/1/90

- Need to push Ops to get "B" steel channel so MRI can work the section closer to the tower. MRI can go ahead and be working the check valves as soon as a site is found, no planning req'd for this.
- Still do not have "B" switchgear at 3:45 pm. They keep saying in 15 minutes.
- DAB working on removal of "2A" HHA Drain Pump. Having trouble dropping coupling.
- General feeling is that if we go ahead and start assembly of ~~Exhibit~~ <sup>BASIC PLATE</sup>
- ~~Exhibit~~ Did DC buy off wells for RHR startup?
- Signed on BAC3 clr. at 4:15 pm. - THERE IS A GCD.
- RC Howard needs to sign off surveillance for Borescope inspection of 'A' TRAIN DIG. Surve. showed 'B' TRN., should have shown 'A' TRN.
- Ops says can't press up to 400 psi w/o changing valves. Revising procedure to press to 350 psi. Tom Clegg estimates 7:00 pm to be at 350 psi. After DC completes inspection, need to load the wagon and get everything back on track. Will check connection @ 400 psi.
- See enclosed list of Mode 3 restraints. Only showing 15 min's for mech/slat/ITC. Need to go ahead and start pushing these now.
- Need clerk to update "Farmer's Comments" in notes from Mode 4 restraint list. Stack of notes for clerk to do tonight on Harris' desk (including AI's to disposition several DC's)

252 Wed Days  
4/4/90

Get Drain Valve welded in at HTR Drain Pump

Most of our staff is out of the Can. I asked WKH to ensure follow up so we don't get caught with our pants down.

I asked that one welder be left in Can to support RULIS work.

7:30A

B-Diesel testing

B-ESFAS - test exceptions

CK Surveillances and give update at 11:00

- Push Copeland on Trip devices -

- Push ptg on Diesel Mod - short time frame

- T-MOD for 1BDR-10 -

- Continue to push paper -

RULIS doc selection - Audit w/ 11:00

12 "6x3" 6

AW doc - 2nd pt

19001728 - hot job need to have valve in closed position, will put record and on transmitter & get valve replaced tonight

Cashier  
USER/

(15281 - MA 04 FILEN

15281 - " " FILE

ETAF

BankRebutable Letter notes

ACM pump used and changed at 7:45AM

Weld Beam - 6x ad START

6" Blind Flange on Concrete Hdr and in 4 ft. shell in 25 min

DD1-I4 inverter 19001707. - ~~bad~~ leak below

MPS → DD1-I4 inverter bld 100 amp coming in 8:15pm 2 day turn  
led blc by end night

GRT → RTD bypass 19001722 Audit due at 3:50pm / IN field

WEN → DRPE 69 - bad connection at connector - time to exit equipment very early

AR → PT MOV's fluctuate

HRA → DCP 133 in D/A 19001721 in 35" w 300 psi - not ap. 1500 psi - (paper)

MRA → Weld Hdr Beam taken

CMC → 19001728 PCH-I4-215 P. failure

Lompson → 19001704 Coat RPT DCP max to next 4/150 rpm

Wed Night  
4/4/90

- Dok inserts for MWD A8801133 should be in tonight @ 8:55 pm
- MWD coming out to remove space anchor bolts on containment level C per MWD 90 VIM113. Crew will work this Thursday on dayshift (WRT 10124)
- MWD on acid pumps in water treatment bldg is complete - at least this is what I was told, but for some reason I don't feel comfortable with this
- DCP - 90 - 133 - B-Tran Diesel complete, need to have Austin Randall make Annunciation windows and install them in order to close pkg.

250016 gaskets, ODS and parts for HC skid are all in our house.

AAJ - setting 1B01-10 complete.

LNT - has gaskets and going to the hole

#### Parham's Wish List for Electricians

- |   |                     |
|---|---------------------|
| <input type="checkbox"/> Calvin Cooper<br><input type="checkbox"/> HN Tolson<br><input checked="" type="checkbox"/> Susan Harper<br><input checked="" type="checkbox"/> DF Wood<br><input checked="" type="checkbox"/> CT Dugger<br><input checked="" type="checkbox"/> KB Rosberry<br><input checked="" type="checkbox"/> GW Jackson<br><input checked="" type="checkbox"/> F.L. Washington<br><input checked="" type="checkbox"/> AR Hammett<br><input checked="" type="checkbox"/> BT Williams | } Definite Requests |
|---|---------------------|

Wed Blights 2  
4/4/90

7:30 AM MORNNG

- BSFAS complete on "B" D14
- Doing try out now for DCP 90-133 → CWP has phy, HBA rounded parts, etc. to do square
- Do FT on DCP 72 (mwo 18904674) on dayshift tomorrow
- Made 4 now targeted for 2:00 pm Friday 4/6/90  
will need to do containment close out prior to that time

(509 PKG is whole again!  
FWC to WPK.  
Don't ASK)

1-90-1573 - RER that was due at 6:00p did not happen  
I pissed an engineer off trying to get him to find  
out where the hell it was.

PMR needing  $\frac{7}{16}$ " Bettelle washers. They should be flown in this  
morning per PMR.

IBD1-10 is complete and installed in gear. waiting Ops to  
complete diesel run to remove t-mad so we can be  
out of this embargement. (1-90-0046 IN BBR)

1-89-04674 - AAI working the 4-4EV BERSL 2 completed  
will work 2 tonite and complete the FTs. I haven't  
figured why we were waiting to Draw Bubble in P2E.

Diesel is running for the money should shut it down at  
around 4:30

1-90-1722 - Cinco swapping people in and out. Should complete  
this morning. (FINAL TORQUE)

Withdrew used 2 pipefitters to remove some bottles and  
some steel from the car. This should be all of our  
material except what has been left to support RULS.

256 Wed Nights  
4/4/90

Work Room Board

- 1-88-2456 - To WPG 4-3  
1-89-6593 - Personnel Air Lock  
1-90-0207 - FWL to WPG  
1-90-1262 - IP to Ron Burns  
1-90-1573 - Need RER  
1-90-1575 - To WPG (Grainger Resolved)

Ops will not allow us to Restore T-moo after 1301-10 was installed. They were running Diesel. Mwo 1-90-480.

HBA Needs to resolve paper problems with 1-89-05020 & 28

- 1-90-00480 - When ops gets ready to support  
1-90-00207 - Complete to WPG  
1-90-01372 - FWL to WPG

Sign Ref. for MSC and give to Greg Lynn to get #5

HTR DRN PAP 2A - Alignment in progress - Should be complete with no problem.

JEB is scheduled for vacation 4-14.

Parts for 142 SKID here. MES should be able to have a party today.

1-89-044771 - To Kersteins to design a FT.

Telecommunications Cable pulled - Needs to be terminated

1-90-1760 - PZR Flange restoration (RWS)

B Diesel should be down and operable this AM.

1-88-00823 - Completed - Need to watch the hell out of this pump when it runs. "Terry Turbine"  
"Need to hold open until it runs"

- PRG IN BBR -

Thursday Days  
4/5/90

257

Is it true that the only reason CLC Don't go to church is He can't stand to see that many people sit on their ass for a whole hour?

7:30 A

CLC - They want to work 24 HHR DRN Pump today.

2A - Diesel Run today

R2215 - DCP - will h.t. today - Circo worked down first Nite!

States MTC at 11.00s

Poss to complete removal of TIMED 1-90-480 mvo

MES has try to invert. Inverter problem

- Fisher rig will be in @ noon tomorrow RER. DAN FISHER
- Prob for live load jacking will be here tomorrow

(Lie Walker pump) #2 Unit 1 irrigated  
and running about Jerry Frey investigating.

# 111-1000

CFT \* 19001734 Pre Start Sample Value (HCN = 3515)

Fuel to WPL # 18904771 PWL TO WPL 4/4/90 4/1/90 Relays Coming out of 100 ft. measured by Kristiansen

Fuel to WPL # 19000480 Temp Read 98-009 Cpt says we work after sunset

Fuel to WPL # 19001630 PWL TO WPL 4/4/90 4/1/90 Fuel Connection Cpt did support 10-2:00 pm -

-18900593-

Fuel to WPL # 19001931 PWL TO WPL 4/4/90 (A)-mcc 8-0/0 - DCP 90-133 Fuel, (Holding 1/2)

# 18905264 (A)-

\* 19001729 (A)-mcc "A" off DCP 90-133 used to work late day shift

\* 18906593 (A)-mcc Interacts on personnel both - and 8 hrs prior to 100 ft

IMG \* 19001758 (A)-mcc DCP 90-136 RERIS - day shift to stay in till work complete 11:00

Fuel to WPL # 19001573 (A)-mcc 1/2C TO WPL 4/3/90 why RER to close paper - got back from 11:00 am, GRT closing paper

# 18901577 (A)-NNI

Fuel to WPL # 18905220 (A)-mcc returned to WPL 4/3/90

Fuel to WPL # 18905221 (A)-mcc not working on paper work

Fuel to WPL # 1900962 (A)-

LDR # 1900721 (SF)

why after unavailable per 100 ft. Should be able to run 100 ft. 6:00 pm tonight

MES # 18904674 PWL of 20072 100 ft this morning, why in sun and do nmo

# 18903485 (A)-NNI

92 PROJECT  
030515

Thursday Day:  
4/5/90

- NRC going through MWD's on "A" D/F. IFC had signed off  
dew point readings were good. They were in fact high. Should  
read 35°F - 50°F. Reading taken ~~during maintenance~~ on 3/29/90  
was 60°F & 80°F. This will probably hold up "A" D/F am.  
Out retaking readings at 2:15 pm. UPDATE: Faded signs
- NSCR "B" Turb is closed up. Tail biter back in place
- Clr for "3" A/F (MWD 29000613) is suppose to be ready for night  
shift tonight. Need to work this ~~out~~ to close a plant  
AI.
- Live load parking work should be completed tomorrow on day shift
- 19001616 → MFN press indication in stat em reading 340. May be  
parts problem. Ops trying to say this is a Mode 4 restraint. It's not.  
Not having remote indication should not affect operability of the two  
MFN's in the north valve room
- There is a lot of talk about a galled fitting on RULS. Per Mark  
Benny, the does not need to be replaced at this time

#### \* MODE 4 RESTRAINTS

FWL TO WPS \*18904585 (2P) Retained to WPS 4/5/90

WKM \*19001719 (2A) Missing bolt & nut from @ more than 4 thumbs. Work in progress 4/6/90

Bored has been cleaned off - now have 3 columns  
 MODE 4 - Green  
 MODE 3 - Blue  
 MODE 2 - Purple

Please push items on bored - people should stay till they  
 complete these paperwork, especially on Mode 4 items  
 Make sure person/supervisor knows that they have Mode  
 restraints in their possession

Thursday Night  
4/5/90

7:30 AM MEETING

- Start 1 @ 180°F, heat up going slow, checking for hte temps
- do dew point checks on 2K and occasional. need dew point below 50°F before start test sequence on 1" 2K
- • Need to have all "B" elect mvo's closed, before can run 1" 2K
- Stake, Sene, Hunt (NRC) to be here for "A" 2K test
- Pct Spray Valves failed PT  
19000983 - now ok
- 18710690 ⇒ work tonight
- • Containment cleanup to continue tonight
- • PNLIS work will continue into night shift. Day shift prep filter staying over till completion. Make sure paper gets closed
- • DCP 72 18904674 ⇒ work busses INAA, INAB, INAOI tonight  
FWC
- Mode 4 still sched for 2:00 pm tomorrow
- Mode 4 restraint meeting tonight @ 11:00 pm
- NRC has a hold fee going to Mode 2 - issue is the D/G's temp/press switch reliability

⇒ Electricians tool average readings on generator heating. They are performing as designed.

⇒ 19001118 - This MVO is to branch and seal penetrations on AFW per NCL-45. The materials needed for sealing have exceeded their shelf life. Talked to Steve Chastot and Bruce Kaplan and it was decided to wait until day shift to get PRG to extend shelf life or engineering to say it is okay or not.

Lee Mansfield working on extending shelf life 0800 4/6

⇒ 19000721 - 1-1205-44123 - IDW - Had satisfactory torque on check valve. To WP 0515 by dual body

⇒ 1-1205-44122 - QC found valve leaking while performing VT. MVO's 18904993 & 19001077 were used to perform corrective work previously. Ready Maint. Eng. for torque application. Beyond 054 and 250 at 0400 or. No response.

21  
Thursday  
4-5

- ⇒ I & C having problems with pot control. Possible open coil. Think they found problem on bridge cable K10 & C11.
- ⇒ 18710690 - Pct. spray valve 0455C not stroking in doses but with spans { Took actuator off and it stroked fine. Reinstalled actuator and valve still will not stroke. Pending not believed to be problem. Package being saved for actuator disassembly.
- Comp. ⇒ 19001767 - AA5 - This MWD is to correct wire problem on 1HV3026B. Complete
- ⇒ 19001771 - WCP - This MWD is to cut off some anchor bolts on i level of containment.
- ⇒ Cliff Baker found valves 1HV3500 (MWD 1890457, <sup>status OF</sup> & 1HV3513 (<sup>status 2A</sup> MWD 19001755) leaking. Torqued body to banst bolts on 19001755 on 4-4. Pending to WP for more instructions.
- ⇒ Unit 2 Heater Drain Pump is ready and opn is warming up yet up to run. See Steve White approx. 0800.
- ⇒ 19001772 - Open spray additive tank system to support chemistry addition of chemicals.
- ⇒ all field work complete on NOVATS. Ron should complete paperwork on <sup>(MWD 1900462 & 1HV362) Flight needed to adjust packing on circ. wtr. imp. tank</sup> dryditch.
- ⇒ New joint on air line not improved. Checked hyd. refrigerant levels and found to be satisfactory. No evidence of hyd. problems.
- ⇒ 18904674 - Engineering performing functional test per Bruce Kugler.
- ⇒ Did not resolve QC problem problem on 18905620 & 5629.

Thursday Night

4-5-90

→ 19001758 - RVLIS - C1MCC completed longer change. SIC to installed tubing under MWD 1900126E.

## Metric - Long Form

DATE  
4-5-90

R.M. Rawell
C.L. Clegg
S.A. P.L.
H.M. Handenker
L. Norwood Jr.

- |   |  |
|---|--|
| <input type="checkbox"/> NOTE AND FILE              | <input type="checkbox"/> FORMAL REPLY FOR BY<br>INVESTIGATOR |
| <input type="checkbox"/> NOTE AND RETURN TO YOU     | <input checked="" type="checkbox"/> TAKE APPROPRIATE ACTION  |
| <input type="checkbox"/> RETURN WITH SIGNATURES     | <input type="checkbox"/> PER YOUR REQUEST                    |
| <input type="checkbox"/> NOTE AND SEE ME ABOUT THIS | <input type="checkbox"/> MEMORANDUM                          |
| <input type="checkbox"/> PLEASE ANSWER              | <input type="checkbox"/> PER YOUR INFORMATION                |
| <input type="checkbox"/> FOR YOUR APPROVAL          | <input type="checkbox"/> INVESTIGATE AND REPORT              |

REF: Chesterton Live Load Parking

## Problems:

- A. Wrong washer: G.P.C had to drill.
- B. Wrong Ballistic Washer: Chesterton sent wrong S.A.S: could not rework
- C. Chesterton Rep made all measurement for same values:
- D. Many power hours lost on this project 168. This needs to be changed to Chesterton.
- E. Chesterton Eng: said values are live load without ballistic washer. Need letter from Chesterton Eng. to verify this statement.
- F. 10% to 20% values cannot be live-load. They should know the values they can or cannot live load.
- G. At the time I do not believe these values are live load proofed.
- H. Until above problem can be solved, would not obtain any more live-load parking from Chesterton. They need to prove this product to G.P.C.

R.M. Rawell

EX-3A63

7:30 AM Meeting

- 119 hrs behind sched, last 6 hrs in past 24 hrs TOTAL AVG SCORE ⇒ 1820
- RVLIS - Work continuing
- Spray Valve - 045SC
- D/G Testing - No change new joint
- 1-1205-44-122 - Body to bonnet leaking
- Spray Additive Tank. 19001772
- Cold Rod Drop Testing
- DCP 072 - 18904674 Coordinate with Ops (Ron Burns)
- Mode 4 Restraints
- 19001630 - 1F - 1HV84851B (Cont. Slm.)
- 19001729 - 1A - Diesel
- 18906593 - 2A - Personnel Hat

Friday Days 26:  
4/6/90

MWD 19001077 RHR Checks value 11305004122  
Reee MWD being written to Tongue  
Bonnet.

Coll Craig Thompson ins tonight  
before we Close-out Containment  
so he can pull MG set for elevation  
in Containment. Lester has phone #.

- JCL on vibration test unit. IR know how 722. larger
- NISSS personnel => Loop will be here Sat, off Sun
  - => WKH, Cagle off both days
  - => withdraw off both days
  - => BAM will be here Fri, Sat, Sun night working IDW's case

- MWD (19001630)  
on HV 8485A failed PT, had ground. JCL went in and found punched wire. FRC TO WPS @ 4:45 pm. Ops needs to release clc and dc,

Completed jacket ate over cut test on "A" 2/6 around 3:30 pm. W/H Ops to bring clc so we can implement DCB 90-123. Called night shift come down in that did the "B" portion. They should be in by 5:30 pm. Hopefully Ops will have clc by then

"A" RHR check value 122 (call 19001780). Plant Eng believes bonnet may be coated. Wants us to loosen 4 bolts and try to redesign bonnet. Waiting on Ops to shutdown "A" RHR. Should shut pump down by 6:00 pm. Told dayshift to get MEAA ready and be ready to go in at 6:00 pm.

• About 2 lost a string of float tiles today and put the unit through a transient. Did not run the chain pump on the "4" today due to this

• Will be ready to do PT on DCB 92 on MEAA tonight. R/H's have been shut down

• Need GE 662 grease or equivalent for escape hatch and need an <sup>o-ring seal</sup> <sub>19001047 (new)</sub> grommet review. Unsuccessful trying to get grease in here Sat

Friday Days  
4/6/90

- Unit 2 "A" SGAP has high vibration. Data was telecopied to Pacific Pump in Calif @ 6:00pm. They are to call the down from San if they feel we have a serious problem. Need to monitor vibration once per shift
- Stripped "I" RCP pump and appears the A-4558 valve is leaking by. Now have problem with few per day valves DCA on hot line with vendor, will probably fly one in tonight if we can get him a flight
- HV-4335 & HV-4334 are bent together. Need 1 piece machined by Towner tonight. Buschett has details
- Buschett has valve in backflushable filter just disassembled plus looks kind of rough, valve seat has a burr on it. AIGB writing DC to get dimension on valve seat
- Both HV's 3000 & 3030 are terminated. Why or Ops to stroke. Everybody off all M&G writing procedures

7:30 pm meeting

- RULIS - IFC work continues
- 19001803 => HV-04556
- 18700690 => HV-04550
- After completion of rod drop test, begin drumming & filling #6's order 13;
- D/G Testing
  - do on 2A
  - Ops perform 14700
  - do UV Test
  - begin D/G assembly for FT
  - Ops perform 14980
  - do high camber zone portion of D/G FT
- (19001780)
- 1-1205-44-122 Bonnet leak => why "A" RHL to be shutdown
- DCP 72 (1890 4674) => work bus 1NAA

Friday Night Shift

4/6/90

- ⇒ 1A O/b DCP is fine - Ready for Ops to pull clearance & run engine 1900 EDT.
- ⇒ End of this NOE's crew tonight. Issued order to investigate Air Pump Shuttle valve sticking on vlv. 3026A, New #1 position 1920 EDT
- ⇒ New 19001780 for RHR ch. vlv. 122 is back in field to measure for cockpit seat.
- ⇒ New 19001780 for RHR ch. vlv. 122 is back out of field because Ops won't let us touch it while running pump. 2215 EDT
- ⇒ New 19001802 for Tygon Tubing installation in field at 2250 EDT
- ⇒ A TRN. O/b DCP E/F Comp - Ops Surv. IN Progress.
- ⇒ RHR ch. vlv. 122 (new 19001780) back to field again. 0210 EDT.
- ⇒ Unit 1. Attr. One pump running fine on miniflow. 0305 EDT.
- ⇒ Replaced gasket on Emerg. Hatch inner door but it still won't seal and leaking int. 0400 EDT
- ⇒ A TRN. O/b - completed Surv. + Dick inspection cell Sat. - Ops. says it should be operable in about 30 min. - 0435 EDT
- ⇒ RHR ch. vlv. #122 back out of field - wtg. Ch. to rework vlv. bonnet. (looks like bolt holes when they are loosened.)  
New to W/P for her 0530 EDT
- ⇒ 19001802 for Tygon Tubing is installed
- ⇒ 19001805 for Hoses to drain down - had to repackage to install hose from 115 vlv. to the 084 vlv. 3/19 "Hose installed"
- ⇒ Parts for LV 4333 & 4334 are machined & ready for M&B.

205

west Days

4/7/90

730 mtg. 4-7-90 168 hrs behind schedule, lost 48 hrs in past 24 hrs

- VLT outlet valve closed for now - need to investigate
- 168 hrs behind - 48 lost in past 24 hrs (Lumining press in R.R.)
- Opt. 1A test & Mod is complete
- Ch. Av 122 on RHR heating by press 2020
- Tygon tube is in place for pump return
- INAA Fuel Test is complete
- Turbine is on Train-gear w/o seal oil
- Need to expedite parts for 2455B&C valves
- Piz. Cool down : to ?
- Mode 4 by now scheduled to 1st Tuesday 4-10-90
- 15593 clc for 1st vlt (Not written by EHG)

For IPV-455B &amp; C

1X6AA06-452-5 Fisher

Fig. #	P/N	<del>SHUTTER</del>
30B	10A5476X012	SHUTTER
31		SL-LET
36		V-NOTCH GATE
37		WASHING,
42		DRIVE SHAFT
83		SEAL LOADING SPRING, SHUTTER

Terry Lunsford trying to get parts

Apparently CCP is ran for about 6 min. with no suction water. Supervisor checking valves taking oil samples, checking bearing temperature. Need to get main eng in to being up off.

Monday Days  
4/9/90

277

Interoffice Correspondence

Georgia Power 

DATE: April 9, 1990  
RE: Dewpoint Readings  
FROM: H. D. Duncan  
TO: C. L. Coursey

The following dewpoint readings are for Unit 1 and Unit 2 Diesel Generator Air Compressor. Samples were taken from air receiver tanks on 4/8/90.

Unit 1A Diesel Generator  
12403G4001K01 34.2°F  
12403G4001K02 33.2°F

Unit 1B Diesel Generator  
12403G4002K01 44.5°F  
12403G4002K02 36.6°F

Unit 2A Diesel Generator  
22403G4001K01 43.9°F  
22403G4001K02 60.9°F

Unit 2B Diesel Generator  
22403G4002K01 33.7°F  
22403G4002K02 44.4°F

Unit 2A Diesel Generator Air Receiver K02 is currently out of specification and is being continuously blown down.

*M. Duncan*

MDD/jbc

\* DCP 90-115 => cooling water piping for TRW - do not have enough. They ordered 40 ft, DCP calls for almost 200 ft. Ordering another 150 ft of schd 40,  $\frac{1}{2}$ " pipe.

\* MWD 19001825 weather last night to adjust limit sets on MWS's  
mws given to TLF

\* Day shift went in on PDC setting values and found a bushing laying on the gearbox. First impression is that the bushing was left out of 455C. NOTE: No longer an impression, it is true. Preparing to chain back down to take A-0455C back apart. Will continue back together with A-0455B. DCA/MWS pulled setbolts off A-0455C before they came out @ noon.

92 PROJECT  
030524

\* 19001827 => EBOP coming down, turbine pump would not auto start

Monday 10/28/81  
10:00

Ops released to fill & vent at 1454

What are we going to do about the Holiday?  
When are we coming off shift?

I've been asked this fifty times tonite.

MSE took 1-90-01834 - Cap removed, Valves flushed closed off with no leakage, Cap restored. Will close when system is pressurized. Per Parmer valve cap only had maybe 6 to 8 drops a minute

RW has 1-89-6377 - ARV-3030 - instructions say to chase threads and Nec tube, this will leak again. Need to see if using a pipe plug will take a act of congress.

This morning was dropped on us for all the ARV's 1-90-01326. Checklist is just basic checks of fluid levels and physical damage

IOW worked on Fire inspection report, MSE & JEB started working fire protection Surveillances

Both Diesels have been run in last 24 hrs. Borescope inspections need to be performed. Surveillances are in Duty office. Also LNT says vibration data has been being taken for Maint Engnng for trending purposes.

Got one of the clerks in WPA to input your comments on MODE RESTRAINT list. Struck comment on MSIV3. Those plugs should start showing up as in closure cycle

Not getting much response from draft after 8 hrs.  
Might have 4-6 people total leaving.

Powell has 455-C together and packed, at 6:00A they were torquing actuator. Ops has filled to 90%O. Decided not to snatch tygon and fill and vent hoses until were sure were out of waste on 455-C

Days

- Tried to put more load on turning gear, like triggered. After turnover in control room, will get Ops to reset bbl and try again. Need to be prepared to troubleshoot problem. Had to get on turning gear tool. Bolo, Sonny, Murdoch, Montgomery still have wanted me try again
- Sent msc 19000997 to control room to allow them to review & clear msc logged to Ops. They are to send back when through for us to until mode 3
- HV-4553/4554 to ITC to set stroke
- TRW pump has problems, does balance coupling not bond correctly
- A&H completed boroscope inspection on both D/G's

7:30 PM meeting

- Aw with Hbl supplied by Start 2
- Looking at why bbl keeps tripping on main turning gear
- Pne 200'F, 350 psi
- When get finished with 4558/FT, will start PCP's  
These will take tygon & <sup>1"</sup> hoses out of containment
- Continue to clean up containment
- Mode 4 msc's (19001802, 19001805, 19000716, 18905593)
- Target Mode 4 entry @ 8:00 am tomorrow morning
- Plan is to rotate lower arm 1 tooth to get lower arm to line.  
late 4558: Hando has had part problems with lower arm not been properly machined from 1/2" want to start PCP "1" so can verify what went in today and torque. consensus value is looking by now
- at 350 psi. He did see movement. Everything was torqued down good and lockwired. He did see bearing at #3 consent. Decon's have been - - - - -

92 PROJECT  
030526

Tues ~~10~~ night  
4/10/90

• Plan to work 6 a.m. / 3 p.m.'s, 2 - 12 hr shifts Friday (Holiday). See Stanley Parker, pick shifts by seniority even though OT involved.

• Told MHS to put that the mechanics/electronics will go back on normal shift beginning Sat morning (5-2, 10-4). This does NOT apply to Janman/sup's/3p's.

RCP started at 1210, released to start work 1220 <sup>No CO</sup>. Ray RMR has moved linkage arm one notch counter clockwise with NO positive result. This reconfiguration made it impossible to hook up actuator to Arm.

DEA called in per Hill when it was decided that we needed to go back to original 2 o'clock position RMR and crew are reconfiguring to original orientation marks per manual.

DEA here at 4:30

1-90-01856 - Bonnet leaking per Kaplan and Mechanic. MHS S/N not on or off WPL

1-90-01857 - MSV 300613 - Repair made and remeshell in progress - should complete by AM.

A-90-11558 - Valves swapped. Screwed up valve is on Mezz for parts.

A-90-458 - spent resin dewatering pump. this is hot and the temp they want to work has a cracked casing.

Tuesday night  
4/10/90

The only positive thing that happened tonite on 455-C is that when ops started RCF our valve did not leak Pn.

Big Sway session on how the hell were going to get stroke set, without tearing Angles off actuator stem. Looking at Lengthing the turnbuckle to gain the 3/4" we need.

1-90-1820 - pump draws higher than Design current Had ops run Sister pump. It also shows higher than nameplate current on B&D. Per Muro pump motor was pulling 80% of nameplate uncoupled. The vibration readings taken were well within spec. Stokes needs to look at this this am. Bearings only thing that could make motor pull this much current unloaded.

Went to put Foreman working crews on 10-4 schedule Blueships on 5 days a week Supervisors alternate weekends

Board to your left. Shows craft scheduled to be here this weekend. Red Dots are Blueships

Knock the pins out of the turnbuckle and get you 3/4" end to tell with the vendor

I think ourselfs but we see all the can in back in there hole.

92 PROJECT  
030529  
LA 6262

AC Miller, TA Kao - 11-12 AM 1986

Will need to work out what we are going to do next

all the Melli's Friday after

will be same and Friday night and Saturday night. Could be same and Friday night and Saturday night. Same time, same place, same day, but will be different night.

all the Melli's Friday after  
Lubing Leeward Thompson Davis Lance  
Chichau 501 411/40, the following people will go back in their boat:  
all right the time:  
I did not yet record to all people Friday yesterday afternoon, but I

will be back Friday

will probably be summer we are back 2/6, and now we are now  
I will start allowing people back in the continent. IAN said to  
make sure and we will be able to do same. this many people

not a problem in the air load due

will start allowing people back in the continent. IAN said to  
make sure and we will be able to do same. this many people

max for that. like this one we are in now is about 2000

TA 11 and 6.25 am, no more capacity to be in Melli's by 6:00 pm. so

will be back Saturday for dinner by 2:30 pm

"G" RHR details, withheld approx 2:15 pm. why do we follow and a

communism being by 3:00 pm tomorrow

will need to work out the Melli's. dinner and the would have  
following down. The " " is 6.1-151 & 6.1-160. Followed by evening work.  
Now DEC 90-6-23 should be next ready to work things at. Example 1 CHI

8/11/90  
LA 6262

4/10/90  
LA 6262

Wednesday 20/10/90

7:30 AM MEETING

- Start 1 made Made 4 @ 17:27
- Heating up to 530°F
- Stacked 3010 & 3020 in ~~wall~~ north value room  
3020 has blown seal, WRT being written  
3010 stacked ok
- MUO 18808640 (inv-6276) - need this value back together  
to put steam in lines. May have to break  
vacuum to install valve
- Inside work will begin tonight after HU completes surveying  
area & suggest ITC on this. There is much  
dust - water that is used
- - DCE 18808640 (inv-6277) - ITC to must work tonight &  
265 has ...
  - I west of ... our 19001836 that honest look was  
on HU stock - we returned man to work after
- Tell CCC next to look at solid for running DK's over  
holiday weekend and be sure we have the right people  
here for the locomotive inspections, etc
- ARV 3030 - west value room stacked good yesterday, CJs are  
to do offload task for operability. ARV 3030 still has  
ITC problem we have card
- 19001847 - we fixing #2 has the problem, calling to my

Ops called saying they had an open LCO. (25715-103) was performed 3-10-90 this should be the paper to close their LCO.

1-89-01584 - Safety Injection - Passed VT-2 but had a small leak. This should not be a plate restraint, RAC 1-90-01894 written to rework at next outage or opportunity. Spec'd had already been forged to RAC. No response from Maintenance Engineering

1-88-08646 - UV-6276 - Complete closing paper

1-90-01886 - DCP 80-033 - FAB - Holding PPS for RAC to address AS-Bufts and we can close the paper. Kuylin working with Ops to get Clearance released so we can stroke

Apparently WKA found a slight leak on condensate today. Denny Parker looked at it this evening and it is a leak. We can't do anything about it now because Rx Engineer has us held up. This morning we need to correct this leak. Door #3, South side. Leak is about Head high.

Anyone going into Cam must now live by 14900 and 20427

WPK revig Mult 1-90-1168 to adjust limits on 1HV-9385 valve, this is a Mod 3 restraint.

Per Borrelli they did not work on K10 at all this evening. They will work this am.

	4-12	4-13	4-14	4-15	4-16	4-17	4-18	4-19	4-20	4-21
TLH	X	X	X	X	X	X	X	O	O	O
RIV	O	O	O	O	X	X	X	X	X	X
-FEF	X	X	X	X	X	X	X	O	O	O
PRH	C	C	C	X	X	X	X	X	X	X
IDL	X	X	X	X	X	X	X	C	C	C
WDL	X	X	X	X	X	X	X	C	C	C
INT	C	C	C	-	X	X	X	X	X	X
NSC	C	C	:		X	X	X	X	X	X
AAS	X	X	X	C	C	X	X	O	O	O
MCS	C	C	C	C	I	X	X	X	X	X
GFL	X	X	X	X	X	X	X	C	O	O
JEB	O	O	C	C	(Var)	(Var)	(Var)	(Var)	(Var)	O

WPB called me and said Ops was getting Devil indication 1-16-9385. They revised 160-1168 to allow us to be able to troubleshoot and repair the valve.

Clay has tagged the main circuitry out and there is going to be much corrective troubleshooting going on until they restore power.

Kapler has 1-90-1880 and is doing the PT with ops.  
Still do not have FCR so don't close until we get it.

CLC - Look at schedule for running Diesels over the weekend. Need to ensure appropriate people here to cover.

ARL-3020 - Seal replaced fitting with hydraulics and should be ready to go this morning.

2A41A has been in service since around midnite LCC cleared. No problems with inverter this morning

IDW ON CAR 15667 for Terry Turbine. Do not sign him off clearance until we are ready to closely watch Turbine & Pump. (High potential for magnesium screw up)

1-90-1867 - EHC pump #2 BTR - Breaker Rocked in and functional. The Gorilla that Rocked this BTR in so tight screwed the cockpit up. This will need to be corrected when Boss can be deenergized.

Friday  
4/13/1

1805 Name n/w n/w 19000995 CCW =  
Pump Sealing oil Motor & Pump  
PM attached to n/w/o.

1-90-01949 - David Hawkins is scheduled to be on  
this AM. He can RESET Gv. SCS (cannot know)  
1B Diesel. PN 190-01516 shows completed Satu  
Why are we doing this?

175 Setting LISA Devices / Set up complete - Fox

1-90-0669 NSC: Bennett lost ACT valve  
Retorque - IDW

Press test and VT2 on Breathing air improves  
going well. Completed without incident

Ops expects to be at NCRT by morning.

INSTALLED Calibrated pressure gauge on MFU 52  
so Ops could stroke valve and valve operable  
when they complete their stroke will have to re-  
charge to 5229. Xmitter problems is reason for a  
shift.

1-90-01787 - 8141C valve - FWC

1-90-01787 - 8141C valve - FWC  
15575 should be hung by morning MUO-C-90-  
LV-7913. South FW Storage tank level control

290

Friday Night 4/15/90  
 Sat Days 4/16/90  
 Sat Night 4/16/90

Saturday Morn 4/14/90  
 Sunday Night 4/15/90  
 Monday Days 4/16/90

for clearance

- While reviewing paper<sup>n</sup> on the famous 036 check valve, it was decided by GC that no one was sure that the shots we took for on the MTR is what the valve gives us. GC and two men were set to go in and look at the valve @ 1:00 pm. HMT call at 1:30 pm and says Henderson has solved problem. Tom Gear calls @ 1:45 pm and said problem not solved. why did I pull insulators back. Sent insulation back to H. DeJesus Kachay call at 2:00 pm and valve seems done. Will have to call TNG & HMT after she lets people in container

UPDATE: Valve now A-OK!

\* CORE moving H.P. Header out this afternoon

- Unit 2 66 H.P. outage, the tomorrow has been postponed until next week after get Unit 1 up. Don't want to start out of

- Torqued 1-1004-04-025 to 700 ft-lbs, did not slow down leak. HMT was to consider leak Repairs. GHT looking into this. If we fix this section, will be the first Q component we have looked at. Should be interesting. GHT trying to get leak Repairs in time.

#### Night Shift 4-16-90

- Leak Repair going into core for measurements on 022 valve. (can't get to 025 valve, because of contamination) Will have to get Leak Repair Eng. to tell us how heavy & how big clamp will be so our Engr. can do calculations.

- Will get H. Davis / R.C. Harvard to sign data sheets for LISA (190XXXX) on 4-17-90.

- Lee Mundale initiated MUO 190:1971 to adjust 8' Flyg Turb. control valve linkage. (To J. Sutphin) We will try to adjust at PCT. Until new Turb. Till Lee Mundale gets in core. MUO

- Leak Repairs just left side (025). They found the measurements to Torsis with ECST of design spec's at 1200 today. This will allow us to make evaluation by our Engr. (They will give us cast at 1200 also. My guess is 45)

- IPS dropped a bunch of rods unexpectedly (Shuttleworth &) but they rest and are doing fine. TDC is trouble shooting but hasn't found any clues. MUO # 190:1972 issued to TDC. Only thing found was transmission to 1 turn loose.

Monday Night Job  
4-16-90

- Ops started D/B 1-A at 0800 - MSE has Serr. when run is complete.
- Discovered leaking blind flange on H<sub>2</sub> destraining tank. (2<sup>nd</sup> flange from right side). Will have to purge H<sub>2</sub> w/ CO<sub>2</sub> for gasket replacement WRT # 6058. MSE is supporting ops. with procedure to roll spans for purge. MWS 19001973 to EBR (MSE)
- Can't locate parts for Drophiaum vlv. 1-1901-U4-366. For 1E018 220. Need several items or whole new valve. ~ Canadian.
- Targeted check vlv. 1-1906-U4-004 (man 19001968) and nuts moved considerably. Left grinding out until Ops. can reassemble.
- Pre-warming still not started. TEC found acceleration Ref. set wrong on controller's

0730 4-17-90

- Turbine warming MSV#2 Bypass
- H<sub>2</sub> seal oil destraining tank gasket repair  
MW0 19D 01973
- 1-1204-U4-025 Bonnet leak 14000543  
investigate leak repair
- Shutdown Bank E Rod movement
- MFNPT 'B' over-speed test

Nights  
Wed. 4/18/64

7:30 AM.

- 252 hrs. behind schedule
- 11% Reactor Pwr.
- Need LLRT on personnel hatch by 0400 4/19
- SGFP "B" Clr. being reinstated
- Need four other extraction valves freed for Turb. roll

⇒ MWD's 19000561, 571, 560, 2054 in full working. MSE  
560 & 561 comp. 2030.

Another MWD are down 19002055

⇒ MWG out of can to 2015. 025 not working.  
Need insulation reinstalled. Told to Jim Steele  
and he was going to notify Due Linsky in  
Blow. Insulation request in BBR.

⇒ Hopkins says they are getting ready to roll  
Jub. 2300. Asked Al Martin to give BBR  
call when actually happens.

- MSE installed 8 MP spool piece
- Ops was performing a Surv. on A1 NSCW #6 & 18 ofk Emerg. Started.  
The surv. has been calculate something in the sequencer panel during the test.  
When they did, it Emerg. started & set unbaud but available. It started  
at approx 0415 EOT. I was in control bus at the time for a Turb Test  
briefing. I went to the 18 ofk at approx. 0418 eot and wrote down all flashing  
annunciators. They were as follows: 1) Lo Temp. Lube oil  
2) Lo Freq. Fuel Oil  
3) Hi Δ? Fuel Oil Filter  
4) Hi Temp. Jacket Wtr. IN  
5) Hi Temp. Lube Oil OUT

92 PROJECT  
030537

Night Shift 4-18-90

Wed night  
4/18/90

- 6) H. ΔP Lube Oil Filter  
7) Gen. Under Freq.  
8) Emerg. Start

All cleared when reset except 'Emerg Start.' Other lights at push buttons on Eng. Control Panel lighted were 1) Ready To Load  
2) Running  
3) Starting  
4) Loss of Off Site Power ST sig

It ran for approx. 35 min. before Gps stopped from Control Room. Gps (Control Room) had same announcement as B off except for Lo Start Air come in at Control Room but not at H. ERT tag on controller at Off.

- \* Eng. has changed Turb test procedure to allow them to Roll Turb up & 100 RPM's so stop valves can open off of closed limit SW. that gives 5505 Relay K-42 activation upon Breaker closure & causes Gen/Turb. Trip. Attempting to pull Turb NCV (0550). Gps page announcement
- \* Check valve Bonnet Gasket replacement on 004 valve at B MFP. Gps setting up functional.
- \* 252 hrs behind sched, last 15 hrs in past 24 hrs  
Total mwo scope  $\Rightarrow$  1877  
mws Completed  $\Rightarrow$  1750 } WAG: =,
- \* Made announcement at 9:35 am that they were commanding turbine cold