

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
LICENSEE CODE 14 18 LICENSE NUMBER 25 28 LICENSE TYPE 30 57 CAT 58 5

CONT 01 REPORT SOURCE L 8 0 5 0 - 0 3 0 2 7 0 9 1 5 8 2 8 0 6 0 1 8 4 9  
DOCKET NUMBER 60 68 EVENT DATE 74 78 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 0540, on September 15, 1982, while performing surveillance on decay heat  
03 line "B", a valve (DHV-111) failed to control flow as intended. This is con-  
04 trary to the requirements of T.S. 3.5.2. Operability was restored at 1500 on  
05 September 16, 1982. Decay heat line "A" was available to provide emergency  
06 core cooling. There was no effect on public health or safety. This is the  
07 fifth occurrence for DHV-111 and the twenty-first report under this Specifi-  
08 cation.

09 SYSTEM CODE C F 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 18  
17 LER/RO REPORT NUMBER 8 2 23 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NFRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER B 0 8 0 0 26  
10 ACTION TAKEN A 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by an inoperable flow switch. The switch was replaced  
11 and calibrated, and DHV-111 was functionally tested with satisfactory re-  
12 sults. An engineering evaluation has determined the following additional  
13 corrective action to be implemented: (1) replace existing flow switch with  
14 electronic controls; (2) change out helical gears in valve actuator,

15 FACILITY STATUS F 28 % POWER 0 9 7 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine Inspection 32

16 ACTIVITY RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43  
8406050394 840601  
PDR AD0CK 05000302  
S PDR

20 PUBLICITY ISSUED DESCRIPTION N 44 DESCRIPTION 45

## SUPPLEMENTARY INFORMATION

REPORT NO. : 50-302/82-059/03X-1  
FACILITY : Crystal River Unit 3  
REPORT DATE : June 1, 1984  
OCCURRENCE DATE: September 15, 1982

### IDENTIFICATION OF OCCURRENCE:

The flow path of decay heat line "B" was found to be inoperable when a valve failed to control the flow as intended. This is contrary to Technical Specification 3.5.2.

### CONDITIONS PRIOR TO OCCURRENCE:

Mode 1, Power Operation (97%)

### DESCRIPTION OF OCCURRENCE:

At 0540, on September 15, 1982, while performing surveillance on decay heat line "B", a valve (DHV-111) failed to control flow as intended. After performing maintenance, the valve was functionally tested and declared operable at 1500 on September 16, 1982. Decay heat line "A" was available to provide emergency core cooling.

### DESIGNATION OF APPARENT CAUSE:

This event was caused by a stuck signal switch.

### ANALYSIS OF OCCURRENCE:

There was no effect on public health or safety.

### CORRECTIVE ACTION:

The signal switch was replaced and calibrated, and the valve was functionally tested satisfactorily. An engineering evaluation determined the following additional corrective action to be implemented:

1. Replace existing flow switch with electronic controls.
2. Change out helical gears in valve actuator.

### FAILURE DATA:

This was the fifth occurrence for DHV-111 and the twenty-first report under this Specification.