

GULF STATES UTILITIES COMPAN

APEA CODE 504

INVERTICAN POST DEFICE BUR 200 ST FRANCISCILLE LOUIS-ANA 70778

635-8084 046-8661

January 20, 1992 RBG- 36, 275 File No. G9.5, G15.4.1

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gertlemen:

River Bend Station - Unit 1 Docket No. 50-458/91-26

Gulf States Utilities Company provided its response to the Notice of Violation contained in Inspection Peport 50-452/91-26 in a letter dated December 20, 1991. Mr. Phil Havell, of NRC's Region IV, requested additional information converning our initial response. The following information is provided as requested.


GSU will perform the hydrogen mixing system test, which is referred to in Attachment 1 to our initial response letter, during the fourth refueling outage schedule to begin in March, 1992. This test will be performed on an 18 month basis as part of the emergency core cooling test. GSU also confirms that we will revise documentation to clearly describe the hydrogen igniter system function as redundant to the combustible gas control system function during a LOCA. This commitment was initially made by GSU during the enforcement conference held October 23, 1991, and was documented in the NRC's letter to GSU dated November 26, 1991. GSU will include this information in the next revision to the Updated Safety frailysis Report (USAR) scheduled for submittal prior to August 29, 1992.

If you have any additional questions please contact David Lorfing at (504) 381-4157.

Sincerely. Odell

Manager - Oversight River Bend Nuclear Group

TEOP



NRC Resident Inspector P.O. Box 1051 St. Francisville, LA 70775

U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

- 63

1

ce:

.