

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ][ ] [1]

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 [0][1] [C][O][F][S][V][I][ ] [2][0][0]-[0][0][0][0][0][0]-[0][0] [3][4][1][1][2][0] [4] [ ] [5]  
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T  
7 [0][1] REPORT SOURCE [L][6] [0][5][0][0][0][2][6][7] [7] [1][2][0][7][8][2] [8] [0][5][3][1][8][4] [9]  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] [ On December 7, 1982, with the reactor plant at low power operation and performing a [ ]  
[0][3] [ special leak isolation test, it was determined that a primary coolant to purification [ ]  
[0][4] [ cooling water system leak was present. The leak was identified as being in the "B" [ ]  
[0][5] [ purification train, helium purification cooler. The cooler is a single pass, coil [ ]  
[0][6] [ tube heat exchanger. The purification cooling water system is designed to confine any [ ]  
[0][7] [ leakage, therefore, there was no potential effect on public health or safety. This [ ]  
[0][8] [ event was reported per AC 7.5.2(b)4 of the Fort St. Vrain Technical Specifications. No ]  
7 8 9 similar reports. 80

[0][9] [C][G] [11] [E] [12] [X] [13] [H][T][E][X][C][H] [14] [C] [15] [Z] [16]  
9 10 SYSTEM CODE 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP. SUBCODE 15 VALVE SUBCODE  
[17] LER/RO REPORT NUMBER [8][2] [ ] [0][4][8] [ ] [0][3] [X] [ ] [1]  
21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO.  
ACTION TAKEN [C] [18] [Z] [19] [Z] [20] [Z] [21] [0][0][0][0] [Y] [23] [Y] [24] [N] [25] [G][2][1][0] [26]  
33 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPRD-4 FORM SUB. 40 PRIME COMP. SUPPLIER 41 COMPONENT MANUFACTURER  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] [ The failure of the cooler is attributed to corrosion caused by the normal operating [ ]  
[1][1] [ environment. For the short term, Public Service Company Change Notice 1599 was [ ]  
[1][2] [ initiated to modify the cooler piping to more efficiently vent the leaking gas to the [ ]  
[1][3] [ gas waste system. In February, 1984, the cooler was replaced with a qualified spare. [ ]  
[1][4] [ No further corrective action is anticipated or required. ]  
7 8 9 80

[1][5] [E] [28] [0][0][2] [29] [N/A] [30] [C] [31] [Special Leak Detection Test] [32]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

[1][6] [Z] [33] [Z] [34] [N/A] [35] [N/A] [36]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

[1][7] [0][0][0] [37] [Z] [38] [N/A] [39]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

[1][8] [0][0][0] [40] [N/A] [41]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

[1][9] [Z] [42] [N/A] [43]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

[2][0] [N] [44] [N/A] [45]  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

8406110224 840531  
PDR ADOCK 05000267  
S PDR

HooS

NRC USE ONLY

NAME OF PREPARER *[Signature]*

PHONE: (303) 785-2224




Public Service Company <sup>of</sup> Colorado

16805 WCR 19 1/2, Platteville, Colorado 80651

50-267

May 31, 1984  
Fort St. Vrain  
Unit #1  
P-84163

Mr. E. H. Johnson, Chief  
Reactor Project Branch 1  
Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, TX 76011



Reference: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Johnson:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/82-048, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)4.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/82-048.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Manager, Nuclear Production

Enclosure

cc: Director, MIPC

DW/djm

H005  
1/1

REPORT DATE: May 31, 1984  
Determined  
OCCURRENCE DATE: December 7, 1982

REPORTABLE OCCURRENCE 82-048  
ISSUE 1  
Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION  
PUBLIC SERVICE COMPANY OF COLORADO  
16805 WELD COUNTY ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/82-048/03-X-1

Final

IDENTIFICATION OF  
OCCURRENCE:

On December 7, 1982, with the reactor operating at less than 2% power, it was determined that the helium purification cooler (E-2302) on the "B" purification train had a primary coolant (helium) to purification cooling water leak. This occurrence was reported per Section AC 7.5.2(b)4 of the Fort St. Vrain Technical Specifications.

EVENT  
DESCRIPTION:

During the month of November, 1982, the reactor plant was maintained in either a non-critical or low power condition due to maintenance and primary coolant chemistry considerations. During this period, the presence of "gas" was noted within the purification cooling water system.

Normally, entrained gas is collected within the purification cooling water system expansion tanks and is then manually vented to the radioactive gas waste system. Because this venting process was becoming more frequent, investigations were undertaken to determine possible points of ingress. At the end of November, these investigations led to the process of isolating each major component served by the cooling water system.

On December 7, 1982, it was determined that a primary coolant (helium) to purification cooling water leak was present in the heat exchanger tubes within the "B" purification train cooler. Due to the location and design of the cooler, the exact location of the leak within the cooler was not known.

CAUSE  
DESCRIPTION:

| Component Failure.

| The "B" purification train cooler failure is attributed to corrosion caused by the normal operating environment of the cooler. The cooling tubes are encased within the shell of the cooler and are continually submerged in the water of the purification cooling water system. The primary coolant system (helium) is subject to various operating conditions, cycles, and transients which may not be conducive to maximum protection of system components.

| The purification system is designed to remove impurities (such as moisture) from the primary coolant helium and may be subject to corrosion by those impurities. However, the possibility of a tube leak, for any reason, does not pose a threat to the health and safety of the public as the entire purification cooling water system is designed for the PCRV Reference Pressure of 845 psig, and any gas that is vented from the system is contained and processed by the radioactive gaseous waste system in a normal manner.

| The cooler was manufactured by Graham Manufacturing Company, Inc. It is a shell and tube type heat exchanger, serial number 4851-68-2 with carbon steel coiled tubes rated at 845 PSI at 800°F. The shell is carbon steel rated at 845 PSI at 150°F.

CORRECTIVE  
ACTION:

| For the short term, Public Service Company Change Notice 1599 was initiated to modify the cooler piping to more efficiently vent the leaking helium gas to the gas waste system. Controlled Work Procedure 82-255 provided guidelines for the installation of the Change Notice.

| In February, 1984, during a plant outage for refueling and maintenance, the "B" purification train cooler was replaced with a qualified spare, using Controlled Work Procedure 83-197.

| No further corrective action is anticipated or required.

Prepared By: Duane L. Frye  
Duane L. Frye  
Senior Technical Services Technician

Reviewed By: Frank J. Novachek  
Frank J. Novachek  
Technical Services Engineering Supervisor

Reviewed By: L. Milton McBride  
L. M. McBride  
Station Manager

Approved By: Don Warembourg  
Don Warembourg  
Manager, Nuclear Production