LICENSEE EVENT REPORT (LER)									U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85													
PACILITY NAME (1)										1	DOCKET	NUMBE	R (2)	PA	PAGE (3)							
SAN ONOFRE NUCLEAR GENERATING STAT							ION HNIT 2						0	1510	1010	013161	1 1 0	F 012				
TITLE	(4)								/14.1 6									13101		1012		
EVENT DATE (5)			1	LER NUMBER (6)					REPORT DATE (7)				OTHER FACILITIES INVOLVED (8)									
MONTH	DAY	YEAR	YEA		SEQ. NUMBER		REV.	MONTH	DAY	YEAR	PACILITY NAMES						DOCKET NUMBER(S)					
				NOMBI			NOMBER				SONGS UNIT				NIT 3	3	0 5 0	0 0 3 6 2				
0 5	0 5	8 4	81	4	0 2	8 -	010	016	0 4	8 4							0 5 0 0 0					
	ERATIN		THIS	REPO	RT IS SUE	MITTE	D PURS	UANT TO	THE RE	EQUIREM	ENTS OF	F 1	0 CF	R §:	(Check	one or	more	of the foll	owing)	(11)		
N	10DE (9)	1		20.402(b)				20.40	20.405(c)			50.73(a)(2)(iv)						73.71(b)				
POW				20.405(a)(1)(i) 20.405(a)(1)(ii)				50.36(c)(1)			X 50.73(a)(2)(v)							73.71(c)				
(1)	0)	100					50.36(c)(2)				0.73	(a)(2)	(vii)			OTHER (Specify in Abstract						
			20.405(a)(1)(iii) 20.405(a)(1)(iv)				50.73(a)(2)(i) 50.73(a)(2)(ii)			X 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B)					4)	Form 366A)						
		L																				
				20.4	05(a)(1)(v)		50.73	3(a)(2)(ii	ii)		5	0.73	(a)(2)	(x)							
							LICE	NSEE C	ONTACT	FORT	HIS LER	ŧ (1	2)									
NAME							1-6-1										7,111,111	EPHONE	NUMBE	R		
		J.	G. H	AYN	ES, ST	ATIO	N MAN	AGER								7 1		41912	1-171	71010		
				CO	MPLETE O	NE LIN	E FOR	EACH CO	MPONEN	T FAILU	RE DESC	RI	BED	IN THI	S REP	ORT (1	3)					
CAUSE	AUSE SYSTEM COMPON		ENT	NT MANUPAC-			PRDS	CAUSES		YSTEM COMPONENT			ANUFAC-		REPORTABLE TO NPRDS							
X	WIE	IP	clv	FI	1217	N							1 1	1	1	1.1						
		11	1		11										1	11						
			-	SUPP	LEMENT	AL RE	PORT	EXPECT	ED (14)	1		***		-		-		MONTH	DAY	YEAR		
	UF (If yes, complete EXPECTED										SI	EXPECTED SUBMISSION DATE (15)										

On 5/5/84, at approximately 1530, with Unit 2 in Mode 1 at 100% power, and Unit 3 in Mode 3, Waste Gas Sampling System Pressure Control Valve 2/3PCV0582 failed open, resulting in flow through Sample Pump Discharge Relief Valve 2/3PSV0580 into the Waste Gas Discharge Header. Flow was routed to the Plant Vent Stack from the Waste Gas Discharge Header causing Plant Vent Monitor 2RE7808C to alarm. At 1840, an Unusual Event was declared because of the alarm on 2RE7808C and the fact that the release had not been terminated. At 1845, the release was terminated by isolating the Waste Gas Decay Tank and the Unusual Event was terminated. The release was calculated to have been approximately 405 curies of Xe-133. The concentration in unrestricted areas, when averaged over one hour, was 8.4E-7 microcuries per cubic centimeter (2.8 times the applicable concentration in Appendix B, Table II of 10 CFR 20 in unrestricted

X NO

Abstract (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

The Waste Gas Sampling System pressure control valve was replaced. In addition, alarm response procedures have been revised to ensure prompt identification of conditions warranting declaration of an Unusual Event and additional training on the radiation monitor alarm response will be provided to Operations personnel.

8406110257 840604 FDR ADOCK 05000361 S PDR

areas, when averaged over one hour).

IEZ?

NAC Form-366A

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104

IEXI	CONTINUATION	EAPIRES: 6/31/63									
PACILITY HAME(1)	DOCKET NUMBER (2)		LE	PAGE (3)							
		YEAR		SEQ. NUMBER		REV.		T		1	
SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2	0 5 0 0 0 3 6 1	8 4	-	0 2 8	-	0 0		OF	0	2	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 5/5/84, at approximately 1530, with Unit 2 in Mode 1 at 100% power, and Unit 3 in Mode 3, during sampling of a Waste Gas Decay Tank, Waste Gas Sampling System (EIIS System Code WE) Pressure Control Valve 2/3PCV0582 (EIIS Component Code PCV) failed open. Flow resulted through Sample Pump Discharge Relief Valve 2/3PSV0580 (EIIS Component Code RV) due to the increased pressure and allowed flow through to the relief valve discharge header. The relief valve discharge header exhausts into the Waste Gas Discharge Header downstream of the Waste Gas Discharge Header Automatic Isolation Valve 2/3FV7202 (EIIS Component Code FSV). The gas was then routed by the Waste Gas Discharge Header into the Plant Vent Stack causing Plant Vent Stack Monitor 2RE7808C (EIIS Component Code IL) to alarm. At 1840, an Unusual Event was declared because of the alarm on 2RE7808C and the fact that the release had not been terminated. The release was terminated at 1845 by isolating the Waste Gas Decay Tank from the Waste Gas Sample System which terminated the Unusual Event.

The release was calculated to have been approximately 405 curies of Xe-133. The concentration in unrestricted areas, when averaged over one hour, was 8.4E-7 microcuries per cubic centimeter (2.8 times the applicable concentration in Appendix B, Table II of 10 CFR 20 in unrestricted areas, when averaged over one hour). In accordance with the action statement of Technical Specification Limiting Condition for Operation (LCO) 3.11.2.1, actions were immediately initiated to terminate the release.

Subsequent inspection determined that Sampling System Pressure Control Valve 2/3PCV0582 had experienced a ruptured bellows and a replacement pressure control valve was installed.

As corrective action the appropriate alarm response procedure, Procedure S023-5-2.24, "Miscellaneous Utilities 61-A" has been revised to refer the operator to the emergency procedure S023-VIII-1 "Recognition and Classification of Emergencies," which requires prompt declaration of an Unusual Event. In addition, this event was discussed with operators during shift briefings.

The 1984-1985 licensed operator requalification program will include additional training concerning appropriate response to radiation monitor alarms, setpoints, and their relation to emergency action levels or Technical Specification actions.

There are no credible circumstances that would have increased the severity of this event.

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES STATION MANAGER

TELEPHONE (714) 492-7700

June 4, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-361

30-Day Report

Licensee Event Report No. 84-028

San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to 10 CFR 50.73(a)(2)(v) and 50.73(a)(2)(viii), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the waste gas sampling system. Since this occurrence involved a shared system between Units 2 and 3, a single LER for Unit 2 is enclosed per NUREG-1022. The health and safety of plant personnel or the public were not affected by this event.

If you require any additional information, please so advise.

JG Laynes

Enclosure: LER No. 84-028

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3) J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, NRC Region V)

Institute of Nuclear Power Operations (INPO)

IEZZ Add: IE/DEPER/EPB 1/1 NKR/DHF5/LQB