

Arizona Public Service Company

P.O. BOX 21866 • PHOENIX, ARIZONA 85038

RECEIVED  
1984

1984 JUN -4 AM 8 50

REGION V

May 29, 1984  
ANPP-29611-TDS/TRB

U. S. Nuclear Regulatory Commission  
Region V  
Creekside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director  
Division of Resident  
Reactor Projects and Engineering Programs

Subject: Interim Report - DER 84-25  
A 50.55(e) Potentially Reportable Deficiency Relating to  
Containment Supply Registers Would Not Cycle  
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between P. Narbut and T. Bradish on  
May 1, 1984

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the referenced telephone conversation. At that time, it was estimated that a determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim Report is attached. It is now expected that this information will be finalized by August 17, 1984, at which time a complete report will be submitted.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Production  
ANPP Project Director

EEVB/TRB:ru  
Attachment

cc: See Page Two

8406110287 840329  
PDR ADOCK 05000528  
S PDR

1E-27.1.

Mr. T. W. Bishop  
DER 84-25  
Page Two

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
D. B. Karner  
W. E. Ide  
D. B. Fasnacht  
A. C. Rogers  
B. S. Kaplan  
L. A. Souza  
D. E. Fowler  
J. Vorees  
J. R. Bynum  
J. M. Allen  
P. P. Klute  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
H. D. Foster  
D. R. Hawkinson  
L. E. Vorderbrueggen  
G. A. Fiorelli  
S. R. Frost  
J. Self  
D. Canady

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, GA 30339

INTERIM REPORT - DER 84-25  
POTENTIAL REPORTABLE DEFICIENCY  
ARIZONA PUBLIC SERVICE COMPANY (APS)  
PVNGS UNITS 1, 2, & 3

I. Potential Problem

During receiving inspection, Containment Supply Registers would not cycle. The tension wire (music wire) that is used for blade adjustments have become brittle and break off.

The same type supply registers have been installed into Units 1, 2 and 3. It has been identified that similar problems were observed in the installed units.

In the event of a shutdown, no air would be able to travel through those devices if the wire was broken.

II. Approach To and Status of Proposed Resolution

Bechtel engineering is currently studying this problem to determine reportability and technical justification for corrective action .

III. Projected Completion of Corrective Action and Submittal of the Final Report

Evaluation of this condition and submittal of the Final Report is forecast to be completed by August 17, 1984.