NRC FORM 365 Update Report - Previous Report Date 3/2/84 U. S. NUCLEAR REGULATORY COMMISSION (, 74) . Attachment to AECM-84/0289 LICENSEE EVENT REPORT Page 1 of 1 CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 - 0 0 3 LICENSE NUMBER 25 2 GG S 0 0 CON'T REPORT 0 1 5000 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 0 [] [On December 1, 1983 at 1420 hours while in Cold Shutdown, breaker 552-[0 3] 2105 from service transformer 21 tripped causing a loss of power to the 0 4 Division 1 ESF bus and all BOP loads. This resulted in a reactor scram [5] [signal, a loss of RPS buses, loss of shutdown cooling, RWCU isolation, [0]6] [Containment/Aux. Bldg. isolations, CRD "A" pump trip, SGTS initiation, [Control Room SFAU initiation, and an auto start of D/G 11. The diesel generator was paralleled to transformer 11 to restore normal power. SYSTEM CAUSE CAUSE COMP VALVE CODE SUBCODE COMPONENT CODE SUBCODE C (13) B (12) Z (15) EB ELECON(14 Z (16) 5 9 SEQUENTIAL OCCURRENCE REVISION REPORT REPORT NO LER RO C006 REPORT 1 18 1 5 013 х 1. IMBER PRIME COMP METHOD TAKEN ACTION EFFECT NPRD-4 COMPONENT (22 ANT ANUFACTURER Z (21) 0 010 18 (20) (25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] [] [Two wires shorted in the breaker handswitch causing the trip. The wires [1] were pinched between a plate and a cover box mounted inside panel 1H13-PB07. The wires and box have been temporarily altered to prevent pinch-1 2 [1] ling. Design change 84/3001 will remove the plate as a final resolution. 114 FACILITY METHOD OF OTHER STATUS (30) % POWER DISCOVERY DESCRIPTION (32) DISCOVERY Alarmed Condition (31 80 ACTIVITY AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) 1 (33) 1 (34) NA 6 11 OSURES ERSONNEL DESCRIPTION (39) 2 (38) NA 0 PERSONNEL RIFS DESCRIPTION (41) -E22 OSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION 8406110314 840530 PDR ADOCK 05000416 2 NA (42) PDR PUBLICITY DESCRIPTION (45) NRC USE ONLY 1(44 11111 69 68 80 Ron Byrd NAME OF PREPARER -PHONE -

## MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

May 50, 1984

NUCLEAR PRODUCTION DEPARTMENT

U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 2900 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File: 0260/L-835.0 Update Report - Loss of Power to Division 1 ESF Bus and BOP Loads LER 83-185/03 X-2 AECM-84/0289

This letter submits an update to a previous update report submitted on March 2, 1984. The event for which the report was submitted occurred on December 1, 1983, while the plant was in Cold Shutdown. Breaker 552-2105 from service transformer 21 tripped and caused a loss of power to the Division 1 ESF bus and all BOP loads. This resulted in a reactor scram signal, a loss of RPS buses, loss of shurdown cooling, RWCU isolation, Containment/Auxiliary Building isolations, CRD "A" pump trip, SGTS initiation, Control Room SFAU initiation, and an automatic start of Diesel Generator 11. Action (a) of Technical Specification 3.4.9.2 was met. This was reported pursuant to Technical Specification 6.9.1.13.b.

This update revises the estimated completion date for corrective action. Attached is LER 83-185/J3 X-2 which is a final report.

Yours truly,

L. F. Dale Director of Nuclear Licensing & Safety

EBS/SHH:rg Attachment

cc: See next page

OFFICIAL COPY

IE22

Member Middle South Utilities System

## MISSISSIPPI POWER & LIGHT COMPANY

AECM-84/0289 Page 2

cc: Mr. J. B. Richard (w/a) Mr. R. B. McGehee (w/o) Mr. N. S. Reynolds (w/o) Mr. G. B. Taylor (w/o)

> Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555