	LICENSEE EVENT REPORT EXHIB	IT A
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
7 1 1 8	1 A R A N 0 2 2 1 0 0 - 0 0 0 0 0 0 0	15
1 1 0 1 1 1	REPORT L 6 0 5 0 0 0 3 6 8 17 1 0 3 2 3 7 9 18 10 6 0 7 8 4 5 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE	19
10121	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During a review of the HVAC installation, it was identified that fire dampers were not installed as required	
10131	Iby architectural design specifications. Nine of these dampers are for safety related area protection. The	-
10141	laffected safety related areas would not be adequately isolated in the event of a fire. There have been no	
10151	Isimilar occurrences. This event is reportable per Technical Specification 6.9.1.9(b).	1
10161		-
10171		-
18101		1
, 8	SYSTEM CAUSE CAUSE COMP VALVE	80
10191	CODE	
, ,	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT REVI	SION
17	LER/RO EVENT YEAR REPORT NO. CODE TYPE NO. REPORT 1 7 9 1 11 0 2 1 6 1 / 1 1 0 1 3 1 X 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	NUMBER 1_21 22 23 24 26 27 28 29 30 31 32	1
T,	CTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT AKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB SUPPLIER MANUFACTURER	
3	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	126
13.0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27	
11101	Cause due to installation Quality Assurance. A continuous fire watch was immediately established for all	_'
	laffected safety related areas as required by Technical Specification 3.7.11. The fire dampers cited above	_'
1121	have been installed as required by design specifications.	_'
11131		_1
7 8	9	80
	FACILITY STATUS % POWER OTHER STATUS DISCOVERY DESCRIPTION	
7 8		132
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE	
7 8	9 10 11 44 45 8	136
13.3.	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION	
7 8	9 11 12 13	139
17.01	PERSONNEL INJURIES NUMBER DESCRIPTION	
7 8	9 11 12 8	141
11:01	11 12 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 1 Z 142 NA	
11191	PDR ADOCK 05000368	143
13101	PUBLICITY S POR ISSUED DESCRIPTION NRC USE ONLY	
7 8	9 10 145 1 1 NA 68 69 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 80
	NAME OF PREPARER: Patrick Rogers PHONE: (501) 964-3100	



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 June 7, 1984

2CANØ684Ø3

U. S. Nuclear Regulatory Commission Docum: Control Desk Washing on, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6 Licensee Event Report No. 79-026/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.(b), attached is the subject report concerning the failure to install fire dampers as required by architectural design specifications. This is an update to a previous submittal dated May 1, 1979.

Very truly yours,

John R. Marshall Manager, Licensing

JRM: RJS: ac

Attachment

cc: Mr. Richard P. Denise, Director
Division of Resident Reactor Projects
and Engineering Programs
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

IE22