
COMPANY Houston Lighting & Power P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

ST-HL-AE-1091 File No.: G12.108



15-2711

Mr. John T. Collins Regional Administrator, Region IV Nuclear Regulatory Commission 611 Ryan Plaza Dr., Suite 1000 Arlington, Texas 76012

Dear Mr. Collins:

The Light

South Texas Project Units 1 & 2 Docket Nos. STN 50-498, STN 50-499 Final Report Concerning Hayward-Tyler Pumps

On February 16, 1983, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P), notified your office of a potentially reportable item concerning pumps manufactured by the Hayward-Tyler Pump Company (HTPC).


In our letter of March 9, 1983 (reference ST-HL-AE-940), HL&P indicated that the next report concerning this item would be submitted sixty (60) days after receipt of the NRC final report. Although the NRC has not yet released their final report, HL&P believes that sufficient information is available to submit a final report. Therefore, the attachment to this letter contains our final report.

If you should have questions concerning this item, please contact Mr. Michael E. Powell at (713) 993-1328.

Very truly yours,

Executive Vice President

MEP/mpg Attachment: Final Report Concerning Hayward-Tyler Pumps



Houston Lighting & Power Company

cc:

Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, DC 20555

Victor Nerses, Project Manager U.S. Nuclear Regulatory Commission 7920 Norfolk Avenue Bethesda, MD 20016

D. P. Tomlinson Resident Inspector/South Texas Project c/o U.S. Nuclear Regulatory Commission P. O. Box 910 Bay City, TX 77414

M. D. Schwarz, Jr., Esquire Baker & Botts One Shell Plaza Houston, TX 77002

J. R. Newman, Esquire Newman & Holtzinger, P.C. 1025 Connecticut Avenue, N.W. Washington, DC 20036

Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

E. R. Brooks/R. L. Range Central Power & Light Company P. O. Box 2121 Corpus Christi, TX 78403

H. L. Peterson/G. Pokorny City of Austin P. O. Box 1088 Austin, TX 78767

J. B. Poston/A. vonRosenberg City Public Service Board P. O. Box 1771 San Antonio, TX 78296 ST-HL-AE-1091 File Number: G12.108 Page 2

Brian E. Berwick, EsquireAssistant Attorney General for the State of TexasP. O. Box 12548, Capitol StationAustin, TX 78711

Lanny Sinkin Citizens Concerned About Nuclear Power 114 W. 7th, Suite 220 Austin, TX 78701

Robert G. Perlis, Esquire Hearing Attorney Office of the Executive Legal Director U.S. Nuclear Regulatory Commission Washington, DC 20555

Charles Bechhoefer, Esquire Chairman, Atomic Safety & Licensing Board U.S. Nuclear Regulatory Commission Washington, DC 20555

Dr. James C. Lamb, III 313 Woodhaven Road Chapel Hill, NC 27514

Judge Ernest E. Hill Hill Associates 210 Montego Drive Danville, CA 94526

William S. Jordan, III, Esquire Harmon & Weiss 1725 I Street, N.W. Suite 506 Washington, DC 20006

Citizens for Equitable Utilities, Inc. c/o Ms. Peggy Buchorn Route 1, Box 1684 Brazoria, TX 77422

Revised 04/03/84

ST-HL-AE-1091 Attachment Page 1 of 2

South Texas Project Units 1 & 2 Final Report Concerning Hayward-Tyler Pumps

I. Summary

As a result of an NRC inspection of the Hayward-Tyler Pump Company (HTPC), several instances of nonconformance with the requirements of the HTPC Quality Assurance (QA) program were identified. The South Texas Project (STP) was specifically mentioned in two of the nonconformances. These two instances were programmatic in nature and not hardware related. To date, a significant safety hazard has not been identified.

II. Description of the Incident

On February 16, 1983, pursuant to 10CFR50.55(e), Houston Lighting & Power Company (HL&P), notified the NRC Region IV of a potentially reportable item concerning pumps manufactured by HTPC.

HL&P received a copy of the NRC Inspection/Investigation Report of HTPC (Inspection Reports 82-01, 02, 03, 04; Docket No. 99900345) from the NRC resident inspector at the STP on February 9, 1983, and performed a preliminary review of the findings in the subject report. These inspections/investigations were conducted by the NRC as a result of allegations received by the NRC pertaining to the HTPC QA program. The NRC concluded that several instances of nonconformances with the requirements of the HTPC QA program were identified and that deficiencies existed in the implementation of the HTPC QA program. The report also identified that uncertainties still remain regarding the quality of certain aspects of hardware associated with nuclear ASME Code pumps or pump parts delivered by HTPC to NRC licensees during the period 1977-1981 and that the NRC staff was currently evaluating the significance of the identified nonconformances and uncertainties with respect to performance reliability of pumps furnished to various nuclear sites and the effects of postulated failures on the specific systems in which the pumps are installed. Lastly, the report identified that upon receipt of the HTPC response to the inspection report, the staff would complete its evaluation and communicate the results to affected licensees.

HL&P purchased fifty-two (52) HTPC pumps for installation at STP. Twenty-eight (28) were originally intended to be installed in safetyrelated systems. Of these 28 safety-related HTPC pumps, only 22 will now be installed at STP.

ST-HL-AE-1091 Attachment Page 2 of 2

A list of the affected pumps and their service application is as follows:

Quantity	Service Application
2/unit	Reactor Makeup Water pumps
3/unit	Essential Cooling Water screen wash booster pumps
2/unit	Component Cooling Water pumps
3/unit	Essential Cooling Water pumps

Previously, the Electrical Auxiliary Building (EAB) chilled water system was to have utilized 6 HTPC pumps (3/unit); however, the system has been redesigned and the 6 subject pumps will not be used at the STP.

The review of the report by HL&P identified only two instances where the STP is specifically mentioned. For these two instances, the concerns appear to be programmatic in nature and not hardware related (i.e., a significant safety hazard has not yet been identified).

In addition NRC IE Bulletin 83-05, "ASME Nuclear Code Pumps and Spare Parts Manufactured by the Hayward-Tyler Pump Company," has been reviewed by HL&P. The requirements of the Bulletin have been addressed by HL&P and appropriate actions are being implemented as identified in our response to the Bulletin (ST-HL-AE-985, dated August 12, 1983). The response identified that (a) HL&P will develop inservice test requirements for each affected HTPC pump installed at the STP in accordance with ASME Section XI, (b) a performance test will be performed on each HTPC pump in accordance with the HTPC "Expanded Commission Tests and Inspections" procedure as submitted with the subject Bulletin and (c) an ASME Code system Hydrostatic Pressure Test will be performed in accordance with our Quality Control and Construction Site Procedures.

III. Corrective Action

Although no specific correction action is required to resolve this deficiency, HL&P will be testing the pumps as delineated in our response to NRC IE Bulletin 83-05.

IV. Recurrence Control

No specific recurrence control measures are required.

V. Safety Analysis

No hardware related deficiencies have been identified. Therefore, pursuant to 10 CFR 50.55(e) there would be no adverse effect on the safety of operation of STP.