9-43)	-					LIC	ENSE	E EVE	NT RE	PORT (LER)	100	PROVED OMB NO PIRES BOTAS	31500104	
ACILITY NAME (1)								D	OCKET NUMBER	2)	PAGE (3)				
			Salle	County	Stat	ion Un	it 1				0	1510101	0 13 1 713	1 OF 0 3	
TITLE (4)		El	ectri	cal Cab	le Pe	netrat	ions	Inop	erabl	е					
EVENT DATE ISI LER NUMBER ISI					REPORT DATE (7) OTH				OTHER P	ER FACILITIES INVOLVED (8)					
MONTH DAY		YEAR	YEAR	SEQUE	SER	REVISION	MONTH	DAY	YEAR	PACILITY NAMES			DOCKET NUMBERISI		
										LaSall	le Co. Uni	t 2	0 15 10 10	10131714	
0 5	1 7	814	814	0 2	16	00	0 6	0 8	8 4				0 5 5 0	, 0 , 1 ,	
		-	THIS R	EPORT IS BUS	MITTED P	URSUANT 1	TO THE R	EQUIREM	ENTE OF	0 CFR & 10	heck one or more o	f the following) (1))		
MODE (8)		1	28	20.402(b)						80.73(a)(2)(iv)		73.71(6)			
POWER LEVEL			2	20.406(a)(1)(II 20.406(a)(1)(B)				90.36(e)(1) 90.36(e)(2)			80,73(a)(2)(v) 80,73(a)(2)(vii)		73,71(e) X OTHER (Specify in Abstract below and in Taxt, NRC Form		
		191	8 2												
			20.408(s)(1)(W) X				\$0,73(a)(2)(i)			80.73(a)(2)(viii)(A)			366AJ		
			7	20.406 is 1(1)(iv)				80,73(a)(Z)(E) 80,73(a			90.73(a)(2)(HH)(8	a)(2)(wH)(B)		Special Report	
			20 a08 (a) (1) (v)				80.73(a)(2)(Hi) 86.73(a)(2)(8C.73(a)(2)(a)	u l				
							ICENSEE	CONTAC	FOR TH	S LER (12)			TELEPHONE NUM		
NAME												AREA CODE	TELEPHONE NON	.een	
	E	dwar	d A.	McVey,	Exten	sion 7	771					811 15	3 5 7 -	1 617 16 П	
				COM	PLETE ON	E LINE FOR	EACH C	OMPONEN	T FAILUP	E DESCRIBE	D IN THIS REPOR	T (13)			
CAUSE	SYSTEM	CON	PONENT	MANUF		PORTABLE TO NPRDS			CAUS	ESYSTEM	COMPONENT	MANUFAC	REPORTABLE TO NPRDS		
		-		-						1					

ABSTRACT (Limit to 1400 species, i.e., approximately fiftgen single-spece typewritten lines) (16

SUPPLEMENTAL REPORT EXPERTED (14)

D Z Z S E A L X X X X

YES III YM COMMIN EXPECTED SUBMISSION DATE!

ABSTRACT

On May 17, 1984, at approximately 1300, Transco personnel were performing repairs on electrical fire penetrations in the Unit 1 Auxiliary Electrical Equipment Room when they identified an unsealed conduit penetrating a firestop. After further investigation, a total of 18 cabinets/panels in the Auxiliary Electrical Equipment Room were identified as having unsealed conduit penetrating the field of the firestop. The Technical Staff notified the Station Fire Marshal. An hourly fire watch was in effect. Repairs were initiated by the Technical Staff. Repairs were completed on May 22, 1984 under Work Request L36892. The Technical Staff also performed a reinspection of cabinets/panels in the Units 1 and 2 Control Rooms and Auxiliary Electrical Equipment Rooms (Special Test LST 84-127). The reinspection identified six other cabinets in the Control Room with unsealed conduit. These penetrations were sealed on June 1, 1984 under Work Request L37240.

8406180328 840608 PDR ADOCK 05000373 S PDR

TEDD.

YEAR

MONTH

DAY

U.S. NUCLEAR REGULATORY COMMISSIO LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85 PAGE (3) DOCKET NUMBER (2) LER NUMBER ISI LaSalle County Station Unit 1 0 |5 |0 |0 |0 |3 | 7| 3 8 |4 - 0 |2 | 6 - 0 |0 | 0 |2 | OF 0 |3

TEXT If more space is required, use additional NRC Form 3664's) (17)

EVENT DESCRIPTION 1.

On May 17, 1984, at approximately 1300, Transco personnel were performing repairs on electrical fire penetrations in the Unit 1 Auxiliary Electrical Equipment Room when they identified an unsealed conduit penetrating a firestop. After further investigation, a total of 18 cabinets/panels in the Unit 1 Auxiliary Electrical Equipment Room were identified as having unsealed conduit penetrating the field of the firestop. Transco informed the Technical Staff of the deviations. The Technical Staff notified the Station Fire Marshal and initiated a work request to seal the conduit. The cabinets/panels identified were:

1H13-P613	1H13-P631
1H13-P615	1H13-P644
1H13-P616	1H13-P654
1H13-P618	1H13-P655
1H13-P621	1H13-P659
1H13-P622	1C61-P001
1H13-P623	1PA03J
1H13-P628	1PA08J
1H13-P629	1PA12J

11. CAUSE

The unsealed conduit was not identified in prior inspections as the surveillance procedure used to meet requirements specified in Technical Specification 4.7.6.1.C does not directly provide for the inspection of and acceptance criteria for conduit penetrating an electrical firestop.

111. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The probable consequences of the occurrence were minimal since an hourly fire watch is in effect in the Auxiliary Electrical Equipment Room at all times and fire detection is operable.

CORRECTIVE ACTION IV.

Repairs and inspections were completed on May 22, 1984 under Work Request L36892. Action Item Record (AIR) 1-84-67087 has been issued to revise Technical Staff Surveillance LTS 1000-10 to include inspection of conduit through electrical penetrations. Special Test LST 84-127 was written and included a reinspection of all cabinets/panels in the Units 1 and 2 Auxiliary Electrical Equipment Rooms and Control Rooms (AIR 1-84-67088). The Technical Staff performed the inspection. Six cabinets in the Control Room were identified as having unsealed conduit penetrating the firestop. These penetrations were sealed under Work Request L37240 on

NAC Ferm MEA 19 631	LICENSEE EVENT RE	APPROVED OME NO. 3150-0104 EXPIRES. 8/31/85				
FACILITY NAME (1)		DOCKET NUMBER (2)	T	LER NUMBER (6)	PAGE (3)	
			YEAR	SEQUENTIAL REVISION		
LaSalle Cou	unty Station Unit 1	0 5 0 0 0 3 7 3	8 4 -	-01216-010	0 3 0 0 3	

V. PREVIOUS OCCURRENCES

No other occurrences of unsealed conduit through electrical penetrations have been reported. LER 84-024-00/50-373 reported the identification of two inoperable electrical penetrations due to personnel errors.

VI. NAME AND TELEPHONE NUMBER OF PREPARER

Edward A. McVey, (815)357-6761, Extension 771.

June 8, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

Reportable Occurrence Report #84-026-00, Docket #050-373 is being submitted to your office in accordance with 10 CFR 50.73.

G. J. Diederich Superintendent LaSaile County Station

GJD/MLD/kg

Enclosure

xc: NRC, Regional Director

INPO-Records Center

File/NRC