LICENSEE EVENT REPORT (LER)							U.E. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85										
FACILITY NAME (1)								DOCKET NUMBER (2)				PAGE (3)					
Browns Ferry - Unit 3								0  5   0   0				10 12 9 16 1 OF					
TITLE 14		Pum	p Inst	rument 1	Nozzle (	racki	ing										
EVENT DATE (6) LER NUMBER (6)									OTHER	ER FACILITIES INVOLVED (B)							
MONTH	DAY	YEAR	YEAR BEQUENTIAL REVOIT			MONTH	DAY	YEAR		FACILITY NA	NAMES DOCKE			ET NUMBER(S)			
THE REAL PROPERTY.				-	NUMBER			+				0   5   0   0   0   1   1					
015	1 7	8 4	8 4 -	0006	-00	0 6	0  8	814				0	1510	10	. 0 .		
	RATING		THIS REPO	AT IS SUSMITTI	D PURSUANT	TO THE R	EQUIREM		CFR 8: 10	Check one or more	of the following) (	-	1-1-	1	1-1		
MODE (9) N			20.402(b)			20.408(c) 80.38(c)(1) 80.38(c)(2)				80.73(a)(2)(iv)			73.71(b)				
POWER LEVEL O O O		20.405(a)(1)(i) 20.405(c)(1)(ii)			50.73(a)(2)(v) 50.73(a)(2)(vii)					73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form							
(10) 0,00																	
			20.40	5(a)(1)(iii)		50.73(a	)(2)(i)			50,73(a)(2)(viii)	(A)		366A		TAXL, NA	L Form	
			20.408(a)(1)(iv) X						50.73(a)(2)(vili	(6)							
			20.40	5(a)(1)(v)		50,73(a				50.73(a)(2)(x)		1					
NAME						LICENSEE	CONTACT	FOR THIS	LER (12)			TEI	EPHON	E AU IM	RED		
David L. Smith										AREA CODE	-	EFROIT	- 14010				
	Dav	Id L	· SELL								2,05	7	,2 ,9	,0	18 6	151	
		Res		COMPLETE	ONE LINE FOR	R EACH CO	DMPONEN	T FAILURE	DESCRIBE	D IN THIS REPO	ORT (13)			-	-	-	
CAUSE	SYSTEM COMP		DNENT	NENT MANUFAC REPORTOR				CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTAL TO NPR					
		1		111						1.1.1	1,,,						
					Total St							1					
				111	Mar .				11	111	1111						
				BUPPLEM	ENTAL REPORT	EXPECT	ED (14)				EXPEC	TED		HTMON	DAY	YEAR	
X YES (IF yes, complete EXPECTED SUBMISSION DATE)					□ NO				SUBMISSION DATE (16)			0,8	1,5	8,4			

Based on information received from a Nuclear Regulatory Commission (NRC) publication "Inside NRC," the Tennessee Valley Authority (TVA) inspected 10 additional welds on the jet pump instrument nozzles. Of these, two welds were determined to need repair. These welds will be repaired by the weld overlay procedure to be completed prior to unit startup. TVA has an inspection plan which is carried out during refueling outages for identifying defective welds. These additional welds will be examined in upcoming units 1 and 2 refueling outages.

8406190216 840608 PDR ADOCK 05000296 S PDR JE22

NAC Form 386A

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO 3150-0104

	EAT-11120 - 0-0-1-0-0										
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)						PAGE (3)		
Power France Well 2		YEAR	R SEQUENTIAL REVISION NUMBER								
Browns Ferry - Unit 3	0  5  0  0  0  2  9	6 8 14	_	0016	_	010	0  2 OF	0  2			

TEXT (If more space is required, use additional NRC Form 366.(2) (17)

During normal operation Unit 1 was operating at 95 percent, Unit 2 at 59 percent, and Unit 3 was in a refueling outage. Only Unit 3 was affected by this event.

Additional welds were inspected on the jet pump instrument nozzles (NZL) based on information received via a Nuclear Regulatory Commission (NRC) publication "Inside NRC." Ten welds were examined and two were determined to need weld repair. "Weld overlay" repairs on both nozzles will be complete prior to returning the unit to operating status. These two 4-inch reducer "safe-end" welds had axial indications up to 82 percent through wall in the base metal. One of the "safe ends" has two indications visible from the outside. These two welds are suspected to be a product of intergranular stress corrosion cracking due to the "safe ends" being moderately sensitized.

TVA is presently in an inspection program to ultrasonically test all twelve recirculation reactor vessel (RPV) penetrations (FEN) for indications of intergranular stress corrosion cracking. Metallography (acid etching) will be done on two out the ten recirculation discharge reactor vessel penetrations and on both of the inlet penetrations. The jet pump instrument nozzle welds will be inspected during the upcoming units 1 and 2 refueling outages (Unit 2 refueling cutage - August, 1984) and depending on the results of the unit 3 ultrasonic test inspection program a decision will be made on the extent of units 1 and 2 ultrasonic test inspections that will be needed. If an opportunity of a short outage presents itself prior to the next refueling outage, Unit-1 will be checked out at that time.

A contributing factor in this issue may be that Units 2 & 3 were procurred from IHI, a Japaneese vendor, while Unit 1 was bought from Coulter Steel & Forging Co. The certified material test reports from the Units 2 & 3 vessel penetrations show a higher carbon content than those of U-1. Thus, also pointing to more susceptibility for sensitization areas.

If the cracked welds had failed during normal operation, a minimum of reactor coolant would be lost because these welds were on a 4-inch reducer to the jet pump instrument nozzle "safe-end" and the penetration has twelve 1-inch instrument lines inside it. These instrument lines have .004 tolerance between themselves and the 4-inch penetration. Therefore, a minimum flow would have been released with the drywell sump pumps unidentified leakage alerting the licensed unit operator to the line break. Since the unit is analyzed for a loss of coolant accident for a 24-inch line, these two jet pump instrument nozzle breaks would be negligible.

## Previous similar events

BFRO-50-259/83-23 BFRO-50-260/82-40 BFRO-50-296/79-19

Responsible Plant Section

N/A

## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

P. 0. Box 2000
Decatur, Alabama 35602

June 8, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFR0-50-296/84006

The enclosed report provides details concerning jet pump instrument nozzle cracking. This report is submitted in accordance with 10 CFR 50.73 (a)(2)(ii).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

G. T. Jones

Power Plant Superintendent Browns Ferry Nuclear Plant

Enclosure

cc (Enclosure):

Regional Administrator
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 2900
Atlanta, GA 30303

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

NRC Resident Inspector, BFN

IE22