

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

June 14 1984 P12:53

BLRD-50-438/84-34

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEVILLE NUCLEAR PLANT UNIT 1 - CONDUIT SUPPORT STIFFENER PLATES NOT  
INSTALLED PER DRAWING - BLRD-50-438/84-34, - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
P. E. Fredrickson on May 10, 1984 in accordance with 10 CFR 50.55(e) as NCR  
3069. Enclosed is our first interim report. We expect to submit our next  
report by September 28, 1984.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*D S Kammer*

for L. M. Mills, Manager  
Nuclear Licensing

Enclosure

cc: Mr. Richard C. DeYoung, Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center (Enclosure)  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8406190249 840604  
PDR ADOCK 05000438  
S PDR

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 1  
CONDUIT SUPPORT STIFFENER PLATES NOT INSTALLED PER DRAWING  
BLRD-50-438/84-34  
NCR 3069  
10 CFR 50.55(e)  
FIRST INTERIM REPORT

Description of Deficiency

During a quality control audit, it was identified that two stiffener plates for support FF-768-6, Mark No. 31, were installed approximately 2 inches from the proper location as shown on TVA design drawing 4RA0560-X2-32 R3. The support is a seismic category I support for electrical conduit carrying safety-related cables. It is located inside the unit 1 Reactor Building.

Interim Progress

TVA is reanalyzing the as-built configuration for support FF-768-6, Mark No. 31, to determine whether modifications are necessary. TVA is also conducting an investigation into the possibility of other supports being affected by this deficiency.