



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

RLB-92-031

January 31, 1992

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Reference: Quad Cities Nuclear Power Station
Docket Number 50-265, DPR-30, Unit Two

Enclosed is Licensee Event Report (LER) 92-002, Revision 00, for Quad Cities Nuclear Power Station.

This report is submitted in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73(a)(2)(ii). Any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded, or that resulted in the nuclear plant being in a condition that was outside the design basis of the plant.

Respectfully,

COMMONWEALTH EDISON COMPANY
QUAD CITIES NUCLEAR POWER STATION

R. L. Bax
R. L. Bax
Station Manager

RLB/TB/plm

Enclosure

cc: J. Schrage
T. Taylor
INPO Records Center
NRC Region III

FEZ
11

LICENSEE EVENT REPORT (LER)

Form Rev 2.0

Facility Name (1) Quad Cities Unit Two
 Docket Number (2) 0 | 5 | 0 | 0 | 0 | 2 | 6 | 5 | 1 | of | 0 | 4
 Page (3) 1 of 4
 Title (4) Exceedance of Technical Specification Local Leak Rate Test Limit 0.6 La While Testing the Containment Purge Four Valve Volume 2-1601-21, 22, 55 and 56

Event Date (5)			LER Number (6)			Report Date (7)			Other facilities Involved (8)	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)
0 1	0 3	9 2	9 2	0 0 2	0 0	0 1	3 0	9 2		0 5 0 0 0 0 5 0 0 0

OPERATING MODE (9) 2

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)

20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)
20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)
20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vii)	Other (Specify in Abstract below and in Text)
20.405(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	
20.405(a)(1)(iv)	X 50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

Name	TELEPHONE NUMBER
David P. Kunzmann, LLRT Coordinator Ext. 2162	AREA CODE 3 0 9 6 5 4 - 2 2 4 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

X Yes (If yes, complete EXPECTED SUBMISSION DATE) | NO

Expected Submission Date (15) 0 | 8 | 0 | 1 | 9 | 2

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

ABSTRACT:

On January 1, 1992, Quad Cities Unit Two was shutdown for refueling and maintenance (Q2R11). On January 3, 1992 at 0715 hours while performing Local Leak Rate Testing (LLRT) of the containment purge four valve volume 2-1601-21, 22, 55 and 56, it was determined that the Technical Specification 3.7.A.2.a.2 limit of 293.75 SCFH (0.6 La) was exceeded.

An Emergency Notification System (ENS) phone call was completed on January 3, 1992 at 1029 (EST) hours in accordance with 10CFR50.72(b)(2)(i).

The cause of the excessive leakages will not be known until repairs have been completed. A supplemental report will be issued to address the causes and corrective actions taken to bring the combined leakage to within Technical Specification limits. This report is being submitted to comply with 10CFR50.73(a)(2)(ii).

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Form Rev 2.0

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			Revision Number	Page (3)		
		Year	Serial Number	Event Number		Page	Of	Total Pages
Quad Cities Unit Two	0 5 0 0 0 2 6 5	9 1	0 0 2 1	0 0	0 3	OF	0 4	

TEXT Energy Industry Identification System (EIIS) codes are identified in the text as {X}

The cause of the excessive leakages cannot be determined until repairs have been completed and the valves and components have been retested. A supplemental report documenting the repairs and corrective actions taken will be issued.

D. SAFETY ANALYSIS OF EVENT:

The safety consequences of the event were minimal since the maximum pathway leakages are used for comparison to the total allowable leakage for Type B and C tests (0.6 La), which is a conservative method. The summation of the maximum pathway leakage rates assumes that for each potential air leakage through primary containment [NH], the best valve or barrier fails and the leakage through the pathway equals the leakage of the worst valve or barrier.

The summation of the minimum pathway leakages, which yields a more realistic total leakage, is used for determining the acceptance of the Type A test results. This method assumes that the best valve or barrier for each pathway remains intact. Although not all of the required as found Type B and C testing is complete, the total as found minimum pathway leakage for the pathways already tested are still within the allowable limit (0.75La).

The minimum pathway leakage will not be known until the containment purge four valve volume can be re-tested after a modification is made to the test method. This modification will be completed during this current outage.

E. CORRECTIVE ACTIONS:

The cause of the excessive leakage will not be known until repairs have been completed. The immediate corrective action was to initiate work requests to repair 2-1601-21 (Drywell purge) valve. A supplemental report will be issued to document the causes and corrective actions taken to bring the combined and the individual leakages below Technical Specification limits (NTS #265 200 92 00201).

F. PREVIOUS EVENTS:

254/90-029 Leak rate from all valves and penetrations including MSIVs on Unit 1 exceeded the Technical Specification Limit.

265/90-003 Leak Rate from all valves and penetrations including MSIVs on Unit 2 exceeded the Technical Specification Limit.

254/89-014 Leak Rate from all valves and penetrations including MSIVs on Unit One in excess of Technical Specification Limit.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Form Rev 2.0

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				Page (3)			
		Year	Sequential Number	Revision Number					
Quad Cities Unit Two	0 5 0 0 0 2 6 5	9 1	- 0 0 2	- 0 0	0 4	0 4	0 4	0 4	

TEXT Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]

- 265/88-007 Leak rate from all valves and penetrations excluding MSIVs on Unit Two in excess of Technical Specification Limit.
- 254/87-016 Leak rate from all valves and penetrations excluding MSIVs on Unit One in excess of Technical Specification Limit.
- 265/86-014 Leak rate from all valves and penetrations excluding MSIVs on Unit Two in excess of Technical Specification Limit.

These are the most recent related events; other similar events have occurred prior to 1986.

G. COMPONENT FAILURE DATA:

Component failure data will not be available until repairs have been completed. This data will be included in a supplemental report which will be completed following valve repairs.