June 12, 1984

Mr. James G. Keppler Regional Administrator U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Subject: Braidwood Station Units 1 and 2

10 CFR 50.55(e) Updated Final Report

Cracked Battery Cells

NRC Docket Nos. 50-456 and 50-457

Reference (a): E. D. Swartz letter to J. G. Keppler

dated December 2, 1983

Dear Mr. Keppler:

On December 2, 1983, the Commonwealth Edison Company provided Reference (a) to document a deficiency reportable pursuant to 10 CFR 50.55(e). For your tracking purposes, this deficiency was assigned Number 83-14.

The purpose of this letter is to provide updated information relative to the cause of the cracking of the Gould Battery Cells and actions taken by the Commonwealth Edison Company to prevent additional occurences. Additionally, Reference (a) stated that the defective cells would be replaced. This action has since been completed.

CRACK ANALYSIS

Based on the GNB Batteries Inc. failure analysis, it was determined that the cracking was caused by the use of excessive quantities and/or prolonged exposure to a cleaning fluid. The cleaning fluid contained Trichlorethylene which acts as a stress releasing agent when it comes in contact with plastic materials.

ACTION TAKEN TO PREVENT RECURRENCE

Braidwood site specific Procedure BWHS-4009-002 is being revised to include direction as to the acceptable method of cleaning batteries. No solvents are allowed. Interim directions have been provided to L. K. Comstock and Operating. In addition, periodic battery inspections will require checks for physical defects including cracks.

B406210079 B40612 PDR ADOCK 05000456 PDR

JUN 15 1986

Please address any questions that you or your staff may have concerning this matter to this office.

Very truly yours,

E. Douglas Swartz Nuclear Licensing Administrator

EDS/rap

cc: RIII Inspector - Braidwood

Director of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D.C. 20555

8719N