U.S. NUC 9-837							APPRO	LEAR REGULATORY COMMISSION PROVED OMB NO. 3150-0104 PIRES 8/31/85		
ACILITY NAME (1)							DOCKET NUMB	ER (2)		PAGE (3)
Washington Nucl	ear Plant -	Unit 2					0 15 10 10	0 1 0	131917	1 OF 01
TLE (4)										
Reactor Irip							-		D (8)	
ONTH DAY YEAR Y	LER NUMBER	L REVISION	MONTH DAY	YEAR		FACILITY N	AMES	00	CKET NUMBER	4(S)
	NUMBER	NUMBER						0	151010	101 1 1
0 5 1 9 8 4 8	4 0 4	3-010	0 6 1 4	8 4				0	151010	101 1 1
OPERATING TH	IS REPORT IS SUBMITT	ED PURSUANT 1	TO THE REQUIREME	NTS OF 10	CFR 5: 10	theck une or mon	e of the following)	(99)		
	20.402(5)	-	20.406(c) 50.36(c)(1)		<u>^</u>	50 73(a)(2)(v)		-	73,71(b)	
LEVEL 0, 1, 1	20.406(a)(1)(u)		60.38(e)(2)			50.73(a)(2)(vii)		X	OTHER SO	ecity in Abstract
	20 406(a)(1'(iii)		60.73(a)(2)(i)			50.73(a)(2)(viii)(A)		- 366A)	
	20.405(a)(1)()+)	-	60.73(e)(2)(ii)		-	50.73(a)(2)(viil) (8)		50.72(b)(2)(ii)
	20.406(s)(1)(v)		SO.73(#)(2)(III)	FOR THIS	LER (12)	90.73(a)(2)(x)				
AME								TEL	EPHONE NUM	6ER
	in that						AREA COD	E		
L.D. Kassakatis	, Plant Comp	pliance	Engineer				5101	93	1 7 71 -	1 2 5101
	COMPLET	E ONE LINE FOR	EACH COMPONENT	FAILURE	DESCRIBE	D IN THIS REPO	DAT (13) EXT		201	
AUSE SYSTEM COMPONE	NT MANUFAC TURER	TO NPRDS		CAUSE	SYSTEM	COMPONENT	TURER	1	TO NPRDS	
JC II	1 111	N			1	111				
		1.					1	.		
	SUPPLEM	IENTAL REPORT	EXPECTED 114						MONTH	DAY YEA
							SUBMIS	SION		
YES IIT vas complete EXPE	CTED SUBMISSION UAT	·E)	X NC				1		1	
buring operation monitors 'A' and tion signal and power to the Ref feedpump turbin caused a Reactor the half isola primary contain have been revise monitor.	d 'C' was bi d load shed eactor Feedw he to run to pr Protection tion signal ment pressu red to inclu	ower nor eing per ding log ater Lev to minim on System receive are monit de the r	formed. U gic was in vel Contro num speed. m (RPS) th d from th tors 'B' a reset of th	pon p nitiat Syst The ip. e pre nd 'D ne iso	e tes ressu ed. em. subs After vious ' hac platio	st of pr rization This re This ca sequent invest ly comp not be on signal	imary co of moni esulted i used the decrease igation leted sum en reset l after t	nta tor n l ope in it rvei	inment 'A' th loss of erating Reacto was fou illance The pr testing	pressure e isola- control Reactor or level und that test of ocedures of each
	8406210237	840614	4 1999							IEI

8406210237 840614 PDR ADOCK 05000397 S PDR

.

LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OM8 NO. 3150-0104 EXPIRES: 8/31/85

FACILITY NAME (1)	OOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
		YEAR SEQUENTIAL REVISION			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	814 - 01413 - 010	0 12 05 0 12		
TEXT (If .nore spece a required, use additional NAC Form 3684's) (17)	a de ante de cardo a de acede a code a code a cod	the second s	And and a second se		

Plant Operating Conditions - Prior to the Event

Power Level - 17% Plant Mode - 1

Event

Surveillance test procedure for the channel functional test of primary containment pressure monitors 'B' and 'D' was performed and completed at 1800 hrs. on May 19, 1984. This test causes a half trip of the Reactor Protection System, a half trip of the Primary and Secondary Containment Isolation Systems, and a half trip of the Load Shedding Logic. The procedure called for reset of the half trip from the Reactor Protection System but did not reset the isolation signal and load shedding logic.

Surveillance test procedure for the channel functional test of primary containment pressure monitors 'A' and 'C' was started. Upon pressurization of monitor 'A' the one out of two twice logic was completed to cause isolation and load shedding initiation of non-essential, non-class IE loads. This caused loss of control power to the Reactor Feedwater Level Control System causing the Reactor feedwater startup valve to fail open and the operating Reactor feedwater pump turbine to go to minimum speed. The subsequent decrease in Reactor level caused a Reactor Protection System trip at 1910 hours on May 19, 1984. The NRC was notified at 2225 hours on May 19, 1984 pursuant to 10CFR50.72(b)(2)(ii).

Safety Significance

Personnel involved in the incident followed the procedures as written. Investigation following the event identified the procedural deficiency. There were no safety consequences associated with this event and all Plant systems performed as required during the event.

Corrective Actions

The procedures have been revised to include reset of the isolation signal after testing of each monitor.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397 June 14, 1984

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2 LICENSEE EVENT REPORT NO. 84-043

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-043 for WNP-2 Plant. This report is submitted in response to the report requirements of Technical Specification Section 6.9.1.7 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 2225 hours on May 19, 1984.

Marten .

D. Martin (M/D 927M) WNP-2 Plant Manager

JDM:mm

Enclosure: Licensee Event Report No. 84-043

cc: Mr. John B. Martin, Administrator Region V, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 1450 Maria Lane Walnut Creek, California 94596 Mr. A. D. Toth, NRC Resident Inspector (901A) Ms. Dottie Sherman American Nuclear Insurers The Exchange Suite 245 270 Farmington Ave. Farmington, CT 06032

LEZZ