MAY 1 0 1984

MEMORANDUM FOR: Karl V. Seyfrit, Chief

Reactor Operations Analysis Branch Office for Analysis and Evaluation

of Operational Data

FROM:

Earl J. Brown, Lead Engineer

Engineering Systems

Reactor Operations Analysis Branch

SUBJECT:

INJECTION VALVE FOR THE HIGH PRESSURE COOLANT INJECTION (MPCI) SYSTEM FAILURE TO OPEN DURING A SURVEILLANCE TEST

The enclosed Technical Review report is forwarded for your information and further consideration. The report indicates the event involved omission of a bypass circuit around the torque switch that represents a common cause failure mechanism with respect to valve operability. This event occurred approximately six months after IE Circular 81-13 had identified a similar problem. Since licensees are not required to report actions concerning circulars, there is no readily available data base to ascertain the status of these bypass circuits at other plants. We plan to continue to monitor for similar events and notify IE if other events are discovered.

151

Earl J. Brown, Lead Engineer Engineering Systems Reactor Operations Analysis Branch

Enclosure: As stated

bcc:	R.	LaGrange	,	NRR
		Knight,		
	-	Bosnak,		-

C. Rossi, IE F. Ashe, AEOD S. Rubin, AEOD M. Chiramal, AEOD

F. Cherry, NRR M. Chiramal, J. Page, NRR C. Hsu, AEOD

V. Noonan, NRR E. Brown, AEOD G. Bagchi, NRR T. Ippolito, AEOD G. Holohan, NRR C.J. Heltemes

W. Campbell, RES
V. Thomas, IE
R. Baer, IE
R. Kiessel, IE
ROAB RF
ROAB SF
AEOD CF
PDR

OFFICE	ES/ROAB	C.ROAB	
SURNAME	EBrown: eh	KSeyfrit	8406210258 840510 PDR ADOCK 05000293
DATE	5/4/84	5//0/84	S PDR



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

DUR

MAY 1 0 1934

AEOD/T410

MEMORANDUM FOR: Karl V. Seyfrit, Chief

Reactor Operations Analysis Branch Office for Analysis and Evaluation

of Operational Data

FROM:

Earl J. Brown, Lead Engineer

Engineering Systems

Reactor Operations Analysis Branch

SUBJECT:

INJECTION VALVE FOR THE HIGH PRESSURE COOLANT INJECTION (HPCI) SYSTEM FAILURE TO OPEN DURING A SURVEILLANCE TEST

The enclosed Technical Review report is forwarded for your information and further consideration. The report indicates the event involved omission of a bypass circuit around the torque switch that represents a common cause failure mechanism with respect to valve operability. This event occurred approximately six months after IE circular 81-13 had identified a similar problem. Since licensess are not required to report actions concerning circulars, there is no readily available data base to ascertain the status of these bypass circuits at other plants. We plan to continue to monitor for similar events and notify IE if other events are discovered.

Earl J. Brown, Lead Engineer

Early Brown

Engineering Systems

Reactor Operations Analysis Branch

Enclosure: As stated