AC Form 9-83)		U.S. NUCLEAR REGULATORY COMMISS APPROVED ONS NO. 3150-0104 LICENSEE EVENT REPORT (LER) EXPIRES 8/31/85								M									
ACILITY	-	1										DX	OCKET N	UMBER	(2)		-	PAG	E (3)
Susquehanna Steam Electric Station-Unit 1								0	151	0 1 0	101	318	17	1 OF	0 12				
TITLE (4)		-											-	-					
	Off	-Gas	Hyd	roge	en Analy	zers -	Missed	Sur	veil1	ance									
EVENT DATE (5) LER NUMBER (6)				REPO	REPORT DATE (7) OTHER				HER F	FACILITIES INVOLVED (8)									
MONTH DAY YEA		YEAR	AR YEAR		SEQUENTIAL REVISION		MONTH DAY		YEAR	YEAR		FACILITY NAMES			DOCKET NUMBER(S)				
			-												0	510	101	01	
			1					. 1	. [										
0 2	25	8 4	8	4	0 1 2	0 1	0 6 1	4	84						0	5 0	101	01	
000	RATING	1	THIS	REPORT	IS SUBMITTE	D PURSUANT	THE REO	UIREME	NTS OF 10	CFR §: /C	heck one or	more of	the follow	wing) (1	1)				
MODE (9) 1				20.402(6) 3				20.405(c) 50.73(a)(2)(iv)			)(iv)	73.71(b)							
POWER			20.405(nM1)(I)			50.38(a)(1)				50.73(a)(2)(v)			73.71(c)						
(10) 01515				20.406(a)(1)(ii)				50.36(c)(2) 50.73(a)(2)(v			(48)	0			OTHER	THER (Specify in Abstract			
				20.50×34a		X	50.73(a)(2	)(1)			50.73(e)(2	A)(##)(A	ð			366A/			
				21.4.84	e)(1)(iv)		50.73(a)(2	)(#)			50.73(a)(2	(vili) (8	,						
				20.406(a)(1)(v)				50.73(a)(2)(III) 50.7			50.73(a)(2	0.73(a)(2)(x)			1				
						1	ICENSEE CO	NTACT	FOR THIS	LER (12)									
AME															TEL	EPHONE	NUMB	ER	
	R T	W4	lke										AHEA	CODE					
	D.L	. WI	IKS	-									171	117	5	1412	-	312	1 31 9
				_	COMPLETE	ONE LINE FOR	EACH COM	PONENT	FAILURE	DESCRIBE	D IN THIS	REPORT	r (13)				-		
CAUSE	SYSTEM	COMP	ONENT	N	TURER	REPORTABLE TO NPROS			CAUSE	SYSTEM	COMPON	ENT	MAN	FAC-	-	EPORTAB	LE		
				-													-		
	TTE			c v				_					1 .						
D	WE		A	UA	1 9 9 9 9	N						_	+				-		
														1. 1	1				
							-	1141				_		1	-	Inc	INTH	DAY	VEAD
					BUPPLEME	HTAL HEPOHT	EXPECTED	1140					-	EXPECT	ED	-	ALL A	UNI	1 CAR
YES IIT VAL COMOUND EXPECTED SUBMISSION DATE						NO					DATE (15)				1	1			
Y	and the second se		and the second se																

During February, 1984, the functional testing requirements of SI-072-201, "Monthly Functional Test of Off-Gas Hydrogen Analyzers AIT-06973A, B" were scheduled to be met by the performance of the quarterly surveillance procedure, SI-072-301. The duc date and violation date were, however, inadvertently omitted from the Surveillance Authorization (SA) cover sheet for SI-072-301; as a result, the foreman was unaware of the violation date for the test. The functional test was completed for the Hydrogen Analyzer Channel A of the Off-Gas System on 2/23/84 and for Channel B on 2/29/84. The violation date was 2/25/84. The missed surveillance for the Channel B Hydrogen Analyzer was discovered at 1400 hours on February 29, 1984 upon completion of SI-072-301.

Corrective actions were taken by changes in administrative procedures that require the inclusion of a statement in the Surveillance Authorization Cover Sheet for surveillance testing requirements needing to be met by a similar procedure of different surveillance frequencies.

Since the Off-Gas System Hydrogen Recombiner functioned properly, no abnormal concentrations of  $H_2$  occurred and diverse system isolation/alarms existed. The health and safety of the public was not affected.

8406210347 8406 PDR ADOCK 0500038

1

19-83) LICENSEE EVENT	TINUATION	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85					
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NU	MBER (6)	PAGE (3)			
Susquehanna Steam Electric Stat	ion	YEAR SEQU	NUNBER				

0 5 0 0 0 3 8 7 8 4 - 0 1 2 - 0 1 0 2 OF 0 2

EXT (If more space is required, use additional NRC Form 366A's) (17)

During the month of February (1984), the testing requirements as required by Technical Specification 4.3.7.11 for the performance of SI-072-201, "Monthly Functional Test of Off-Gas Hydrogen Analyzers AIT-06973A,B", were scheduled to be met by the performance of the quarterly (calibration) surveillance procedure SI-072-301. The due date and violation date were, however, inadvertently omitted from the Surveillance Authorization (SA) cover sheet for the quarterly calibration procedure, SI-072-301, and as a result, the foreman was not aware that the violation date for the monthly functional test was 2/25/84. Functional testing of Hydrogen Analyzer Channel A was completed on 2/23/84, two days before the violation date. Hydrogen Analyzer Channel B was functionally tested on 2/29/84, four days following the violation date. The missed surveillance for the Channel B Hydrogen Analyzer was discovered at 1400 hours on February 29, 1984 upon completion of the quarterly surveillance procedure SI-072-301. Hydrogen Analyzer Channel A was properly surveilled and operational during this event.

A review of Unit 1 operating power history indicates the plant was at approximately 50% power for nineteen hours on February 25, 1984, shutdown during February 26 and 27, 1984, in startup for four hours on February 28, 1984 and at a maximum power level of 45% on February 29, 1984. The Hydrogen Analyzers for the Off-Gas System are required to be functioning when the Off-Gas System and hence Unit 1 is operational.

Data recorded during the period of this event indicates the percent of  $H_2$  as recorded for (redundant) Channels A and B of the Hydrogen Analyzers shows no changes in the percent of  $H_2$  by either channel. The  $H_2$  recombiner outlet temperature, as recorded during the event, indicates the recombiners were operational and that no abnormal  $H_2$ concentrations existed in the Off-Gas Stream. Furthermore, all twenty-four Off Gas System alarms and the six alarm functions (i.e. result in Off-Gas System isolation) remained operable. Had an excessive amount of  $H_2$  gas entered the Off-Gas System between February 25 and February 29, 1984, while Unit 1 was operating, the missed surveillance on Hydrogen Analyzer Channel B would not have prevented the system from functioning as it was designed.

in the REMARKS section of the Surveillance Authorization Cover Sheet when similar testing requirements are to be met by a similar procedure of different surveillance frequency. This change makes personnel aware of the surveillance requirement date and its corresponding violation date.

Since the Off-Gas System Hydrogen Recombiner functioned properly, no abnormal concentrations of H<sub>2</sub> occurred and diverse system isolation/alarms existed. The health and safety of the public was not affected.

1



Pennsylvania Power & Light Company

Two North Ninth Street . Allentown, PA 18101 . 215 / 770-5151

June 14, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATIONLICENSEE EVENT REPORT 84-012-01ER 100450FILE 841-23PLA-2238Docket No. 50-387License No. NPF-14

Attached is Licensee Event Report No. 84-012-01. This event was originally determined to be reportable per 10CFR50.73(a)(2)(i) in that functional testing of the Common Off-Gas System Hydrogen Analyzer Channel B, required by February 25, 1984 in accordance with Technical Specification 4.3.7.11, was not performed until February 29, 1984. Revision 1 of the Licensee Event Report is provided for additional information concerning the corrective actions taken as a result of this event.

2 Keese

H.W. Keiser Superintendent of Plant-Susquehanna

BLW/pjg

cc: Dr. Thomas E. Murley Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 18406

> Mr. R.H. Jacobs Senior Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655

IE22 1/1