

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 4	PAGE (3) 1 OF 0 2
------------------------------------------------	--------------------------------------	----------------------

TITLE (4)  
Diesel Generator Output Breaker Did Not Open After Diesel Tripped

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 5	1 9	8 4	8 4	0 0 6	0 0 0 6	1 8	8 4				0 5 0 0 0
0 5 0 0 0											

OPERATING MODE (9) 1

POWER LEVEL (10) 1 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 60.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(e)(1)	<input type="checkbox"/> 60.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(e)(2)	<input checked="" type="checkbox"/> 60.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 365A)  Voluntary Report
<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 60.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 60.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 60.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME W. G. Hairston, III	TELEPHONE NUMBER AREA CODE 2 0 5 8 9 9 - 5 1 5 6
-----------------------------	-----------------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 5-19-84, a maintenance run of Diesel Generator 2B was performed. This run was performed following scheduled maintenance during the preceding six days and prior to returning the diesel to operable status. At 2043, the diesel tripped on High Jacket Water Temperature (non-essential engine protection), however the generator output breaker did not open automatically. The plant operator observed this and opened the breaker remotely. A review of the circuit design revealed that under certain circumstances the generator output breaker would not have opened if the diesel tripped following a non-emergency test start. A design change has been implemented to correct this condition. Emergency starting and operation would not have been affected. Health/safety of the public was not affected.

8406220209 840618  
PDR ADOCK 05000364  
S PDR

IE22

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Joseph M. Farley - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 3 6 4 8 4	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			0 0 6	0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 388A's) (17)

On 5-19-84, during steady state operation with the unit in Mode 1 at 100% power, a maintenance run of Diesel Generator 2B was being performed. The diesel had been removed from service for scheduled maintenance during the preceding six days and had not yet been restored to operable status. At 2043, the diesel tripped on High Jacket Water Temperature (non-essential engine protection); however, the generator output breaker did not open automatically. The plant operator observed that control room instrumentation indicated a reverse power condition and opened the generator output breaker remotely. The reverse power condition existed for only a few seconds.

Following a design review, it was determined that, with the existing circuit design, the generator output breaker may or may not have opened if the diesel tripped following a non-emergency test start. Since a certain amount of variance exists in relay actuation times, the trip signal would not have remained in long enough to open the breaker in all cases. Therefore, the generator output breaker might have opened at some times and not at others. This circuitry had been tested during the initial startup testing program and found to operate properly.

Investigation revealed that the remaining four diesel generators incorporated a different circuit design not subject to this condition. The circuit for Diesel Generator 2B was modified to be consistent with the circuits for the other diesel generators. The modified circuitry was tested satisfactorily.

The affected portion of the circuitry is used only during non-emergency test starts and would not have been used in the event that the diesel had started in response to an emergency condition. Therefore, emergency operation of the diesel generator was not affected.

Work on the Amot thermostatic valve in the jacket water system had been included in the maintenance performed on the diesel generator. Following the high temperature occurrence, further maintenance on the Amot valve was performed and the system tested satisfactorily. Following satisfactory performance of FNP-2-STP-80.1 (Diesel Generator 2B Operability Test), Diesel Generator 2B was declared operable at 0358 on 5-24-84.

**Mailing Address**  
Alabama Power Company  
600 North 18th Street  
Post Office Box 2641  
Telephone 205 783-6090

**R. P. McDonald**  
Senior Vice President-  
Nuclear Generation  
Flintridge Building



**Alabama Power**  
*the southern electric system*

June 18, 1984

Docket No. 364

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report No. LER 84-006-00 is being voluntarily submitted. This report was prepared using a draft version of IEEE Std. 805-1984 since a final version has not been published.

If you have any questions, please advise.

Yours very truly,

R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IE-22

11