



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

DMB

June 14, 1984

MURRAY R. EDELMAN

VICE PRESIDENT
NUCLEAR

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Operator Stem Keys for Motor
Operated Valves Supplied by
Borg-Warner [RDC 89(84)]

Dear Mr. Keppler:

This letter serves as the final report for Unit 1 only pursuant to 10CFR50.55(e) concerning motor operated valve (MOV) stem keys that are too long. Mr. P. R. Pelke of your office was notified on January 11, 1984, by Mr. B. D. Walrath of The Cleveland Electric Illuminating Company that this problem was being evaluated.

An interim report on this subject was submitted February 10, 1984. This report contains a description of the deficiency, an analysis of safety implications, and the corrective action taken.

Description of Deficiency

The Borg-Warner Fluid Controls Division has supplied MOV motor operators with stem keys that are too long, extending beyond the adapter yoke. When the mounting bolts are torqued, the keys are forced against the key retainer plate causing indentation and distortion of the retainer.

Analysis of Safety Implications

Large distortion of the upper key retainer could cause increased operating torque requirements and may impair operability of the valve. Failure of a valve to operate, depending on its function, could constitute a significant event.

8406220247 840614
PDR ADOCK 05000440
S PDR

JUN 18 1984

I-Ed7
110

Corrective Action


All Unit 1 valves supplied by Borg-Warner which utilize stem keys have been inspected for the subject condition. Three valves with discrepant stem keys were identified on Nonconformance Reports as described in our interim report. No additional cases of improper stem keys were found. The three discrepant valves have been repaired and the corresponding Nonconformance Reports are closed out.

The indeterminate status of the Unit 2 Borg-Warner valves which utilize stem keys has been documented on Nonconformance Report OPQC 727.

We will contact your office by December 13, 1985, concerning scheduling of the inspection of Unit 2 valves.

Please call if there are any questions.

Sincerely,



Murray R. Edelman
Vice President
Nuclear Group

MRE:pab

cc: Mr. J. A. Grobe
NRC Site Office

Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

Records Center, SEE-IN
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339