

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **Prairie Island Unit 1** DOCKET NUMBER (2) **05000282** PAGE (3) **1 OF 02**

TITLE (4) **Both Unit 1 Shield Building doors opened during airlock test**

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | | | |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|---|------------------|---|---|---|---|---|---|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | DOCKET NUMBER(S) | | | | | | |
| 0 | 5 | 2 | 1 | 8 | 4 | 8 | 4 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | 5 | 2 | 1 | 8 | 4 | 8 | 4 | 0 | 0 | 2 | 0 | 0 | 0 | 0 | 6 | 2 | 0 |
| | | | | | | | | | | | | | | | | | |

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)

| | | | | |
|------------------------------|-------------------|------------------|--|--|
| OPERATING MODE (9) N | 20.402(b) | 20.406(e) | 50.73(a)(2)(iv) | 73.71(b) |
| POWER LEVEL (10) 1010 | 20.405(a)(1)(i) | 50.38(e)(1) | <input checked="" type="checkbox"/> 50.73(a)(2)(v) | 73.71(e) |
| | 20.405(a)(1)(ii) | 50.38(e)(2) | 50.73(a)(2)(vii) | OTHER (Specify in Abstract below and in Text, NRC Form 366A) |
| | 20.405(a)(1)(iii) | 50.73(a)(2)(i) | 50.73(a)(2)(viii)(A) | |
| | 20.405(a)(1)(iv) | 50.73(a)(2)(ii) | 50.73(a)(2)(viii)(B) | |
| | 20.405(a)(1)(v) | 50.73(a)(2)(iii) | 50.73(a)(2)(ix) | |

LICENSEE CONTACT FOR THIS LER (12)

NAME **Arne A Hunstad, Staff Engineer** TELEPHONE NUMBER **612 388 1121**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
| | | | | | | | | | |
| | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE) NO EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During normal operation, the maintenance airlock leakage test was begun. The test calls for pressurization of the airlock with station air. An air hose was routed thru both shield building ventilation doors, causing a breach in shield building integrity. Procedures and air supply routing will be changed.

8406250240 840620
PDR ADOCK 05000282
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | |
|--|---|----------------|-------------------|-----------------|----------|--|
| FACILITY NAME (1) Prairie Island Unit 1 | DOCKET NUMBER (2) 0 5 0 0 0 2 8 2 8 4 - 0 0 2 - 0 0 0 2 OF 0 2 | LER NUMBER (5) | | | PAGE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | |

TEXT (If more space is required, use additional NRC Form 308A's) (17)

On the morning of May 21, the leakage test of the maintenance airlock (AL) was begun. The test calls for pressurization of the airlock with the station air system. At about 1020 hours, an air hose was routed through both shield building ventilation doors (DR); this action caused a breach in shield building integrity. At about 1050, the doors were closed after the NRC Resident Inspector questioned this action.

Cause of the event was procedure. The doors had traditionally been treated as Category I Ventilation doors, which can both be opened provided the Control Room is notified of the opening. This treatment was incorrect and led to the event. The test procedure says that both doors can be opened.

The airlock leakage test procedure will be revised before its next use to emphasize shield building integrity requirements. Design changes are in progress to provide a better routing of station air for the leakage tests.



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

June 20, 1984

U S Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Both Unit 1 Shield Building Doors Opened During Airlock Test

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72 on May 21, 1984.

Eugene Edelholz

for David Musolf
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IE22
1/1