

# The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483


February 20, 1992  
ST-HL-AE-4014  
File No.: G26  
10CFR50.73

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project  
Unit 2  
Docket No. STN 50-499  
Licensee Event Report 92-002 Regarding A Safety  
Analysis Deficiency Due to Veritrak Transmitter Uncertainties

Pursuant to 10CFR50.73, Houston Lighting & Power Company (HL&P) submits the attached Licensee Event Report 92-002 regarding a safety analysis deficiency due to Veritrak transmitter uncertainties. This event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or me at (512) 972-7205.

  
William J. Jump  
Manager,  
Nuclear Licensing

SDP/amp

Attachment: LER 92-002 (South Texas, Unit 2)

TE22 1/1

Houston Lighting & Power Company  
South Texas Project Electric Generating Station

ST-HL-AE-4014  
File No.: G26  
Page 2

cc:

Regional Administrator, Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

Georg Dick, Project Manager  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

J. T. Tapia  
Senior Resident Inspector  
c/o U. S. Nuclear Regulatory  
Commission  
P. O. Box 910  
Bay City, TX 77414

J. R. Newman, Esquire  
Newman & Holtzinger, P.C.  
1615 L Street, N.W.  
Washington, DC 20036

D. E. Ward/T. M. Puckett  
Central Power and Light Company  
P. O. Box 2121  
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee  
City of Austin  
Electric Utility Department  
P.O. Box 1088  
Austin, TX 78767

K. J. Fiedler/M. T. Hardt  
City Public Service Board  
P. O. Box 1771  
San Antonio, TX 78296

Rufus S. Scott  
Associate General Counsel  
Houston Lighting & Power Company  
P. O. Box 61867  
Houston, TX 77208

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, NY 11713

D. K. Lacker  
Bureau of Radiation Control  
Texas Department of Health  
1100 West 49th Street  
Austin, TX 78756-3189

Revised 10/11/91

L4/NRC/

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. TOWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT & BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) **South Texas, Unit 2** DOCKET NUMBER (2) **0 5 0 0 0 4 9 9 1** PAGE (3) **OF 0 4**

TITLE (4) **Safety Analysis Deficiency Due to Verittrak Transmitter Uncertainties**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
01	22	92	92	002	00	02	22	92		05000
										05000

OPERATING MODE (9) **1** THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

20.402(b)	20.405(x)	50.73(x)(2)(ix)	73.71(b)
20.405(x)(1)(ii)	50.35(x)(1)	50.73(x)(2)(iv)	73.71(c)
20.405(x)(1)(iii)	50.35(x)(2)	50.73(x)(2)(v)	OTHER (Specify in Abstract below and in Text, NRC Form 760A)
20.405(x)(1)(iii)	50.73(x)(2)(i)	50.73(x)(2)(v)(1A)	
20.405(x)(1)(iv)	<input checked="" type="checkbox"/> 50.73(x)(2)(ii)	50.73(x)(2)(v)(1B)	
20.405(x)(1)(iv)	50.73(x)(2)(iii)	50.73(x)(2)(ix)	

LICENSEE CONTACT FOR THIS R (12)

NAME	TELEPHONE NUMBER
<b>Charles Ayala - Supervising Licensing Engineer</b>	<b>5 1 2 9 7 2 - 8 6 2 8</b>
AREA CODE	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15) MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On January 22, 1992, it was determined that STP Unit 2 had been operated in a configuration which resulted in an Over Temperature Delta Temperature (OTDT) trip setpoint which was not conservative relative to the UFSAR Safety Analysis. For a period of approximately one month beginning on September 19, 1990, Unit 2 was operated with a failed T<sub>HOT</sub> Resistance Temperature Detector (RTD) which was bypassed until the unit entered a refueling outage. Although within the limits of the Technical Specifications, operation with the failed RTD coincident with the nonconservative OTDT setpoint, which should have incorporated Verittrak transmitter uncertainties, represented a reportable condition pursuant to 10CFR50.73 for operation in an unanalyzed condition. The cause of this event was personnel error through a lack of attention to detail in the review and resolution of NSSS vendor recommendations. Administrative compensatory actions allow STP Units 1 and 2 to continue normal operation within the presently defined safety limits until the plant safety analysis is revised and any necessary Technical Specification changes are approved.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530) U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20563.

FACILITY NAME (1)  South Texas, Unit 2	DOCKET NUMBER (2)  0500049992	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		92	002	00	02	04

TEXT (if more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

In 1986 Westinghouse identified a concern relative to drift in the calibration of Verittrak/Tobar transmitters. Westinghouse had reported that during adverse temperature conditions the output of the transmitters may drift beyond the assumptions used to develop the STP Reactor Trip and ESP setpoints. The notification identified the setpoints of concern. The only setpoint identified at that time requiring action was the Pressurizer Pressure Low Safety Injection (SI) setpoint. The recommendation, which was implemented, was to raise that setpoint to 1869 PSIG.

In 1988 Westinghouse sent a final report to STP on this issue. That final report provided a series of recommendations for the setpoints impacted by the Verittrak/Tobar issue. It also provided a series of other actions that should be considered. Believing no other actions were required, HL&P provided a letter to the NRC based on the Westinghouse report, stating that, with the incorporation of the interim setpoint for Pressurizer Pressure Low SI, the STP setpoints were conservative relative to the safety analyses and further changes were not required.

In mid-January, 1992, during preparation for an STP internal Nuclear Assurance Instrumentation Setpoint Assessment, the topic of Verittrak transmitters was selected for review. In the course of resolving questions raised on the 1988 letter, discussions were held with Westinghouse personnel to better understand the issues. Through these discussions, it was determined that the Technical Specification setpoint used for the  $K_1$  constant in the Over Temperature Delta Temperature (OTDT) evaluation was not conservative relative to the UFSAR Safety Analysis. The non-conservatism in the calculation was caused by a combination of Verittrak transmitter uncertainty and an additional .33 percent Delta T span bias which was included as part of the STP design change to eliminate the Resistance Temperature Detector (RTD) bypass lines. Neither the Westinghouse 1988 letter, nor the HL&P review identified that additional bias was present that made the change to  $K_1$  necessary. The bias is only applicable if one of the three hot leg RTDs for a given Reactor Coolant loop fails. Therefore, operation with the Technical Specification value of 1.08 for the OTDT constant  $K_1$  is non-conservative when all error contributions are considered.

Immediate actions taken to investigate this problem identified a period of approximately one month beginning on September 19, 1990, when Unit 2 was operated outside of the bounds of the Safety

LICENSEE EVENT REPORT (LER),  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-830), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  South Texas, Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 4 9 9 9 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 0 2	0 0	0 3	0 4

TEXT (If more space is required, use additional NRC Form 386A (1/17))

DESCRIPTION OF EVENT: (CONT'L)

Analysis. A T<sub>HOT</sub> RTD had failed time response testing and was bypassed until the Unit entered a refueling outage. Although within the limits of the Technical Specifications, this represents a reportable condition pursuant to 10CFR50.73 for operation in an unanalyzed condition. This determination was reported to the NRC pursuant to 10CFR50.72 on January 23, 1992 at 1453 hours.

HL&P immediately implemented compensatory action to impose additional administrative control on OTDT channel operability, which allowed continued operation within the existing safety limits.

CAUSE OF EVENT:

The cause of this occurrence was inadequate attention to detail in the review and resolution of Vendor recommendations, which resulted in the failure to update the Technical Specification to reflect the new value of K<sub>1</sub>.

ANALYSIS OF EVENT:

A bias for loss of an RTD within the Temperature Averaging Scheme combined with the allowance for Veritrac transmitter temperature compensation resulted in the K<sub>1</sub> factor being outside the Safety Analysis Limit. The bases for the Technical Specifications describe the methodology of combining errors associated with a protection channel. The discovered condition resulted in the combination of errors, using the Technical Specification methodology, exceeding the Safety Analysis Limit for OTDT. This is a condition outside the design basis described in the STP UFSAR Chapter 15 safety analysis and is reportable under 10CFR50.73(a)(2)(ii)(B).

A Justification for Continued Operation (JCO) was issued which administratively provides for operation of an OTDT channel if all of the associated T<sub>HOT</sub> RTDs are operable. If an RTD is inoperable, the JCO requires the affected channel to be put in the trip condition. In addition the Technical Specification limit on OTDT maximum trip setpoint is being administratively controlled to not exceed the computed OTDT trip setpoint by more than 1.3% delta-T span. This eliminates the need for an additional uncertainty allowance and results in the present setpoint being within the Safety Analysis Limit.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-330), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1)  South Texas, Unit 2	DOCKET NUMBER (2)  0500049992	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		92	002	000	4	OF 04

TEXT (if more space is required, use additional NRC Form 386A-1 (17))

CORRECTIVE ACTION:

The present engineering review process has been reviewed and determined to be adequate. The process for the review of NSSS recommendations has evolved over the past four years, and has been incorporated into the Vendor Technical Information Program (VETIP).

The following corrective actions are being taken as a result of this event:

1. JCO 920020, which assures that no unsafe condition exists, was prepared and approved. The JCO's administrative compensatory actions allow STP Units 1 and 2 to continue normal operation within the presently defined safety limits until the plant safety analysis is revised and any necessary Technical Specification changes are approved.
2. Revisions to the STP Setpoint Methodology (WCAP 11273) to incorporate current changes to the safety analyses and setpoint analyses will be established with Westinghouse. It is expected that changes will be incorporated by the fourth refueling outage for Unit 2 and the fifth refueling outage for Unit 1.

ADDITIONAL INFORMATION

At the time of issuance of the operating license a more rigorous program for verification of Technical Specification changes was implemented. This program requires verification of implementation of changes by the Nuclear Assurance Department.

On November 24, 1987, HL&P reported a similar event (LER 87-017) where the revision process for vendor recommendations was not performed in accordance with accepted practice.