

February 18, 1992

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

ULNRC-2559

Gentlemen:

DOCKET NUMBER 50-483 CALLAWAY PLANT UNIT 1 FACILITY OPERATING LICENSE FFF-30 ' CENSEE EVENT REPORT 92-001-00 'A' TRAIN EMERGENCY EXHAUST SYSTEM INCOMPLETE SURVEILLANCE DUE TO A HUMAN PERFORMANCE ERROR

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73(a)(2)(i)(B) concerning operation of the Callaway Plant with a condition prohibited by the plant's Technical Specifications. The Emergency Exhaust System was not run a full ten hours as required by the monthly Technical Specification surveillance 4.7.7.a.

Ú. D. Blosser Manager, Callaway Plant

JDB/TPS/JGB/1rj

Enclosure

cc Distribution attached

Mailing Address: P.O. Box 620, Futton, MO 65251

cc distribution for ULNRC-2559

Mr. A. Bert Davis Regional Administrator U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Manager, Electric Department Missouri Public Service Commission P. O. Box 360 Jefferson City, MO 65102

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

NRC Senior Resident Inspector

Mr. L. Raynard Wharton (2 copies) U.S. Nuclear Regulatory Commission OWFN - Mail Stop 13E21 Washington, D.C. 20555

Mr. Merlin Williams Supt. of Regulatory Quality and Administrative Services Wolf Creek Nuclear Operating Corp. P. O. Box 411 Burlington, KS 66839

Mr. R. L. Hague Chief, Project Section 3C U.S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

NRC FORM HE	US NUCLEAR REQULATORY	CONMISSION	APPROVED OR	ae 425 3150-0104				
LICENSEE EVENT REPORT (LER)			ENFINITION OF THE PROPERTY WITH THE ENFINES ADDREET TO COMPLY WITH THE INFORMATION, COLLECTION REQUEST, SO G. HES. FORWART COMMENTS, REGARDING BURDEN LETIMATE TO THE RECORD AND REFORTS MANAGEMENT BRANCH (F-83), U.S. NOILLEAF REGULATORY COMMISSION WASHINGTON, DC 20565, AND TO THE FAREINGORE REDUCTION PROJECT DISPOSION (DC 20563)					
ACILITY NAME (1)		DO	RET NUMBER (2)	PAGETS				
Callaway Plant Unit 1		0	15101010	0 4 8 1 3 1 0 0 0 3				
"A" Train Emergency Exhaust Error	System Incomplete	Surveillance	Due To A	Human Performance				
EVENT DATE (5) LER NUMBER (6)	REPORT DATE (7)	OTHER FA	OTHER FACILITIES INVOLVED					
MONTH DAY YEAR YEAR BEDUENTIAL HEUR	IN MONTH DAY YEAR	FACILITY NAME	D	OCKET NUMBER(S)				
				15101010111				
0 9 1 2 9 1 9 2 0 0 1 0	0 0 2 1 8 9 2			151010101 1 1				
THIS REPORT IS SUBMITTED PURSUA	NT TO THE REQUIREMENTS OF 10	SFR & IChack one or more 'i	the following) (11)					
MODE (8)] 20.402(6)	20.405(c)	60.73(61(2))(x)		73.73 (81				
POWER LEVEL 101 1913 20.406 (#1110) 20.406 (#1110)	\$0.38(c)(1)	50 73(a)(2)(4.		73.71(c)				
(10) 913 20.406(a)(1)(a) 20.406(a)(1)(a)	50.361e1(2) X 86.75(a)(21(i)	50 73(s)(2)(vii) 50 73(s)(2)(vii)	i i se	DTHER (Specify in Abstract below and in Taxt, NRC Form MEA)				
20.409 (a)(11)(1	60.73(a)(2)(a)	80.73(a)(2)(c)(1)(B)	202.34					
20.406(s)(1)(v)	60.7.3 (41(2) (iii)	80 73(s1(21(x)	in pairie					
ana ana amin'ny soratra ana amin'ny tanàna amin'ny tanàna amin'ny tanàna amin'ny tanàna dia kaominina	LICENSEE CONTACT FOR THIS I	EN (12)		and and independent of the second				
NAME			And and a second se	ELEPHONE NUMBER				
			AREA CODE					
Dale E. Young, Superintendent, (perations		3 1 1 14	617131-18121016				
COMPLETE ONE LINE	FOR EACH COMPONENT FAILURE	DESCRIBED IN THIS REPORT	(13)	a				
CAUSE SYSTEM COMPONENT MANUFAC REPORT		EVETEM COMPONENT	MANUFAC TURER	REPORTABLE TO NPRDS				
			111					
			111					
BUPPLEMENTAL RE	PORT EXPECTED (14)	and an international states and the second	EXPECTE					
YES III ver complete EXPECTED SUBMISSION DATE:	X NO		SUBMIESIO DATE HE	N				

On 1/21/92, a utility Quality Assurance engineer discovered flow had not been maintained through the 'A' Train Emergency Exhaust for the required 10 hours during a Technical Specification (T/S) 4.7.7.a monthly surveillance on 9/12/91. On 9/12/91 at 0108 CDT, licensed operators performed the T/S 4.7.7.a surveillance for only 9 hours and 21 minutes. The plant was in Mode 1-Power Operation, 93 percent reactor power at the time of the event.

The root cause of this event is cognitive human performance error during the completion and review of the surveillance procedure Acceptance Criteria Data Sheet. This Data Sheet did not include the 10 hour acceptance criteria nor require the total run time be calculated and recorded.

The individuals involved have been instructively coached and they have revised the Emergency Exhaust surveillance procedure to add the 10 hour T/S acceptance criteria and run time calculation steps to the Acceptance Criteria Data Sheet. Other similar T/S surveillance procedures were reviewed. One was revised to require the calculated total run time to be recorded. This event will be included in licensed operator regualification training.

NRC 9080 MR03 000	APPROVED OME NO. 3160-0104 EXPIRES 4/30/82							
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION		ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD C'IMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS. AND REPORTS MANAGEMENT BRANCH (FAST) U.Z. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20065 AND TO THE FARERWORK REDUCTION PROJECT (3)500104, OF FICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20003						
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	FAGE (3)					
		YEAR BEQUENTIAL REVEION						
Callaway Plant Unit 1	0 5 0 0 0 4 8 3	912 - 0 0 1 1 - 0 0	012 01 013					
TEXT Iff more space is required, use additional NRC Form SREA's) (17	li se a la companya de	and the state of the	A construction of the second second second					

BASIS FOR REPORTABILITY :

Technical Specification (T/S) 4.7.7.a states that "each Emergency Exhaust System⁽¹⁾ shall be demonstrated operable at least once per 31 days on a staggered test basis by initiating, from the Control Room, flow through the HEPA filters⁽²⁾ and charcoal absorbers and verifying that the system operates for at least 10 continuous hours with the heaters operating." On 1/21/92, it was discovered by a utility Quality Assurance (QA) engineer that during a T/S 4.7.7.a monthly surveillance on 9/12/91, flow had been maintained through the 'A' Train Emergency Exhaust for only 9 hours and 21 minutes. Since the system was not operated for 10 continuous hours, this report is submitted pursuant to 10CFR50.73(a)(2)(i)(B) to report a condition prohibited by the plant's T/S.

CONDITION AT TIME OF EVENT:

Mode 1 - Power Operations, Reactor Power at 93% for repair of tube leaks in the '1B' low pressure feedwater heater. (3)

DESCRIPTION OF EVENT

On 9/12/91 at 0108 CDT, a T/S 4.7.7.a surveillance of the 'A' Emergency Exhaust System was commenced by a licensed utility Reactor Operator per surveillance procedure OSP-GG-00001, "Emergency Exhaust System Operability Test". At 1206 on 9/12/91, a licensed Senior Reactor Operator signed a surveillance completion form indicating the completed surveillance satisfied the required acceptance criteria. On 1/21/92, a utility QA engineer discovered during a routine, periodic review of completed surveillance Acceptance Criteria Data Sheets, that the 'A' Train Emergency Exhaust System was operated for only 9 hours and 21 minutes. This review included complete documentation for 50 other performances of this surveillance. The acceptance criteria was met for these other surveillances.

ROOT CAUSE :

The root cause of this event is cognitive human performance error by a licensed utility Reactor Operator when calculating the stop time for the surveillance test. A contributing factor was the failure of the licensed Senior Reactor Operator to identify the inadequate run time when reviewing the Acceptance Criteria Data Sheet to determine if it met the procedure's acceptance criteria. This Data Sheet did not include the acceptance criteria of 10 hours nor require the total run time to be calculated and recorded.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION		APPROVED OMB NO. 3150-0104 EXFIRES 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN BETIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH JP.530/ U.S. NUCLEAR REGILATORY COMMISSION WASHINGTON DE 20568 AND TO						
FACILITY NAME (1) DOCKEY NUMBER (2)		THE PAPERWORK REDUCTION PROJECT (3)50-0104) OFFICE OF MANAGEMENT GND BUDGET WASHINGTON, DC 20003 LER NUMBER 10: PAGE (3)						
		YEAR	BEQUENTIAL NUMBER	RECEICN				
Callaway Plant Unit 1	0 5 0 0 0 4 8 3	912	-0011		0 3	OF	0] :	3
TEX: J more spece is required, use adultional NRC Form 3664 a/ (17)								

CORRECTIVE ACTION:

- The individuals involved have been instructively coached and they have revised the procedure as noted below. This event will be included in licensed operator regualification training.
- The surveillance procedure, OSP-GG-00001, has been changed to add the 10 hour T/S acceptance criteria to the Acceptance Criteria Data Sheet. Steps have been added to the data sheet to actually calculate and record the run time.
- Other similar T/S surveillance procedures requiring a specific run time were reviewed. One of these required revision to add the calculated total run time.

SAFFT7 SIGNIFICANCE:

The 9/12/91 surveillance run time of 9 hours and 21 minutes did verify the proper functioning of the 'A' Train Emergency Exhaust System. The same monthly surveillance was performed satisfactorily on 10/10/91 and thereafter. All equipment functioned as required by plant design. This event posed no threat to the health or safety of the public.

PREVIOUS OCCURRENCES:

None.

FOOTNOTES

The system and component codes listed below are from IEEE Standard 805-1984 and 803A-1984, respectively.

- (1) System VG
- (2) System VG, Component FLT
- (3) System SJ, Component HX