
ATTACHMENT

Consumers Power Company Palisades Plant - Docket 50-255

COPIES OF NON-RADIOLOGICAL NPDES PERMIT VIOLATION REPORTS November 1983 through April 1984



10 Pages

IEOL

*

ATTACHMENT

Consumers Power Company Palisades Plant - Docket 50-255

COPIES OF NON-RADIOLOGICAL NPDES PERMIT VIOLATION REPORTS November 1983 through April 1984

10 Pages

• • • •

File No P10.2.1 Incident No: PAL-84-03-AD92

A

Apparent Difference From Daily Average/Maximum Limitation April 5, 1984

Plant: Palisades

Permit No: MI 0001457

Outfall Description: Radwaste (OOE)

Outfall Code No: 800217

Parameter Code No: 01022, 01034

Parameter: Boron, Total Chromium

- 1. Date of Incident: March 11 to March 14, 1984
- 2. Identification of specific effluent limitation or monitoring requirement affected:

The NPDES Permit requires radwaste releases be analyzed for boron and total chromium content.

3. Description of Incident:

From March 11 to March 14, 1984, 87,500 gallons of water from the condensate storage tank was released without being monitored for boron and total chromium. This oversight was discovered on March 15, 1984 at 1500 hours.

4. Apparent Cause:

Plant Procedure HP3.6 did not identify boron and chromium as required analyses of the condensate storage tank if the tank was released as a radwaste batch.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA.

 Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

Plant Procedure HP3.6 will be revised to include the required monitoring.

7. Additional Comments:

NA.

8. Signed:

RLFobes RZF

Revised 10/26/83

RP0384-0612A-TP02


STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES REPORT OF OIL, SALT OR POLLUTING MATERIAL LOSSES

Pursuant to the provisions of Act 245 of the Public Acts of Michigan 1929 as amended, regulations have been issued which require that all owners, managers or operators of versels, oil storage or on land facilities shall notify the Water Resources Commission or his authorized representative of oil, salt and polluting material losses. This notification shall be made promptly by telephone or telegraph, giving briefly the particulars, and by mail, giving a detailed account of events and conditions.

Date	Company Name		
March 8, 1984	Consumers Power Con	apany	and the second
Location of Loss (Be Specific)			
CP Co - Palisades	Nuclear Plant, Route 2.	, Box 154, Covert, Mic	chigan 49043
T-10 (Diesel Fuel Material Lost	0il Storage Tank) area	- south of plant Name of Surface Water Invo	blved
Fuel oil	40 gallons	None	
Date Loss was Discovered	40 garions	Time of Discovery	
February 24, 1984		1430	
	Resources Representative Contacted		
Operator 24, PEAS			
Telephoned or Telegraphed by W	A DESCRIPTION OF THE OWNER		Time
A. Clark Kahn			2/24/84 @ 1600 hours
Cause of Loss (Include Type of E	quipment and Other Details)		
Fuel oil tank (T-	10) was overfilled, for	ing oil through the	flame arresting vent.
		A STREET BOOK STREET BOOK	
	a state of the state of the state		
Nature of Loss (Include Complet	e Description of Damage)		
As the oil evited	the flame arrester nine	e it spilled onto the	south side of T-10 along
a trailer and ont	o the ground. Thirty to	o forty gallons were .	lost.
	and it is such as the second		
Additional Comments (Include A	Athod of Control, Plans for Prevention of	of Becurrence etc.)	
			mba alaan un matamiala
A crew was immedi	ately mobilized to clear	a up the spilled oil.	The clean-up materials
and the oil-conte	minated soil was removed	d and the waste place	d into barrels. The waste
will then be dien	ored of in the annuari	ate manner In the f	uture, the filling operation
will then be disp	osed of in the appropria	ace maimer, in the i	abure, one ritting operation
of Tank T-10 mill	be closely supervised	in order to prevent a	ny recurrence.
Company Name	te croseri subcraised	THE R. LEWIS CO., LANSING MICH.	gnature)
Consumers Power (ompany		C Kahn
consumers rower o	ompany	NAMES OF TAXABLE PARTY OF TAXABLE PARTY OF TAXABLE PARTY.	
		24-H	Emergency Notification Number
			(800) 292-4706
Return this form to:			and the state state

1

Environmental Department Parnall Road Jackson, Michigan



File No P10.2.1 Incident No: PAL-84-02-AD91

Apparent Difference From Daily Average/Maximum Limitation March 8, 1984

Plant: Palisades

Permit No: MI 0001457

Parameter Code No: 50060

Outfall Description: Discharge to Lake Michigan (001) Outfall Code No: 800095

Parameter: Total Residual Chlorine (TRC)

- 1. Date of Incident: 2/17/84
- 2. Identification of specific effluent limitation or monitoring requirement affected:

The NPDES permit requires three grab samples of the plant discharge to be collected and analyzed for TRC during the chlorination of the plant circulating and cooling water systems.

3. Description of Incident:

On 2/17/84 during chlorination of the service water system, only two grab samples for TRC were collected instead of the required three samples.

4. Apparent Cause:

Technician error. The technician had not been involved with chlorination procedures for the past six months. The plant's chemistry procedures specifically require that three grab samples for TRC be collected during chlorination.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA

6. Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

All technicians were reminded of the TRC sampling requirements as well as other responsibilities and requirements of the NPDES permit. The plant's chlorination data sheet is also being revised to include the NPDES sampling requirements during a chlorination.

7. Additional Comments:

The second sample of the plant discharge was taken at the end of chlorination and measured less than detectable (< .02 ppm) TRC.

8. Signed: R L Fobes

File No P10.2.1 Incident No: PAL-84-01-AD90

Apparent Difference From Daily Average/Maximum Limitation February 15, 1984

Plant: Palisades		Permit No: MI 0001457
Outfall Description:	Intake (000) and Discharge to Lake Michigan (001)	Outfall Code No: 800149 800095
Parameter: Temperatu	are and pH	Parameter Code No: 00011 00400

- 1. Date of Incident: 1/7/84 and 2/4/84
- 2. Identification of specific effluent limitation or monitoring requirement affected:

Continuous monitoring of intake and discharge temperature and pH is required.

3. Description of Incident:

On 1/7/84 the pH recorder, pHR 1312, was found to be malfunctioning. The pH readings were erratic, fluctuating off scale from low to high. The pH recorder remained out of service until 2/3/84. On 2/4/84 the temperature recorder, TR 5370, failed to operate properly. The recorder was out of service until 2/8/84.

4. Apparent Cause:

The ribbon cable on the pH recorder shorted out to the instrument case. The temperature recorder had a faulty switch and ribbon cable.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA

 Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

The pH recorder was removed from service. A maintenance order was filed. The ribbon cable was replaced and a loose wire to the probe was also repaired. The pH recorder was calibrated and returned to service after repairs were completed. The recorder ribbon cable will be made a stock item.

A maintenance order for the temperature recorder was initiated. The recorder's switch was repaired and the ribbon was replaced. The temperature reco. der was then returned to service.

7. Additional Comments:

While the pH recorder was out of service, the discharge to Lake Michigan was grab sampled and analyzed three times per day for pH. While the temperature recorder was out of service, temperature readings of the intake and discharge

were taken once per shift. The plant is investigating placement of a redundant temperature recorder for each parameter to be placed at a local sample point to minimize recurrence of this event.

8. Signed: R L Fobes

.

STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

REPORT OF OIL, SALT OR POLLUTING MATERIAL LOSSES

Pursuant to the provisions of Act 245 of the Public Acts of Michigan 1929 as amended, regulations have been issued which require that all owners, managers or operators of vessels, oil storage or on land facilities shall notify the Water Resources Commission or his authorized representative of oil, salt and polluting material losses. This notification shall be made promptly by telephone or telegraph, giving briefly the particulars, and by mail, giving a detailed account of events and conditions.


Danuary 19, 1983		ny Name Isumers Power	· Company			
Location of Loss (Be Specific)		ite leasted	at the CP	Co Police	dec Nucles	Dient near Couert
At the 1-10 stor	age tank :	site located	at the CF	CO Failse	ides Nuclei	ar Plant near Covert,
Material Losi		Amount	Name	of surface water	nvoived	
Fuel Oil		150		one		
Dete Loss was Discovered				SEO has		
January 11, 1984		auve Contacted		850 hrs		
Operator 15 (Bet	h Mersch)		partment of	Natural	Resources	Martin Cantilla South (
elaphoned or Telegraphed by W						Time
T Kanicki, Duty	Shift Supe	Prvisor Detata				2053 hrs
			ing excessi	ve pressi	re to fil	1 the T-10 storage
ank, near the o	ompletion	of the fill	operation	COP atts	ched man)	
			operation	(see atte	iched map)	•
ature of Loss (Include Competi The fuel oil ove	Description of Dan erflowed fr	rom the T-10	vent pipe	while the	tank true	ck was pumping in the
Halume of Loss (Include Competit	Description of Dan erflowed fr	rom the T-10	vent pipe	while the	tank true	
Helune of Loss (Fraude Complete The fuel oil ove last 500 gallons	Peschpuon of Dan erflowed fr of fuel c	rom the T-10 - - Dil. The los	vent pipe	while the	tank true	ck was pumping in the
Helune of Loss (Fraude Complete The fuel oil ove last 500 gallons	Peschpuon of Dan erflowed fr of fuel c	rom the T-10 - - Dil. The los	vent pipe	while the	tank true	ck was pumping in the
The fuel oil ove last 500 gallons and the south si	Description of Dan erflowed fr of fuel c de of the	rom the T-10 - Dil. The los tank.	vent pipe et oil was	while the	tank true	ck was pumping in the
taine of Loss (France Compete The fuel oil ove last 500 gallons and the south si dateonal Comments (incude Ma	Description of Dan erflowed fr of fuel o de of the mod of Control Pic	rom the T-10 - Dil. The los tank.	vent pipe at oil was	while the	n the snot	ck was pumping in the
tature of Loss (Fraude Compete The fuel oil ove last 500 gallons and the south si destant Comments (Fraude Ma Clean-up was imm	Description of Dam erflowed fr d of fuel c de of the mos of Control Pic mediate. T	rom the T-10 - - - - - - - - - - - - - - - - - -	vent pipe et oil was rewrmence etc.) snow was r	while the trapped i emoved ar	tank true n the snow	ck was pumping in the w around the vent pipe
taiure of Loss (Froude Compete The fuel oil ove last 500 gallons and the south si domain Comment (Incude Ma Clean-up was imm will be added to	Description of Dan erflowed fr of fuel c de of the mod of Control Pin mediate. T the barre	rom the T-10 bil. The los tank. tank. The effected els and they	vent pipe et oil was rewrmence etc.) snow was r	while the trapped i emoved ar	tank true n the snow	ck was pumping in the w around the vent pipe in 8 barrels. Oil dry
ature of Loss (Fronde Compete The fuel oil ove last 500 gallons and the south si domonal Comments (Incude Ma Clean-up was imm will be added to	Description of Dan erflowed fr of fuel c de of the mod of Control Pin mediate. T the barre	rom the T-10 bil. The los tank. tank. The effected els and they	vent pipe et oil was rewrmence etc.) snow was r	while the trapped i emoved ar	tank true n the snow	ck was pumping in the w around the vent pipe in 8 barrels. Oil dry
and the south si downal Comments (incude Ma Clean-up was imm	Description of Dan erflowed fr of fuel c de of the mod of Control Pin mediate. T the barre	rom the T-10 bil. The los tank. tank. The effected els and they	vent pipe et oil was rewrmence etc.) snow was r	while the trapped i emoved ar	tank true n the snow	ck was pumping in the w around the vent pipe in 8 barrels. Oil dry

Return this form to:

Environmental Department Farnall Road Jackson, Michian 24 hr. Emergency Notification Number

(800) 292 -4706

R4618



File No P10.2.1 Incident No: PAL-83-12-AD89

NPDES NOTIFICATION

Apparent Difference From Daily Average/Maximum Limitation January 6, 1984

Plant: Palisades	Permit No: MI 0001457
Outfall Description: Intake (00J) and Discharge to Lake Michigan (001)	o Outfall Code Nos: 800149 800095
Parameter: Temperature	Parameter Code No: 00011

- 1. Date of Incident: 12/16/83 through 12/20/83
- 2. Identification of specific effluent limitation or monitoring requirement affected:

Continuous monitoring of the intake and discharge temperature is required.

3. Description of Incident:

From 12/16/83 at 2100 hours to 12/20/83 at 1700 hours the temperature recorder for the intake and discharge samples from/to Lake Michigan was malfunctioning.

4. Apparent Cause:

Printer malfunction.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA

6. Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

A maintenance order was initiated and the recorder was repaired.

7. Additional Comments:

As an interim measure, daily grab measurements of intake and discharge temperatures were performed.

8. Signed: R L Fobes

File No P10.2.1 Incident No: PAL-83-11-AD88

Apparent Difference From Daily Average/Maximum Limitation December 22, 1983

rlant: Palisades		Permit No: MI 0001457	
Outfall	Description:	Turbine Sump Oil Separator	Outfall Code No: 800218

Wastewater (00G)

Parameter: Oil and Grease (Freon)

Parameter Code No: 0055C

- 1. Date of Incident: Week of 11-20-83 through 11-26-83
- 2. Identification of specific effluent limitation or monitoring requirement affected:

The Turbine Sump Oil Separator Wastewater is required to be sampled and analyzed for oil and grease once per week.

3. Description of Incident:

During the week of November 20 through November 26, 1983, the Turbine Sump Wastewater was not sampled.

4. Apparent Cause:

Failure to take routine sample on 11-21-83.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA

6. Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

A sample was collected on 12-1-83 when the oversight in sampling was discovered. This matter was also discussed at the weekly Technician meeting. A weekly checklist of required sampling and analyses was prepared. Additionally, a Plant Procedure CH 9.1, Site Surveys, is under development.

7. Additional Comments:

Daily visual observations of the final discharge to the lake showed no oil or grease during this period. Visual analysis of the Turbine Sump Oil Separator Wastewater on 11-21-83 and 11-25-83 also showed no oil or grease.

8. Signed: R L Fobes RZF

DMB

JUN 4 1984 IE01 1



General Offices: 1945 West Parnall Road, Jackson, MI 49201 + (517) 788-0550

May 31, 1984

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 -PALISADES PLANT - COPIES OF NON-RADIOLOGICAL NPDES PERMIT VIOLATION REPORTS

Section 3.2 entitled "Reporting Related to the NPDES Permits and State Certification" of Appendix B to Provisional Operating License No DPR-20 Palisades Plant Consumers Power Company Docket 50-255 Environmental Protection Plan (Non-Radiological) dated January 22, 1981 states that copies of reports to the state of Michigan indicating violation of NPDES permits are to be sent to the NRC. Attached to this letter are copies of five (5) NPDES Notifications covering the six (6) month period from November 1983 through April 1984. Also attached are copies of two (2) Reports of Oil, Salt or Polluting Material Losses that occurred during the same period.

Brian & phuser

Brian D Johnson Staff Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Palisades

Attachments

0C0584-0021A-NL02