

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Washington Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 1	PAGE (3) 1 OF 0 2
--	--	----------------------

TITLE (4)  
Auto Start of the Control Room Emergency Filtration System on Hi Chlorine

EVENT DATE (6)			LER NUMBER (5)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
06	05	84				06	28	84			0 5 0 0 0
06	12	84	84	05	7	00	06	28			0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more of the following) (11)

OPERATING MODE (9) 2	20.402(b)	20.406(e)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0, 0, 3	20.406(a)(1)(i)	50.36(e)(1)		50.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	50.36(e)(2)		50.73(a)(2)(vi)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 365A)
	20.406(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(vii)(A)	50.72(b)(2)(ii)
	20.406(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME C.M. Powers, Reactor Engineering Supervisor	TELEPHONE NUMBER 5 0 9 3 7 7 - 1 2 5 0 1 1
---	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) Ext. 2996

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	KND	DET	M02B	N					

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
--	--	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces - a space is every seven single-space typewritten lines) (16)

A false high chlorine signal from the ventilation chlorine detector, on sample rack WOA-SR-15, started the Control Room Emergency Filtration System. The false chlorine signal was a result of depletion of chlorine sensitive paper tape which discolors on contact with chlorine or extended exposure to moisture.

B407030260 840628  
PDR ADOCK 05000397  
S PDR

IE22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Washington Nuclear Plant - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 3 9 7 8 4 -	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0 5	7 -	0 0 0	2	OF

TEXT (if more space is required use additional NRC Form 388A's) (17)

Plant Conditions

Event 1                      Event 2

- a) Rx Power                      0%                                  3%
- b) Mode Switch                  4 - Refueling    2 - Startup

Event

1. On 6-5-84 WOA-SR-15, the Chlorine Detector on the inlet for the Control Room ventilation, ran out of tape. This tape is chemically treated to produce a color change when exposed to chlorine in the air stream. The resulting color change is measured by an optics block and converted to a signal proportional to ppm chlorine present in the influent. When the tape in the detector ran out the last portion was left in front of the optics block and began to discolor as dirt and moisture accumulated. This discoloration was sensed as increasing chlorine, eventually causing a hi alarm which started the Control Room Emergency Filtration System. A fresh roll of paper tape will run for approximately 7 days.
2. On 6-12-84 WOA-SR-15 again ran out of tape with the same consequences listed above.

Immediate Corrective Action

In both cases the tape was replaced in WOA-SR-15, the alarm reset, and the Emergency Filtration System returned to its normal standby configuration.

Future Long Term Corrective Action

Daily checks of this sample rack are provided in plant procedure PPM 10.24.166, PM Daily Check of WOA-SR-15 & 16 Chlorine Monitors. The importance of implementing the directions contained in this procedure has been re-emphasized to the maintenance organization. In response to this, the Instrument and Controls group has developed a checklist of required daily actions to ensure the chlorine detectors are properly serviced.

Safety Significance

This event carries no safety significance as all equipment operated correctly to place the Control Room Ventilation System in an isolation configuration.

## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

June 28, 1984

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2  
LICENSEE EVENT REPORT NO. 84-057

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-057 for WNP-2 Plant. This report is submitted in response to the report requirements of Technical Specification Section 6.9.1.7 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 0215 & 1655 hours on June 5 & June 12, 1984 respectively.

Very truly yours,

*J. D. Martin for*  
J. D. Martin (M/D 927M)  
WNP-2 Plant Manager

JDM:mm

Enclosure:  
Licensee Event Report No. 84-057

cc: Mr. John B. Martin, Administrator  
Region V, Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
1450 Maria Lane  
Walnut Creek, California 94596  
Mr. A. D. Toth, NRC Resident Inspector (901A)  
Ms. Dottie Sherman  
American Nuclear Insurers  
The Exchange Suite 245  
270 Farmington Ave.  
Farmington, CT. 06032

IE22  
1/1