RC Form	344				LIC	ENSEE	EEVE	NT RE	PORT	LER)	US NU A	CLEAR R PRHOVED XPIRES B	ONE NO	3150-01	-153-10% 34			
ACILITY										0	OCKET NUMBER	(2)		TAG	E 13.			
LaSalle County Station Unit 2						· · · · · · · · · · · · · · · · · · ·				0 15 10 10 10 1 317 14 1 OF 01								
ITLE (4)		-								· · · ·								
Reac	tor S	cram		traction for a				a second second										
EVE	NT DATE	(8)		LER NUMBER (6	1	REP	ORTDA	TE 17:		OTHIR	ACILITIES INVO	LVED (B)						
MONTH	CAY	YEAR	YEAR SEQUENTIAL NUMBER		NUMBER	NONTH DAY		YEAR	FACILITY VAN		ES	DOCKET NUMBERIS						
												0 5	1010	101	1 1			
0 6	0 6	8  4	8 4	0 2 5	- 00	0 6	2   1	8 4				0 5	10 10	101	1.1			
OPE	RATING		THIS REP	ORT IS SUBMITTED	PURSUANT		OUREN	ENTS OF 10	CFR \$ 10	nect one or more o	t the following) (1	1)						
M	DE (.)	1	20 402(6)				20 406 (c) X 80.7			60.73ia1(2)(iv)	60.73(a)(2)(iv)			73.71(b)				
POWER			20.405(4)(1)(0			60.36(ef(1)				60.73(a)(2)(v)		1.71 ie)	tie)					
(10)		2 14	20.406(a)(1)(H)			60.36ic)(2)				50.73(a)(2)(vii)	OTHER ISP			n Text NEC Form				
			20 406 (s) (1) (iii) 20 405 (s) (1) (iv)				60.73(a)(2)(i) 60.73(a)(2)(ii)			50.73(a)(2)(+iii)(A	0	3664/						
		6C.73(a)(2)(viii)(8)																
20.406(a)(1)(-			06(a)(1)(v)	60.73 (a) (2) (iii)														
_			_			ICENSEE	CONTAC	T FOR THIS	LER 1121			** **			-			
NAWE											AREA CODE	TELEPHO	ONE NUM	REP				
Kenr	neth J	I. Ka	lmon,	extension	325				125		8 11 15	315	171-	1617	611			
				COMPLETE	ONE LINE FOR	EACH CO	MPONER	T FAILURE	DESCRIBE	D IN THIS REPOR	T (13)							
CAUSE	SYETEN	COMP	ONENT	MANUFAC. TURER	REPORTABLE TO WPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPO TO	NPRDS	1				
А	JE	Z <sub>1</sub> 9	99	z 9 9 9	Ň					111	1111							
		1	1.1		161.5				1	1-1-10-	1.1.1							
SUPPLEMENTAL REPORT EXPECTED (14								EXPECTED SUBMISSION DATE 1151		MONTH	DAY	YEAR						
SEE 11 YER COMPINE EXPECTED SUBMISSION DATEL X NO										1	1	1						
On . Wate var	une é er Lev iable-	, 19 vel 2 side	184, a Leve of t	n Instrum 1 Indicat he instrum	ent Mec ing Tra ment.	hanic nsmit This	was ter s sent	in the switch a pres	when sure	ess of te he accide surge thr	sting Un ntally v ough the	it 2 ented inst	React the rumer	tor				

These switches tripped both Reactor Recirculation pumps, initiated a Reactor Core Isolation Cooling (RCIC) injection, and gave a Reactor Protection System (RPS) half scram trip. The RCIC injection tripped the Main Turbine and the Main Turbine trip initiated another RPS half scram trip. A full reactor scram resulted.

Instrument Maintenance personnel were trained on this event and made aware of the consequences of personnel errors. The need to eliminate personnel error was again stressed.

E22

NEC IS - Sed

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

EXPIRES. 8/31/85

ACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)						PAGE 13		
		L	-		SEQUENTIAL		NUMBER	1			
LaSalle County Station Unit 2	0 15 10 10 10 13 17	4	814	-	01215	-	010	0	12	OF	013

## i. EVENT DESCRIPTION

TEXT IF many seaso a required, use addit

-----

On June 6, 1984, at 0530 hours with LaSalle Unit 2 at 24% power, several instruments on the 2H22-P027 instrument rack (JL) actuated when Instrument Maintenance personnel were testing Level Indicating Transmitter Switch (LITS) 2B21-N026B (JM) under Work Request L37424. The instruments that actuated caused Reactor Recirculation (AD, RR) pumps 2A and 2B to trip, Reactor Core Isolation Cooling (BN, RCIC) to inject, and a Reactor Protection System (JC, RPS) half scram trip on Channel B1.

The RCIC injection caused a Main Turbine (TA) trip. When the Main Turbine Stop Valves reached the 95% open position, a RPS half scram trip signal on Channel A1 was received, and a full reactor scram occurred.

### 11. CAUSE

HC Form 366A

At the time of the occurrence an Instrument Mechanic had just isolated instrument LITS 2B21-N026B, Low-Low Reactor Water Level Transmitter/Switch and opened the instrument's equalizing valve. He was in the process of opening the vent valve on the variable side of the instrument when he accidently bumped open the variable-side isolation valve. (The two valves are approximately three inches apart.) He quickly closed the isolation valve, but the Control Room alarm printout shows that a RCIC injection occurred very soon after the instrument's isolation valve was bumped open. A Main Turbine trip and full reactor scram followed within two seconds.

The level switches on panel 2H22-P027 use differential pressure to sense water level. The venting of the variable side of instrument LITS-2B21-N026B caused instruments LIS-2B21-N037B and D and LIS-2B21-N036C and D to see a low pressure on their variable side and the switches actuated. The bumping open of the LITS-2B21-N026B isolation valve apparently also sent a pressure transient through the instrument's reference line causing instrument LIS-2B21-N024B to actuate. LIS-2B21-N037B and D (Reactor Vessel Low Low Level 2) initiated a RCIC injection, LIS-2B21-N036C and D (ATWS Trip) tripped RR pumps 2A and 2B, and LIS-2B21-N024B initiated a RPS half scram trip on Channel .B1 (Reactor Vessel Low Level 3).

The opening of the RCIC Injection Valve (2E51-F013) caused a Main Turbine trip. When Main Turbine Stop Valve #2 reached the 95% open position a RPS half scram trip on Channel A1 was initiated, completing the full scram signal.

It is allowable to have the Reactor half scram trip from stop valve closure bypassed up to 30% power. This half scram bypass had already dropped out at 24% power. This lower setpoint is conservative but within acceptable limits.

Lund Low Man		U.S. NUCLEAR REGI	LATORY COMMISSION
(9-43)	LICENSEE EVENT REPORT (LER) TEXT CONT	INUATION APPROVED ON EXPIRES: 8/21	48 NO. 3150-0104 185
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE 130
		TEAR SEQUENTIAL AEVISION	

LaSalle County Station Unit 2

0 15 10 10 10 13 17 1 4 8 4 - 01215 - 010 0 13 OF 0 13 TEXT (If more species a required, use additional MRC Form 3064's) (17)

# 111. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The venting of the variable side of instruments on panel 2H22-P027 simulated a low reactor water level condition. All instruments actuated and trips occurred as expected for low level conditions. The plant was brought to a safe shutdown.

## IV. CORRECTIVE ACTIONS

Instrument Maintenance personnel were informed of this scram and made aware of the consequences of errors made when working on instruments located on the 2H22-P027 panel. The need to eliminate personnel error was stressed.

#### PREVIOUS OCCURRENCES ν.

No similar occurrences have happened within the year prior to the June 6, 1984 occurrence.

#### NAME AND TELEPHONE NUMBER OF PREPARER V1.

Kenneth J. Kalmon, 815/357-6761, extension 325.



**Commonwealth Edison** LaSai.e County Nuclear Station Rural Route #1, Box 220 Marseilles, Illinois 61341 Telephone 815/357-6761

June 21, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

Reportable Occurrence Report #84-025-00, Docket #050-374 is being submitted to your office in accordance with 10 CFR 50.73.

41 Puderick

G, J. Diederich Superintendent LaSalle County Station

GJD/MLD/kg

Enclosure

xc: NRC, Regional Director INPO-Records Center File/NRC

