

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Callaway Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 8 3	PAGE (3) 1 OF 0 2
--------------------------------------	--	----------------------------

TITLE (4)
Technical Specification Violation - Missed Hourly Fire Watch

EVENT DATE (6)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																									
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																							
0 6	1 2	8 4	8 4	0 0 1	0 0	0 7	0 6	8 4			0 5 0 0 0																							
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:15%;">OPERATING MODE (9) N</td> <td style="width:25%;">20.402(b)</td> <td style="width:25%;">20.406(c)</td> <td style="width:35%;">50.73(a)(2)(iv)</td> <td style="width:20%;">73.71(b)</td> </tr> <tr> <td rowspan="5">POWER LEVEL (10) 0 0 0</td> <td>20.406(a)(1)(i)</td> <td>50.36(e)(1)</td> <td>50.73(a)(2)(v)</td> <td>73.71(c)</td> </tr> <tr> <td>20.406(a)(1)(ii)</td> <td>50.36(e)(2)</td> <td>50.73(a)(2)(vii)</td> <td rowspan="4">OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td> </tr> <tr> <td>20.406(a)(1)(iii)</td> <td>X 50.73(a)(2)(i)</td> <td>50.73(a)(2)(viii)(A)</td> </tr> <tr> <td>20.406(a)(1)(iv)</td> <td>50.73(a)(2)(ii)</td> <td>50.73(a)(2)(viii)(B)</td> </tr> <tr> <td>20.406(a)(1)(v)</td> <td>50.73(a)(2)(iii)</td> <td>50.73(a)(2)(ix)</td> </tr> </table>												OPERATING MODE (9) N	20.402(b)	20.406(c)	50.73(a)(2)(iv)	73.71(b)	POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(c)	20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)	20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)
OPERATING MODE (9) N	20.402(b)	20.406(c)	50.73(a)(2)(iv)	73.71(b)																														
POWER LEVEL (10) 0 0 0	20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(c)																														
	20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)																														
	20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(viii)(A)																															
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)																															
	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)																															

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

LICENSEE CONTACT FOR THIS LER (12)

NAME James E. Davis - Superintendent, Compliance	TELEPHONE NUMBER AREA CODE: 3 1 4 6 7 6 - 8 2 3 6
---	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO X

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 6/12/84, from 1600 to 1700 CDT, prior to initial fuel loading, hourly fire watch patrols for four rooms in the Control Building were missed in violation of Technical Specification action statement 3.7.11.a. The missed rooms resulted in fire barriers with inoperable penetration seals not being patrolled during the 1700 hour patrol. The cause of this was door locks being changed to coincide with receipt of the operating license and new keys not being made promptly available to fire watch personnel. Appropriate keys were issued and patrols to at least one side of the inoperable seals were re-established during the 1800 hour patrol. Patrols to both sides of the inoperable seals were re-established during the 1900 hour patrol. The required room fire detection and suppression systems were operable and this incident posed no threat to the public health or safety.

8407100438 840706
PDR ADOCK 05000483
S PDR

IE22
|||

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Callaway Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 8 3 8 4 - 0 0 1 - 0 0 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
					OF	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 6/12/84, from 1600 to 1700 CDT, prior to initial fuel loading, fire watch patrol missed entering rooms 3306, 3418, 3419 and 3505 in the Control Building. This resulted in fire barriers (3306 ceiling/3419 floor and 3418 ceiling/3505 floor) with inoperable penetration seals not being patrolled during the 1700 hour in violation of Technical Specification action statement 3.7.11.a which requires either a continuous fire watch or that detectors on at least one side of the penetration are verified operable with an hourly fire watch patrol established. The seals for the 3306/3419 penetrations had been installed but not yet accepted as operational, and the 3418/3505 seals were in the process of being installed. Exception to having these seals installed prior to receipt of the operating license was submitted via ULNRC-814 dated May 7, 1984 and accepted by the NRC as shown in License Condition 2.C.7.a.

This incident was caused by lack of coordination of activities by personnel changing door locks due to receipt of the operating license. This resulted in fire watch personnel not having the correct keys to these rooms and, therefore, being unable to successfully complete their watch.

Immediate corrective action included: (1) the issuance of appropriate keys to fire watch personnel, and (2) re-establishment of patrols to at least one side of the inoperable seals during the 1800 hour and to both sides during the 1900 hour. Action to prevent recurrence is as follows: (1) the security locksmith has been instructed to coordinate future lock changes with fire watch supervision and key room personnel, and (2) key room and fire watch personnel have been instructed to utilize the building master key for any further instances of this type.

The required room fire detection and suppression systems were operable and this incident posed no threat to the public health or safety.

Previous occurrences: none.

UNION ELECTRIC COMPANY
CALLAWAY PLANT

July 6, 1984

MAILING ADDRESS:
P. O. BOX 620
FULTON, MO. 65251

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

ULNRC-862

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-25
LICENSEE EVENT REPORT 84-001-00
TECHNICAL SPECIFICATION VIOLATION-MISSED HOURLY FIRE WATCH

Gentlemen:

The enclosed Licensee Event Report is submitted pursuant to
10 CFR 50.73(a)(2)(i) concerning a violation of Technical Specifications
due to missed hourly fire watch.

Andrew P. Neuhalfen

for S. E. Miltenberger
Manager, Callaway Plant

PTA/MED/WRR/DRM/drs
PTA/MED/WRR/DRM/drs
Enclosure

cc: James G. Keppler
USNRC Region III Office
799 Roosevelt Road
Glen Ellyn, IL 60137
Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555
American Nuclear Insurers
c/o Dottie Sherman, Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032
Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

NRC Resident Inspector
Missouri Public Service Commission
D. F. Schnell
J. E. Davis (Z40LER)
R. L. Powers
D. W. Capone
A.C.Passwater/D.E.Shafer/D.J.Walker
G. A. Hughes
W. R. Robinson (QA Record)
P. T. Appleby
SEM Chrono
3456-0021.6
Z40ULNRC
G56.37
N. Date

IE22
1/1