




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

September 27, 1984
RBG-19048
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-240

On August 26, 1984, GSU notified Region IV by telephone that it had determined DR-240 to be reportable under 10CFR50.55(e). This deficiency concerns three potential problems with random trip output of Westinghouse Electric Corporation type SA-1 differential relays. The three potential problems with the SA-1 relay pertain to faulty silicon-controlled rectifiers (SCRs) in the relay output circuit, insufficient surge-withstand-capability (SWC), and internal capacitor failure. The SA-1 relays were identified as being used for River Bend Station equipment and are located in 1EGS*PNL2A, 1EGS*SWG4A, and 1ENS*SWG4B.

An interim or final status report will be provided by October 27, 1984.

Sincerely,

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

3410100349 840927
PDR ADOCK 05000458
S PDR

PSD
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

IE-27 110