U.S. NUCLEAR REGULATORY COMMINS 9-83) LICENSEE EVENT REPORT (LER) EXPIRES: 8/31/85															TORY COMMISSION 40. 3150-0104						
ACILITY)				-							DOCKET NUMBER	(2)	PAGE (3)						
Quad-Cities Nuclear Power Station, Unit 1													0 15 10 10 10 12 15 1 4 1 OF 01 3								
TITLE (4)																					
FUE	leacto	ors	T	am o	n Spur	IOL	is Main	Ste	am Lin	e High	n Flov	v Signal	FACILITIES INVO	VED (B)							
MONTH DAY YEAR YEAR SEQUENTIAL REVISION									H DAY	YEAR		FACILITY NA	NAMES DOCKET NUMBER(S)								
			+					-	1			NA		0 15 10 1	0 0 1 1 1						
10	- 10	ali				-															
0 8	2 8	81	1 8	4	101	6		0	926	84				0 15101	010111						
OPE	RATING	1	-	20.4	02(b)	TTE	DPURSUAN	20.40	REQUIREN	ENTS OF 10	Y CFM 9: 10	BO.73(a)(2)(iv)	or the following) (1	73,71(b)							
POWE	A		+	20.4	06(a)(1)(i)			80.36	H(c)(1)		L^	50.73(a)(2)(r		73.71(e)							
LEVEL 01610				20.4	05(s)(1)(ii)			50.36	l(c)(2)			50.73(a)(2)(vii)		OTHER (Specify in Abstract						
			20.406(a)(1)(iii)				-	60.73	Ha)(2)(i)		_	50.73(a)(2)(viii)(A)	366A)							
			20.408(a)(1)(iv) 20.408(a)(1)(iv)				60.73	(e)(2)(k)		H	50.73(a)(2)(viii)(.)									
			1	1 40.0				LICENSE	E CONTACT	FOR THIS	LER (12)	DO. / JUN 2/(A)		L							
AME														TELEPHONE NU	MBER						
J. Eagle													AREA CODE	654 - 224							
				Lug	0010	ETC.	ONE LINE CO	B FACH	COMPONIES		OFFCE		1 21013		1-1-1-1						
					MANUEL	ere .	DEPODITAR	E	COMPONEN	TAILURE	DESCHIBE	O IN THIS REPOR		herear							
CAUSE	SYSTEM	COM	PONE	NT	TURER		TO NPROS			CAUSE	SYSTEM	COMPONENT	TURER	TO NPRDS							
	1	1	1	1	11	1							111		·						
		1		,																	
			-		SUPPL	EME	NTAL REPOR	T EXPEC	TED (14)				+ + + + + + + + + + + + + + + + + + + +	MONT	H DAY YEAR						
_													SUBMISS	ED ION 5)							
YES	8 (If yes, c	omplete	EXPE	CTEDS	UBMISSION D	ATE	y 		X NO												
			60 p Tow Grou Grou Coult Crar Syst Read Safe	On percy ip l in w tine sem tor tor	August ent con gnal wa lsolat as that surve nt in c causing safety implica	t 2 re tic til ill one g a ti	28, 198 therma receiv on and Instrum lance t divis systems ions of	4, Un red in an am nent f est, ion ous and thi	nit On wer. n the utomat Mainte inadv of the isolat promp s occu	e was At 13 Contro ic Rea nance ertent Main ion s t Open	in th 52 hou ol Roc actor perso tly cr Stean ignal. rator	ne RUN mo urs, a hi om. This scram. onnel, wh reated a n High F1 . Proper action m	de at app gh Main S resulted The cause ile condu low press ow Trip L operatic inimized	oroximate team Lin in a of the acting a ure ogic on of all the	ly e						
							84101 PDR A	1007 00CK	1 840 0500	926 0254 PDR				IE	22						

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85

ACILITY NAME (1)	DOCKET NUMBER (2)						LER NUMBER (6)									PAGE (3)				
							YEAR			SEQUENTIAL P				NUMBER						
Quad-Cities Nuclear Power Station Unit 1	0	15	10	10	10	215	5 1	4	814	4	_	01	11	6	_	0	0	01205	0	12

Event Description

On August 28, 1984, at 1352 hours, Unit One was in the RUN mode at approximately 60 percent core thermal power. While Instrument Maintenance personnel were performing the Main Steam Line (MSL) Hi Flow Surveillance, QIS 21-1, a Group I Isolation was received and an automatic Reactor scram occurred. The 901-5 Panel in the Control Room indicated that the first trip signal was caused by high main steam line flow. All control rods inserted to 00 position and a normal trip recovery was initiated. All Reactor safety systems were operable and functioned as designed, therefore, the safety implications of this occurrence were minimal.

This event is being reported as required by the Code of Federal Regulations, 10 CFR 50.73(a)(2)(iv).

Cause

The cause of this event is personnel error. Sixteen differential pressure (dP) switches, four per MSL, constitute the MSL High Flow Trip Logic. The switches are wired in a one-out-of-two-twice logic arrangement to give a Group I Isolation on high steam line flow. While calibrating one of the switches, the Instrument Mechanic inadvertently opened its isolation valve on the low pressure side prior to pressurizing the instrument to approximate Reactor pressure. This resulted in a low pressure transient which satisfied the one-out-oftwo-twice logic for the corresponding MSL. Therefore, a Group I Isolation and subsequent Reactor scram occurred.

Corrective Action

The immediate corrective action was to ensure all control rods were fully inserted and initiate a normal scram recovery. The Instrument Mechanic involved was carefully counseled on his responsibilities by Station's Management. No further corrective action is deemed necessary at this time due to the fact that this Instrument Mechanic has, over the years, successfully demonstrated his proficiency at this exact task hundreds of times without error.



Commonwealth Edison Quad Cities Nuclear Power Station 22710 206 Avenue North Cordova, Illinois 61242 Telephone 309/654-2241

NJK-84-293

September 26, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Reference: Quad-Cities Nuclear Power Station Docket Number 50-254, DPR-29, Unit One

Enclosed please find Licensee Event Report number 84-016 for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73(a)-(2)(iv), which requires reporting of any event or condition that resulted in manual or automatic actuation of any engineered safety feature.

Respectfully,

COMMONWEALTH EDISON COMPANY QUAD-CITIES NUCLEAR POWER STATION

apropola

N. J. Kalivianakis Station Superintendent

NJK:HQD/bb

Enclosure

cc B. Rybak A. Morrongiello INPO Records Center NRC Region III