

Enclosure 3

Revised Page E1-4
for
Monthly Operating Report
August 1995

HL-5044

9510160270 951009
PDR ADDCK 05000321
R PDR

UNIT SHUTDOWNS AND POWER REDUCTIONS

UNIT NAME: E. I. HATCH - UNIT TWO

DOCKET NO: 50-366

DATE: OCTOBER 2, 1995

COMPLETED BY: S. B. ROGERS

TELEPHONE: (912) 367-7781 x2878

REPORT MONTH: SEPTEMBER 1995

NO.	DATE	TYPE	DURATION (HOURS)	REASON	METHOD	LICENSEE EVENT REPORT NUMBER	SYSTEM CODE	COMPONENT CODE (SUBCODE)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
95-004	950902	F	57.0	A	2	95-003	HF	HTEXCH (D)	The unit was manually scrammed due to a decreasing vacuum on the "A" Main Condenser as a result of "D" Waterbox becoming airborne after fill material in Cell 10 of Cooling Tower No. 5 collapsed and clogged the screens at the tower. The "D" Waterbox was vented, and Cooling Tower No. 5 was cleaned and returned to service. Operations personnel are being briefed on the event.
95-005	950922	S	0.0	C	5	N/A	RC	FUELXX	Shift began reducing power to shut down the unit for the 12th Refueling Outage.
95-006	950923	S	191.0	C	2	N/A	RC	FUELXX	The unit entered the 12th Refueling Outage when Shift inserted a manual scram and subsequent turbine trip.

TYPE:	REASON:	METHOD:	EVENTS REPORTED INVOLVE A GREATER THAN 20% REDUCTION IN AVERAGE DAILY POWER LEVEL FOR THE PRECEDING 24 HOURS.
F-FORCED S-SCHEDULED	A-EQUIPMENT FAILURE (EXPLAIN) B-MAINTENANCE OR TEST C-REFUELING D-REGULATORY RESTRICTION E-OPERATOR TRAINING & LICENSE F-ADMINISTRATIVE G-OPERATIONAL ERROR (EXPLAIN) H-OTHER (EXPLAIN)	1-MANUAL 2-MANUAL SCRAM 3-AUTOMATIC SCRAM 4-CONTINUATIONS 5-LOAD REDUCTION 9-OTHER (EXPLAIN)	

UNIT SHUTDOWNS AND POWER REDUCTIONS

UNIT NAME: E. I. HATCH - UNIT ONE

DOCKET NO.: 50-321

DATE: SEPTEMBER 1, 1995

COMPLETED BY: S. B. ROGERS

TELEPHONE: (912) 367-7781 x2878

REPORT MONTH: AUGUST 1995

NO.	DATE	T Y P E	DURATION (HOURS)	R E A S O N	M E T H O D	LICENSEE EVENT REPORT NUMBER	S Y S T O M E	COMPONENT CODE (SUBCODE)	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
95-005	950814	F	0.0	A	5	N/A	RC	FUELXX	Unit load was reduced to approximately 400 GMWe to locate a potential leaking fuel bundle utilizing Flux Tilt Testing.

TYPE:	REASON:	METHOD:	EVENTS REPORTED INVOLVE A GREATER THAN 20% REDUCTION IN AVERAGE DAILY POWER LEVEL FOR THE PRECEDING 24 HOURS.
F-FORCED S-SCHEDULED	A-EQUIPMENT FAILURE (EXPLAIN) B-MAINTENANCE OR TEST C-REFUELING D-REGULATORY RESTRICTION E-OPERATOR TRAINING & LICENSE F-ADMINISTRATIVE G-OPERATIONAL ERROR (EXPLAIN) H-OTHER (EXPLAIN)	1-MANUAL 2-MANUAL SCRAM 3-AUTOMATIC SCRAM 4-CONTINUATIONS 5-LOAD REDUCTION 9-OTHER (EXPLAIN)	