

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Beaver Valley Power Station, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 3 4	PAGE (3) 1 OF 0 1
--	--------------------------------------	----------------------

TITLE (4)  
Inoperable Hydrogen Recombiner

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
0	3	15	84	01	0	0	9	13	N/A	0 5 0 0 0
0	3	15	84	01	0	0	9	13	N/A	0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

OPERATING MODE (9) 1	20.402(b)	20.405(c)	80.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 1 0 0	20.405(a)(1)(i)	80.36(e)(1)	80.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	80.36(e)(2)	80.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 306A)
20.405(a)(1)(iii)	X 80.73(a)(2)(i)	80.73(a)(2)(vii)(A)		
20.405(a)(1)(iv)	80.73(a)(2)(ii)	80.73(a)(2)(vii)(B)		
20.405(a)(1)(v)	80.73(a)(2)(iii)	80.73(a)(2)(x)		

LICENSEE CONTACT FOR THIS LER (12)

NAME Robert J. Druga, Manager of Technical Services	TELEPHONE NUMBER AREA CODE: 4 1 2 6 4 3 - 5 3 0 8
--	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A				N	A	B	F	H 1 2 9	

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 3/15/84, during the performance of the Six Month Hydrogen Recombiner 1A Test, the "A" Recombiner's Thermal Blower tripped while attempting to adjust flow through the unit. The Blower continued to trip when other flow adjustment attempts were made. As a result, the Recombiner was declared inoperable. The cause of the Recombiner failure was due to a wire interfering with the Flow Indicator. It was first believed that the wire "relaxed" into this position. But after further investigation, it is now believed that the wire was mispositioned during the replacement of a cracked flow indicator cover on 1/31/84. Hence, the Recombiner was inoperable for greater than 30 days, in violation of Technical Specification 3.6.4.2. The Hydrogen Recombiner was declared operable on 3/16/84 after the mispositioned wire was repositioned. To prevent future occurrences, Maintenance personnel were instructed to use caution when working on meter movements. Additionally, these concerns were incorporated into Maintenance Training courses. There were no safety implications since the redundant Recombiner remained operable. On 8/17/84, an investigation ensued to determine if the Recombiner failure was due to a mispositioned wire, versus the previously believed "relaxed" wire. The thirty-day reporting requirement is satisfied under these time constraints.

8410120204 840913  
PDR ADDCK 05000334  
S PDR

IEZZ  
X



**Duquesne Light**

Nuclear Division  
P.O. Box 4  
Shippingport, PA 15077-0004

Telephone (412) 393-6000

September 13, 1984  
ND1SS1:2186

Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334, License No. DPR-66  
LER 84-010

Dr. Thomas E. Murley  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
Park Avenue  
King of Prussia, PA 19046

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 84-010, 10 CFR 50.73.a.2.1, "Condition Prohibited by Technical Specifications."

Very truly yours,

  
Wm. S. Lacey  
Plant Manager

md

Attachment

1/1  
IE 22

T. E. Murley  
September 13, 1984  
ND1SS1:2186  
Page two

cc: Director of Management & Program Analysis  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

C. A. Roteck, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

W. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. A. Triggiani, Operating Plant Projects Manager  
Mid Atlantic Area  
Westinghouse Electric Corporation  
Nuclear Services Integration Division  
Box 2728  
Pittsburgh, PA 15230

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange Suite 245  
270 Farmington Avenue  
Farmington, CN 06032