

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 1 | 1 A R A I N 1 0 1 1 2 | 0 0 0 0 1 0 0 0 0 0 1 0 1 0 0 1 3 | 1 4 1 1 1 1 1 4 | 1 1 1 1 1 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

0 1 1 | REPORT L 1 6 | 0 5 0 0 0 0 3 1 1 3 1 7 | 0 3 2 9 8 | 2 1 8 | 0 9 2 5 8 4 1 9  
7 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | On 3/29/82, while at cold shutdown with the decay heat system in service, the Reactor Building (RB) isolation  
0 3 | valve for the RB coolers chilled water supply, CV-6202, would not completely close during the stroke test  
0 4 | which is required by Technical Specification (T.S.) 4.4.1.4, this occurrence is reportable per T.S.  
0 5 | 16.12.3.2(b).  
0 6 |  
0 7 |  
0 8 |

LER/RO REPORT NUMBER	EVENT YEAR	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE	REVISION NO
17	18   21	A   A	E   11	B   12	V   A   L   V   E   X   13   14	X   15   19	X   16   20	1   1
	22		23					32
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
D   18   33	X   19	Z   20   35	Z   21   36	0   0   0   0   22   37	Y   23   41	Y   24   42	A   25   43	V   0   9   5   26   44   47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The "O" - rings in the Pneumatic Relay in the air supply to valve CV-6202 failed and caused the relay to  
1 1 | go to an intermediate position. This prevented the valve CV-6202 from going fully closed or fully open.  
1 2 | because the failed Pneumatic Relay provided both an air supply path and a vent path. The Pneumatic Relay  
1 3 | is installed in parallel with the air supply solenoid valves for the actuator of valve CV-6202 and is a  
1 4 | backup to assure valve closure upon loss of instrument air. The relay was repaired and reinstalled.  
7 8 9

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
G   28   9	0   0   0   29   10   12	Cold Shutdown   13   44	B   31   45	Routine Surveillance   132   46

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z   33   9	Z   34   10	NA   11   44	NA   136   45   80

PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION
0   0   0   137   9	Z   138   11	NA   13   139

PERSONNEL INJURIES NUMBER	DESCRIPTION
0   0   0   140   9	NA   11   141

LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION
Z   142   9	NA   143

PUBLICITY ISSUED	DESCRIPTION
N   144   9	NA   10   145

NRC USE ONLY  
68 69 | | | | | | | | | | | |  
80

NAME OF PREPARER: Patrick Rogers PHONE: (501) 964-3100

8410120271 840925  
PDR ADOCK 05000313  
S PDR

IE22  
11

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/82-008/03X-1

Occurrence Date: 03/29/82

Cause Description and Corrective Actions (Continued)

Functional checks proved satisfactory. Valve CV-6202 was tested and proved operable. Engineering evaluation of the failed Pneumatic Relay determined the failure mechanism to be "O" - ring breakdown due to oil impregnation. A design change in the air supply to the actuator of valve CV-6202, completed in April 1982, included relocating an oiler installed upstream of the actuator solenoid valves and pneumatic relay to a downstream location. No additional problems have been noted for this valve since completion of the design change.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 25, 1984

1CAN098412

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report  
No. 82-008/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2(b), attached is the subject report concerning the failure of the Reactor Building (RB) isolation valve for the RB coolers chilled water supply, CV-6202, to close properly. This is an update to a previous submittal dated April 21, 1982.

Very truly yours,

John R. Marshall  
Manager, Licensing

JRM:RJS:ac

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
1/1