NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (7-77) LICENSEE EVENT REPORT EXHIBIT A CONTROL BLOCK: 1__1_1_1_1_1_1 11 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10111
REPORT
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I
I</t EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 10121 10n 10/9/81, while in Mode 3, the steam driven Emergency Feedwater Pump, 2P7A, tripped on overspeed while the Imonthly surveillance test was being performed. On 10/11 . the EFW Pump, 2P7A, tripped on overspeed 01 141 I following a manual start during a unit trip ecovery. On 10/12/81, the EFW Pump, 2P7A, tripped on overspeed lafter receiving an auto start signal following a turbine/reactor trip. The electric driven EFW Pump, 2P7B 1015 10161 Iwas available at all times. Reportable per Technical Specification (T.S.) 6.9.1.9.b. 0 SYSTEM LAUSE CAUSE COMP VALVE CODE CONE SUB .ODE 10 112 COMPONENT CODE SUBCODE SUBCODE 0191 2 113 |<u>H</u>|<u>H</u>|11 UIRIBIIIN 14 |<u>Z</u>|15 | Z |16 18 SEQUENTIAL OCCURRENCE REPORT LER/RO REVISION I EVENT YEAR REPORT NO. CODE TYPE 17 REPORT NO $| \frac{18}{21} | \frac{1}{21}$ 01318 0 1 3 1 X I 30 111 NUMBER ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD SUBMITTED FORM SUB HOURS 1 <u>Z</u> |20 SUPPLIER 1 Z 119 MANUFACTURER 1<u>X</u> 118 1 2 121 1_1_1_1_4_1_7_126 $\frac{1010101010122}{40}$ 1 A 125 1<u>Y</u>123 1<u>Y</u>|24 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 11101 The 10/9/81, occurrence was believed to be caused by an oil leak in the turbine hydraulic system. The oil []eak was repaired, and the EFW Pump, 2P7A was tested, found to be operable, and returned to service. [10/11/81, occurrence was attributed to condensation in the steam lines which resulted from insulation not 3 1 Ibeing reinstalled and a steam trap not being unisolated after a maintenance activity. The insulation was [replaced and the trap was unisolated. Also, the trap bypasses were opened to ensure that condensation (cont'd)] 1 | 4 | FACILITY METHOD OF STATUS % POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION <u>1 G 128 1 0 1 0 1 0 129 1 NA</u> 9 10 12 13 1151 130 | A 131 | Operator Observation 4 45 46 132 13 44 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE 1 Z 133 1<u>2</u>|34 | 10 11 NA 135 | NA 136 45 PERSONNEL EXPOSURES 80 NUMBER TYPE DESCRIPTION $\frac{1 \ 0 \ 1 \ 0 \ 1 \ 0 \ 137}{9} \frac{1 \ 2 \ 138}{11} \frac{1 \ 2 \ 138}{12} \frac{1}{13}$ 139 PERSONNEL INJURIES 80 NUMBER DESCRIPTION 1181 0 1 0 1 0 140 1 12 NA 141 LOSS OF OR DAMAGE TO FACILITY 80 TYPE DESCRIPTION Z 42 1 NA 11-191 143 PUBLICITY ISSUED DESCRIPTION NRC USE ONLY 2101 145 1_1_1_1_1_1_1_1_1_1_1_1 8 69 NAME OF PREPARER: Patrick Rogers PHONE: (501) 964-3100

8407250569 840716 PDR ADOCK 05000368 S PDR TEQU

LICENSEE EVENT REPORT

LER No. 50-368/81-038/03X-1

Occurrence Date: 10/09/81

Cause Description and Corrective Actions (Continued)

would not accumulate in the lines. The EFW Pump, 2P7A, was tested, found operable and returned to service. The 10/12/81, occurrence was caused by the steam supply control valve not being properly reset after maintenance. The valve limits were reset properly and the EFW Pump, 2P7A, was tested, and returned to operable status. The design of the governor for the turbine driver was determined to have a high sensitivity to minor system deficiencies which should not by themselves cause the driver to overspeed. Consequently, a design change to reduce sensitivity to overspeed was installed. The new design changed the startup method so that steam is admitted to the turbine through a new bypass line for 15 seconds prior to opening the steam inlet valves (2CV-0340-2). This allows the turbine speed to increase to the idle speed which pressurizes the hydraulic portion of the governor system. This facilitates the governor to respond quickly enough to prevent an overspeed to operations on 11/17/82.



ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 July 16, 1984

2CANØ784Ø2

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

> Subject: Arkansas Nuclear One - Unit 2 Docket No. 50-368 License No. NPF-6 Licensee Event Report No. 81-038/03X-1

Gentlemen:

In accordance with Arkansas Nuclear one - Unit 2 Technical Specification 6.9.1.9b, attached is the subject report concerning steam driven Emergency Feedwater Pump (EFW) 2P7A. This is an update to a previous submittal dated October 30, 1981. Change bars have been added to indicate the updated material.

Very truly yours.

Dohn R. Marshall Manager, Licensing

JRM: RJS: ac

Attachment

cc: Mr. Richard C. DeYoung Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, DC 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, DC 20555

1620