

LICENSEE EVENT REPORT (LER)

|   |                                      |                      |
|---|--------------------------------------|----------------------|
| FACILITY NAME (1)<br>Davis-Besse Unit 1 | DOCKET NUMBER (2)<br>0 5 0 0 0 3 4 6 | PAGE (3)<br>1 OF 0 3 |
|---|--------------------------------------|----------------------|

TITLE (4)  
INADVERTENT TURBINE TRIP FROM 70 per cent FULL POWER

| EVENT DATE (5) |     |      | LER NUMBER (6) |                   |                 | REPORT DATE (7) |     |      | OTHER FACILITIES INVOLVED (8) |  |                  |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|--|------------------|
| MONTH          | DAY | YEAR | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH           | DAY | YEAR | FACILITY NAMES                |  | DOCKET NUMBER(S) |
| 0              | 9   | 1    | 1              | 8                 | 4               | 8               | 4   |      |                               |  | 0 5 0 0 0        |
|                |     |      |                |                   |                 |                 |     |      |                               |  | 0 5 0 0 0        |

|                           |  |  |   |  |   |  |                                    |                                      |                                      |   |  |   |   |   |  |  |  |  |                                   |                                   |  |
|---------------------------|--|--|---|--|---|--|------------------------------------|--------------------------------------|--------------------------------------|---|--|---|---|---|--|--|--|--|-----------------------------------|-----------------------------------|--|
| OPERATING MODE (9)        | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11) |  |   |  |   |  |                                    |                                      |                                      |   |  |   |   |   |  |  |  |  |                                   |                                   |  |
| POWER LEVEL (10)<br>0 7 0 | <input type="checkbox"/> 20.402(b)   | <input type="checkbox"/> 20.406(a)(1)(i) | <input type="checkbox"/> 20.406(a)(1)(ii) | <input type="checkbox"/> 20.406(a)(1)(iii) | <input type="checkbox"/> 20.406(a)(1)(iv) | <input type="checkbox"/> 20.406(a)(1)(v) | <input type="checkbox"/> 20.406(c) | <input type="checkbox"/> 50.36(e)(1) | <input type="checkbox"/> 50.36(e)(2) | <input type="checkbox"/> 50.73(a)(2)(i) | <input type="checkbox"/> 50.73(a)(2)(ii) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input checked="" type="checkbox"/> 50.73(a)(2)(iv) | <input type="checkbox"/> 50.73(a)(2)(v) | <input type="checkbox"/> 50.73(a)(2)(vi) | <input type="checkbox"/> 50.73(a)(2)(vii)(A) | <input type="checkbox"/> 50.73(a)(2)(vii)(B) | <input type="checkbox"/> 50.73(a)(2)(ix) | <input type="checkbox"/> 73.71(b) | <input type="checkbox"/> 73.71(a) | OTHER (Specify in Abstract below and in Text, NRC Form 386A) |

| LICENSEE CONTACT FOR THIS LER (12)             |  |  |  |  |  |  |  |                  |                   |
|--|--|--|--|--|--|--|--|------------------|-------------------|
| NAME<br>Jan Stotz, Technical Section, Ext. 372 |  |  |  |  |  |  |  | TELEPHONE NUMBER |                   |
|  |  |  |  |  |  |  |  | AREA CODE        |                   |
|  |  |  |  |  |  |  |  | 4 1 9            | 2 5 9 - 1 5 0 1 0 |

| COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) |        |           |              |                     |  |       |        |           |              |                     |  |
|--|--------|-----------|--------------|---------------------|--|-------|--------|-----------|--------------|---------------------|--|
| CAUSE  | SYSTEM | COMPONENT | MANUF. TURER | REPORTABLE TO NPROS |  | CAUSE | SYSTEM | COMPONENT | MANUF. TURER | REPORTABLE TO NPROS |  |
| A  | J I    | L S       | M 0 4 0      | N                   |  |       |        |           |              |                     |  |
| X  | S B    | P S V     | C 6 0 0      | Y                   |  |       |        |           |              |                     |  |

|   |  |  |                               |     |      |
|---|--|--|-------------------------------|-----|------|
| SUPPLEMENTAL REPORT EXPECTED (14)   |  |  | EXPECTED SUBMISSION DATE (15) |     |      |
| <input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO |  |  | MONTH                         | DAY | YEAR |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

Davis-Besse was operating at approximately 70% of full power during the power coastdown of Cycle 4. The refueling outage was scheduled to begin on September 14, and Maintenance personnel were positioning the rotor lifting beam onto the turbine deck in preparation for the outage. A 12" x 12" timber being used as dunnage was inadvertently slid into the piping supporting the Moisture Separator Reheater (MSR) High Water Level Switch. The switch activated, tripping the turbine at 1235:17 hours. The ARTS tripped the reactor in response to the turbine trip.

The post trip plant response was as expected. Since the unit was in the outage burnup window, it was decided to begin the refueling outage. A plant cooldown was initiated.

8410190036 841011  
PDR ADOCK 05000346  
S PDR

IE22  
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

|   |  |                |                   |                 |          |    |     |
|---|--|----------------|-------------------|-----------------|----------|----|-----|
| FACILITY NAME (1)<br><br>Davis-Besse Unit 1 | DOCKET NUMBER (2)<br><br>0 5 0 0 0 3 4 6 | LER NUMBER (6) |                   |                 | PAGE (3) |    |     |
|   |  | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER |          |    |     |
|   |  | 8 4            | - 0 1 3           | -               | 0 2      | OF | 0 3 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description of Occurrence: On September 11, 1984 at 1235 hours, Davis-Besse experienced a turbine trip from 70 per cent full power. The turbine trip initiated an Anticipatory Reactor Trip System, ARTS, (JD) trip of the reactor. The post trip response was normal for a trip from 70 per cent full power. Pressurizer (PZR) level remained on scale, and minimum Reactor Coolant System, RCS, (AB) pressure was about 1880 psig. The Power Operated Relief Valve, PORV, (PSV) was not operated. Adequate subcooling margin existed at all times. The #1 Atmospheric Vent Valve, AVV (PSV) did not fully reseal on its own and operators had to lower steam header pressure to get it to reseal.

Since the unit was in the outage burnup window it was decided to begin the refueling outage. A Plant cooldown was initiated.

Later in the cooldown, in Mode 3, with one Reactor Coolant Pump, RCP (P) shutdown, operators had difficulty balancing pressure in the two Once Through Steam Generators, OTSG. At 0109 hours on September 12, 1984, the station received a Steam and Feedwater Rupture Control System SFRCS, (JB) trip from low pressure in OTSG #1. This initiated another ARTS trip of the reactor.

Designation of Apparent Cause of Occurrence: The cause of the trip was an error by personnel positioning a rotor lifting beam on the turbine deck in preparation for the refueling outage turbine work. A 12 x 12 inch timber being used as dunnage was inadvertently slid into the piping which supports the Moisture Separator Reheater, MSR, (SB) High Water Level Switch (LS). The bump caused the switch to actuate. The switch is intended to cause the turbine to be isolated when the water level gets too high in the MSR. This is to protect the turbine from damage that would occur if water hit the blades. The switch caused the turbine to trip which initiated an ARTS trip of the Reactor.

The cause of the #1 AVV not fully reseating was determined to be in the valve control circuit specifically the air control solenoids which are in need of replacement or refurbishment.

The cause of the SFRCS trip on September 12, 1984 was that the Plant Shutdown and Cooldown Procedure PP 1102.10 did not adequately cover an RCS cooldown using the Main Feed Pump Turbine, MFPT (SJ). This change in method of shutting down is due to not being able to use the Startup Feedpump due to pipe break criteria, (See LER 84-009.)

Analysis of Occurrence: The reactor was tripped by ARTS before any Reactor Protection System, RPS (JD) trip setpoint was reached. The PORV was not challenged. Adequate subcooling margin existed at all times. OTSG water levels were properly controlled. The AVV failure to fully reseal did not have a significant safety consideration since the valve was only slightly open. The leakage was not sufficient to affect steam pressure.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

|   |  |                |                   |                 |          |        |
|---|--|----------------|-------------------|-----------------|----------|--------|
| FACILITY NAME (1)<br><br>Davis-Besse Unit 1 | DOCKET NUMBER (2)<br><br>0 5 0 0 0 3 4 6 | LER NUMBER (6) |                   |                 | PAGE (3) |        |
|   |  | YEAR           | SEQUENTIAL NUMBER | REVISION NUMBER |          |        |
|   |  | 8 4            | - 0 1 3           | - 0 0           | 0 3      | OF 0 3 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Corrective Action: The maintenance workers who actuated the switch were counseled on being more careful around operating equipment. The station is working with engineering to place some type of removable guard around the MSR High Level Switches. Engineering will also review the possibility of adding a redundant switch to increase the reliability of the unit.

The AVV will be repaired during the 1984 refueling outage. The soldenoids will be replaced with a new type per the equipment qualification program.

Failure Data: The previous occurrence of this level switch being bumped causing a turbine trip was not reportable per the guidelines in effect prior to 1984.

Report No: NP-33-84-13

DVR No(s): 84-142, 84-143



October 11, 1984

Log No. K84-1283  
File: RR 2 (NP-33-84-13)

Docket No. 50-346  
License No. NPF-3

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Gentlemen:

LER No. 84-013  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: September 11, 1984

Enclosed is Licensee Event Report 84-013, which is being submitted in accordance with 10CFR50.73, to provide 30 day written notification of the subject occurrence.

Yours truly,

A handwritten signature in cursive script that reads "Stephen M. Quennoz".

Stephen M. Quennoz  
Plant Manager  
Davis-Besse Nuclear Power Station

SMQ/bec

Enclosure

cc: Mr. James G. Keppler,  
Regional Administrator,  
USNRC Region III

Mr. Walt Rogers  
DB-1 NRC Resident Inspector

JCS/001

Handwritten initials "LE22" with a vertical line through them, possibly indicating a stamp or a specific filing mark.