Turkey Point Unit 4 Title 14: Engineered Safety Feature Actuation - Reactor Trip EVENT DATE (8) LER NUMBER 18: REPORT DATE (7) OTH MONTH DAY YEAR YEAR SEQUENTIAL NEVERON MONTH DAY YEAR N/A 0 6 2 6 8 4 8 4 0 1 4 0 0 0 7 2 5 8 4 N/A	APPROVED OMB NO 3180-0104 EXPIRES 8/31/86										
Engineered Safety Feature Actuation - Reactor Trip EVENT DATE IS: LER NUMBER IS: REPORT DATE IT: MONTH DAY YEAR YEAR SEGUENTIAL REVISION MONTH DAY YEAR N/A	DOCKE' NUMBER (2)										
Engineered Safety Feature Actuation - Reactor Trip EVENT DATE (B) LER NUMBER (B) REPORT DATE (7) OTH MONTH DAY YEAR YEAR SEGUENTIAL NEVERON MONTH DAY YEAR N/A	0 5 0 0 0 2 5 1 1 0 0 2										
MONTH DAY YEAR YEAR SEQUENTIAL NEVERON MONTH DAY YEAR NAMED NAMED NOTH DAY YEAR NAMED NAMED NOTH DAY	10 0 0 0 2 7 1 1 0 0 7										
MONTH DAY YEAR YEAR SEQUENTIAL NEVERON MONTH DAY YEAR NAMED NAMED NOTH DAY YEAR NAMED NAMED NOTH DAY YEAR NAMED NA											
MONTH DAY YEAR YEAR BEQUENTIAL NUMBER MONTH DAY YEAR NAMED NAMED NOTH DAY YEAR NAMED	ER FACILITIES INVOLVED IN										
N/A											
	0 5 0 0 0 1 1										
06268484 014 00072 58 4 N/A											
	0 15 10 10 10 1 1										
OPERATING THIS REPORT IS BURMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & IChart one or nic	ore of the following (11)										
MODE (8) X 80 73(a)(2)(n)	The same of the sa										
POWER 20 406(a)(1)(0)											
110 0 0 0 0 20 406(a)(1)(b) 80.36(c)(2) 80.73(a)(2)(7)											
20 408 (a)(1)((iii) 80 73(a)(2)(ii) 90 73(a)(2)(iii)	beion and in Taxt NRC Same										
20 408 (a1111(iv) 80 73(a)(2)(iv) 80 73(a)(2)(iv)											
20 408(a)(1)(v) 80.73(a)(2)(m) 80.73(a)(2)(m)											
LICENSEE CONTACT FOR THIS LER (12)											
NAME	TELEPHONE NUMBER										
	AREA CODE										
Randall D. Hart, Licensing Engineer	3,0,5 2,4,5,-,2,9,1,0										
COMPLETE ONE LINE FOR EACH COMPONE TEAL THE DESCRIBED IN THIS REF											
CAUSE SYSTEM COMPONENT MANUFAC REPORTABLE TO NPROS CAUSE SYSTEM COMPONEN											
B I1 G D1 E T1 W 1 2 0 Y											
SUPPLEMENTAL REPORT EXPECTED (14)	MONTH DAY YEAR										
YES III VOL COMPINE EXPECTED SUBMISSION DATE:	EXPECTED SUBMISSION										

On June 26, 1984, Unit 4 experienced a reactor trip while at hot shutdown conditions. The root cause was due to a source range detector, N-32, that failed high above the reactor trip setpoint. Reactor power was below the P6 permissive which unblocks the reactor trip logic for a source range high neutron flux level at shutdown trip. Therefore, when N-32 failed high, the reactor trip logic was completed and a reactor trip occurred. All equipment functioned as designed on initiation of the Engineered Safety Feature Actuation Signal (ESFAS). Immediate corrective actions included: 1) I and C switched the failed detector for N-32 with the spare detector for refueling, 2) N-32 was recalibrated by I and C, and 3) Operations performed a source range periodic functional test on both source range detectors N-32 and N-31. Subsequently, on July 16, 1984, the failed detector was replaced and the system returned to normal configuration. The health and safety of the public were not affected. Similar occurrences: None.

8408010311 840725 PDR ADOCK 05000251 S PDR

ABSTRACT (Limit to 1400 speces is approximately fifteen single spece typewritten lines) [16]

IE 23/1

NRC Form 366A (9-8-3)					U.S	NUC	LEAF	REC	JULA	TOR	Y CON	MISS	SION	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION						APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85								
	DOCKET NUMBER (2)	LER NUMBER (6							PAGE (3)					
		YEAR SEQUENT												
	0 5 0 0 0 2 5 1	8 4	_	0	4	_	0	0	0	2	OF	0	2	
TEXT (If more space is required, use additional NRC Form 366A's)	(17)			-		-	-	-		-		-	-	

On June 26, 1984, at 11:23 a.r..., the Unit 4 reactor tripped from hot shutdown conditions while the unit was being made subcritical for practice start-ups. The root cause was determined to stem from a source range detector, N-32, that failed high above the reactor trip setpoint while power was below the P6 permissive.

When both intermediate range detectors decrease their readings to below 10-10 amps, the source range detectors energize and begin reading in counts per second. When N-32 energized, it failed high (at 4 x 105 cps). This fulfilled the reactor trip logic for a source range high flux at shutdown (1 out of 2 channels) reactor trip. The unit was stabilized and I and C was called to investigate the problem and effect repairs. They found that the detector was bad and proceeded to witch N-32 to the spare refueling detector. Operations commenced and completed a source range periodic functional test on both N-32 and N-31. I and C calibrated N-32 with high voltage and discriminator adjustments as per operating procedure. The calibration was completed and N-32 was returned to service and released to Operations. The unit was returned to power operation at approximately 4:33 p.m., on June 27, 1984. On July 16, 1984, the failed detector was replaced and the system returned to normal configuration.



July 25, 1984 PNS-LI-84-257

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

Re:

Reportable Event 84-14 Turkey Point Unit 4

Date of Event: June 26, 1984 Engineered Safety Feature Actuation - Reactor Trip

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

J. W. Williams, Jr. Group Vice President

Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC

Harold F. Reis, Esquire

File 933.1 TP

IEZZ