PACILITY NAME (1)														U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES. 8/31/85					
														DOCKET NUMBER (2)				PAGE (3)	
														10	1 41813	1	OF O	13	
TITLE (4)											-			_		-		-	
		1	Loss	s of	Samp	le	Flow fo	r Un	it Ver	nt Wid	e Ran	ge Gas M	fonitor						
EVEN	T DATE	(5)	T		LER NUM	BER (6)	RE	PORT DAT	E (7)		OTHE	R FACILITIES INV	DLVE	D (8)				
MONTH	DAY	YEAR	YEAR		SEQUENTIA		REVISION	MONTH	DAY	YEAR	FACILITY NA		AMES		DOCKET NUMBER				
														0	15101	0 0	1	L	
0 6	1 8	8 4	8	/-		16	- 01	0 7	2 5	0/4				0	15101	0 1 0 1	1		
OPER	ATING	0 4	+	REPOR	T IS SUB	MITTE	PURSUANT T	O THE R	EQUIREM	ENTS OF 10	CFR 8: 10	Check one or more	e of the following) (11)		-	-		
		6	20.402(b)					20.405(c)				50.73(a)(2)(iv)			73.71(b)				
POWER				20.406(a)(1)(i)				50.36(e)(1)			50.73(a)(2)(v)				73.71(e)				
(10) 0 1 0 1 0		20.406(a)(1)(ii)					50.36(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text NRC Form						
				20.406	(a)(1)(iii)		X	50,73(a	1(2)(i)			50.73(a)(2)(viii)(A)		366A/				
				20.405	(a)(1)(iv)			50,73(e)(2)(ii)			50.73(a)(2)(viii)(8)						
				20.405	(a)(1)(v)			50.73(a				50.73(a)(2)(x)		\perp				_	
NAME	-					-	L	ICENSEE	CONTACT	FOR THIS	LER (12)			751	EPHONE NU	MRED			
									AREA CODE		EPHONE NO	MIDEN		-					
James Earl Davis - Superintendent, Compliance									31 11 4	6	1 7: 61	10	2121	4					
					COMP	ETE	ONE LINE COR	EACH C	DMPONENT	FAULURE	DESCRIBE	D IN THIS REPO		10	17161-	- 10 1	2 3	0	
CAUSE SYSTEM		сомя	OMPONENT		MANUFAC		REPORTABLE TO NPROS	EACH COMPONEN			SYSTEM	COMPONENT	MANUFAC		REPORTABLE				
					TURER		10 NPHUS						TURER		TO NPROS				
			1 1		1 1	1							1 1 1						
			-		-	-							1	1				-	
	1	-1	1 1		1.1	1						1111	1111						
					SUP	PLEME	NTAL REPORT	EXPECT	ED (14)						MONT	H DA	Y YE	AR	
													EXPECT SUBMISS	SION					
YES	Ilt yes co	omplete I	EXPEC	TED SU	BMISSION	DATE			W NO				DATE	101		1			

On 6/18/84 the sample pump for the Unit Vent Wide Range Gas Monitor (WRGM) was turned off due to operator error, therefore causing the Unit Vent WRGM to alarm on low flow. The loss of sample flow put Technical Specification 3.3.3.10 action (b) into effect requiring continuous auxiliary sampling of iodine and particulate. Due to the fact that continuous auxiliary sampling was not initiated, this event is reported pursuant to 10 CFR 50.73(a)(2)(i). Upon discovery, the sample pump was started reinitializing sample flow from the Unit Vent WRGM.

Due to the plant operating condition, this event had no effect on power operations. There was no effect on public health or safety.

8408070123 840725 PDR ADDCK 05000483 S PDR

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (16)

U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85 DOCKET NUMBER (2) LER NUMBER (6) PAGE (3) SEQUENTIAL YEAR Callaway Plant Unit 1 0 |5 |0 |0 |0 |4 |8 | 3 |8 |4 | 0 0 6

On 6/18/84 at 0802 CDT, the sample pump for Unit Vent Wide Range Gas Monitor GT-RE-21B was turned off due to operator error, causing loss of sample flow to GT-RE-21B. The loss of sample flow put Technical Specification 3.3.3.10 action (b) into effect. Action (b) requires 1) a grab sample for noble gases be taken every 12 hours, and 2) a continuous sample for iodine and particulate be taken by auxiliary sampling equipment. The condition was first discovered at 1320 on 6/18/84 during Health Physics' routine check of radiation monitor skids. It was discovered at this time that there was no flow through the sampler for GT-RE-21B. The Control Room was notified, but no action was taken due to the miscommunication of which radiation monitor was malfunctioning. At 1425 during Health Physics' routine check of radiation monitors on the RM-11 radiation monitor control and display module, it was discovered that there was still no sample flow through GT-RE-21B. Sample flow was immediately reinitiated to GT-RE-21B via the RM-11.

The required continuous sample for iodine and particulate was not commenced due to the Shift Supervisor's interpretation that the 12-hour grab sample for noble gases would also suffice for the iodine and particulate. The 12-hour grab sample for noble gases was waived due to the problem being resolved and the channel returned to service within 12 hours.

After further investigation, it was concluded that the 12-hour grab sample did not satisfy the continuous sample requirements for iodine and particulate. Therefore, this event is being reported pursuant to 10 CFR 50.73(a)(2)(i).

Actions taken to prevent recurrence are as follows: 1) An alarm response procedure has been issued for RM-11 and RM-23 radiation monitor control and display modules. 2) A training program has been developed for the radiation monitors console operation relative to the Technical Specifications. This training includes alarm response pattern, the alarm printout, and other applicable information relative to the operation of the RM-11 and RM-23 consoles. 3) Provided additional training for operations supervisory personnel on the Technical Specifications. 4) Design changes (Callaway Modification Request 84-0232A) have been initiated for an audible alert for the RM-11 and re-flash capability on the main control board for monitor failures from both RM-11 and RM-23. 5) Radiation monitors GT-RE-10A and GT-RE-21A are now on line (these are backup monitors for sampling of iodine and particulate).

Due to the plant operating condition, this event had no effect on power operations. There was no effect on public health or safety.

Previous occurrences: none

TEXT (If more space is required, use additional NRC Form 366.4's) (17)

UNION ELECTRIC COMPANY

July 25, 1984

MAILING ADDRESS: P.O. BOX 620 FULTON, MO. 65251

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

ULNRC-882

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
LICENSEE EVENT REPORT 84-006-01
LOSS OF SAMPLE FLOW FOR
UNIT VENT WIDE RANGE GAS MONITOR

Gentlemen:

The enclosed Licensee Event Report is submitted to correct typographical errors on pages 1 and 2 of LER 84-006-00 transmitted via ULNRC-874, dated 7/18/84. No other changes have been made.

S. E. Miltenberger

WRR/RRG/drs Enclosure

cc: Distribution attached

IE-22

cc distribution for ULNRC-882

James G. Keppler USNRC Region III Office 799 Roosevelt Road Glen Ellyn, IL 60137

American Nuclear Insurers c/o Dottie Sherman, Library Th. change Suite 245 270 Farmington Avenue Farmington, CT 06032

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

NRC Resident Inspector Missouri Public Service Commission

D. F. Schnell

J. E. Davis (Z40LER)

R. L. Powers

D. W. Capone

A. C. Passwater/D. E. Shafer/D. J. Walker

G. A. Hughes

W. R. Robinson (QA Record)

L. K. Robertson (470) (NSRB)

M. E. Taylor

A. P. Neuhalfen

J. R. Peevy

SEM Chrono

3456-0021.6

Z40ULNRC

G56.37

N. Date